

7421 West 129th Street Overland Park, KS 66213-2713 913-319-8662 • kansasgasservice.com

February 21, 2014

Ms. Kim Christiansen Executive Director Kansas Corporation Commission 1500 SW Arrowhead Road Topeka, KS 66604-4027

Re: Docket No. 12-KGSG-721-TAR; Compliance Filing; Docket 13-KGSG-538-CPL.

Dear Ms. Christiansen,

The Commission's order in Docket No. 12-KGSG-721-TAR required KGS to submit annually the remaining cast iron pipe in its system, further identified by pipe diameter. In addition, the Commission requested the number of leaks discovered each year due to corrosion, organized by pipe diameter.

The required information is attached. The first table highlights the leaks caused by corrosion, further identified by pipe size. The second table identifies the inventory of KGS cast iron remaining on its system split by pipe diameter.

Sincerely,

Dave Dittemore

Mgr. Rates and Regulatory Affairs

Kansas Gas Service, a Division of ONE Gas, Inc.

Dikmoze

cc: Leo Haynos

2013 KGS Corrosion Leaks in Cl Pipe by Size												
Area		Total										
	4"	6"	8"	10"	12"	16"	20"					
KCK	0	2	0	0	0	0	0	2				
Topeka	8	2	0	0	0	0	0	10				
Wichita	1	0	7	0	1	0	0	9				
Total	9	4	7	0	1	0	0	21				

2013 Cl Inventory by Size											
	4"	6"	8"	10"	12"	16"	20"	Total Feet	Total Miles		
Feet	219,726	131,089	27,472	27,675	31,034	1,844	520	439,360			
Miles	41.61	24.83	5.20	5.24	5.88	0.35	0.10		83.21		