THE STATE CORPORATION COMMISSION OF THE STATE OF KANSAS

Before Commissioners: Andrew J. French, Chairperson

Dwight D. Keen Annie Kuether

In the matter of the failure of Elendil)
Resources, LLC (Operator) to comply with)
K.A.R. 82-3-111 at the Jensen #3 and Lonker)
Conservation Division

"A" #1 wells in Barber and Edwards)
Counties, Kansas.

License No.: 36092

PENALTY ORDER

The Commission finds Operator has violated K.A.R. 82-3-111 regarding the captioned wells, assesses a \$200 penalty, directs Operator to come into compliance, and further rules as more fully described below.

I. JURISDICTION

- 1. K.S.A. 74-623 provides the Commission exclusive jurisdiction and authority to regulate oil and gas activities in Kansas. K.S.A. 55-152 provides the Commission with jurisdiction to regulate the construction, operation, and abandonment of any well, and also the protection of the usable water of this state from any actual or potential pollution from any well. The Commission has licensing authority under K.S.A. 55-155.
- 2. K.S.A. 55-162 and K.S.A. 55-164 provide the Commission authority to issue penalty orders for violations of Chapter 55 of the Kansas Statutes Annotated, or of any rule, regulation, or order of the Commission. Under K.S.A. 55-164, a penalty order may include a monetary penalty of up to \$10,000, the penalty must constitute a substantial and actual economic deterrent to the violation, and each day of a continuing violation constitutes a separate violation.
- 3. K.A.R. 82-3-111 provides that within 90 days after operations cease on any well, the operator of that well shall plug the well, return the well to service, or file an application with

the Conservation Division requesting temporary abandonment (TA) status. If not plugged or returned to service, the operator must obtain TA approval; TA status may be denied by the Conservation Division if necessary to prevent pollution. A well shut-in for 10 years or more cannot be granted TA status without the operator filing an application for an exception pursuant to K.A.R. 82-3-100 and approval from the Commission. K.A.R. 82-3-111(e) provides a TA exemption for certain wells fully equipped and capable of production.

II. FINDINGS OF FACT

- 4. Operator is licensed to conduct oil and gas activities in Kansas and is responsible for the following wells (Subject Wells):
 - a. Jensen #3, API #15-047-21453-00-00, located in Section 6, Township 23 South, Range 20 West, Edwards County, Kansas; and
 - b. Lonker "A" #1, API #15-007-03309-00-00, located in Section 2, Township33 South, Range 13 West, Barber County, Kansas.
- 5. On September 5, 2024, Commission records indicated the Subject Wells had been inactive and unplugged for longer than the 90 days allowed by K.A.R. 82-3-111, that the wells were not exempt pursuant to K.A.R. 82-3-111(e), and that the wells were not approved for TA status. Thus, Commission Staff sent letters to Operator, requiring Operator to bring the Subject Wells into compliance with K.A.R. 82-3-111 by September 19, 2024.
- 6. Between October 8, 2024, and October 9, 2024, Commission Staff inspected the Subject Wells, because the deadline in the letters had passed and the violations had not been resolved, verifying that the wells continued to be inactive and unplugged.²

² Exhibit B.

¹ Exhibit A.

III. CONCLUSIONS OF LAW

- 7. The Commission has jurisdiction over Operator and this matter under K.S.A. 74-623 and K.S.A. 55-152.
- 8. Operator has committed two violations of K.A.R. 82-3-111 because the Subject Wells have been inactive in excess of the time allowed by regulation without being plugged, returned to service, or approved for TA status.³

THEREFORE, THE COMMISSION ORDERS:

- A. Operator shall pay a \$200 penalty.
- B. Operator shall plug the Subject Wells, or return the wells to service, or obtain TA status for the wells if eligible.
- C. Commission Staff may require Staff-witnessed static fluid level measurements before a Subject Well is returned to service. A Subject Well may not be returned to service if (1) any measurement has shown fluid in the wellbore at or above the appropriate minimum surface casing requirement described in Table I of the Commission's August 1, 1991, Order in Docket 34,780, (2) any measurement has shown fluid in the wellbore at or above any salt formation or other corrosive formation, or (3) in the opinion of Staff, variation in measurements indicates the possibility of a casing leak. Provided, however, a Subject Well may be returned to service upon (a) passing a casing integrity test after issuance of this Penalty Order to the satisfaction of Staff, or (b) Staff providing written, well-specific authorization after issuance of this Penalty Order.
- D. Operator may request a hearing on the above issues by submitting a written request, pursuant to K.S.A. 55-164, K.S.A. 77-537, and K.S.A. 77-542, to the Commission at 266 N. Main St., Suite 220, Wichita, Kansas 67202, within 30 days from the date of service of this Order. <u>A request for hearing must comply with K.A.R. 82-1-219.</u>

3

³ K.S.A. 55-164; K.A.R. 82-3-111(b).

E. <u>Failure to timely request a hearing will result in a waiver of Operator's right to a</u>

hearing. If no party timely requests a hearing, then this Order shall become final.

F. If Operator is not in compliance with this Order and the Order is final, then

Operator's license shall be suspended without further notice and shall remain suspended until

Operator complies. If a Subject Well has been inactive for more than 10 years and Operator

applies for an exception to the 10-year limit on TA status for the Subject Well prior to this Order

becoming final, and Operator would be in compliance with this Order if the application were

approved, then suspension shall not be enforced unless: (1) the application is denied, and (2) 30

days have elapsed since the denial. The notice and opportunity for a hearing on this Order shall

constitute the notice required by K.S.A. 77-512 regarding license suspension.

G. A party may petition for reconsideration of a final order pursuant to the

requirements and time limits established by K.S.A. 77-529(a)(1).⁴

H. Credit card payments may be made by calling the Conservation Division at 316-

337-6200. Checks and money orders shall be payable to the Kansas Corporation Commission.

Payments shall be mailed to the Kansas Corporation Commission at 266 N. Main St., Suite 220,

Wichita, Kansas 67202. Payments must reference the docket number of this proceeding.

BY THE COMMISSION IT IS SO ORDERED.

French, Chairperson; Keen, Commissioner; Kuether, Commissioner

Lynn M. Retz Executive Director

Mailed Date: __10/22/2024

TSK

⁴ See K.S.A. 55-162; K.S.A. 55-164; K.S.A. 55-606; K.S.A. 55-707; K.S.A. 77-503(c); K.S.A. 77-531(b).

4



Andrew J. French, Chairperson Dwight D. Keen, Commissioner Annie Kuether, Commissioner Corporation Commission

Laura Kelly, Governor

NOTICE OF VIOLATION

September 05, 2024 KCC Lic.-36092

ELENDIL RESOURCES LLC 12333 SOWDEN RD STE B PMB 50808 HOUSTON TX 77081-2059

RE: API Well No. 15-047-21453-00-00

JENSEN 3

6-23S-20W, N2SWNW EDWARDS County, Kansas

Dear Operator:

According to KCC records, the temporary abandonment (TA) status for this well expired on August 21, 2024, and you are in probable violation of K.A.R. 82-3-111. An operator may apply to the Conservation Division for a TA status extension prior to the expiration of its TA approval period.

If you file a TA application with the District Office by SEPTEMBER 19, 2024, we will process the application. If you do not file an application by this date, or advise the District Office in writing the date the well returned to service, I will refer the matter to our legal department with a recommendation that the Commission take formal enforcement action including a monetary penalty and an order for you to plug the well.

You may contact me at the number below if you have any questions.

Sincerely,

MICHAEL MAIER
KCC District # 1



Andrew J. French, Chairperson Dwight D. Keen, Commissioner Annie Kuether, Commissioner Corporation Commission

Laura Kelly, Governor

NOTICE OF VIOLATION

September 05, 2024 KCC Lic.-36092

ELENDIL RESOURCES LLC 12333 SOWDEN RD STE B PMB 50808 HOUSTON TX 77081-2059

RE: API Well No. 15-007-03309-00-00

LONKER "A" 1 2-33S-13W, N2NE

BARBER County, Kansas

Dear Operator:

According to KCC records, the temporary abandonment (TA) status for this well expired on August 21, 2024, and you are in probable violation of K.A.R. 82-3-111. An operator may apply to the Conservation Division for a TA status extension prior to the expiration of its TA approval period.

If you file a TA application with the District Office by SEPTEMBER 19, 2024, we will process the application. If you do not file an application by this date, or advise the District Office in writing the date the well returned to service, I will refer the matter to our legal department with a recommendation that the Commission take formal enforcement action including a monetary penalty and an order for you to plug the well.

You may contact me at the number below if you have any questions.

Sincerely,

MICHAEL MAIER
KCC District # 1

KCC OIL/GAS REGULATORY OFFICES

Date: 10/9/24	District: _1	<u> </u>	Case #:	
	New Situa	ation	Lease Inspe	ection
	Response	to Request	Complaint	
	Follow-U	p.	Field Repor	·t
Operator License No: 36092		ber: <u>15-047-2145</u>		nort I read to the
Op Name: Elendil Resources, LLC				S Rng 20 E / W
Address 1: 12333 Sowden Rd., Ste. B, PMB 50808				N/ S Line of Section
Address 2:				✓E/ W Line of Section
City: Houston				Date: 10/9/24
State: TX Zip Code: 77081 -2059	Lease Name:	ensen		Well #: 3
Operator Phone #: <u>(979) 574-6211</u>	County: Edw	ards		
Reason for Investigation:				
Request to check well status.				
Problem:				
Inactive well.				
inideate mem				
	1			
Persons Contacted:				
None.				
Findings:		1,60,40,1		and a
This well is fully-equipped with a gas powere work missing. Tank battery equipment includes separator; and a small gaspack. There is also No current tank ID sign. The paper chart gadeadline of 9/19/24. Last production reported	des: 200 bbl fil so a junk 200 l s meter has no	berglass, partiall obl steel stock ta o chart. NOV TA	ly netted tank ank on locatio A letter sent 9	k; 30" X 6' vertical on. No pit or dike. 9/5/24 with a
- Aug 1				
×Yr =				
Action/Recommendations: Follo	w Up Required	Yes No	Date:	
Penalty recommendation for TA. Send tank	ID sign NOV	letter.		
-				
Verification Sources:				Photos Taken: 2
Month of Color Col	TA Program			
✓ RBDMS ✓ KGS T-I Database District Files Other: On-site inspection.	TA Program Courthouse	By: <u>Eric MacLa</u>	iren	
- in the second	* 1			
Retain 1 Copy District Office Send 1 Copy to Conservation Division				

Exhibit B Page 1 of 5




10/9/24

Elendil Resources, LLC

Jensen #3

NW 6-23S-20W, Edwards County

Picture of inactive well and pump jack, facing Northeast.



10/9/24

Elendil Resources, LLC

Jensen #3

NW 6-23S-20W, Edwards County

Picture of uncharted gas meter, facing North.

KCC OIL/GAS REGULATORY OFFICES

Date: 10/8/24	District:1	Case #:		
	New Situation	Lease Inspection		
	Response to Request	Complaint		
	Follow-Up	Field Report		
				
Operator License No: 36092	API Well Number: <u>15-007-03309-00-00</u>			
Op Name: Elendil Resources LLC		Sec _2Twp _33S Rng _13E / \subseteq W		
Address 1: 12333 Sowden Rd.		Feet from N/ S Line of Section		
Address 2: Suite B PMB 50808		Feet from Feet from W Line of Section		
City: Houston	GPS: Lat: 37.20863	Long: 98.70008 Date: 10/8/24		
State: TX Zip Code: <u>77081 -2059</u>	Lease Name: Lonker "A"	Well #:1		
Operator Phone #: (979) 574-6211	County: Barber	A STORY OF STREET		
Reason for Investigation:				
NOV; Expired TA.	- T-17 , T-1	w production in		
Problem:				
Potential Violations.				
Toterital violations.		[] of the destruction of the contract of		
Persons Contacted:				
None		and the second s		
Findings:				
3:00 PM		The second section		
Tank battery located 4570' FSL, 1397' FEL. water tank, no dike. Water trucked off lease. Meter off. Gas compressor next to meter not #1 NW NW NW. Fully equipped oil well with	Meter run located 391 operating.	8' FSL, 4695' FEL Sect. 1-T33S-R13W.		
No current leaks, spills or scarring.				
Action/Recommendations: Follow	v Up Required Yes ✓N	o Date:		
germent by the routing and the properties and an employed state.				
Forward to legal. Send NOV no sign letter.				
Seria NOV no significater.				
		H		
Verification Sources:		Photos Taken:		
✓ RBDMS ✓ KGS	ΓA Program			
	Courthouse By: Day	vid Ring, ECRS		
✓ Other: Leo 7, On-site inspection.				
V Carrie Leo 1, On-Site inspection.				

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: 10/08/2024



10/08/2024

Elendil Resources, LLC

KLN #36092

Lonker "A" #1

15-007-03309-00-00

GPS: 37.20863, -98.70008 4595' FSL, 1324' FEL NE SE NW NE Sec. 2-T33S-R13W Barber County Valves closed.

CERTIFICATE OF SERVICE

25-CONS-3141-CPEN

I, the undersigned, certify that a true copy of	the attached Order has been served to the following by means of
first class mail and electronic service on	
TRISTAN KIMBRELL, LITIGATION COUNSEL KANSAS CORPORATION COMMISSION CENTRAL OFFICE 266 N. MAIN ST, STE 220 WICHITA, KS 67202-1513 tristan.kimbrell@ks.gov	ATTN: LAND DEPARTMENT ELENDIL RESOURCES LLC 12333 SOWDEN RD STE B PMB 50808 HOUSTON, TX 77081-2059
FRED MACLAREN KANSAS CORPORATION COMMISSION DISTRICT OFFICE NO. 1 210 E. FRONTVIEW SUITE A DODGE CITY, KS 67801 frederic.maclaren@ks.gov	KENNY SULLIVAN, DISTRICT #1 SUPERVISOR KANSAS CORPORATION COMMISSION DISTRICT OFFICE NO. 1 210 E. FRONTVIEW SUITE A DODGE CITY, KS 67801 kenny.sullivan@ks.gov
	/S/ KCC Docket Room

KCC Docket Room