



7421 West 129<sup>th</sup> Street  
Overland Park, KS 66213-2713  
913-319-8662 • kansasgasservice.com

February 28, 2018

Kansas Corporation Commission  
Attn: Lynn M. Retz, Secretary to Commission  
1500 SW Arrowhead Road  
Topeka, KS 66604-4027

Re: Docket No. 12-KGSG-721-TAR; Compliance Filing; Docket 13-KGSG-538-CPL.

Dear Ms. Retz,

The Commission's order in Docket No. 12-KGSG-721-TAR required KGS to submit annually the remaining cast iron pipe in its system, further identified by pipe diameter. In addition, the Commission requested the number of leaks discovered each year due to corrosion, organized by pipe diameter.

The required information is attached. The first table highlights the leaks caused by corrosion, further identified by pipe size. The second table identifies the inventory of KGS cast iron remaining on its system split by pipe diameter.

Sincerely,



Janet Buchanan  
Director - Rates and Regulatory Affairs  
Kansas Gas Service, a Division of ONE Gas, Inc.

cc: Leo Haynos

2017 KGS Corrosion Leaks in CI Pipe by Size								
Area	Size							Total
	4"	6"	8"	10"	12"	16"	20"	
KCK	7	5	0	0	5	0	0	17
Topeka	3	0	0	1	0	0	0	4
Wichita	0	0	0	0	0	0	0	0
Total	10	5	0	1	5	0	0	21

2017 CI Inventory by Size									
	4"	6"	8"	10"	12"	16"	20"	Total Feet	Total Miles
Feet	47,086	30,567	2,794	11,161	4,915	0	0	96,523	
Miles	8.92	5.79	0.53	2.11	0.93	0.00	0.00		18.28