20190821153807 Filed Date: 08/21/2019 State Corporation Commission of Kansas

## DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

**Kansas Highway Patrol** 

MOTOR CARRIER SAFETY ASSISTANCE

700 SW Jackson, Ste 704

Topeka, KS 66603

Phone: (785)296-7189 Fax: (785)296-2858

Report Number: KSHP01130895 Inspection Date: 07/23/2019

Start: 1:45 PM CT End: 03:00 PM CT Inspection Level: II - Walk-Around

HM Inspection Type: None

AMERICAN ALLIANCE, LLC

5313 W 124TH TER

LEAWOOD, KS 66209-3199

**USDOT#**: 03318044 **MC/MX#**: 00000000

Phor

Phone#: Fax#:

Driver: BANI-ARDALAN, BAHRAM -

License#: Date of Bi State: KS

CoDriver: License#:

State:

Date of Birth:

Location: WYANDOTTE COUNTY - 209

MilePost: 6.5

Shipper: CARRIER

Origin: TIFFANY SPRINGS,MO B

Bill of Lading:

County:

Highway: 1-635

State#:

2

Destination: OLATHE,KS

Cargo: ASPHALT/HEAVY EQUIPMENT

**VEHICLE IDENTIFICATION** 

Unit Type Make Year State Plate #

1 TR INTL 2009 KS 509MC

ST NORRI 1997 LA

509MCS E405104 Equipment ID 01 001 <u>VIN</u> 192335 007832

GVWR 5 33,000 2 24,000 CVSA# New CVSA#

OOS#

BRAKE ADJUSTMENTS: No Brake Measurements Required For Level 2

VIOLATIONS			,			
Vio Code	Section	<u>Unit</u>	OOS Citation #	Verify	Crash	Violations Discovered
392.2RG	392.2RG	1	N	N	N	State vehicle registration or License Plate violation: 8-142(12)No registration receipt in truck
396.17C	396.17C	1	N	N	N	Operating a CMV without proof of a periodic inspection
390.21B	390.21B	1	N	N	N	Carrier name and/or USDOT Number not displayed as required
396.5B	396.5B	1	N	Ν	N	Oil and/or grease leak
393.43	393.43	2	Y	Α	N	No/improper breakaway or emergency braking: BRAKE AWAY CABLE NOT ATTACHED TO TOWING VEHICLE
393.9TS	393.9TS	2	Υ	U	N	Inoperative turn signal: LEFT REAR TURN SIGNAL INOP
393.25F	393.25F	2	N	Ν	N	Stop lamp violations: RIGHT STOP LAMP INOP
393.9T	393.9T	2	N	Ν	N	Inoperable tail lamp: RIGHT TAIL LAMP INOP
393.9	393.9	2	N	N	Ν	Inoperable Required Lamp: REAR LEFT MARKER LAMP INOP
393.11LR	393.11LR	2	N	N	N	No Lower rear retroreflective sheeting or reflex reflective materials as required for vehicles manufactured after December 1993
393.130	393.130	2	Υ	U	N	No/improper heavy vehicle/machine securement: Heavy Case skidloader indirectly secured with one chain on the fron and one chain on bak. Front chain was loose. Required minimum of four tiedowns
396.17C	396.17C	2	N	N	N	Operating a CMV without proof of a periodic inspection
391.41A-F	391.41A-F	D	N	N	N	Operating a property-carrying vehicle without possessing a valid medical certificate.
383.91A	383.91A	D	Υ	N	N	Operating a cmv with improper CDL group: Vehicle combination requires Class A CDL

Report Prepared By:

R.G. Armitage

Badge #: 0113

Copy Received By: BAHRAM BANI-ARDALAN

Page 1 o



03318044

KSHP01130895

Report Number: KSHP01130895

**Kansas Highway Patrol** Inspection Date: 07/23/2019 **MOTOR CARRIER SAFETY ASSISTANCE** Start: 1:45 PM CT End: 03:00 PM CT 700 SW Jackson, Ste 704 Inspection Level: II - Walk-Around Topeka, KS 66603 Phone: (785)296-7189 Fax: (785)296-2858 HM Inspection Type: None AMERICAN ALLIANCE LLC Driver: BANI-ARDALAN, BAHRAM -5313 W 124TH TER License#: State: KS Date of Bi LEAWOOD, KS 66209-3199 **USDOT#**: 03318044 Phone#: CoDriver: MC/MX#: 00000000 License#: State: Fax#: Date of Birth: State#: Unit OOS Citation # Violations Discovered Vio Code Section Verify Crash State or International Fuel Tax (IFTA) Violation: 392.2FT 392.2FT Ν Ν Ν NO RECORD 392.2-SLLEWA1 392.2-SLLEWA1 D N Ν Ν State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.: 8-1908 -AXLE 2/RIGHT Wheel over max allowed per wheel of 10000lb, actual 10700LB (700lbs) USDOT REGISTRATION REQUIRED. (1st Ν 392.9BA-NOREG 392.9BA-NOREG 1 Ν Ν Offense) Operating a commercial motor vehicle in interstate commerce without a USDOT Registration. Failure to pay UCR Fee: NO RECORD 392.2UCR 392.2UCR Ν Ν Ν HazMat: No HM Transported Placard: No Cargo Tank: Special Checks: Size & Weight; \* Pursuant to the authority contained in Title 49, CFR; K.S.A. 66-1,129; K.C.C. Reg. 82-4-3, I hereby declare BAHRAM BANI-ARDALAN "OUT OF SERVICE". No person and/or carrier shall permit and/or require this driver to operate any commercial vehicle until: Driver has proper class CDL. This Out of Service condition may result in the assessment of a Civil Penalty being issued against the Carrier indicated on this report. Driver Initials \* Pursuant to the authority contained in Title 49, CFR; K.S.A. 66-1,129; K.C.C. Reg. 82-4-3, I hereby declare the above marked unit(s) as "OUT OF SERVICE". No person and/or carrier shall permit and/or require the removal of the "OUT OF SERVICE" stickers or the operation of this motor vehicle until ALL out of service defects have been corrected. This Out of Service condition may result in the assessment of a Civil Penalty being issued against the Carrier indicated on this report. Driver Initials \* NOTE TO MECHANIC: The undersigned certifies that all mechanical defects listed on this report HAVE BEEN CORRECTED at the time of signature. Signature Of Repairer X: Date:

must be corrected or acknowledged PRIOR TO RE-DISPATCH and then certified by a responsible carrier official who must sign below. RETURN THIS FORM WITHIN 15 DAYS to

Repo	rt Prepared	By:
R.G.	Armitage	

Signature Of Motor Carrier X:

Badge #:

\*\*\\\*\* DRIVER: THIS FORM IS REQUIRED TO BE RETURNED TO THE CARRIER BY REGULATION. \*\*//\*\*

the Motor Carrier Division of the KANSAS HIGHWAY PATROL at the address listed at the top of this form.

Copy Received By: **BAHRAM BANI-ARDALAN** 



\*CARRIER CERTIFICATION: All defects on this sheet

## DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

Kansas Highway Patrol

MOTOR CARRIER SAFETY ASSISTANCE

700 SW Jackson, Ste 704

Topeka, KS 66603

Phone: (785)296-7189 Fax: (785)296-2858

Phone#:

Fax#:

Report Number: KSHP01130895 Inspection Date: 07/23/2019

Start: 1:45 PM CT End: 03:00 PM CT Inspection Level: II - Walk-Around

HM Inspection Type: None

AMERICAN ALLIANCE LLC

5313 W 124TH TER

LEAWOOD, KS 66209-3199

**USDOT#**: 03318044

MC/MX#: 00000000

State#:

Driver: BANI-ARDALAN, BAHRAM -

License#: Date of Bi

CoDriver:

License#:

Date of Birth:

State: KS

State:

## **Inspection Notes**

Two axle dump truck pulling a two axle heavy trailer. On trailer was a heavy Case skid loader, scoop bucket for the loader, and two other heavy pieces of equipment. Skid loader was to the trailer with two (R4) chains. Each chain was connect to the side of the trailer and passed over the skid loader and secured to the opposite side. One chain on the front and one chain on the back. The front chain was loose. The owner stated that he had just registered the truck and had not had time to apply for USDOT. Truck was loaded with asphat.

Special Studies No Special Study Data Recorded								

Report Prepared By: R.G. Armitage

Badge #:

Copy Received By: BAHRAM BANI-ARDALAN



KSHP01130895