



7421 West 129th Street
Overland Park, KS 66213-2713
913-319-8662 • kansasgasservice.com

February 11, 2016

Kansas Corporation Commission
Attn: Ms. Amy Green, Commission Secretary
1500 SW Arrowhead Road
Topeka, KS 66604-4027

Re: Docket No. 12-KGSG-721-TAR; Compliance Filing; Docket 13-KGSG-538-CPL.

Dear Ms. Green,

The Commission's order in Docket No. 12-KGSG-721-TAR required KGS to submit annually the remaining cast iron pipe in its system, further identified by pipe diameter. In addition, the Commission requested the number of leaks discovered each year due to corrosion, organized by pipe diameter.

The required information is attached. The first table highlights the leaks caused by corrosion, further identified by pipe size. The second table identifies the inventory of KGS cast iron remaining on its system split by pipe diameter.

Sincerely,



Dave Dittmore
Director - Rates and Regulatory Affairs
Kansas Gas Service, a Division of ONE Gas, Inc.

cc: Leo Haynos

2015 KGS Corrosion Leaks in CI Pipe by Size

Area	Size							Total
	4"	6"	8"	10"	12"	16"	20"	
KCK	1	1	0	0	0	0	0	2
Topeka	1	4	0	0	0	0	0	5
Wichita	0	0	1	0	0	0	0	1
Total	2	5	1	0	0	0	0	8

2015 CI Inventory by Size

	4"	6"	8"	10"	12"	16"	20"	Total Feet	Total Miles
Feet	133,385	83,525	17,364	25,117	23,026	1,844	520	284,781	
Miles	25.26	15.82	3.29	4.76	4.36	0.35	0.10		53.94