

**THE STATE CORPORATION COMMISSION
OF THE STATE OF KANSAS**

Before Commissioners: Andrew J. French, Chairperson
 Dwight D. Keen
 Annie Kuether

In the matter of the failure of RFORTUNA,) Docket No.: 25-CONS-3056-CPEN
LLC (Operator) to comply with K.A.R.)
82-3-111 at the Boles #3-11 well in Seward) CONSERVATION DIVISION
County, Kansas.)
_____) License No.: 36101

PENALTY ORDER

The Commission finds Operator violated K.A.R. 82-3-111 regarding the captioned well, assesses a \$100 penalty, directs Operator to come into compliance, and further rules as more fully described below.

I. JURISDICTION

1. K.S.A. 74-623 provides the Commission exclusive jurisdiction and authority to regulate oil and gas activities in Kansas. K.S.A. 55-152 provides the Commission with jurisdiction to regulate the construction, operation, and abandonment of any well, and also the protection of the usable water of this state from any actual or potential pollution from any well. The Commission has licensing authority under K.S.A. 55-155.

2. K.S.A. 55-162 and K.S.A. 55-164 provide the Commission authority to issue penalty orders for violations of Chapter 55 of the Kansas Statutes Annotated, or of any rule, regulation, or order of the Commission. Under K.S.A. 55-164, a penalty order may include a monetary penalty of up to \$10,000, the penalty must constitute a substantial and actual economic deterrent to the violation, and each day of a continuing violation constitutes a separate violation.

3. K.A.R. 82-3-111 provides that within 90 days after operations cease on any well, the operator of that well shall plug the well, return the well to service, or file an application with

the Conservation Division requesting temporary abandonment (TA) status. If not plugged or returned to service, the operator must obtain TA approval; TA status may be denied by the Conservation Division if necessary to prevent pollution. A well shut-in for 10 years or more cannot be granted TA status without the operator filing an application for an exception pursuant to K.A.R. 82-3-100 and approval from the Commission. K.A.R. 82-3-111(e) provides a TA exemption for certain wells fully equipped and capable of production.

II. FINDINGS OF FACT

4. Operator is licensed to conduct oil and gas activities in Kansas and is responsible for the Boles #3-11 well (Subject Well), API #15-175-20768-00-01, located in Section 11, Township 32 South, Range 34 West, Seward County, Kansas.

5. On June 10, 2024, Commission records indicated the Subject Well had been inactive and unplugged for longer than the 90 days allowed by K.A.R. 82-3-111, that the well was not exempt pursuant to K.A.R. 82-3-111(e), and that the well was not approved for TA status. Thus, Commission Staff sent a letter to Operator, requiring Operator to bring the Subject Well into compliance with K.A.R. 82-3-111 by July 10, 2024.¹

6. On July 18, 2024, Commission Staff inspected the Subject Well, because the deadline in the letter had passed and the violation had not been resolved, verifying that the well continued to be inactive and unplugged.²

III. CONCLUSIONS OF LAW

7. The Commission has jurisdiction over Operator and this matter under K.S.A. 74-623 and K.S.A. 55-152.

¹ Exhibit A.

² Exhibit B.

8. Operator has committed one violation of K.A.R. 82-3-111 because the Subject Well has been inactive in excess of the time allowed by regulation without being plugged, returned to service, or approved for TA status.³

THEREFORE, THE COMMISSION ORDERS:

A. Operator shall pay a \$100 penalty.

B. Operator shall plug the Subject Well, or return the well to service, or obtain TA status for the well if eligible.

C. Commission Staff may require Staff-witnessed static fluid level measurements before a Subject Well is returned to service. A Subject Well may not be returned to service if (1) any measurement has shown fluid in the wellbore at or above the appropriate minimum surface casing requirement described in Table I of the Commission's August 1, 1991, Order in Docket 34,780, (2) any measurement has shown fluid in the wellbore at or above any salt formation or other corrosive formation, or (3) in the opinion of Staff, variation in measurements indicates the possibility of a casing leak. Provided, however, a Subject Well may be returned to service upon (a) passing a casing integrity test after issuance of this Penalty Order to the satisfaction of Staff, or (b) Staff providing written, well-specific authorization after issuance of this Penalty Order.

D. Operator may request a hearing on the above issues by submitting a written request, pursuant to K.S.A. 55-164, K.S.A. 77-537, and K.S.A. 77-542, to the Commission at 266 N. Main St., Suite 220, Wichita, Kansas 67202, within 30 days from the date of service of this Order. A request for hearing must comply with K.A.R. 82-1-219.

E. Failure to timely request a hearing will result in a waiver of Operator's right to a hearing. If no party timely requests a hearing, then this Order shall become final.

³ K.S.A. 55-164; K.A.R. 82-3-111(b).

F. If Operator is not in compliance with this Order and the Order is final, then Operator's license shall be suspended without further notice and shall remain suspended until Operator complies. If a Subject Well has been inactive for more than 10 years and Operator applies for an exception to the 10-year limit on TA status for the Subject Well prior to this Order becoming final, and Operator would be in compliance with this Order if the application were approved, then suspension shall not be enforced unless: (1) the application is denied, and (2) 30 days have elapsed since the denial. The notice and opportunity for a hearing on this Order shall constitute the notice required by K.S.A. 77-512 regarding license suspension.

G. A party may petition for reconsideration of a final order pursuant to the requirements and time limits established by K.S.A. 77-529(a)(1).⁴

H. Credit card payments may be made by calling the Conservation Division at 316-337-6200. Checks and money orders shall be payable to the Kansas Corporation Commission. Payments shall be mailed to the Kansas Corporation Commission at 266 N. Main St., Suite 220, Wichita, Kansas 67202. Payments must reference the docket number of this proceeding.

BY THE COMMISSION IT IS SO ORDERED.

French, Chairperson; Keen, Commissioner; Kuether, Commissioner

Dated: 08/13/2024



Lynn M. Retz
Executive Director

Mailed Date: 08/13/2024

TSK

⁴ See K.S.A. 55-162; K.S.A. 55-164; K.S.A. 55-606; K.S.A. 55-707; K.S.A. 77-503(c); K.S.A. 77-531(b).

Conservation Division
District Office No. 1
210 E. Frontview, Suite A
Dodge City, KS 67801



Phone: 620-682-7933
<http://kcc.ks.gov/>

Andrew J. French, Chairperson
Dwight D. Keen, Commissioner
Annie Kuether, Commissioner

Laura Kelly, Governor

06/10/2024

Rohan Siddhanthi
RFORTUNA LLC
3401 PUTTER PLACE
COLUMBUS, IN 47203-2711

Re: Temporary Abandonment
API 15-175-20768-00-01
BOLES 3-11
SW/4 Sec.11-32S-34W
Seward County, Kansas

Dear Rohan Siddhanthi:

Your application for Temporary Abandonment (TA) for the above-listed well is denied for the following reasons(s):

Shut-in Over 10 years

Pursuant to K.A.R. 82-3-111, the well must be plugged, or returned to service, or obtain temporary abandonment status by 07/10/2024.

This deadline does NOT override any compliance deadline given to you in any Commission Order.

You may contact me if you have any questions.

Sincerely,
Michael Maier
KCC DISTRICT 1

KCC OIL/GAS REGULATORY OFFICES

Date: 07/18/24

District: D1

Case #: _____

New Situation

Lease Inspection

Response to Request

Complaint

Follow-Up

Field Report

Operator License No: 36101

API Well Number: 15-175-20768-00-01

Op Name: Rfortuna LLC

Spot: SW-NE-NW-SW Sec 11 Twp 32 S Rng 34 E / W

Address 1: 4301 Putter Place

22794 Feet from N / S Line of Section

Address 2: _____

4561 Feet from E / W Line of Section

City: Columbus

GPS: Lat: 37.27794 Long: 100.99294 Date: 5/10/24

State: IN Zip Code: 47203 -2711

Lease Name: Boles Well #: 3-11

Operator Phone #: (312) 752-0925

County: Seward

Reason for Investigation:

Verify production

Problem:

KGS shows no production for this well since 2009

Persons Contacted:

Rohan Siddhaunthi

Findings:

7/8/24: There are no changes to this lease. The well was denied a TA and given a deadline of 7/10/2024.

5/10/24: # 3-11: Is an inactive flowing gas well that the master valve appeared to be closed. I contacted the operator and he confirmed that the well was shut in. I told him that he need to file a TA on this well. No one has been to this well in several months, there is no road to the well. There is no tank battery or meter run on this location.

NO leaks or spills.

Action/Recommendations:

Follow Up Required Yes No

Date: 7/10/24

Unsatisfactory, send penalty letter for failure to file CP-111

Verification Sources:

Photos Taken: _____

RBDMS KGS TA Program
 T-I Database District Files Courthouse
 Other: Onsite Inspection

By: _____

Max Ball

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: _____



Date: 7/18/2024.

Operator: R Fortuna LLC.

Well Name: Boles 3-11

Legal: SW-NE-NW-SW Section 11-32s-34w Seward County

Description: Wellhead, showing closed valves and overgrown with grass and weeds.

CERTIFICATE OF SERVICE

25-CONS-3056-CPEN

I, the undersigned, certify that a true copy of the attached Order has been served to the following by means of first class mail and electronic service on 08/13/2024.

TRISTAN KIMBRELL, LITIGATION COUNSEL
KANSAS CORPORATION COMMISSION
CENTRAL OFFICE
266 N. MAIN ST, STE 220
WICHITA, KS 67202-1513
tristan.kimbrell@ks.gov

FRED MACLAREN
KANSAS CORPORATION COMMISSION
DISTRICT OFFICE NO. 1
210 E. FRONTVIEW SUITE A
DODGE CITY, KS 67801
frederic.maclaren@ks.gov

ROHAN SIDDHANTHI
RFORTUNA LLC
3401 PUTTER PL
COLUMBUS, IN 47203-2711

ROBYN STALKFLEET, ADMINISTRATIVE SPECIALIST
KANSAS CORPORATION COMMISSION
DISTRICT OFFICE NO. 1
210 E. FRONTVIEW SUITE A
DODGE CITY, KS 67801
robyn.stalkfleet@ks.gov

KENNY SULLIVAN, DISTRICT #1 SUPERVISOR
KANSAS CORPORATION COMMISSION
DISTRICT OFFICE NO. 1
210 E. FRONTVIEW SUITE A
DODGE CITY, KS 67801
kenny.sullivan@ks.gov

/S/ KCC Docket Room
KCC Docket Room