

Staff Assigned:

In the Matter of Kansas Gas Service, a Division of ONEOK,
Inc.'s Compliance with the Commission's Order in Docket No.
12-KGSG-721-TAR.

)
)
)
)
)

Docket Number
13-KGSG-538-CPL

FILE DATE: March 01, 2013



2013.03.01 10:41:52
Kansas Corporation Commission
/s/ Patrice Petersen-Klein

February 27, 2013

Patrice Petersen-Klein
Executive Director
Kansas Corporation Commission
1500 SW Arrowhead Road
Topeka, KS 66604-4027

Received
on

MAR 01 2013

by
State Corporation Commission
of Kansas

Re: Docket No. 12-KGSG-721-TAR; Compliance Filing

Dear Ms. Petersen-Klein,

Enclosed please find an original and eight (8) copies of Kansas Gas Service's *Compliance Filing* for filing in the above referenced matter. Please return one stamp file copy in the enclosed self-addressed stamped envelope.

The Commission's order in Docket No. 12-KGSG-721-TAR required KGS to submit annually the remaining cast iron pipe in its system, further identified by pipe diameter. In addition, the Commission requested the number of leaks discovered each year due to corrosion, organized by pipe diameter.

The required information is attached. The first table highlights the leaks caused by corrosion, further identified by pipe size. The second table identifies the inventory of cast iron remaining on the KGS system, split by pipe diameter.

Sincerely,

Dave Dittmore
Mgr. Rates and Regulatory Affairs
Kansas Gas Service, a Division of ONEOK, Inc.

cc: Leo Heynos

KANSAS GAS SERVICE
7421 West 129th Street
Overland Park, KS 66213-2634
P.O. Box 25957
Shawnee Mission, KS 66225-5957
kgas.com

2012 KGS Corrosion Leaks in CI Pipe by Size								
Area	Size							Total
	4"	6"	8"	10"	12"	16"	20"	
KCK	4	10	1	0	2	0	0	17
Topeka	7	5	0	0	0	0	0	12
Wichita	1	1	0	0	0	0	0	2
Total	12	16	1	0	2	0	0	31

2012 CI Inventory by Size									
	4"	6"	8"	10"	12"	16"	20"	Total Feet	Total Miles
Feet	262,483	148,838	35,121	27,694	39,920	1,844	520	516,420	
Miles	49.71	28.19	6.65	5.25	7.56	0.35	0.10		97.81