

Patrick Development Corporation
3408 W 93d St
Leawood, KS 66206

April 24, 2018

Kansas Corporation Commission
366 N, Main St. Ste. 220
Wichita, KS 67202-1513

Dear Commission:

I would like to request a hearing on the \$1000 penalty assessed on Docket No. 18-CONS-3356-CPEN.

On December 1, 2017 the Grandon No. 9 well failed a mechanical integrity test. This well has been shut in since the day of the test. The well is located in a low area by a creek and it was difficult to get a big pulling unit in place. When the conditions permitted, a pulling unit was brought in. Bob Reusch met Levi Short of the KCC to determine the best course of action. We planned to run 650 feet of 2" pipe in the well but the bottom was tagged at 606' and Levi asked for the well to be washed out since the bottom had not been reached. We will have to dig pits to contain the contents of the well and hire Consolidated to wash the well. When the bottom has been reached we will determine if there is a packer in the well. At that time Larry Marchant and Levi will determine if another MIT should be performed. It is my understanding that the leak that occurred during the initial MIT was a seal between the 4" casing and the 2" pipe that connects to the well head, and that the integrity of the 4" pipe may be sound.

Because of our ongoing conversations with Levi Short we were under the impression that we were being given some time to accomplish this task, since the well has been shut in. We didn't realize that we were still operating under the time line mentioned in the penalty letter. We intend to continue to work with Levi and the KCC and correct this matter as soon as it is possible, given the conditions at this location. Please let me know if you require additional information. Thank you for your consideration of this matter.

Sincerely,

Kerry Patrick
Patrick Development