2009.10.13 16:40:15 Kansas Corporation Commission /S/ Susan K. Duffy

## BEFORE THE STATE CORPORATION COMMISSION OF THE STATE OF KANSAS

)

)

)

)

STATE CORPORATION COMMISSION

In the Matter of the Application of Atmos Energy for Approval of the Commission for Gas System Reliability Surcharge per K.S.A. 66-2201 through 66-2204.

OCT 1 3 2009 Docket No. 10-ATMG-133-TAB

## **NOTICE OF FILING OF STAFF MEMORANDUM**

The Commission Staff (Staff) of the State Corporation Commission of the State of Kansas (Commission) files its memorandum recommending approval of Atmos Energy (Atmos)'s request for approval of its new Gas System Reliability Surcharge (GSRS) tariff.

1. On August 14, 2009, Atmos submitted for filing a new tariff schedule, GSRS, which is designed to allow for the adjustment of Atmos' rates and charges to provide for recovery of costs for eligible infrastructure system replacements.

2. Staff has thoroughly reviewed and investigated Atmos' application and hereby

files a memorandum prepared by Justin Grady and Leo Haynos dated October 12, 2009,

recommending approval of Atmos' application as discussed in Staff's memo.

WHEREFORE, Staff recommends approval of the new tariff schedule in Atmos Energy's application.

Respectfully submitted,

ha Bradbury, No. T

Litigation Counsel Kansas Corporation Commission 1500 S.W. Arrowhead Road Topeka, KS 66604 Phone: (785) 271-3196 Fax: (785) 271-3167

DB:acc

## CERTIFICATE OF SERVICE

EMAIL LIST 10-ATMG-133-TAR

I, the undersigned, hereby certify that a true and correct copy of the above and foregoing Notice of Filing of Staff Memorandum was served electronically and a copy placed in the United States mail, postage prepaid, or hand-delivered this 13th day of October, 2009, to the following:

JAMES G. FLAHERTY, ATTORNEY ANDERSON & BYRD, L.L.P. 216 SOUTH HICKORY PO BOX 17 OTTAWA, KS 66067 Fax: 785-242-1279 jflaherty@andersonbyrd.com

C. STEVEN RARRICK, ATTORNEY CITIZENS' UTILITY RATEPAYER BOARD 1500 SW ARROWHEAD ROAD TOPEKA, KS 66604 Fax: 785-271-3116 s.rarrick@curb.kansas.gov \*\*\*\* Hand Deliver \*\*\*\*

SHONDA SMITH CITIZENS' UTILITY RATEPAYER BOARD 1500 SW ARROWHEAD ROAD TOPEKA, KS 66604 Fax: 785-271-3116 sd.smith@curb.kansas.gov \*\*\*\* Hand Deliver \*\*\*\*

DANA BRADBURY, LITIGATION COUNSEL KANSAS CORPORATION COMMISSION 1500 SW ARROWHEAD ROAD TOPEKA, KS 66604-4027 Fax: 785-271-3354 d.bradbury@kcc.ks.gov \*\*\*\* Hand Deliver \*\*\*\* NIKI CHRISTOPHER, ATTORNEY CITIZENS' UTILITY RATEPAYER BOARD 1500 SW ARROWHEAD ROAD TOPEKA, KS 66604 Fax: 785-271-3116 n.christopher@curb.kansas.gov \*\*\*\* Hand Deliver \*\*\*\*

DELLA SMITH CITIZENS' UTILITY RATEPAYER BOARD 1500 SW ARROWHEAD ROAD TOPEKA, KS 66604 Fax: 785-271-3116 d.smith@curb.kansas.gov \*\*\*\* Hand Deliver \*\*\*\*

DAVID SPRINGE, CONSUMER COUNSEL CITIZENS' UTILITY RATEPAYER BOARD 1500 SW ARROWHEAD ROAD TOPEKA, KS 66604 Fax: 785-271-3116 d.springe@curb.kansas.gov \*\*\*\* Hand Deliver \*\*\*\*

TERRI PEMBERTON, LITIGATION COUNSEL KANSAS CORPORATION COMMISSION 1500 SW ARROWHEAD ROAD TOPEKA, KS 66604-4027 Fax: 785-271-3354 t.pemberton@kcc.ks.gov \*\*\*\* Hand Deliver \*\*\*\*

KIM DAVUS Legal Assistant



Kathleen Sebelius, Governor Thomas E. Wright, Chairman Michael C. Moffet, Commissioner Joseph F. Harkins, Commissioner

## MEMORANDUM

To: Thomas E. Wright, Chairman Michael C. Moffet, Commissioner Joseph F. Harkins, Commissioner

From: Leo Haynos Justin Grady

Date: October 13, 2009

Date Submitted to Legal: \_10/13/09 Date Submitted to Commissioners: 10/13/09

Re: Docket No. 10-ATMG-133-TAR: In the Matter of the Application of Atmos Energy for Approval of the Commission for Gas System Reliability Surcharge per K.S.A. 66-2201 through 66-2204.

## Summary:

In the subject docket, Atmos Energy, Inc. (Atmos) filed a request for a new tariff schedule, labeled the Gas System Reliability Surcharge, (GSRS). This tariff is designed to allow for the adjustment of Atmos's rates and charges to provide for the recovery of \$9.8 million of capital costs for eligible infrastructure system replacements. Atmos's GSRS surcharge as filed amounts to \$765,529 in annual revenue.

Commission Staff recommends approval of approximately \$7.01 million of the proposed capital projects. However, as discussed in the accounting section below, Staff's revenue requirement recommendation is unchanged from Atmos's filing. Atmos's filing includes 140 specific infrastructure projects with a requested recovery of \$4.1 million<sup>1</sup> and additional "functional projects" with a requested recovery of \$5.7 million<sup>2</sup>. Functional projects included in Atmos's filing are less than 250 feet in length and are completed in order to comply with pipeline safety regulations. After reviewing these exhibits, the testimony of Atmos staff Wilkes and Armstrong, and the Atmos responses to Staff data requests, Staff believes that a number of projects with a total cost of \$1.9 million do not meet the requirements for recovery under the Gas Safety and Reliability Policy Act found in K.S.A. 66-2202(f). Additionally, because of the nature of how the functional projects are accounted for, Staff is recommending the disallowance of an

<sup>&</sup>lt;sup>1</sup> Exhibit KPW-2 of Karen Wilkes Testimony.

<sup>&</sup>lt;sup>2</sup> Exhibit KPW-3 of Karen Wilkes Testimony.

additional \$856,209 of functional projects from Atmos's GSRS surcharge. This is discussed in more detail in the accounting section below.

The GSRS statute requires the Commission Staff to examine information from the utility and confirm that the underlying costs are in accordance with the statute. Staff is required to file its report and recommendation within 60 days of receiving the application. The Commission is required to issue a final order on the application within 120 days of receipt. In this case, the final order is due by December 14, 2009.

## Background:

The GSRS was enacted by the Kansas legislature in July of 2006. This statute allows natural gas public utilities to recover costs for certain infrastructure projects through a monthly customer surcharge. The statute only applies to projects that entail the replacement of infrastructure or the extension of the useful life of infrastructure. The replacement projects are further limited to those projects that are required for compliance with pipeline safety regulations or for facility relocation projects caused by other public works projects such as road improvement.

In its review of the application, the Commission is required to confirm the replacement projects included in the application meet the provisions of the Act. The Commission is also charged with the obligation of confirming the proposed surcharge has been properly calculated and is based solely on the projects included in the application. As a first step in making this determination, Staff relies on two essential provisions of the statute. Those requirements, with emphasis provided, are as follows:

## K.S.A. 66-2202 (f)

"natural gas utility plant projects" may consist only of the following:

(1) Mains, valves, service lines, regulator stations, vaults and other pipeline system components installed to comply with state or federal safety requirements as replacements for existing facilities;

(2) main relining projects, service line insertion projects, joint encapsulation projects and other similar projects extending the useful life or enhancing the integrity of pipeline system components undertaken to comply with state or federal safety requirements; and

(3) facility, relocations required due to construction or improvement of a highway, road, street, public way or other public work....provided that the costs related to such projects have not been reimbursed to the natural gas public utility;

## K.S.A. 66-2203 (a)

...a natural gas public utility providing gas service may file a petition...to establish or change GSRS rate schedules...to provide for the recovery of costs for eligible infrastructure system **replacements**.

Kansas pipeline safety regulations are primarily adopted from federal pipeline safety regulations. As stated in the scope of the federal code, the regulation prescribes the **minimum** safety requirements for pipeline facilities. When evaluating projects for the applicability of GSRS, the decision must rest on defining which portion of the project brings the system into compliance

with safety regulations and which portion of a given project is being completed as a business decision to renew an aging infrastructure or improve operating efficiency. To make this determination, Staff must rely on the description of each project provided in the operator's application or through responses to data requests.

## Analysis:

## **Pipeline Safety**

In its application, Atmos has asked for recovery of costs associated with 140 replacement projects. Of that total, 90 projects are designated by Atmos as being performed in order to comply with Kansas pipeline safety regulations. Based on the data provided, Staff believes the 90 pipeline safety related projects listed in Exhibit KPW-2 meet the requirements of the GSRS for consideration in this tariff.

In its application, Atmos included an additional \$5.7 million for a variety of small projects that are labeled as "functional projects." These projects are under 250 feet in size and are tracked under blanket work orders. Exhibit KPW-3 provides a complete listing of the functional projects. The cost allocation methodology for the blanket work orders is discussed in the accounting section of this memorandum. For analysis of the applicability of GSRS to functional projects related to pipeline safety requirements, Staff grouped the projects as follows:

Categories	Number in Filing	\$/Unit	<b>Dollars in Filing</b>
Meter Loops	767	773	592,546
Leak Clamps	528	2,196	1,159,714
Anodes	330	2,117	698,629
Service Lines	688	1,303	897,987
Main	13,731 Feet	170	2,340,247
Totals	alle alle and gan bain dan dan dan dan dan dan dan dan dan da		5,689,123

Based on the information provided in Exhibit KPW-3, the projects included for replacing anodes, service lines, and sections of main were performed to control infrastructure leakage which is a requirement of pipeline safety regulations. Therefore, Staff believes these categories are acceptable for inclusion in the GSRS tariff. However, as discussed below in the accounting section, Staff is recommending the removal of \$856,209 of service line projects from Atmos's GSRS surcharge.

The installation of leak clamps is also a means of controlling infrastructure leakage. However, GSRS limits recovery for those projects where replacement of infrastructure occurs.<sup>3</sup> While installing leak clamps is clearly an acceptable maintenance function that can be performed to meet pipeline safety requirements, it is Staff's opinion that it does not constitute replacing infrastructure and therefore is not recommended by Staff for inclusion in the GSRS tariff.

<sup>&</sup>lt;sup>3</sup> See reference to K.S.A. 66-2203(a) as discussed in background section of this memorandum.

For the category of meter loops replacements, Atmos states the meter loops were replaced because of leakage that occurred on the meter loop and/or on its associated service line.<sup>4</sup> However, Atmos provided no differentiation between those meters that were replaced as a general equipment upgrade verses those meters that were replaced as a means of controlling leakage. While replacing a leaking meter is an acceptable maintenance function that can be performed to meet pipeline safety requirements of controlling leakage, updating gas measuring equipment at the same time a leaking service line is being repaired is not a requirement of pipeline safety regulations but simply a good business practice. Because Staff has no means of differentiating which meter loops were replaced because of leaking meters or simply updated during required maintenance work being performed on the meter's associated service line, we recommend not including the meter loop category in the GSRS filing at this time. If Atmos can provide Staff with the number of meter loops that were replaced because they were leaking, Staff would agree that that portion of meter loop replacements is appropriate for inclusion in a GSRS tariff. However, for reasons discussed below in the accounting section, Staff is recommending the removal of all meter loops costs from the GSRS surcharge.

## Public Works Projects

In its application, Atmos also asked for recovery under the GSRS mechanism for 50 facility relocation projects that were required because of conflict with a public works improvement projects. The GSRS statute identifies a public works project as any project where a political entity or any entity having eminent domain authority requires a gas facility relocation.<sup>5</sup> In its review of the Atmos testimony and their responses to data requests, Staff has identified 7 projects that do not meet the definition of a project performed because of a conflict with a public works project. Therefore, we recommend these projects not be included in the GSRS application. A detailed explanation of Atmos' description and data responses along with Staff's opinion on these projects is attached as Attachment 1. The projects recommended for exclusion are listed as follows:

Exhibit KPW-2	Amount	Staff Reason for Recommending Denial
Line No.	in Filing	
30	7,613	Movement of a fence around a warehouse is not considered a pipeline facility eligible for recovery under GSRS.
50	6,136	Project was 100% reimbursed to Atmos
56	3,739	Project not required because of a public works project.
100	20,570	Project not required because of a public works project.
114	6,416	Project not required because of a public works project.
122	22,635	Project not required because of a public works project.
130	14,613	Utility easement in question was not vacated by a public entity.
Totals	\$81,722	

<sup>&</sup>lt;sup>4</sup> Exhibit KPW-3; column labeled "Description".

 $<sup>^{5}</sup>$  K.S.A. 66-2203(f)(3): facility, relocations required due to construction or improvement of a highway, road, street, public way or other public work by or on behalf of the United States, this state, a political subdivision of this state or another entity having the power of eminent domain provided that the costs related to such projects have not been reimbursed to the natural gas public utility;

In addition to the above listed projects, Staff recommends projects described in Line numbers 53 and 110 of KPW-2 also be excluded from the GSRS filing. The total amount of the two projects is \$45,148. Although the two projects were the result of a relocation of facilities for a public works project, Atmos used the opportunity of the relocation to install higher capacity facilities to serve future growth. While this is a good business decision on the part of Atmos, it is Staff's position that relocated facilities allowed for recovery under GSRS should not include capacity upgrades unless the larger capacity project can be completed for same cost or less than a like-for-like (similar gas volume capacity and similar operating pressure), replacement. Because Staff has no means of determining the proper allocation of costs for a like-for-like replacement, we recommend not including these projects in the GSRS filing at this time. If Atmos is able to provide a methodology for allocating that portion of the replacement costs that are comparable to the previous facilities, Staff would consider that portion for inclusion in the GSRS application. **Accounting** 

Staff is recommending approval of Atmos's GSRS surcharge as filed. That is, Staff recommends that Atmos be allowed to collect \$765,529 in GSRS revenue requirement per year via the percustomer monthly surcharges listed in Exhibit KPW-4 attached to the testimony of Atmos witness Karen Wilkes. Although Staff is recommending approval of Atmos's revenue requirement as filed, Staff's revenue requirement calculation was actually higher than Atmos's, at \$789,279. As discussed below, Atmos's filing contained some errors that mistakenly lowered Atmos's request. These errors were shared with Atmos, and Atmos chose not to re-file its application, so Staff's recommendation is simply to approve the revenue requirement as filed. The individual findings of Staff's audit and the components that led to Staff's revenue requirement calculation are presented below.

- Staff issued discovery requesting work orders and general ledger entries in support of a random sample of projects included the application. Staff encountered no material errors in this regard.
- Staff sought information from Atmos both formally and informally regarding various errors in Atmos's revenue requirement calculation. Some of these errors increased Atmos's revenue requirement, and some decreased the requirement. For example, Atmos did not include depreciation expense in its revenue requirement. That had the effect of artificially lowering Atmos's revenue requirement by \$132,748.<sup>6</sup> Conversely, the state tax rate used in Atmos's filing was 7.35%, versus the actual state tax rate of 7.05%. In Staff Data Request No. 8<sup>7</sup>, Staff attempted to gain consensus on various components of the revenue requirement that we felt should be changed. The various changes we felt necessary, including the two examples given above, were referred to in the data request and Atmos agreed that the changes should be made. See Staff Exhibit JTG-1 for a copy of the data request response listing each of the agreed upon changes. This exercise was important because these agreed-upon principles will be reflected in Atmos's next GSRS filing.
- Staff examined the costs included in Atmos's filing referred to above as "functional projects." These project costs are not tracked separately like the "specific projects"

<sup>&</sup>lt;sup>6</sup> Calculated using Staff's revenue requirement schedules. If calculated using Atmos's filing, this amount would be much larger.

<sup>&</sup>lt;sup>7</sup> See Staff Exhibit JTG-2

included in Atmos's filing. Instead, they are tracked via a functional number, which identifies the project type, location, some specifics about the type of infrastructure used and the total cost of all the projects included in the function. Again, this system does not allow Atmos to tie costs to individual projects. Therefore, an average cost allocation methodology was employed, also referred to as prorated cost methodology. That is, Atmos simply divides the total cost of a functional number by the number of units recorded to that functional number (inclusive of both GSRS eligible units and non-GSRS eligible units) to derive an average unit cost. This average unit cost is then applied to all of the units that Atmos has identified as being eligible for GSRS recovery. The product is the amount of "functional project" cost that Atmos included in its filing.

This approach is problematic for many reasons. First, the average unit cost of the different functional projects included in Atmos's filing can vary by a very significant amount. The following table provides a view of the extreme nature of the variance of projects included in Atmos's filing.

Category	High Per Unit Cost	Low Per Unit Cost
Clamps	\$15,001	\$796
Meter Loops	\$3,788	\$141
Anodes	\$20,068	\$422
Service Lines	\$3,406	\$378

Staff is concerned that the extreme variance in these per unit costs could contribute to the possibility of non-GSRS eligible projects artificially raising the average unit cost amount applied to GSRS eligible projects in Atmos's application. Of course, because project costs are not tracked separately, there is no way for Staff to verify this concern. Staff issued KCC Data Request No. 7<sup>8</sup> in an attempt to understand the nature and cause of these variances. Atmos's response, attached to this memo, was that in each of the referred cases, Atmos had entered an incorrect number of units into the functional number. This has the effect of increasing the average unit cost that is then applied to the eligible GSRS units identified by Atmos. Given this data request response, coupled with the extreme nature of the variance in per unit averages included in Atmos's application, Staff cannot recommend recovery of any of the prorated functional project costs through Atmos's GSRS surcharge. Therefore, Staff has removed all of the cost of Meter Loop functional projects, and \$856,209 of the Service Line functional projects from Staff's revenue requirement calculation. It should be noted that Staff has been informed during discussions with Atmos that the average cost methodology will no longer be necessary with the cost tracking procedures put in place at Atmos during October, 2009. Although Atmos will continue to account for functional projects as a whole rather than individually, GSRS projects will be tagged and accounted for as a group, therefore eliminating the need to establish an average per unit cost to apply to a portion of the group.

• Staff's calculation of Atmos's GSRS revenue requirement assumes a Return on Equity of 10.2%, the same rate Atmos assumed in its filing. This rate is calculated according to the methodology that Staff agreed to use in its Stipulated Settlement Agreement with Atmos

6

<sup>&</sup>lt;sup>8</sup> See Staff Exhibit JTG-3.

in the 08-ATMG-280-RTS docket. Staff notes CURB has argued that a non-unanimous Stipulated Settlement Agreement between Atmos and Staff in the 280 Docket doesn't qualify as an "agreed-upon basis" as contemplated in K.S.A. 66-2204(d)(9). If Atmos, CURB and Staff cannot agree on the 10.2% ROE, Staff is agreeable to using the average of Staff's and Atmos' ROE contained in the filed testimony in Atmos last general rate case, leading to a calculated ROE of 10.3%. Staff believes its alternatives are consistent with K.S.A. 66-2204(d)(9). In this case, because Staff is recommending Atmos's filing be approved in full, the choice of a 10.3% ROE instead of a 10.2% ROE would be of no consequence.

• With all of the above taken into account, Staff's GSRS revenue requirement calculation is \$789,279. This compares to the \$765,529 that Atmos requested in its application. Staff's GSRS revenue requirement schedules are attached as Exhibit JTG-1.

## Recommendation:

In Summary, Staff recommends the Commission approve Atmos's GSRS revenue requirement of \$765,529. Staff's recommendation includes recovery of approximately \$7.1 million of capital projects that meet the criteria outlined in K.S.A. 66-2201 et seq. under the GSRS and the disallowance of approximately \$2.7 million of Atmos projects contained in the application that do not meet the criteria mandated in either K.S.A. 66-2203(a) or K.S.A. 66-2202(f). Staff recommends the Commission approve Atmos's GSRS amount with the following conditions:

- Atmos shall file an updated GSRS Tariff Schedule reflecting the final Commissionordered GSRS amount.
- During Atmos's next GSRS filing Staff will ensure that the amount of GSRS revenue actually collected is compared to the amount intended to be collected, with the under or over recovery being collected in subsequent years.

## ATTACHMENT 1

## Description of Relocation Projects Recommended by Staff for Exclusion from the GSRS Application

<u>KPW-2 Line 30, Atmos Explanation:</u> Warehouse fence relocation was required by the City of Herington due to a conflict with new road construction and installation of railroad overpass. We had to move our fence back due to installation of the overpass project over the railroad tracks, since it was going to take some of our leased property for the project. We had to remove and install new fence to secure our equipment and for public safety reasons.

<u>Staff Recommendation</u>: Although the fence relocation was required because of a public works project, the expense required of Atmos did not involve a "natural gas utility plant project" as described in K.S.A. 66-2202(f). In Staff's opinion, this paragraph clearly limits facilities eligible for consideration to those that transport natural gas. A fence around a warehouse site does not meet this criterion.

<u>KPW-2 Line 56, Atmos Explanation:</u> Relocate approximately 215' of 2" PE plastic main with 2" PE plastic due to conflict with a pool. After further review, it has been determined that this was not a city request and this project needs to be removed. <u>Staff Recommendation:</u> Relocation was not requested by a public entity. Therefore, it does not qualify for GSRS consideration.

<u>KPW-2 Line 100, Atmos Explanation:</u> Replace approximately 1100' of 2" steel main with 2" PE plastic by relocation due to existing main being under a building. This pipe was installed on private property and a building was built over it at an unknown date. About 200' of pipe was under the building. There was 900' of pipe installed to get around the property and 200' was installed to replace a section with two active leaks on it. If you do not feel that this explanation is adequate we will remove this item from our filing. Staff Recommendation: Staff would consider including the 200 feet of main that was replaced because of leakage. However, the main that was rerouted because of failure to obtain proper easements should not be eligible for GSRS consideration.

<u>KPW-2 Line 114, Atmos Explanation:</u> Relocate approximately 415' of 2" steel main with 2" PE plastic to clear from being under a building. The 2" gas line was in the alley way and the owner built an open sided building on the 2" gas line and then enclosed the building.... After checking on the status of the easement where the line was located, they found that there were no city easements after all. We then proceeded to re-route the line around the area to meet compliance rules. We installed 415' of 2" PE to re-route the main of the personal property of the landowner. If you do not feel that this explanation is adequate we will remove this item from our filing.

<u>Staff Recommendation</u>: Again, in this case it appears the main was rerouted because of failure to obtain proper easements. Therefore, we recommend the line should not be eligible for GSRS consideration.

<u>KPW-2 Line 122, Atmos Explanation:</u> Replace approximately 450' of 4" steel & 3" PE plastic main with 4" PE plastic due to piping being outside public right-of-way and imbedded in roadway concrete. This line had to be moved into the ROW because the Catholic Church is building on an addition to their current building. The line would have been under the addition. The 3" PE was inserted into the 4" steel on 9/8/1975. The 3" line was about 6" deep. I do not know if this alley was cut down at some time or not. We replaced the whole alley section so we could get the pipe to the minimum depth needed. If you do not feel that this explanation is adequate we will remove this item from our filing. Staff Recommendation: Relocation was not requested by a public entity. Therefore, it does not qualify for GSRS consideration.

<u>KPW-2 Line 130, Atmos Explanation:</u> Relocate approximately 300' of 2" steel main with 2" PE plastic to clear construction of addition to the Council Grove School and the road vacation by the City of Council Grove. The Street was vacated by the Council Grove Governing Body on December 22, 2008. The school was building in the vacated street for the new addition. See Ordinance No. 2042.

<u>Staff Recommendation:</u> Although the street was vacated by the city for the purposes of expanding the school, Section 5 of Ordinance 2042 expressly states, "Any current easements or utility rights in or upon the property so vacated herein shall continue." Because the utility easement was not vacated by a governmental body, Staff believes any request made by the school district to relocate the line in question was not requested by a public entity. Therefore, it does not qualify for GSRS consideration.

Atmos Energy Corporation PROPOSED RATE ADJUSTMENT FOR GSRS

### LINE **NUMBER** DESCRIPTION AMOUNT (a) (b) (C) (d) 1 Gas Plant \$7,067,217 2 **Depreciation & Amortization Reserve** (150, 584)3 Net Gas Plant 6,916,633 4 5 Accumulated Deferred Income Taxes (346, 448)6 **Total Rate Base** 6.570.185 7 8 Rate of Return [line 22] 8.08% 9 Required Operating Income [line 6 \* line 8] 530.871 10 Operating Income At Present Rates [line 28] (2,266)11 12 Deficiency [line 9 + line 16] 528,605 13 Tax Factor [line 36] 60.418% 14 **Total Proposed Rate Adjustment** \$874.920 15 16 Weighted 17 Rate of Return Percent Cost Cost 18 19 08-ATMG-280-RTS; Joint Stipulation & Agreement; Paragraph 10 20 Debt 51.9% 6.11% 3.17% 21 Equity 48.1% 10.20% 4.91% 22 100.00% 8.08% 23 24 **Operating Income at Present Rates Calculation** 25 25(a) Depreciation & Amortization Expense - related to Additions \$146.496 Depreciation & Amortization Expense - related to Retirements (13,748)25(b) 26 Income Taxes on Depreciation Adjustment 39.583% (132,748)(52, 545)Income Taxes on Adjusted Interest Expense 27 (208, 346)39.583% (82, 469)**Operating Income At Present Rates** 28 (\$2,266)29 Change in Rate Base \$6,570,185 30 Cost of Debt 6.11% 31 **Capital Percentage** 51.9% 32 Adjusted Interest Expense 208,346 33 **Tax Factor Calculation** KansasTax Rate 34 7.05% 35 Federal Tax Rate 35.00% 36 Tax Factor 60.418%

STAFF Exhibit STG-

### Atmos Energy Corporation GSRS Allocation

		]						SALES S	ERVICE						1	RANSPORTAT	non
				RESIDE	NTIAL/COMMEN	CIAL/SCHO	OL			INDU	JSTRIAL						
					TOTAL			TOTAL		LG INDUST.	SM GENERATOR	TOTAL	IRRIGATION	TOTAL			TOTAL
LINE		TOTAL	RESIDENTIAL	RESIDENTIAL	RESIDENTIAL	COMMERCIAL	SCHOOL	COM / PA	INDUSTRIAL	INTERRUPT.	SERVICE	INDUSTRIAL	ENGINE	SALES	FIRM	INTERRUPTIBLE	TRANSPORTATION
NUMBER	DESCRIPTION	COMPANY		SPECIAL		PUBLIC		WITH	Div 081	Điv 081	Div 081	AND	Div 086		TRANSPORTATION	TRANSPORTATIO	FIRM AND
				Div 086		AUTHORITY		SCHOOLS	830	955	940	NTERRUPTIBL	965 \$W				INTERRUPTIBLE
	(a)	(b)	(c)	(ď)	(e)	(f)	(g)	(h)	(i)	(j)	(k)	(I)	(m)	(n)	(0)	(p)	(q)
1	Total Annual Bills	1,485,089	1,362,261	24	1,362,285	113,959	1,774	115,733	239	35	560	834	3,514	1,482,366	2,212	511	2,723
2	Volumes																
3	Step 1	155,651,804	97,835,751	38,045	97,873,796	32,760,217	1,517,684	34,277,901	1,094,995	530,130	297	1,625,422	6,693,004	140,470,123	10,254,256	4,927,425	15, 181, 681
4	Step 2	9,697,430	0	0	0	0	0	0	0	634,840	0	634,840	0	634,840	0	9,062,590	9,062,590
5	Total Adj. Volumes	165,349,234	97,835,751	38,045	97,873,796	32,760,217	1,517,684	34,277,901	1,094,995	1,164,970	297	2,260,262	6,693,004	141,104,963	10,254,256	13,990,015	24,244,271
6	Rates																
7	Facilities Charge		\$12.25	\$159.25		\$30.00	\$30.00		\$50.00	\$250.00	\$32.25		\$45.00		\$50.00	\$250.00	
8	Volumetric Charge S1		\$0.13573	\$0.13573		\$0.13573	\$0.13573		\$0.13573	\$0.07000	\$0.11000		\$0.08045		\$0.13573	\$0.07000	
9	Volumetric Charge S2									\$0.06200						\$0.06200	
10	Revenue At Present Rates																
11	Facilities Revenue	\$20,598,749	\$16,687,697	\$3,822	\$16,691,519			\$3,471,990	\$11,950	\$8,750	\$18,060	\$38,760	\$158,130	\$20,360,399	\$110,600	\$127,750	\$238,350
12	Volumetric Revenue S1	20,397,897	13,279,246	5,164	13,284,410	4,446,544	205,995	4,652,540	148,624	37,109	33	\$185,765	538,452	18,661,167	1,391,810	344,920	1,736,730
13	Volumetric Revenue S2	601,241								39,360		\$39,360	0	39,360	00	561,881	561,881
14	Total Revenue	\$41,597,887	\$29,966,944	\$8,986	\$29,975,930	\$7,865,314	\$259,215	\$8,124,530	\$160,574	\$85,219	\$18,093	\$263,886	\$696,582	\$39,060,927	\$1,502,410	\$1,034,550	\$2,536,960
15	GSRS Allocation																
16	Customer Class Allocation Percent	6.10%			72.06%			19.53%				0.63%	1.67%				6.10%
17	GSRS Annual Revenue \$ [KPW-1]	\$874,920			\$630,555			\$170,872				\$5,512	\$14,611				\$53,370
18	Less Statutory Limit Adjustment	(85,641)			(85,641)												
19	Net Revenue \$ ((Lir	\$789,279			\$544,914			\$170,872	ı			\$5,512	\$14,611				\$53,370
20		1)/12)			\$0.40			\$1.48				\$6.61	\$4.16				\$19.60

21 Staff Billing Determinents 08-ATMG-280-RTS; Paragraph 12 of Joint Stipulated Settlement Agreement

## 376-1

# Specific ProJects - STAFF Schedules

Year								Description We need to be expended prior to filing
2007	7/20/2006		060.1455C		Olathe	132nd & Lakeshore		Replace approximately 2400' of 2" steel main with 2" PE plastic due to leakage
2007	4/26/2007	4/27/2007	060.15311	Public Improvements	Overland Park	1-435 & US 69	\$5,566	Relocate approximately 250 of 3" steel main with 250" of 4" steel to clear road improvements for KDOT.
2007	8/15/2006	5/9/2007	060.14604	Public improvements	Bonner Springs	130th & State Aven	\$8,449	Relocate approximately 200 * of 4" PE plastic main and 350* of 4" steel main for KDOT road improvement.
2007	2/22/2007	5/10/2007	060.15172	Safety Upgrade (Odori Reg Stations)	Overland Park	159th & Quivina	\$3,158	Replace regulator at district regulator station due to existing regulator being obsolet
2007	4/26/2007	6/8/2007	060.15307		Strong City	5th & Cottonwood	\$19,689	Replace approximately 500' of 3" & 2" steel main with 2" PE plastice due to leakage
2007	2/20/2007	6/12/2007	080.15168	Leakage	Elsimore	Sth & Main	\$2,024	Replace 382' of 1" steel main with 2", PE plastic due to leakage
2007	6/15/200E	7/9/2007	060.1450E	Leakage	Olathe	Church & Popular	\$5,497	Replaced old steel main at Westenfield Apartments with 7531' of 2" PE plastic due to leakage
2007	7/10/2006	7/9/2007	060.14531	Non-Standard Plot	Coffeyville	4th - Central to Wild	\$6,928	Replace approximately 3865 of 4" cast iron & 550" of steel min with 2" PE plastic, along with 62 service lines
2007	8/29/2006		060.14622	Safety Upgrade (Odori Reg Stations)	Peabody	9th & Vine		Replace regulator at town border station due to existing regulator, piping and fittings being obsole
2007	4/23/2007	7/30/2007	060.15297	Leakage	LaFountaine	Harper Rd & CR300	\$5,292	Replace approximately 850° of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" PE plastic due to leakage minimum contraction of 2" steel main with 2" steel main with 2" steel main with 2" steel main with 2" steel main contraction of 2" steel main contraction of 2" steel main
2007	5/30/2007	8/6/2007	060.15369	Public Improvements	Overland Park	119th Street	\$14,377	Replace approximately 100' of 4" p.e. And 25' of 2" p.e. and a 2" valve to clear an edge drain for road iprovements for the City of Overland Park, Kansas.
2007	3/20/2007	8/16/2007	060.15254	Leakage	Kansas Čity, Ks	82nd & State	\$17,233	Replace approximately 500 of 4* steel main with 4* PE plastice due to leakage
2007	6/14/2007	8/21/2007	060.1538C	Public Improvements	Olathe	146th & Locus	\$15,107	Relocate approximately 800° of 2° PE plastic rain due to conflicts with new sewer line replacement.
2007	8/31/2006	8/22/2007	060.14631	Abnormal Operating	Council Grove	Jefferson & Hays	\$10,571	Replace the Council Grove district regulator station to rerove obsolete regulators and fittings
2007	4/23/2007	8/22/2007	060.15298	Condition Above Ground Pipins	Savonburg	Forest & Walnut	\$5,279	Replace approximately 400' of 2" steel main with 2" PE plastic due to main being above ground
2007	5/30/2007	8/28/2007	060.15441	Public Improvements	Herington	Trapp Street	\$16,568	Main replacement mandated by the City of Herington. Existing 2 inch and 3 inch steel was in conflict with City road and stor
2007	2/26/2007	9/4/2007	060.1517E	Public Improvements	Lenexa	Monticello & Prairle	0.92 M	water replacement construction and was replaced with 2 inch PE plastic to clear construction. (hell main replaced = 930 feet Relocate approximately 133' of 2" PE plastic main to clear City of Lenexa road improvement project.
				·		Star Parkway		
2007	2/7/2007	9/4/2007	060.15158	Leakage	Olethe	Popular & Mardie	\$16,559	Replace approximately 1220' of 2" steel main with 2" PE plastic due to leakage
2007	1/2/2007	9/4/2007	060.15091	Leakage	Olathe	Keeler between Poplar & Prairie	\$1,800	Replace approximately 700' of 2" steel main with 2" PE plastic due to leakage
2007	1/30/2007	9/6/2007	080.15148	Safety Upgrade (Odori Reg Stations)	Olathe	151st & Pflumm	\$10,784	Replace regulator at district regulator station due to existing regulator being obsolet
2007	4/26/2007	9/6/2007	060.1530E	Leakage	Olathe	Dennis & Parker	\$3,202	Replace approximately 500' of 2" steel main with 2" PE plastic due to leakage
2007	2722/2007	9/6/2007	060.15171	Safety Upgrade (Odorf Reg Stations)	Olathe	159th & Cottonwoo	\$7,259	Replace regulator et district regulator station due to existing regulator being obsolet
2007	2/22/2007	9/6/2007	060.15172	Safety Upgrade (Odori Reg Stations)	Olathe	159th & Ridgeview	\$6,192	Replace regulator at district regulator station due to existing regulator being obsolet
2007	4/20/2007	9/6/2007	060.15294	Leakage	Olathe	Chestnut - South to	\$5,436	Replace approximately 660' of 2" bare steel main with 2" PE plastic main due to leakage
2007	3/5/2007	9/9/2007	060.15207	Leakage	Fredonia	Grace 3rd & Harrison	\$12.312	Replace approximately 1250 of 2" steel main with 2" PE plastic due to leakage along with relocating a district regulator statio
	1/22/2007			Public Improvements				
2007	112212007	3/10/2007	000.10275	Papie inprovements	Pleasanton	Hwy. 69	\$25,522	Relocte approximately 14,500 of 6" steel to clear the highway improvements for the Kansas Department of Transportation

2007	3/26/2007	9/19/2007	060.15284	Public Improvements	Olathe	Iowa Street	\$14,807	Replace 3-1* road crossings and approximately 25' of 2" p.e. to clear the road improvements for the City of Olathe
2007	1/25/2007	9/19/2007	060.15125	Public Improvements	Lenexa	Lackman Rd - 105tr	\$157.76	Relocate approximately 2500 of 8" steel, 1400' of 4" steel & 100' of 2" steel with 2500' of 8" PE plastic, 360' of 2" PE plastic and 1
2007	7/10/2007	9/20/2007	060.15410	Leakage		to 107th Jackson St - Nichols		plastic due to the City of Lenexa road improvement project. Replace approximately 2050' of 2" steel main with 2" PE plastic due to leakage
				-		to Spring		
2007	9/18/2007			Public Improvements	-	McClaren Street		Warehouse fence relocation was required by the City of Herington due to a conflict with new road construction and installation of railroad overpase.
2007	6/15/200E		060.14507	Leakage	Olathe	Church & Poplai	\$82,100	Replace services to the Westerfield Apartments, total of 259 units, due to leakage
2007	2/15/2006	9/26/2007	060,15308	Public Improvements	Basehor	147th & Paralle	\$23,41	Relocate approximately 1400° of 67 sidel with 61 ateel to clear the road inprovements for the City of Basehor, Kans as the side of the City of Basehor, Kans as the side of the City of Basehor, Kans as the side of the city of the c
2007	8/23/2007	9/27/2007	060.15481	Public Improvements	Syracuse	CR10 from CRJ to k	\$3,320	Relocate approximately 2460° of 2" PVC with 2" PE plastic due to County of Stanton rebuilding the roa
2007	6/1/2007	9/27/2007	060.1535E	Public Improvements	Uiysses	Michigan & Carter	\$11,26	Relocate approximately 850 of 2" steel main with 2" PE plastic due to the request of City of Ulysses for a road inprovement project
2007	7/12/2007	9/28/2007	060.15420	Public Improvements	Syracuse	CR10 & CRJ		Relocate approximitely 2640' of 2" PVC main with 2" PE plastic due to request of County of Stanton for a road inprovement project.
2007	8/1/2007	9/28/2007	060.15450	Non-Standard Pipe	Ulysses .	Hwy 160 & CRH	\$59,897	Relocate approximately 9550° of 2" PVC main with 2" PE plastic, along with 60 PVC services, due to non-standard pipe and CP is:
2007	7/12/2007	9/28/2007	060.15422	Above Ground Pipins		Hwy 270 & Arkansa River	\$49,54	Replace existing 400' river crossing that is 4* steel and has obsolete welds/fittings
2007	8/1/2007	9/29/2007	060,15449	Non-Standard Pipe		Eddle Rd & Weinut	\$38,136	Replace approximately 2480' of 2" PVC main with 2" PE plastic due to request of County of Stanton for a road ignovement project.
2007	8/1/2007	9/30/2007	060.15448	Non-Standard Pipe	Ulysses	Rose Ln & CRI	\$17,840	Replacement of 5 PVC services to also be replaced. Replace approximately 1400' of 2° PVC main and 5 PVC services due to non-standard plp#
2007	6/6/2007	10/2/2007	060,15364	CP Code Requires	Ness City	Main & Topeka	\$9,18	Add additional anodes to the existing recifier groundbed due to low apprage output. Unable to maintain constant CP protection
2007	6/6/2007	10/2/2007	060.15368	CP Code Requirec	Council Grove	U Ave & 975 Rd	\$13,210	PRelocated and replaced existing rectifier groundbed due to anode inefficientcy due to buildup of chiorine gr
2007	6/6/2007	10/2/2007	060.15367	CP Code Requirec	Hilsborg	Lincoln & FSt	\$14,200	Installation of new recifier and groundbed to provide additional CP to the City of Hillsboro that had been experiencing tow rea
2007	6/6/2007	10/2/2007	060.15365	CP Code Requirec	Ness City	Iowa & Magnolia		Relocate and increase the size of a rectifier groundbed which provides CP protection to the City of Nes Cit
2007	11/13/2006			Public Improvements	-	94th - Parallel to St		Relocate approximately 2650' of 3" sheet & 2100' of 2" steel main with 4700' of 4" PE plastic due to a City of Kansas City, Kansas re
				1.000 C				improvement project.
2007	2/6/2007		060.15153	Leakage	Olathe	Cedar - Willie to Wa		Replace approximately 1500' of 3" steel main with 4" PE plastic due to leakage
2007	7/10/2007		060.15415	Flood	Yates Center	various locations	\$1,690	C Repair unsafe ploing and equipment caused by flooding
2007	4/5/2007	10/30/2007	060.15273	Leakage	Longton	24A & Evergreer	\$5,82	3 Replace approximately 1100' of 4" steel main with 4" PE plastic due to leakage
2007	9/19/2007	11/15/2007	060.15885	Public Improvements	Olathe	Dennis Avenue	\$43,84;	Install approximately 900' of 4" p.e. and 200' of 2" p.e. so that the fine on Dennis Ave can be abandoned so the bridge can the removed. This is a City of Diathe, Kansas roadway inprovement project.
2007	9/20/2007	11/26/2007	060.15884	Public Improvements	Olathe	Dennis Avenue		Relocate approximately 700° of 4" p.e. and retire approximately 1355° of 4" p.e. and steel to clear roadway improvements for the City of Olathe, Kansas.
2007	8/14/2007	12/3/2007	060,15465	Public Improvements	Fredonia	15th & Madison		Relocate approximately 450° of 2" steel main due to conflict with the new Hospital parking lot
2007	10/22/2007	12/3/2007	060.15882	Above Ground Piping	Cottonwood Fails	Union & Walnut	\$7,53	Relocate and replace approximately 1370' of 2" steel main which was above ground and in proximity of dirt work for new building
2007	10/3/2007	12/12/2007	060.1562E	Above Ground Piping		Hwy 75 & CR410	\$5,87	Replace approximately 500° of 1 1/2" steel main with 2" PE plastic due to being above ground and leaking
2007	11/16/2007	12/21/2007	060.15943	Public Improvements	Kansas City	123rd Street		Relocate approximately 1100' of 2" p.e. with 4" p.e. and 150' of 2" p.e. (2 road crossings) to clear road iprovements for the

				Unified Government of Kansas City, Kansas
Total April 2007-December 20	07		\$1,109,766	

#VALUE! 2008	Approval Date 11/26/2007	10-Service Date 1/9/2008	Project Numbe 060.15953	Pro Category Flood	City Coffeyville	Location (Address) Davis - between 10 & 11th	Non-reimbulsable Amount \$5,041	Description - Will need to be expanded prior to filing Replace approximately 500' of 4" steel main with 2" PE plastic to serve customers affected by the flood
2008	11/5/2007	1/9/2008	060,15902	Flood	Coffeyville	Hwy 166 & 6th St	\$20,268	Replace approximately 1300° of 6* steel main with 2* PE plastic to serve customers affected by the flood
2008	7/24/2007	1/14/2008	060.15437	Abnormal Operating Conditions	Overland Park	124th & Nieman		Relocate approximately 215' of 2" PE plastic main with 2" PE plastic due to conflict with a pool.
2008	11/26/2007	1/29/2008	060.15952	Flood	Coffeyville	3rd & Sunflower	\$22,748	Replace approximately 1400° of 3* steel & 2* steel main with 2* PE plastic to serve customers affacted by the flood
2008	11/14/2007	2/29/2008	060.1594C	Public Improvements	Bonner Springs	K-7 & State Ave	\$666,741	Relocate approximately 6250' of 6" steel and 2400' of 4" p.e. to clear road inprovements and a new interchange for KDOT
2008	3/27/2006	3/27/2006	060.16098	Public Improvements	Olathe	Ridgeview Road	\$24,821	Relocate approximately 350° of 3" steel with approximately 350° of 4" steel to clear the improvement for the new RR backs for the City of Olathe, Kansas.
2008	9/21/2007		060.15556	Public Improvements	Olathe	Downtown		City is renovating downtown Olathe and nain replacements are necessary to avoid road improvements as these bare steel mains are shallow and under the street paverant. Replaced bare steel pipe with 2 inch PE plastic pipe. Total main replaced = 1,094 fee
2008	9/14/2007		060.15542	Abave Ground Piping		Redribbon & CR 25		Replaced 1261" of 3" steel main creek crossing that was aerial and had experienced support failure. New 2" PE plastic ain was bo creek.
2008	1/30/2008		060.16008	Flood	Coffeyville	8th & Forest		Replace approximately 2650' of 2" steel main with 2" PE plastic to serve customers affected by the floood
2008	11/26/2007		060.15954	Flood	Colfeyville	5th & Park		Replace approximately 750° of 3" & 2" steel main with 2" PE plastic to serve customers affected by the floood
2008 2008	10/16/2007		060.15877	Abnormal Operating Condition	Overland Park	112th & Quivire		Replacement of town border regulator due to being obsolete and unable to function at required capaci Replace, by insertion, approximately 2600 of 3" steel main with 2" PE plassic to serve customers affected by the flood
2008	4/24/2008		060.16132	Public Improvements	Olathe	Elm Street		City is renovating downtown Olathe and nain replacements are necessary to avoid road improvements
2008	10/17/2007		060.16013	Leakage	Olathe	Church & Poplar		as these bare steel mains are shallow and under the street pavement. Additionally, this new 2 inch Is being switched to the intermediate pressure fromlow pressure. Total main replaced = 565 fee Bare steel service lines were replaced due to leakage found within the Visterfield Apartment complex.
2008	3/27/2008		060.16100	Public Improvements	Olathe	153rd Street		In Olathe, Ks. at Church and Poptar. This was the second phase of replacement in the complex and consisted of applicating the steel with PE plastic. Total services replaced = 135 Relocate approximately 1200' of 2"p.e. with 1200' of 2" p.e. and lower approximately 250' of 2" p.e. in place to clear road war improvements for the City of Olathe, Kansas.
2008	1/25/2008	5/15/2006	060,16005	Leakage	Olathe	120 S. Keelei	\$31,200	Replacement of 3 inch bare steel pipe with 4 inch PE plastic pipe, under driveway, at 120 Keeler Stree Diathe, Ks. due to known leakage. Ibtal main replaced = 467 feet
2008	1/11/2008	5/16/2008	060.15983	Public Improvements	Olathe	I-35 & Lone Eirr	\$142,756	Abandon approximately 5000' of above ground 2" bare steel with 4" p.e. to clear road inprovements for the City of Olathe Kansas and KDOT.
2008	5/18/2007	5/19/2006	060,15341	Public Improvements	Bonner Springt	Woodend Roac	\$58,132	Install approximately 1875' of 4" p.e. and 250' of 2" p.e. and abandon approximately 400' of 2" steel pipe to clear road, improvements by the City of Bonner Springs Kansas.
2008	1/25/2008		060.16110	Public Improvements	Burlington	3rd Street		Relocation of 2 Inch and 4 Inch steel main was required by the City of Burlington due to conflict with the 3rd Street bridg replacement project. To clear construction of the bridge Atnos had to install a new low pressure district regulator station and 242 feet of 2 Inch PE plastic pipe. Total main replaced = 242 fee
2008	3/28/2008		060.16107	Leakage	Olathe	Kansas - Eim to Gra		Replace approximately 640° of 4" steel main with 2" PE plastic main due to leakage
2008	6/29/2007		060.15405	Public Improvements	Oiathe	143rd & St. Andrew		Install approximately 2200° of 4" PE plastic main to replace the main that was removed from service along Dennis Avenue due to a Olathe road improvement project.
2008	4/2/2008		060,16111	Leakage	Fredonia	Madison & W. Mou		Replace approximately 320' of 1" steel main with 2" PE plastic due to leakage
2008	6/18/2008		060.16175	Public Improvements	Olathe	Ridgeview Road		Replace 3 Crossings and abandon 1- 6" nordstromand relocate approximately 250' of 6" p.e. to clear road improvements for the City of Olathe, Kansas.
2008	6/27/2008	1/22/2008	060.16188	Leakage	DeSolo	Lexington & Lake	\$8,499	Replace approximately 500° of 2" steel main with 2" PE plastic due to feakage

2008	9/12/2008	8/1/2006	060.16349	Above Ground Piping	Pleasanton	County Rd. 400	\$74,880	Bare 6" steel main was replaced due to being,washed out along a creek bed along 400 Road in Lli County, Ks. Bare steel pipe was replaced with coated steel pipe. @tal main replaced = 500 feet.
2008	7/10/2008	B(4/2006	060.16198	Public Improvements	Spring Hill	Main & Nichola	\$10,230	Relocation of 3 lock hare steel pipe due to a City stormewer project in Spring Hill, Ks. Various conflicts due to the depth and installation of the stormewer required gas line relocation. Replaced the
2008	7/31/2008		060.16218	Public Improvements	Council Grove	Washington Street		3 Inch bare steal with 2 Inch PE plastic pipe. Btal replaced main = 500 feel Relocation of gas main along Washington Street was mandated by the City of Council Grove due to a road inprovement project. The existing 2 Inch steel main was in conflict with the proposed road and stomsewer replacements. To clear construction 1650 feet of 2 Inch PE plastic main was installed. Total main replaced = 1,650 fee
2008	5/7/2008	8/27/2006	060.16141	Leakaga	Colleyville	5th & Inglewood	\$38,470	Replace approximately 2800' of 12' steel main with 4' PE plastic due to leakage
2008	2/28/2008	8/29/2008	060.1604E	Public Improvements	Ulysses	Hwy 160 & Stubbs	\$44,757	Relocate approximately 120' of 2" steel main due to a KDOT road improvement project.
2008	6/6/2008	8/29/2006	060.16173	Public Improvements	Ulysses	Kansas & Mss.	\$148,425	Relocate approximately 1300' of 4" & 2" steel main with 4" & 2" PE plastic to clear conflicts with the City of Ulysses installation of a water drainage systemproject. Additionally, replaced services that are also in conflict.
2008	8/21/2008	8/29/2008	060.16237	Leakage	Kansas City, Ks	Hwy 32 & 88th Si	\$11,772	Replace approximately 900' of 2" steel main and relocate a district regulator station due to leakage
2008	3/22/2007	9/5/2006	060.15280	Abnormal Operating Condition	Colfeyville		\$31,442	Replace the regulators at the Coffeyville DRS due to being obsolet.
2008	5/21/2008	9/16/2008	060.1615E	Above Ground Pipins	Stark	Victory Road	\$6,364	Replace approximately 315' of 2" steel main with 2" PE plastic due to it being above ground at a customer' driveway.
2008	8/13/2008	9/17/2006	060.16228	Leakege	Elk Fells	19th & Dove	\$6,534	Replace approximately 400° of 4" PE plastic main that is inseted inside 6" steel with 4" PE plastic due to cold fusion joints leaking
2008	8/20/2008	9/17/2008	060.16235	Safety Upgrade (Odori	Independence	13th & Magnolia	\$3,748	Replace district regulator station due to obsolete equiprent.
2008	3/27/2008	9/18/2006	060.16105	Reg Stations) CP Code Regulaec	Pleasanton	Hwy 69 & Hwy K52	\$6,433	Replace groundbed for rectifier which protects the 6" steel rain and which has depleted
2008	9/13/2008	9/25/2008	060.16421	Public Improvements	Olathe	Santa Fe	\$15,983	Replace approximately 335' of 3" steel with 4" steel to clear road inprovements for the City of Olathe, Kansas
2008	7/17/2008	9/29/2008	060.16205	Leakage	Burlington	3rd & Mami	\$11,428	Relocate approximately 500' off 4" & 2" steel main with 4" & 2" PE plastic due to leakage
2008	8/27/2008	9/29/2008	060.16252	Safety Upgrade (Odori	Independence	CR 3575	\$5.676	Replace district regulator station due to obsolete equiprent.
2008	9/12/2008	0/20/200	060.16306	Reg Stations)	Johnson	Elm & Grant	\$5.50	Replace approximately 1530' of 2" PVC plastic main with 2" PE plastic due to leakage. Isolated risers will also be replaced
2008	7/9/2008		060.16194					
				Safety Upgrade (Odori Reg Stations)		145th & Moonlight		Relocate town border station & equipment from the N. Olathe DRS to eliminate the low pressure areas in the W Olathe system.
2008	8/13/2008		060.16227	Leakage	Independence	9th & Main		Replace approximately 380' of 4" & 3" steel main, by insertion, with 2" PE plastic due to leakage
2008	8/27/2008	10/22/2006	060.16253	Above Ground Piping	Neodesha	4th & Bethe	\$11,388	Replace approximately 800' of 2" steel main with 2" PE plastic due to leakage on above ground piping
2008	9/18/2008	10/29/2008	060.16348	Above Ground Piping	Hillsdale	Old KC Road	\$1,575	Relocation of e 3 inch coaled steel pipe across a creek along Old Kansas City Road south of Hilledal. Ks. Main was exposed and was susceptible to possible washout. The 3 inch coaled sites pipe was replaced with 4 inch PE plastic pipe. "Data main replaced # 236 fee
2008	9/10/2008	10/31/200	060.16285	Leakage	Independence	5th & Morningside	\$33,672	Replace approximately 2800° of 2 <sup>st</sup> Marlex plastic main with 2 <sup>st</sup> PE plastic due to leakage fromcracking.
2008	9/12/2006	10/31/200	060.16308	Leakage	Mantei	5th & Jackson	\$63,699	Rectace approximately 4015' of 2" PVC plastic main with 2" PE plastic due to leakage
2008	9/2/2008	10/31/2008	060.16264	Abnormal Operating Conditions	Independence	CR 4400 & CR 430		Replace approximately 1100' of 2" steel main with 2" PE plastic by relocation due to existing main being under a building
2008	10/16/2006	11/6/2001	060.16676	Public Improvements	Bonner Springs	Park & Kump	\$89,004	Relocate approximately 1440' of 4" & 2" plastic & steel rain to clear KDOT and City of Bonner Springs road improvement project.
2008	10/23/2008	11/11/2000	060.16685	Public Improvements	Spring Hill	Nichols Street	\$8,022	Replacement was due to a conflict with the City drainage ditch inprovements along Nichols Street and Washington Street in Spring Hill, Ks. Nain was exposed numerous times during construction which
2008	7/9/2008	11/13/200	060.16200	Public Improvements	Edwardsville	Woodend Road	\$5,973	required the permanent replacement of the 2 inch bare steel with 2 inch PE plastic. Total main = 672 feel Lower approximately 100 of 6" p.e. and 100 of 2" p.e. To clear road improvements for the City of Edwardsville, Kansas and KDOT.
2008	11/24/2008	11/25/2000	060.16720	Abnormal Operating	Linwood	170th & Cantrel	\$6,722	Install district regulator station to provide additional feed into City of Linwood which has been experiencing outages due to liquids
1	1		1	Conditions	l	1	1	local gas supplier.

2008	10/22/2008	120/2000	060.16681	CP Code Reguires	Herington	6th & Broadway	\$5,500	Replace a depleted restifier groundbed
8005	7/15/2008	12/16/2008	060.16205	Public Improvements	Olathe	Chestnut Streel	\$30,481	Relocate approximately 1800' of 2" bare steel with 2" p.e. and services to clear road way inprovements for the City of Olathe Kansas.
2008	12/22/2008	12/17/2006	060.16752	Leakage	Olathe	Cherry & Elm	\$2,559	Install district regulator station to provide gas supply to area experiencing water in min due to leakage
2008	12/8/2008	12/20/2008	060.16750	Public Improvements	Kansas City	Parallel Parkway	\$32,224	Lower approximately 1200' of 6" steel to clear road way improvements for Wal-Mart and the Unified Government of
	Total Calenda	r Year 2008		l Prince line of these	sullier ei sidhiost		\$2,068,477	Kansas City, Kansas.
_								3739
UE! 2009	Approval Date 9/21/2008	In-Service Onto 1/12/2009	Project Numbe 060.16357	Proj Gategory Public Improvements	City Lawrence	Hwy 59 & CR 1100		Description - Will need to be expanded prior to lling. Replace approximately 4120' of 3" steel main with 4" PE plastic & 4" steel to clear conflicts with KDOTroad improvement project.
2009	1/27/2006	1/27/2005	060.16962	Public Improvements	Basehor	166ih & Evans		Relocate approximately 1000° of 2* PE plastic main with 4* PE plastic to dear County of Leavenworth road inprovement project.
2009	2/17/2009	2/17/2009	060.16890	Non-Standard Pipe	Kansas City, Ki	99th & Hutton	\$6,907	Replace approximately 350° of 1° Mariex plastic main with 2° PE plastic due to non-standard pipe
2009	10/20/2008	2/27/2009	060.16677	Public Improvements	Bonner Springs	138th & Kump	\$140,450	Relocate approximately 2600° of 6° steel, 4° steel, 4° PE plastic, 2° steel & 2° PE plastic rain with 4° steel, 4° PE plastic & 2° PE plastic and a steel at the plastic & 2° PE plastic at the plastic a
2009	3/16/2009	3/11/2009	060.16912	Above Ground Pipins	Easton	Easton Rd.	\$10,47€	KBOT & City of Benner Springs road Inprovement project. Replace approximately 1500' of 2" steel main with 2" PE plastic due to being above ground piping
2009	1/12/2006	3/16/2009	060.16762	Abnormal Operating	Anthony	Penn & Hayes		Relocate approximately 415' of 2" steel main with 2" PE plastic to clear from being under a building
2009	3/9/2009	3/20/2009	060.16903	Conditions	Edwardsville	4th & Hwy K32	\$3,685	Replace approximately 380' of 4" steel main with 4" PE plastic due to leakage
009	1/6/2009	3/27/2000	060.1675	Leakage	Coffeyville	7th & Elm		Replace approximately 1300° of 6° & 4° steel main with 2° PE plastic due to leakage
2009	11/12/2008							
			060.16711	Leakage	Coffeyville	4th & Poplar		Replace approximately 1500' of 4" steel main with 2" PE plastic due to leakage
2009	1/14/2009	4/15/2009	060,16775	Public Improvements	Overland Park	College Blvd US6 to Pflumm	\$49,755	Relocate approximately 160' of A* & 2" PE plastic mein to clear City of Overland Park road improvement project.
2009	3/6/2009	4/2/2009	060.16902	Leakage	Olathe	Cherry & Poplai	\$14,274	Relocate district regulator station due to leakage at existing site
2009	3/5/2009	4/21/2006	060.16901	Above Ground Piping	Olathe	Dennis & Dianne	\$44,724	Replace approximately 1200 of 4* steel main with 4* PE plastic due to being above ground pipins
2009	4/3/2009	4/30/2009	060.16932	Above Ground Piping	Lowemont	Lowemont Rd. & Millcreek Rd.	\$9,855	Replace approximately 1500' of 2" steel main with 2" PE plastic due to being above ground piping. Replace 4 service lines attache ground main.
2009	4/6/2009	5/1/2009	060,16935	Flood	Independence	Myrtle & Park		Replace approximately 450' of 4" species 3" PE plastic main with 4" PE plastic due to piping being outside public right-of-way and it roadway concrete
2009	3/11/2009	5/18/2009	060.16909	Public Improvements	Olathe	Cherry & Chestnul	\$42,826	Relocate approximately 1250' of 2" steel main with 2" PE plastic to clear City of Olathe road improvement project. Also replace 16 st to clear construction.
2009	5/27/2009	5/27/2009	060.16986	Public Improvements	Olathe	Alta Lane - Dennis to Valley	\$16,832	Relocate approximately 120' of 2" steel main with 2" PE plastic to clear City of Olathe road inerovement project
2009	4/9/2009	6/1/2009	060.16939	Above Ground Pipins	Kansas City, Ks	1. Sec. 1. Sec. 1.	\$16,803	Relocate approximately 700' of 2" steel main with 2" PE plastic due to being above ground pipint
2009	4/28/2006	6/19/2009	060.16954	CP Code Regulred	Löst Springs	Washington & Broadway	\$9,863	Réplace deplated rectifier groundber
2009	3/19/2009	6/23/2009	060.1691€	Above Ground Piping	Havana	Moore & Cemetary	\$14,655	Replace approximately 1400' of 1 1/4" steel main with 2" PE plastic due to being above ground piping
2009	5/29/2009	6/30/2009	060,17000	Non-Standard Pipe	Kansas City, K	88th & Paralle	\$16,876	Replace approximately 1345 of 2" Mariex plastic main with 2" PE plastic due to non-standard pipe. Also replace 9 services lines the
2009	5/27/2009	7/7/2009	060.16985	Above Ground Pipins	Neodesha	4th & Granby	\$14.168	from this mein section. Replace approximately 1020' of 2" steel main with 2" PE plastic due to being above ground piping

9	2/18/2006	7/9/2009	060.16891	Public Improvements	Council Grave	Hall & Wood	And the second sec	Relocate approximately 300° of 2" steel main with 2" PE plastic to clear construction of addition to the Council Grove School and racation by the City of Council Grove.
9	5/20/2008	7/23/2009	060.16155	Public Improvements	Lenexa	83rd & Clare		Relocate approximately 4120' of 4" steel, 2" steel & 2" PE plastic with 6" PE plastic to clear conflicts with the City of Lenexa road project. Services were also replaced to clear construction.
	1/26/2009	8/3/2009	060.16855	Public Improvements	Olathe	Santa Fe & Chestnu	\$26,312 R	Relocate approximately 185° of 6" steel main to clear road improvement by the City of Olathe
9	11/19/2008	2/11/2009	060.16717	Public Improvements	Overland Park	Switzer Road - 143r to 151st	\$175,50E F	Relocate approximately 3800' of 4" & 2" PE plastic main to clear City of Overland Park road improvement project.
9	5/25/2005	7/21/2005	060.16980	Above Ground Piping	Strong City	Chase & Central	\$10,927 F	Replace approximately 600° of 3" steel main with 2" PE plastic due to being above ground pipint
3	4/30/2005	5/29/2009	060.16957	Above Ground Piping	Neodesha	Newton & Granby	\$10,572 F	Replace approximately 2000' of 2" steel main with 2" PE plastic due to being above ground piping
9	3/19/2009	4/21/2005	060.16915	Above Ground Pipins	Havana	Main & Mary	\$7,355 F	Replace approximately 450° of 2* steel main with 2* PE plastic due to being above ground piping
9	3/30/2009	7/13/2009	060.16928	Leakage	Olathe	Cedar & Cherry	\$13,842 F	Replace approximately 1500' of 4" & 2" steel main with 2" PE plastic due to leakage
9	5/25/2006	5/29/2005	060.16981	Above Ground Piping	Strong City	270th & Trall Road	\$16,975 F	Repjace approximately 700' of 4* steel main with 4*PE plastic due to being above ground pipint
9	7/1/2009	7/29/2009	060.1704€	Leakage	Olathe	Fredrickson west of Ridgeview	\$11,448 F	Replace approximately 825' of 4" steel main with 2" PE plastic due to leakage. Attached services were also replaced
, T	6/29/2009	5/27/2009	060.17043	Above Ground Piping	Strong City	Cottonwood & Weshington	\$2,894 F	Replaced approximately 340° of 2° steel main with 2° PE plastic due to being above ground piping
T	otal January 2	009 - August :	3. 2001	3	L		\$815,850	

Total non-growth specific project \$3,994,096
---

## Specific Prosects - Depreciation, Accum

		FERC	In Service	File	Months	Depreclation	Book Annual	Accumulated	YR 1	Tax YR 2	Accumulated	
ategory ublic Improvements	Code Public improvements	Acct 376	Date 1/31/2007	Date 8/1/2009	In Svc 30	Rate 2.02%	Depreciation 34.77	Depreciation 88.18	Rate 5.00%	Rate 9.50%	Depreciation 249.62	Tax > Book (161.44)
ublic Improvements	Public Improvements	376	4/27/2007	8/1/2009	28	2.02%	112.43	258.28	5.00%	9.50%	807.05	(548.77)
iblic Improvements	Public improvements	376	5/9/2007	8/1/2009	27	2.02%	170.67	386.38	5.00%	9.50%	1,225.11	(838.73)
strict Stations	192.625	378	5/10/2007	8/1/2009	27	2.02%	63.80	144.26	5.00%	9.50%	457.97	(313.71)
ain	192.317	376	6/8/2007	8/1/2009	26	2.02%	397.72	867.25	5.00%	9.50%	2,854.95	(1,987.70)
ain	192.703	376	6/12/2007	8/1/2009	26	2.02%	40.88	88.69	5.00%	9.50%	293.43	(204.74)
ain	192.703	376	7/9/2007	8/1/2009	25	2.02%	111.04	232.57	5.00%	9.50%	797.04	(564.47)
ain and Service	192.613	376/380	7/9/2007	8/1/2009	25	2.02%	139.95	293.12	5.00%	9.50%	1,004.60	(711.48)
urchase Stations	192.739	379	7/9/2007	8/1/2009	25	2.53%	740.51	1,550.96	5.00%	9.50%	4,244.05	(2,693.09)
ain	192.703	376	7/30/2007	8/1/2009	24	2.02%	106.90	217.66	5.00%	9.50%	767.36	(549.70)
ublic improvements	Public Improvements	376	8/6/2007	8/1/2009	24	2.02%	290.41	585.66	5.00%	9.50%	2,084.62	(1,498.96)
ain	192.703	376	8/16/2007	8/1/2009	24	2.02%	348.10	692.33	5.00%	9.50%	2,498.71	(1,806.38)
ublic improvements	Public Improvements	376	8/21/2007	8/1/2009	24	2.02%	305.17	602.71	5.00%	9.50%	2,190.54	(1,587.83)
strict Stations	192.739	378	8/22/2007	8/1/2009	24	4.74%	501.08	988.24	5.00%	9.50%	1,532.83	(544.59)
ain	192.317	376	8/22/2007	8/1/2009	24	2.02%	106.64	210.32	5.00%	9.50%	765.45	(555.13)
ublic improvements	Public Improvements	376	8/28/2007	8/1/2009	23	2.02%	334.60	654.33	5.00%	9.50%	2,401.86	(1,747.53)
ublic Improvements	Public Improvements	s 376	9/4/2007	8/1/2009	23	2.02%	88.47	171.29	5.00%	9.50%	635.03	(463.74)
lain	192.703	376	9/4/2007	8/1/2009	23	2.02%	334.49	647.61	5.00%	9.50%	2,401.04	(1,753.43)
lain	192.703	376	9/4/2007	8/1/2009	23	2.02%	36.36	70.40	5.00%	9.50%	261.01	(190.61)
istrict Stations	192.739	378	9/6/2007	8/1/2009	23	4.74%	511.15	986.80	5.00%	9.50%	1,563.65	(576.85)
lain	192.703	376	9/6/2007	<b>8/1/200</b> 9	23	2.02%	64.68	124.87	5.00%	9.50%	464.26	(339.39)
District Stations	192.739	37 <del>8</del>	9/6/2007	8/1/2009	23	4.74%	344.08	664.27	5.00%	9.50%	1,052.57	(388.30)
istrict Stations	192.739	378	9/6/2007	8/1/2009	23	4.74%	293.50	566.62	5.00%	9.50%	897.83	(331.21)
lain	192.703	376	9/6/2007	8/1/2009	23	2.02%	109.81	211.99	5.00%	9.50%	788.25	(576.26)
fain	192.703	376	<del>9</del> /9/2007	8/1/2009	23	2.02%	248.71	478.08	5.00%	9.50%	1,785.27	(1,307.19)
ublic improvements	Public improvements	s 376	9/10/2007	8/1/2009	23	2.02%	515.55	989.57	5.00%	9.50%	3,700.72	(2,711.15)

Depresienti

ADIT -

Public Improvements	Public Improvement	s 376	9/19/2007	8/1/2009	23	2.02%	299.10	566.63	5.00%	9.50%	2,146.98	(1,580.35)	
Public Improvements	Public Improvement	s 376	9/19/2007	8/1/2009	23	2.02%	3,186.82	6,037.25	5.00%	9.50%	22,875.68	(16,838.43)	
Main	192.703	376	9/20/2007	8/1/2009	23	2.02%	179.87	340.25	5.00%	9.50%	1,291.12	(950.87)	
Public Improvements	Public Improvement	s 375	9/24/2007	8/1/2009	23	3.10%	235.99	443.79	5.00%	9.50%	1,103.85	(660.06)	
Services	192.703	380	9/25/2007	8/1/2009	23	2.02%	1,658.54	3,114.37	5.00%	9.50%	11,905.35	(8,790.98)	
Public Improvements	Public Improvement	s 376	9/26/2007	8/1/2009	23	2.02%	473.02	886.91	5.00%	9.50%	3,395.44	(2,508.53)	
Public Improvements	Public Improvement	s 376	9/27/2007	8/1/2009	22	2.02%	67.06	125.55	5.00%	9.50%	481.37	(355.82)	
Public Improvements	Public improvement	s 376	9/27/2007	8/1/2009	22	2.02%	227.48	425.89	5.00%	9.50%	1,632.89	(1,207.00)	
Public Improvements	Public Improvement	s 376	9/28/2007	8/1/2009	22	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00	
Main and Service	192.613	376/380	9/28/2007	8/1/2009	22	2.02%	1,209.81	2,261.67	5.00%	9.50%	8,684.31	(6,422.64)	
Main	192.317	376	9/28/2007	8/1/2009	22	2.02%	1,000.81	1,870.96	5.00%	9.50%	7,184.06	(5,313.10)	
Main and Service	192.613	376/380	9/29/2007	8/1/2009	22	2.02%	770.35	1,437.99	5.00%	9.50%	5,529.73	(4,091.74)	
Main and Service	192.613	376/380	9/30/2007	8/1/2009	22	2.02%	360.36	671.67	5.00%	9.50%	2,586.77	(1,915.10)	
Main	192.463	376	10/2/2007	8/1/2009	22	2.02%	185.46	344.65	5.00%	9.50%	1,331.28	(986.63)	
Main	192.463	376	10/2/2007	8/1/2009	22	2.02%	267.00	496.18	5.00%	9.50%	1,916.61	(1,420.43)	
Main	192.463	376	10/2/2007	8/1/2009	22	2.02%	286.94	533.23	5.00%	9.50%	2,059.70	(1,526.47)	
Main	192.463	376	10/2/2007	8/1/2009	22	2.02%	227.51	422.79	5.00%	9.50%	1,633.15	(1,210.36)	
Public improvements	Public Improvement	s 376	10/2/2007	8/1/2009	22	2.02%	3,080.02	5,723.70	5.00%	9.50%	22,109.04	(16,385.34)	
Main	192.703	376	10/2/2007	8/1/2009	22	2.02%	1,770.22	3,289.66	5.00%	9.50%	12,706.99	(9,417.33)	
Main and District Station	192.613	376/378	10/23/2007	8/1/2009	22	2.02%	34.30	61.74	5.00%	9.50%	246.20	(184.46)	
Main	192.703	376	10/30/2007	8/1/2009	21	2.02%	117.63	209.45	5.00%	9.50%	844.36	(634.91)	
Public Improvements	Public Improvement	s 376	11/15/2007	8/1/2009	21	2.02%	881.57	1,530.50	5.00%	9.50%	6,328.13	(4,797.63)	
Public Improvements	Public Improvement	s 376	11/26/2007	8/1/2009	20	2.02%	453.26	773.06	5.00%	9.50%	3,253.60	(2,480.54)	
Public Improvements	Public Improvement	s 376	12/3/2007	8/1/2009	20	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00	
Main	192.317	376	12/3/2007	8/1/2009	20	2.02%	152.24	256.69	5.00%	9.50%	1,092.83	(836.14)	
Main	192.317	376	12/12/2007	8/1/2009	20	2.02%	118.72	197.21	5.00%	9.50%	852.18	(654.97)	
Public Improvements	Public improvement	s 376	12/21/2007	8/1/2009	20	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00	

\$23,596 \$44,794 \$160,916 (\$116,122)

Main	192.613	Acct 376	Date 1/9/2008	Date 8/1/2009	In Svc 19	Rate 2.02%	Depreciation 101.82	Depreciation 161.22	Rate 5.00%	Rate 9.50%	Depreciation 730.88	Tax > Book (569.66)
Main	192.613	376	1/9/2008	8/1/2009	19	2.02%	409.41	648.23	5.00%	9.50%	2,938.86	(2,290.63)
Main	192.613	376	1/14/2008	8/1/2009	19	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
Main	192.613	376	1/29/2008	8/1/2009	18	2.02%	459.52	702.04	5.00%	9.50%	3,298.52	(2,596.48)
Public Improvements	Public Improvement	s 376	2/29/2008	8/1/2009	17	2.02%	13,468.16	19,416.60	5.00%	9.50%	96,677.42	(77,260.82)
Public Improvements	Public Improvement	s 376	3/27/2008	8/1/2009	16	2.02%	501.37	685.21	5.00%	9.50%	3,598.98	(2,913.77)
Public Improvements	Public Improvement	s 376	4/14/2008	8/1/2009	16	2.02%	562.57	740.72	5.00%	9.50%	4,038.23	(3,297.51)
Main	192.317	376	4/14/2008	8/1/2009	16	2.02%	474.19	624.35	5.00%	9.50%	3,403.83	(2.779.48)
Main	192.613	376	4/14/2008	8/1/2009	16	2.02%	607.91	800.41	5.00%	9.50%	4,363.72	(3,563.31)
Main	192.613	376	4/14/2008	8/1/2009	16	2.02%	462.11	608.44	5.00%	9.50%	3,317.15	(2,708.71)
Purchase Stations	192.613	379	4/17/2008	8/1/2009	16	2.02%	627.96	821.58	5.00%	9.50%	4,507.63	(3,686.05)
Main	192.613	376	4/22/2008	8/1/2009	16	2.02%	887.18	1,148.41	5.00%	9.50%	6,368.34	(5,219.93)
Public Improvements	Public Improvement	ts 376	4/24/2008	8/1/2009	15	2.02%	72.11	92.94	5.00%	9.50%	517.63	(424.69)
Services	192.703	380	4/28/2008	8/1/2009	15	3.49%	543.91	695.00	5.00%	9.50%	2,259.78	(1,564.78)
Public Improvements	Public Improvement	ts 376	5/5/2008	8/1/2009	15	2.02%	756.62	952.08	5.00%	9.50%	5,431.16	(4,479.08)
Main	192.703	376	5/15/2008	8/1/2009	15	2.02%	630.24	775.55	5.00%	9.50%	4,524.01	(3,748.46)
Public Improvements	Public Improvement	ts 376	5/16/2008	8/1/2009	15	2.02%	2,883.67	3,540.51	5.00%	9.50%	20,699.62	(17,159.11)
Public Improvements	Public Improvement	ts 376	5/19/2008	8/1/2009	15	2.02%	1,174.26	1,431.94	5.00%	9.50%	8,429.09	(6,997.15)
Public Improvements	Public Improvement	ts 376/378	5/30/2008	8/1/2009	14	2.02%	356.24	423.53	5.00%	9.50%	2,557.13	(2,133.60)
Main	192.703	376	6/12/2008	8/1/2009	14	2.02%	265.32	305.86	5.00%	9.50%	1,904.50	(1,598.64)
Public Improvements	Public Improvement	ts 376	6/13/2008	8/1/2009	14	2.02%	479.38	551.29	5.00%	9.50%	3,441.10	(2,889.81)
Main	192.703	376	6/23/2008	8/1/2009	13	2.02%	80.21	90.01	5.00%	9.50%	575.73	(485.72)
Public Improvements	Public Improvement	ts 376	7/8/2008	8/1/2009	13	2.02%	471.05	509.00	5.00%	9.50%	3,381.33	(2,872.33)
Main	192.703	376	7/22/2008	8/1/2009	13	2.02%	171.68	178.83	5.00%	<b>9</b> .50%	1,232.33	(1,053.50)

Main	192.317	376	8/1/2008	8/1/2009	12	2.02%	1,512.58	1,533.59	5.00%	9.50%	10,857.64	(9,324.05)	
Public Improvements	Public Improvements	376	8/4/2008	8/1/2009	12	2.02%	206.64	207.79	5.00%	9.50%	1,483.34	(1,275.55)	
Public Improvements	Public Improvements	376	8/26/2008	8/1/2009	11	2.02%	1,046.74	988.59	5.00%	9.50%	7,513.71	(6,525.12)	
Main	<b>192.7</b> 03	376	8/27/2008	8/1/2009	11	2.02%	777.09	731.76	5.00%	9.50%	5,578.11	(4,846.35)	
Public Improvements	Public improvements	376	8/29/2008	8/1/2009	11	2.02%	904.09	846.33	5.00%	9.50%	6,489.72	(5,643.39)	
Public Improvements	Public improvements	376	8/29/2008	8/1/2009	11	2.02%	2,998.27	2,806.71	5.00%	9.50%	21,522.25	(18,715.54)	
Main	192.703	376	8/29/2008	8/1/2009	11	2.02%	237.79	222.60	5.00%	9.50%	1,706.93	(1,484.33)	
District Stations	192.739	378	9/5/2008	8/1/2009	11	4.74%	1,490.37	1,366.17	5.00%	9.50%	4,559.15	(3,192.98)	
Main	192.317	376	9/16/2008	8/1/2009	11	2.02%	128.55	113.91	5.00%	9.50%	922.76	(808.85)	
Main	192.703	376	9/17/2008	8/1/2009	11	2.02%	131.99	116.59	5.00%	9.50%	947.43	(830.84)	
District Stations	192.625	378	9/17/2008	8/1/2009	11	4.74%	177.66	156.93	5.00%	9.50%	543.46	(386.53)	
Main	192.463	376	9/18/2008	8/1/2009	11	2.02%	129.95	114.43	5.00%	9.50%	932.82	(818.39)	
Public Improvements	Public Improvements	376	9/25/2008	8/1/2009	10	2.02%	322.86	278.02	5.00%	9.50%	2,317.58	(2,039.56)	
Main	192.703	376	9/29/2008	8/1/2009	10	2.02%	230.79	196.17	5.00%	9.50%	1,656.69	(1,460.52)	
District Stations	192.625	378	9/29/2008	8/1/2009	10	4.74%	269.05	228.69	5.00%	9.50%	823.04	(594.35)	
Main and Service	192.703	376/380	9/29/2008	8/1/2009	10	2.02%	111.66	94.91	5.00%	9.50%	801.50	(706.59)	
Purchase Stations	192.613	379	9/29/2008	8/1/2009	10	2.53%	114.86	97.63	5.00%	9.50%	658.27	(560.64)	
Main	192.703	376	10/16/2008	8/1/2009	10	2.02%	242.68	194.82	5.00%	9.50%	1,742.00	(1,547.18)	
Main	192.317	376	10/22/2008	8/1/2009	9	2.02%	230.04	180.84	5.00%	9.50%	1,651,30	(1,470.46)	
Main	192.317	376	10/29/2008	8/1/2009	9	2.02%	31.82	24.40	5.00%	9.50%	228.40	(204.00)	
Main	192.703	376	10/31/2008	8/1/2009	9	2.02%	680.17	517.68	5.00%	9.50%	4,882.38	(4,364.70)	
Main	192.703	376	10/31/2008	8/1/2009	9	2.02%	1,072.60	816.37	5.00%	9.50%	7,699.39	(6,883.02)	
Main	192.613	376	10/31/2008	8/1/2009	9	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00	
Public Improvements	Public Improvement:	s 376/380	11/6/2008	8/1/2009	9	2.02%	1,797.88	1,338.42	5.00%	9.50%	12,905.5€	(11,567.14)	
Public Improvements	Public Improvements	s 376	11/11/2008	8/1/2009	9	2.02%	162.04	118.38	5.00%	9.50%	1,163.17	(1,044.79)	
Public improvements	Public Improvements	\$ 376	11/13/2008	8/1/2009	9	2.02%	120.66	87.48	5.00%	9.50%	866.09	(778.61)	
District Stations	192.613	378	11/25/2008	8/1/2009	8	4.74%	318.61	220.37	5.00%	9.50%	974.65	(754.28)	

Main	192.463	376	12/9/2008		8 app	2.02%	117.26	76.54	5.00%	9.50%	841.70	(765.16)	
Public Improvements	Public Improvement	ts 376	12/16/2008		8	2.02%	615.71	389.95	5.00%	9.50%	4,419.70	(4.029.75)	
District Stations	192.703	378	12/17/2008	8/1/2009	8	4.74%	121.28	76.47	5.00%	9.50%	371.00	(294.53)	
Public improvements	Public Improvement	ts 376	12/20/2008	8/1/2009	7	2.02%	650.93	405.02	5.00%	9.50%	4,672.49	(4,267.47)	
							\$43,400	\$50,451		Į	\$299,925	(\$249,478)	
		FERC	In Service	File		Depreciation		Accumulated	YR 1		Accumulated	To a Deat	
Public Improvements	Public Improvement	<u>Acct</u> ts 376	Date 1/12/2009	Date 8/1/2009	In Svc 7	Rate 2.02%	792.56	442.51	Rate 5.00%	Rate 9.50%	Depreciation 5,689.20	Tax > Book (5,246.69)	
Public Improvements	Public Improvement	ts 376	1/27/2009	8/1/2009	6	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00	
Main	192.613	376	2/17/2009	8/1/2009	6	2.02%	139.52	63.95	5.00%	9.50%	1,001.51	(937.56)	
Public Improvements	Public Improvement	ts 376/380	2/27/2009	8/1/2009	5	2.02%	2,837.08	1,221.52	5.00%	9.50%	20,365.20	(19,143.68)	
Main	192.317	376	3/11/2009	8/1/2009	5	2.02%	211.62	84.06	5.00%	9.50%	1,519.05	(1,434.99)	
Main	192.613	376	3/16/2009	8/1/2009	5	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00	
Main	192.703	376	3/20/2009	8/1/2009	4	2.02%	74.44	27.71	5.00%	9.50%	534.33	(506.62)	
Main	192.703	376	3/27/2009	8/1/2009	4	2.02%	675.35	238.25	5.00%	9.50%	4,847.78	(4,609.53)	
Main	192.703	376	3/29/2009	8/1/2009	4	2.02%	381.68	132.53	5.00%	9.50%	2,739.79	(2,607.26)	
Public Improvements	Public Improvemen	ts 376	4/15/2009	8/1/2009	4	2.02%	1,005.06	301.52	5.00%	9.50%	7,214.55	(6,913.03)	
District Stations	192.703	378	4/2/2009	8/1/2009	4	2.02%	288.33	96.91	5.00%	9.50%	2,069.66	(1,972.75)	
Main	192.317	376	4/21/2009	8/1/2009	3	2.02%	903.43	255.97	5.00%	9.50%	6,485.04	(6,229.07)	
Main	192.317	376	4/30/2009	8/1/2009	3	2.02%	199.06	51.42	5.00%	9.50%	1,428.93	(1.377.51)	
Main	192.613	376	5/1/2009	8/1/2009	3	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00	
Public Improvements	Public Improvemen	ts 376/380	5/18/2009	8/1/2009	3	2.02%	865.09	180.23	5.00%	9.50%	6,209.82	(6,029.59)	
Public Improvements	Public Improvemen	ts 376	5/27/2009	8/1/2009	2	2.02%	340.00	62.33	5.00%	9.50%	2,440.60	(2.378.27)	
Main	192.317	376	6/1/2009	8/1/2009	2	2.02%	339.42	57.51	5.00%	9.50%	2,436.40	(2,378.89)	
Main	192.463	376	6/19/2009	8/1/2009	1	2.02%	199.24	23.80	5.00%	9.50%	1,430.19	(1,406.39)	
Main	192.317	376	6/23/2009	8/1/2009	1	2.02%	296.02	32.07	5.00%	9.50%	2,124.92	(2,092.85)	
Main and Service	192.613	376/380	6/30/2009	8/1/2009	1	2.02%	336.85	29.94	5.00%	9.50%	2,418.00	(2,388.06)	
Main	192.317	376	7/7/2009	8/1/2009	1	2.02%	286.20	19.88	5.00%	9.50%	2,054.38	(2,034.50)	

Public Improvements	Public	: improvements	376	7/9/2009	8/1/2009	1	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00	
Public Improvements	Public	: Improvements	376/380	7/23/2009	8/1/2009	0	2.02%	737.34	18.43	5.00%	9.50%	5,292.75	(5,274.32)	
Public Improvements	Public	: Improvements	376	8/3/2009	8/1/2009	(0)	2.02%	531.50	(2.95)	5.00%	9.50%	3,815.20	(3,818.15)	
Public Improvements	Public	: Improvements	376/380	2/11/2009	8/1/2009	6	2.02%	3,545.22	1,683.98	5.00%	9.50%	25,448.34	(23,764.36)	
Main		192.317	376	7/21/2009	8/1/2009	0	2.02%	220.72	6.74	5.00%	9.50%	1,584.40	(1,577.66)	
Main		192.317	376	5/29/2009	8/1/2009	2	2.02%	213.56	37.97	5.00%	9.50%	1,532.99	(1,495.02)	
Main		192.317	376	4/21/2009	8/1/2009	3	2.02%	148.57	42.09	5.00%	9.50%	1,066.46	(1,024.37)	
Main		192.703	376	7/13/2009	8/1/2009	1	2.02%	279.61	14.76	5.00%	9.50%	2,007.13	(1,992.37)	
Main		192.317	376	5/29/2009	8/1/2009	2	2.02%	342.97	60.97	5.00%	9.50%	2,461.91	(2,400.94)	
Main and Service		192.703	376/380	7/29/2009	8/1/2009	0	2.02%	231.26	1.93	5.00%	9.50%	1,660.03	(1,658.10)	
Main		192.317	376	5/27/2009	8/1/2009	2	2.02%	58.47	10.72	5.00%	9.50%	419.70	(408.98)	
								\$16,480	\$5,197		[	\$118,298	(\$113,102]	
								\$83,475	\$100,442		E	\$579,144	(\$478,702)	

# FUNCTIONAL Products - STAFF Schedules -

Cost Center	LOCATION	Year F	unctional No	Task Number	Units I	Dollars by Task F	unctional No. Dollars by Task	Total CY Spend	Average per unit	Used in Filing	Units used	Amt in Filing category	Code Task Type
3136 Herington	Herington Herington	2007	060.14727	01202	1811 2063	\$36,398.54 0 \$22,961.33	60.15601 \$7,739.50 \$2,352.34	\$44,138.04 \$25,313.67	\$24.37 \$12.27		1811 0	\$44,138.04 Main \$0.00 Main	192.703 2" PE main - ft,
(dinglori	risington	2007		01980	2003	\$22,80 (.33	¥2,30£.34	\$20,313.07	♦12.21	N	U	au.uu Main	Main retire - ft.
	Herington	2007		02101	1	\$420,81	\$0.00	\$420.81		Y		Services	192,703 1" st. service - #
	Herington	2007		02201	131	\$193,745.56	\$128,572.66	\$322,318.22	\$2,277.71	Y	55	Services	192.703 1" PE service - #
	Herington Herington	2007 2007		0220125	2	\$1,011.35 \$1,719.89	\$0.00 \$242.95	\$1,011.35 \$1,962.84		Ŷ		Services Services	192.703 1 1/4" PE serv # 192.703 2" PE service - #
	Herington	2007		02980	145	\$133,376.22	\$26,860.65	\$160,236.87	\$1,105.08	Ň	o	\$0.00 Services	Service retire - #
	Herington	2007		19800	23	\$14,467.16	\$7,446.48	\$21,913.64	\$952.77	Y	23	Clamps	192.703 Lk. clamps - #
	Herington Herington	2007 2007		19898 38200	2 296	\$334.73 \$223,855.91	\$0.00 \$128,282.30	\$334.73 \$352,138.21	\$167.37 \$1,189.66	N N	57	Meter Loops	Retire ik. clamp - # Meter loops - #
	Herington	2007		38298	280	\$44,776.92	\$17,107.61	\$61,884.53	\$221.02		5/	Weter Loops	Retire mtr loop - #
3139	Ulysses	2007	060.14729	01102	40	\$0.00.00	60.15604 \$1,377.72	\$1,377.72	\$34.44	Ŷ	40	\$1,377.72 Main	192.703 2" steel main - ft.
Ulysses	Ulysses	2007		01202	425	\$13,009.29	\$51.91	\$13,061.20	\$30.73		425	\$13.061.20 Main	192.703 2" PE main - ft.
	Ulysses	2007		01980	246	\$4,547.68	\$486.25	\$5,033.93	\$20.46	N	0	\$0.00 Main	Main retire - ft.
	Ulysses	2007		02201	6	\$5,584.45	\$2,158.64	\$7,743.09		Y		Services	192.703 1" PE service - #
	Ulysses	2007		0220125	86	\$22,581.02	\$40,044.66	\$62,625.68	\$751.14	Ŷ	45	Services	192.703 1 1/4" PE serv #
	Ulysses Ulysses	2007 2007		02202 02980	7	\$2,535.71	\$1,458.73	\$3,994.44		Ŷ	-	Services	192.703 2" PE service - #
	Ciyeses	2007		02980	62	\$13,521.02	\$1,743.87	\$15,264.89	\$246.21	N	0	\$0.00 Services	Service retire - #
	Ulysses Ulysses	2007 2007		38200	100	\$5,650.27	\$8,520.98	\$14,171.25	\$141.71	N	47	Meter Loops	Meter loops - #
				38298	54	\$22,867.67	\$2,318.22	\$25,185.89	\$466.41	N			Retire mtr loop - #
3143 Olathe	Olathe Olathe	2007 2007	060.14731	01202 01980	250 250	\$332,303.66 0		\$532,398.37	\$2,129.59		250	\$532,398.37 Main	192.703 2" PE main - ft.
	Olaine	2007		01980	250	\$9,154.44	\$390.45	\$9,544.89	\$38.18	N	0	\$0.00 Main	Main retire - ft.
	Olathe	2007		02101	6	\$3,305.66	\$318.12	\$3,623.78		Y		Services	192.703 1" steel serv - #
	Olathe Olathe	2007 2007		02201	1202	\$358,296.42	\$191,873.53	\$550,169.95	\$477.68	Ŷ	115	Services	192.703 1" PE service - #
	Olathe	2007		0220125	47 11	\$1,057.74 \$47,028.91	\$289.11 \$2,568.07	\$1,346.85 \$49,596.98		Ŷ		Services Services	192.703 1 1/4" PE serv # 192.703 2" PE service - #
	Olathe	2007		02980	285	\$130,598.35	\$49,397.41	\$179,995.76	\$631.56	Ň	0	\$0.00 Services	Service retire - #
	Olathe	2007		19800	3	\$23,998,18	\$21.006.54	\$45.004.72	\$15,001.57	Y	3	Clamps	192.703 Lk. ciamps - #
	Olathe	2007		19900	11	\$151,698.02	\$69,060.52	\$220,758.54	\$15,001.57 \$20,068.96		3 11	\$220,758.54 Anodes	192.703 LK. clamps - # 192.463 Anodes - #
	Olathe	2007		38200	1331	\$155,302.17	\$74,583.13	\$229,885.30	\$172.72		116	Meter Loops	Meter loops - #
	Olathe	2007		38298	281	\$81,048.27	\$10,523.87	\$91,572.14	\$325.88	N			Retire mtr loop - #
3145	Independence	2007	060.14733	0120125	2	\$0.00 06	60.15610 \$648.10	\$648.10	\$324.05	Y	2	\$648.10 Main	192.703 1 1/4" PE main - ft.
Independence	Independence	2007		01202	535	\$56,275.72	\$42,494.64	\$98,770.36	\$184.62		535	\$98,770.36 Main	192.703 2" PE main - ft.
	Independence Independence	2007 2007		01204 01980	1 1917	\$11,813.33 \$4,351.02	\$4,324.29 \$2,889.37	\$16,137.62 \$7,240.39	\$16,137.62 \$3.78		1	\$16,137.62 Main \$0.00 Main	192.703 4" PE main - ft.
							#2,008.31				U	ao.oo main	Main retire - ft.
	Independence Independence	2007 2007		02201 02980	115 271	\$128,962.86 \$23,107.88	\$54,514.19 \$7,255.78	\$183,477.05 \$30,363.66	\$1,595.45 \$112.04	Y N	29 0	Services	192.703 1" PE service - #
							<i>\$1,200.10</i>	430,303.00	\$112.04	1	v	\$0.00 Services	Service retire - #
	Independence	2007		19800	38	\$128,136.16	\$39,498.83	\$167,634.99	\$4,411.45		38	Clamps	192.703 Lk. clamps - #
	Independence independence	2007 2007		19900	12	\$14,320.45	\$13,827.84	\$28,148.29	\$2,345.69	Ŷ	12	\$28,148.29 Anodes	192.463 Anodes - #
	independence	2007		38200 38298	133 277	\$71,580.60 \$36,544.20	\$41,267.17 \$15,939.12	\$112,847.77 \$52,483.32	\$848.48 \$189.47	N N	33	Mater Loops	Meter loops - # Retire mtr loop - #
3146	Yates Center	2007	000 4 1705		40.47								•
Yates Center	Yates Center	2007	060.14735	01202	1047 240	\$20,840.96 06 \$1,637.05	60.15613 \$6,992.29 \$5.229.47	\$27,833.25 \$6,866,52	\$26.58 \$28.61	Ŷ	1047 240	\$27,833.25 Main \$6,866.52 Main	192.703 2* PE main - ft. 192.703 4* PE main - ft.
	Yates Center	2007		01980	1126	\$1,221.67	\$499.42	\$1,721.09	\$1.53		240	\$0.00 Main	Main retire - ft.
	Yates Center	2007		02201	76	\$67,683,13	\$35.907.22	\$103,590.35		v		Pandasa	192.703 1" PE service - #
	Yates Center	2007		02202	2	\$577.96	\$1,243.19	\$1,821.15	\$1,351.43	Ý	28	Services Services	192.703 1" PE service - #
	Yates Center	2007		02980	116	\$11,923.39	\$1,837.64	\$13,761.03	\$118.63	Ń	0	\$0.00 Services	Service retire - #
	Yates Center	2007		19700	16	\$8,773.68	\$8,788.05	\$17,561.73	\$1,097,61	N	0	\$0.00 Ext coverage	192.463 Ext coverage
	Yates Center	2007		19800	34	\$46,753.42	\$17,817.57	\$64,570.99	\$1,899.15		34	Clamps	192.703 Lk. clamps - #
	Yates Center	2007		19900	10	\$6,872.20	\$8,662.84	\$15,535.04	\$1,553.50	Y	10	\$15,535.04 Anodes	192.463 Anodes - #
	Yates Center Yates Center	2007 2007		38200 38298	330 344	\$55,032.88 \$16,764.46	\$27,237.89 \$10,920.04	\$82,270.77 \$27,684.50	\$249.31 \$80.48	N N	33	Meter Loops	Meter kops - #
				00200	•	\$10,104.40	\$10,820.0 <del>1</del>	421,004.00	400.46	14			Retire mtr loop - #
	38	2007										\$1,005,673.05	
3136	Herington	2008	060,15601	01102	5	\$5,723.08 0	60.16386 \$0.00	\$5,723.08	\$1,144.62	Y	5	\$5,723.08 Main	192.703 2" steel main - ft.
Herington	Herington	2008		01104	373	\$39,096.63	\$0.00	\$39,096.63	\$104.82	Ŷ	373	\$39.096.63 Main	192.703 2" steel main - ft. 192.703 4" steel mian - ft.
	Herington	2008		01202	1355	\$56,087.08	\$17,758.52	\$73,845.60	\$54,50	Ŷ	1355	\$73,845.60 Main	192.703 2" PE main - ft.
	Herington Herington	2008 2008		01204 01980	120 3246	\$11,646.96 \$8,374,12	\$0.00 \$1,172.04	\$11,646.96 \$9,546.16	\$97.06 \$2.94	Y N	120	\$11,646.96 Main	192.703 4" PE main - ft.
									<i>4</i> 2.84		U	\$0.00 Main	Main retire - ft.
	Herington Herington	2008 2008		02201	180	\$343,838.23	\$91,729.61	\$435,567.84		Y		Services	192.703 1" PE service - #
	Herington	2008		0220125 02202	73	\$5,758.70 \$12,333.27	\$4,233.46 \$320.48	\$9,992.16 \$12,653.75	\$2,411.65	Ŷ	44	Services	192.703 1 1/4" PE serv #
	Herington	2008		02980	197	\$82,125.50	\$31,794.37	\$12,655.75	\$578.27	Ň	0	Services \$0.00 Services	192.703 2" PE service - # Service retire - #
	Herington	2008		10900		£10 410 TO							
	Herington	2008		19800 19900	36 23	\$19,112.78 \$10.028.32	\$9,545.56 \$0.00	\$28,658.34 \$10,028.32	\$796.07 \$436.01	Y Y	36 23	Clamps \$10.028.32 Anodes	192.703 Lk. clamps - # 192.463 Anodes - #
	Herington	2008		38200	403	\$394,741.62	\$129,820.75	\$524,562.37	\$1,301.64		23	\$10,028.32 Anodes Meter Loops	192.463 Anodes - # Meter loops - #
		_,				4001,141.02	\$ 128,020.73	40K4,002.01	#1,301.64	N	53	Meter Loops	Meter loops - #

576-1

	Herington	2008	38298	390	\$43,962.13	\$11,933.16	\$55,895.29	\$143.32	N			Retire mtr loop - #
3139	Ulysses	2008	060.15604 01102	93	\$3,996.54 060.16389	\$5,011.83	\$9,008.37	\$96.86	Y	93	\$9,008.37 Main	192.703 2" steel main - ft.
Ulysses	Ulysses Ulysses	2008 2008	01104 01202	342 462	\$7,314.0 <del>6</del> \$20,288.20	\$12,830.57 \$34.641.58	\$20,144.63	\$58.90	Ŷ	342	\$20,144.63 main	192.703 4" steel mian - ft.
	Ulysses	2008	01202	462 787	\$3,066.38	\$34,641.58 \$507.18	\$54,929.78 \$3,573.56	\$118.90 \$4.54	Y N	462 0	\$54,929.78 Main \$0.00 Main	192.703 2" PE main - ft. Main retire - ft.
	Ulysses	2008	02201	71	\$18,162.47	\$6,234.28	\$24,396.75		Y		Services	192.703 1" PE service - #
	Ulysses	2008	0220125	48	\$18,386.33	\$2,118.58	\$20,504.91	\$436.39	Ý	22	Services	192.703 1 1/4" PE serv #
	Ulysses Ulysses	2008 2008	02202 02204	7	\$10,231.73 \$288.27	\$0.00 \$0.00	\$10,231.73 \$288.27	4400.00	Ŷ	LL	Services Services	192.703 2" PE service - # 192.703 4" PE service - #
	Ulysses	2008	02980	82	\$3,230.02	\$507.18	\$3,737.20	\$45.58	Ň	o	\$0.00 Services	Service retire - #
	Ulvases	200B	38200	118	\$23,010.70	\$7,683,19	\$30,693.89	\$260.12	N	24	Meter Loops	Meter loops - #
	Ulysses	2008	38298	104	\$4,863.24	\$2,650.80	\$7,514.04	\$72.25	N	24	MOIO LOOPS	Retire mtr loop - #
3143	Olathe	2008	060.15607 01104	284	\$72,912.59 060.16392	\$24,742.69	\$97,655.28	\$343.86	Y	284	\$97,655.28 Main	192.703 4" steel main - ft.
Olathe	Olathe Olathe	2008 2008	01202	1949 233	\$521,843.48 \$88,622.54	\$76,626.81 \$26,008.72	\$598,470.29 \$114,631.26	\$307.07 \$491.98	Ŷ Ŷ	1949 233	\$598,470.29 Main \$114,631.26 Main	192.703 2" PE main - ft. 192.703 4" PE main - ft.
	Olathe	2008	01206	112	\$6,570.10	-\$1,313.47	\$5,256.63	\$46.93	Y	112	\$5,256.63 Main	192.703 6" PE main - ft.
	Olathe	2008	01980	2296	\$1,487.79	\$514.94	\$2,002.73	\$0.87	N	0	\$0.00 Main	Main retire - ft.
	Olathe	2008	02102	2	\$697.59	\$1,978.62	\$2,676.21		Y		Services	192.703 2" steel serv - #
	Olathe Olathe	2008 2008	02201 0220125	1134 30	\$425,055.63 \$63.57	\$131,573.35 \$230.46	\$556,628.98 \$294.03	\$474.52	Ŷ	111	Services Services	192.703 1" PE service - # 192.703 1 1/4" PE serv #
	Olathe	2008	02202	19	\$455.69	\$2,246.56	\$2,702.25		Ý		Services	192.703 2" PE service - #
	Olathe	2008	02980	286	\$105,248.34	\$25,103.85	\$130,352.19	\$455.78	N	0	\$0.00 Services	Service retire - #
	Olathe Olathe	2008 2008	19800 19900	8	\$45,780.94	\$18,204.27	\$63,985.21	\$7,998.15	Y	8	Clamps	192.703 Lk. clamps - #
	Olathe	2008	19900	17 1188	\$146,017.99 \$165,565.28	\$24,063.78 \$50,982.61	\$170,081.77 \$216,547.89	\$10,004.81 \$182.28	Y N	17 114	\$170,081.77 Anodes Mater Loops	192.463 Anodes - # Meter loops - #
	Olathe	2008	38296	278	\$5,990.01	\$7,085.52	\$13,075.53	\$47.03	Ň		motor Ecopo	Retire mtr loop - #
3145	Independence	2008	060.15610 01102	3	\$453.78 060.16395	\$0.00	\$453.78	\$151.26	Y	3	\$453.78 Main	192.703 2" steel main - ft.
Independence	Independence	2008 2008	0120125 01202	2 574	\$650.82 \$31,198.64	\$0.00 \$5,807.92	\$650.82	\$325.41	Ŷ	2	\$650.82 Main	192.703 1 1/4" PE main - ft.
	Independence	2008	01202	364	\$14,593.51	\$279.81	\$37,006.56 \$14,873.32	\$64.47 \$40.86	Ý	574 364	\$37,006.56 Main \$14.873.32 Main	192.703 2" PE main - ft. 192.703 4" PE main - ft.
	Independence	2008	01980	1173	\$5,305.94	\$83.87	\$5,389.81	\$4.59	Ň	0	\$0.00 Main	Main retire - ft.
	Independence	2008	02101	2	\$376.54	\$481.05	\$857.59		Y		Services	192.703 1" steel serv - #
	Independence Independence	2008 2008	02201	172 212	\$93,539.51 \$0.00	\$41,397.91 \$10,189.51	\$134,937.42 \$10,189.51	\$378.20	Ŷ	59	Services Services	192.703 1" PE service - # 192.703 2" PE service - #
	Independence	2008	02980	240	\$31,998.45	\$4,249.72	\$36,248.17	\$151.03	'n	0	\$0.00 Services	Service retire - #
	Independence	2008	19800	188	\$270,737.19	\$55,821.03	\$326,558.22	\$1,737.01	Y	188	Ciamps	192.703 Lk. clamps - #
	Independence Independence	2008 2008	19900	127	\$37,507.99	\$16,129.24	\$53,637.23	\$422.34	Ý	127	\$53,637.23 Anodes	192.463 Anodes - #
	Independence	2008	38200 38298	273 342	\$130,886.30 \$46,191.71	\$42,729.07 \$8,959.64	\$173,615.37 \$55,151.35	\$635.95 \$161.26	N N	67	Meter Loops	Meter koops - # Retire mtr koop - #
3146	Yates Center	2008	060.15613 01202	284	\$13,929.62 060.16398	\$1,636.44	\$15,566.08	\$54.81	Y	284	\$15.566.06 Main	192.703 2" PE main - ft.
Yates Center	Yates Center	2008	01980	284	\$961.73	\$303.11	\$1,264.84	\$4.45	Ń	0	\$0.00 Main	Main retire - ft.
	Yates Center	2008	02201	59	\$76,938.33	\$6,480.59	\$83,418.92	\$1 919 07	Y	20	Services	192,703 1" PE service - #
	Yates Center Yates Center	2008 2008	0220125 02980	6 86	\$1,988.96	\$0.00	\$1,988.96	\$1,313.97	Y	38	Services	192.703 1 1/4" PE serv #
					\$26,984.80	\$1,461.80	\$28,446.60	\$330.77	N	0	\$0.00 Services	Service retire - #
	Yates Center Yates Center	2008	19700 19800	13	\$10,394.07	\$5,202.93	\$15,597.00	\$1,199.77	N	0	\$0.00 Ext coverage	192.463 Ext coverage
	Yates Center	2008	19900	40 31	\$90,163.62 \$9,887.16	\$16,161.00 \$3.636.89	\$106,324.62 \$13,524.05	\$2,658.12 \$436.26	Ý	40 31	Clamps \$13,524,05 Apodes	192.703 Lk. ciamps - # 192.463 Anodes - #
	Yates Center	2008	38200	243	\$66,761.87	\$20,466.27	\$87,228.14	\$358.96	N	50	Meter Loops	Meter loops - #
	Yates Center	2008	38298	258	\$24,522.07	\$6,517.88	\$31,039.95	\$120.31	N			Retire mtr loop - #
	DE DE	2908									\$1,346,230.42	
3136	Herington	2009	060.16386 01102	5			Ar40.04	****	v	-	AT40 04 14-1-	
Herington	Herington	2009	01202	835	\$510.84 \$26,653.19		\$510.84 \$26,653.19	\$102.17 \$31.92	Ŷ	5 835	\$510.84 Main \$26,653.19 Main	192.703 2" steel main - ft. 192.703 2" PE main - ft.
	Herington	2009	01980	720	\$4,365.45		\$4,365.45	\$6.06	Ň	0	\$0.00 Main	Main retire - ft.
	Herington	2009	02201	59	\$196,802.41		\$196,802.41	An 170	Y		Services	192.703 1" PE service - #
	Herington Herington	2009 2009	0220125 02202	1 2	\$8,521.34 \$4,136.36		\$8,521.34 \$4,136.36	\$3,378.39	Ŷ	20	Services Services	192.703 1 1/4" PE serv # 192.703 2" PE service - #
	Herington	2009	02980	114	\$77,201.45		\$77,201.45	\$677.21	Ń	0	\$0.00 Services	Service retire - #
	Herington	2009	19800	11	\$11,978.94		\$11,978.94	\$1,088,99	Y	11	Ciamos	192.703 Lk. clamps - #
	Herington	2009	19900	3	\$1,285.52		\$1,285.52	\$428.51	Ý	3	\$1,285.52 Anodes	192.463 Anodes - #
	Herington Herington	2009 2009	38200 38298	179 201	\$315,341.91 \$36,327.94		\$315,341.91 \$36,327.94	\$1,761.69 \$180.74	N N	34	Meter Loops	Meter loops - # Retire mtr loop - #
											•	
3139 Lilvases	Ulysses Ulysses	2009 2009	060.16389 01102 01202	8 22	\$6,232.08 \$7,667,83		\$6,232.08 \$7,667.83	\$779.01 \$348.54	Ŷ	8 22	\$6,232.08 Main \$7,667.83 Main	192.703 2" steel main - ft. 192.703 2" PE main - ft.
0.,0000	Ulysses	2009	01980	30	\$1,613.51		\$1,613.51	\$53.78	Ň	0	\$0.00 Main	Main retire - ft.
	Ulvsses	2009	02201	6	\$17.018.92		\$17.018.92		Y		Services	192.703 1" PE service - #
	Ulysses	2009	0220125	16	\$5,230.20		\$5,230.20	\$1,365.44	Ŷ	18	Services	192.703 1 1/4" PE serv #
	Ulysses Ulysses	2009 2009	02202 02980	1 23	\$9,156.06 \$3,385.86		\$9,156.06 \$3,385.86	\$147.21	Y N	0	Services \$0.00 Services	192.703 2" PE service - #
		2000	J280V	23	40,000.00		40,000.00	\$141.21	14	v	QUUU SEIVICES	Service retire - #

	Ulysses	2009	38200	28	\$26,247.21	\$26,247,21	\$937.40	N	18	Meter Loops	Meter loops - #
	Ulysses	2009	38298	108	\$5,066.48	\$5,066.48	\$46.91	N N			Retire mtr loop - #
	Olathe	2009	060.16392 0120125	85	\$525.72	\$525.72	\$6.18	Y	85	\$525.72 Main	192.703 1 1/4" PE main - ft.
Olathe	Olathe	2009	01202	790	\$245,252.65	\$245,252.65	\$310.45	Ŷ	790	\$245,252.65 Main	192.703 2" PE main - ft.
	Olathe	2009	01204	21	\$132,199.16	\$132,199.16	\$6,295.20	Y	21	\$132,199.16 Main	192.703 4" PE main - ft.
	Olathe	2009	01206	-1	\$7,050.10	\$7,050.10	\$7,050.10	Ý	1	\$7,050.10 Main	192,703 6" PE main - ft.
	Olathe	2009	01980	1013	\$1,451.98	\$1,451.98	\$1.43	Ň	ò	\$0.00 Main	Main retire - ft.
	Olathe	2009	02201	104	\$399,156.84	\$399,156.84		Y		Services	192.703 1" PE service - #
	Olathe	2009	0220125	1	\$824.70	\$824.70	\$3,406.57	Y	39	Services	192.703 1 1/4" PE service - #
	Olathe	2009	02202	16	\$12,213,16	\$12,213.16		Y		Services	192.703 2" PE service - #
	Olathe	2009	02980	137	\$76,386.46	\$76,386.46	\$557.57	N	0	\$0.00 Services	Service retire - #
	Olathe	2009	19800	6	\$45,924.16	\$45,924.16	\$7,654.03	Y	6	Clamps	192.703 Lk, clamps - #
	Olathe	2009	19900	9	\$84,113.09	\$84,113.09	\$9,345.90	Y	9	\$84,113.09 Anodes	192.463 Anodes - #
	Olathe	2009	38100	2	\$59,965.42	\$59,965.42	\$29,982.71	N			Meter
	Olathe	2009	38200	110	\$416.714.46	\$416,714.46	\$3,788.31	N	40	Meter Loops	Meter loops - #
	Olathe	2009	38298	130	\$25,168.35	\$25,168.35	\$193.60	N N N			Retire mtr loop - #
3145	Independence	2009	060.16395 01102	2	\$3,452.40	\$3,452.40	\$1,726.20	Y	2	\$3,452.40 Main	192.703 2" steel main - ft.
Independence	Independence	2009	01103	3	\$1,848.60	\$1,848.60	\$616.20	Y	3	\$1,848.60 Main	192,703 3" steel main - ft.
	Independence	2009	01202	966	\$59,768.55	\$59,768.55	\$61.87	Ŷ	966	\$59,768.55 Main	192,703 2" PE main - ft.
	Independence	2009	01204	176	\$10,719.96	\$10,719.96	\$60.91	Ý	176	\$10,719.96 Main	192.703 4" PE main - ft.
	Independence	2009	01980	1333	\$9,469.62	\$9,469.62	\$7.10	Ň	0	\$0.00 Main	Main retire - ft.
	Independence	2009	02201	109	\$190,157.16	\$190,157,16	\$1,744.56	Y	53	Services	192.703 1" PE service - #
	Independence	2009	02980	260	\$45,860.00	\$45,860.00	\$176.38	Y N	0	\$0.00 Services	Service retire - #
	Independence	2009	19800	103	\$205,408.81	\$205,408.81	\$1,994.26	Y	103	Clamps	192.703 Lk. clamps - #
	Independence	2009	19898	126	\$1,217.41	\$1,217.41	\$9.66	N			Ret ik clamps - #
	Independence	2009	19900	83	\$91,891.30	\$91,891.30	\$1,107,12	Y	83	\$91.891.30 Anodes	192.463 Anodes - #
	Independence	2009	38200	133	\$111,820,70	\$111.820.70	\$840.76	N	69	Meter Loops	Meter loops - #
	independence	2009	38298	220	\$34,530.24	\$34,530.24	\$156.96	N			Retire mtr loop - #
3146	Yates Center	2009	060.16398 02201	12	\$39,953.32	\$39,953.32	\$3,329.44	Y	12	\$39,953.32 Services	192,703 1" PE service - #
Yates Center	Yates Center	2009	02980	81	\$17,742.39	\$17,742.39	\$219.04	N	0	\$0.00 Services	Service retire - #
	Yates Center	2009	19800	38	\$71,751.82	\$71,751.82	\$1,888.21	Y	38	Clamps	192.703 Lk. clamps - #
	Yates Center	2009	19900	4	\$9,626.31	\$9,626.31	\$2,406.58	Y	4	\$9,626.31 Anodes	192.463 Anodes - #
	Yates Center	2009	38200	44	\$69,413.68	\$69,413.68	\$1,577.58	N	12	Meter Loops	Meter loops - #
	Yates Center	2009	38298	110 45,973	\$12,293.10	\$20,082.28 12,105,889	\$182.57	N N			Retire mtr loop - #
				-0,973		12,103,005			2009	\$728,750.62	- avg

Funct \$3,080,654.09

Specific \$3,994,095.82

total \$7,074,749.91

# JTG-1

# FUNCTIONAL PROJECTS - Depreciation, Accum, ADIT

	FERC	In Service	File	Months	Depreciation	Book	Accumulated	YR 1	Tax YR 2	Accumulated	
Description	Acct	Date	Date	In Svc	Rate	Depreciation	Depreciation	Rate	Rate	Depreciation	Tax > Book
Replace 1811' main with 2" PE plastic due to leakage in various short sections throughout the service area of Herington, Kansas office. Retire 2063' of various size main due to leakage in various short sections throughout the service area of Herington, Kansas office.	376 376	12/31/2007 12/31/2007	8/1/2009 8/1/2009	19 19	2.02% 2.02%	891.59 0.00	1,433.97 0.00	5.00% 5.00%	9.50% 9.50%	6,400.02 0.00	(4,966.05) 0.00
Replace 1 service line with 1* steel due to leakage in the service area of Herington, Kansas office.	380	12/31/2007	8/1/2009	19	3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 131 service lines with 1" PE plastic due to leakage throughout the service area of Herington, Kansas office.	380	12/31/2007	8/1/2009	19		0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 2 service lines with 1 1/4" PE plastic due to leakage throughout the service area of Herington, Kansas office.	380	12/31/2007	8/1/2009	19		0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 9 service lines with 2" PE plastic due to leakage throughout the service area of Herington, Kansas office. Retire 145 of various size services due to leakage throughout the service area of Herington, Kansas office.	380 380	12/31/2007 12/31/2007	8/1/2009 8/1/2009	19 19		0.00 0.00	0.00 0.00	5.00% 5.00%	9.50% 9.50%	0.00	0.00
	360	12/3 1/2007	6/1/2008	19	3.4970	0.00	0.00	0.00%	9.00%	0.00	0.00
intailed 23 leak clamps on distribution piping to repair leaks in various locations in the service area of Herington, Kansas office.	376	12/31/2007	8/1/2009	19	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
Retired 2 leak clamps that were no longer needed to repair mains from leakage in the service area of Herington, Kansas office.	376	12/31/2007	8/1/2009	19	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 296 meter loops due to service line/ meter loop leakage at various locations in the service area of Herington, Kansas office. Retire 280 meter loops due to service line/ meter loop leakage at various locations in the service area of Herington, Kansas office.	382 382	12/31/2007 12/31/2007	8/1/2009 8/1/2009	19 19		0.00 0.00	0.00 0.00	5.00% 5.00%	9.50% 9.50%	0.00	0.00
	302	12/3/1200/	a 1/2005	10	0.00%	0.00	0.00	0.00 /#	0.0078	0.00	0.00
Replace 40' main with 2" steel due to leakage in various short sections throughout the service area of Ulysses, Kansas office.	376	12/31/2007	8/1/2009	19		27.83	44.76	5.00%	9.50%	199.77	(155.01)
Replace 425' main with 2" PE plastic due to leakage in various short sections throughtout the service area of Ulysses, Kansas office.	376	12/31/2007	8/1/2009	19		263.84	424.34	5.00%	9.50%	1,893.87	(1,469.53) 0.00
Retire 246' of various size main due to leakage in various short sections throughtout the service area of Ulysses, Kansas office.	376	12/31/2007	8/1/2009	19	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 6 service lines with 1" PE plastic due to leakage throughout the service area of Ulysses, Kansas office.	380	12/31/2007	8/1/2009	19	3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 86 service lines with 1 1/4" PE plastic due to leakage throughout the service area of Ulysses, Kansas office.	380	12/31/2007	8/1/2009	19		0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 7 service lines with 2" PE plastic due to leakage throughout the service area of Ulysses, Kansas office.	380	12/31/2007	8/1/2009	19		0.00	0.00	5.00%	9.50%	0.00	0.00
Retire 62 of various size services due to leakage throughout the service area of Ulysses, Kansas office.	380	12/31/2007	8/1/2009	19	3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 100 meter loops due to service line/ meter loop leakage in various locations in the service area of Ulysses, Kansas office. Retire 54 meter loops due to service line/ meter loop leakage in various locations in the service area of Ulysses, Kansas office.	382 382	12/31/2007 12/31/2007	8/1/2009 8/1/2009	19 19		0.00 0.00	0.00	5.00% 5.00%	9.50% 9.50%	0.00	0.00
Replace 250' main with 2" PE plastic due to leakage in various short sections throughout the service area of Olethe, Kansas office.	376	12/31/2007	8/1/2009	19		10,754.45	17,296.74	5.00%	9.50%	77,197.76	(59,901.02)
Retire 250' of various size main due to leakage in various short sections throughout the service area of Olathe, Kansas office.	376	12/31/2007	8/1/2009	19	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 6 service lines with 1" steel due to leakage throughout the service area of Olathe, Kansas office.	380	12/31/2007	8/1/2009	19	3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 1202 service lines with 1" PE plastic due to leakage throughout the service area of the Olathe, Kansas office.	380	12/31/2007	8/1/2009	19		0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 47 service lines with 1 1/4" PE plastic due to leakage throughout the service area of the Olathe, Kansas office.	380 380	12/31/2007	8/1/2009 8/1/2009	19		0.00	0.00	5.00%	9.50% 9.50%	0.00	0.00
Replace 11 service lines with 2" PE plastic due to leakage throughout the service area of the Olathe, Kansas office. Retire 285 of various size services due to leakage throughout the service area of Olathe, Kansas office.	380	12/31/2007 12/31/2007	8/1/2009	19 19		0.00	0.00	5.00%	9.50%	0.00	0.00
		12/3/12/00/	0 1/2/003	10	3.46 /6	0.00	0.00	0.0074	3.50 14	0.00	0.00
installed 3 leak clamps on distribution piping to repair leaks in various locations in the service area of Olathe, Kansas office.	376	12/31/2007	8/1/2009	19		0.00	0.00	5.00%	9.50%	0.00	0.00
Installed 11 anodes on distribution piping to prevent corrosion at various locations in the service area of Olathe, Kansas office.	376	12/31/2007	8/1/2009	19		4,459.32	7,172.07	5.00%	9.50%	32,009.99	(24,837.92)
Replace 1331 meter loops due to service line/ meter loop leakage at various locations in the service area of the Olathe, Kansas office. Retire 281 meter loops due to service line/ meter loop leakage at various locations in the service area of Olathe, Kansas office.	382 382	12/31/2007 12/31/2007	8/1/2009 8/1/2009	19 19		0.00	0.00 0.00	5.00% 5.00%	9.50% 9.50%	0.00 0.00	0.00
	302	12/3/12007	Q/ 1/2008	19	0.0075	0.00	0.00	3.00%	9.00%	0.00	0.00
Replace 2' main with 1 1/4" PE plastic due to leakage in various short sections throughout the service area of independence, Kansas office.	376	12/31/2007	8/1/2009	19		13.09	21.05	5.00%	9.50%	93.97	(72.92)
Replace 535' main with 2" PE plastic due to leakage in various short sections throughout the service area of independence, Kansas office.	376	12/31/2007	8/1/2009	19		1,995.16	3,208.88	5.00%	9.50%	14,321.70	(11,112.82)
Replace 1' main with 4" PE plastic due to leakage in various short sections throughout the service area of independence, Kansas office. Retire 1917' of various size main due to leakage in various short sections throughout the service area of independence, Kansas office.	376 376	12/31/2007 12/31/2007	8/1/2009 8/1/2009	19 19		325.98 0.00	524.28 0.00	5.00% 5.00%	9.50% 9.50%	2,339.95 0.00	(1,815.67) 0,00
	5/0	12/3/12/00/	6/ 1/2008	10	2.02.10	0.00	0.00	0.007#	3.00 /0	0.00	0,00
Replace 115 service lines with 1" PE plastic due to leakage throughout the service area of the Independence, Kansas office.	380	12/31/2007	8/1/2009	19		0.00	0.00	5.00%	9.50%	0.00	0.00
Retire 271 of various size services due to leakage throughout the service area of independence, Kansas office.	380	12/31/2007	8/1/2009	19	3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
Installed 38 leak clamps on distribution piping to repair leaks in various locations in the service area of independence, Kansas office.	376	12/31/2007	8/1/2009	19	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
instance of rear competition provides prime to repair teach in various locations in the service area of integrations, remease onities, instance 12 and ease of integration of the service area of integration devices areas of integration of the service areas of integration devices areas of integration of the service areas of integration devices areas of integration devices areas of integration devices are areas of integration devices areas of integra	376	12/31/2007	8/1/2009	19		568.60	914.50	5.00%	9.50%	4,081.50	(3, 167.00)
Replace 133 meter loops due to service line/ meter loop leakage at various locations in the service area of the independence, Kansas office		12/31/2007	8/1/2009	19	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00
Retire 277 meter loops due to service line/ meter loop leakage at various locations in the service area of indenpendence, Kansas office.	382	12/31/2007	8/1/2009	19	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 1047' main with 2" PE plastic due to leakage in various short sections throughout the service area of Yates Center, Kansas office.	376	12/31/2007	8/1/2009	19	2.02%	562.23	904.25	5.00%	9.50%	4,035.82	(3,131.57)
Replace 100 min with 4" PE plastic due to leakage in various siont sections injugicul the service area of rates center, hansas once. Replace 240 min with 4" PE plastic due to leakage in various short sections throughout the service area of rates center, hansas office.	376	12/31/2007	8/1/2009	19		138.70	223.08	5.00%	9.50%	995.65	(772.57)
Retire 1126 of various size main due to leakage in various short sections throughout the service area of Yates Center, Kansas office.	376	12/31/2007	8/1/2009	19		0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 76 service lines with 1" PE plastic due to leakage throughout the service area of the Yates Center, Kansas office. Replace 2 cender Uncentral DE relation to be the service area of the Yates Center, Kansas office.	380 380	12/31/2007	8/1/2009 8/1/2009	19		0.00	0.00	5.00%	9.50% 9.50%	0.00	0.00
Replace 2 service lines with 2" PE plastic due to leakage throughout the service area of the Yates Center, Kansas office. Retire 116 of various size services due to leakage throughout the service area of Yates Center, Kansas office.	380	12/31/2007 12/31/2007	8/1/2009	19 19		0.00 0.00	0.00	5.00%	9.50%	0.00	0.00
		120 / 2001	0		•	0.00	0.00				
Installed cathodic protection to 16 sections in various locations in the service area of Yates Center, Kansas office.	376	12/31/2007	8/1/2009	19		0.00	0.00	5.00%	9,50%	0.00	0.00
Installed 34 leak clamps on distribution piping to repair leaks in various locations in the service area of Yates Center, Kansas office, Installed 10 exected and installed to the service and the service area of Yates Center, Kansas office,	376 376	12/31/2007	8/1/2009 8/1/2009	19 19		0.00	0.00	5.00% 5.00%	9.50% 9.50%	0.00 2.252.58	0.00 (1,747.87)
installed 10 anodes on distribution piping to prevent corrosion at various locations in the service area of Yates Center, Kansas office. Replace 330 meter loops due to service line/ meter loop leakage at various locations in the service area of the Yates Center, Kansas office.		12/31/2007 12/31/2007	8/1/2009	19		313.81 0.00	504.71 0.00	5.00%	9.50%	2,252.58	0.00
Retire 344 meter loops due to service line/ meter loop leakage at various locations in the service area of varies Center, Kansas office.	382	12/31/2007	8/1/2009	19		0.00	0.00	5.00%	9.50%	0.00	0.00
									.1.1		in tagent site tage
						\$20,314.60	\$32,672.63			\$145,822.58	(\$113,149.95)
Replace 5' main with 2" steel due to leakage in various short sections throughout the service area of Herington, Kansas office.	376	12/31/2008	8/1/2009	7	2.02%	115.61	68.40	5.00%	9,50%	829.85	(761.45)
Replace 373' main with 4" steel due to leakage in various short sections throughout the service area of Herington, Kansas office.	376	12/31/2008	8/1/2009	.7	2.02%	789.75	467.27	5.00%	9.50%	5,669.01	(5,201.74)
Replace 1355 main with 2" PE plastic due to leakage in various short sections throughout the service area of Herington, Kansas office.	376	12/31/2008	8/1/2009	7		1,491.68	882.58	5.00%	9.50%	10,707.61	(9,825.03)
Replace 5' main with 2" steel due to leakage in various short sections throughout the service area of Herington, Kansas office. Retire 3246' of various size main due to leakage in various short sections throughout the service area of Herington, Kansas office.	376 376	12/31/2008 12/31/2008	8/1/2009 8/1/2009	7		235.27 0.00	139.20 0.00	5.00% 5.00%	9.50% 9.50%	1,688.81	(1,549.61) 0.00
างแรง ระวง รางแอนอ อเธอ กลอก แนน เขาอลุกุญา อาจสาวนอ อางาร อองเอรอ แลยปญางน และอองหวอ ลเอล อา กลาแรงเอก, Kansas Onice.	510	(213)/2008	0/ 1/2008	1	2.027	0.00	0.00	0.0076	9,0078	0.00	0.00
Replace 180 service lines with 1" PE plastic due to leakage throughout the service area of Herington, Kansas office.	380	12/31/2008	8/1/2009	7		0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 7 service lines with 1 1/4" PE plastic due to leakage throughout the service area of Herington, Kansas office.	380	12/31/2008	8/1/2009	7	3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 3 service lines with 2" PE plastic due to leakage throughout the service area of Herington, Kansas office. Retire 197 of various size services due to leakage throughout the service area of Herington, Kansas office.	380 380	12/31/2008 12/31/2008	8/1/2009 8/1/2009	7	3.49% 3.49%	0.00	0.00 0.00	5.00% 5.00%	9.50% 9.50%	0.00	0.00
itonio tor of remove size services due to rearrage incorpriote the service area of meringion, ransas onice.	360	12/31/2008	e/ 1/2009		3.49%	0.00	0.00	3.00%	9.00%	0.00	0.00
Intalled 36 leak clamps on distribution piping to repair leaks in various locations in the service area of Herington, Kansas office.	376	12/31/2008	8/1/2009	7	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
Installed 23 anodes on distribution piping to prevent corrosion at various locations in the service area of Herington, Kanaas office.	376	12/31/2008	8/1/2009	7	2.02%	202.57	119.85	5.00%	9.50%	1,454.11	(1,334.26)
Replace 403 meter loops due to service line/ meter loop leakage at various locations in the service area of Herington, Kansas office.	382	12/31/2008	8/1/2009	7	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00

Retire 390 meter loops due to service line/ meter loop leakage at various locations in the service area of Herington, Kansas office.	382	12/31/2008	8/1/2009	7	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00	
Replace 93' main with 2° steel due to leakage in various short sections throughout the service area of Ulysses, Kansas office. Replace 342' main with 4° steel due to leakage in various short sections throughout the service area of Ulysses, Kansas office. Replace 462' main with 2° FP islatic due to leakage in various short sections throughout the service area of Ulysses, Kansas office. Retire 787' of various size main due to leakage in various short sections throughout the service area of Ulysses, Kansas office.	376 376 376 376	12/31/2008 12/31/2008 12/31/2008 12/31/2008	8/1/2009 8/1/2009 8/1/2009 8/1/2009	7 7 7 7	2.02% 2.02% 2.02% 2.02%	181.97 406.92 1,109.58 0.00	107.67 240.76 656.50 0.00	5.00% 5.00% 5.00% 5.00%	9.50% 9.50% 9.50% 9.50%	1,306.21 2,920.97 7,964.82 0.00	(1,198.54) (2,680.21) (7,308.32) 0.00	
Replace 71 service lines with 1° PE plastic due to leakage throughout the service area of Ulysses, Kansas office. Replace 48 service lines with 1 1/4° PE plastic due to leakage throughout the service area of Ulysses, Kansas office. Replace 7 service lines with 2° PE plastic due to leakage throughout the service area of Ulysses, Kansas office. Replace 1 service lines with 4° PE plastic due to leakage throughout the service area of Ulysses, Kansas office. Replace 2 of various size services due to leakage throughout the service area of Ulysses, Kansas office.	380 380 380 380 380	12/31/2008 12/31/2008 12/31/2008 12/31/2008 12/31/2008	8/1/2009 8/1/2009 8/1/2009 8/1/2009 8/1/2009	7 7 7 7 7	3.49% 3.49% 3.49% 3.49% 3.49%	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	5,00% 5,00% 5,00% 5,00% 5,00%	9.50% 9.50% 9.50% 9.50% 9.50%	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	
Replace 118 meter loops due to service line/ meter loop leakage at various locations in the service area of Ulysses, Kansas office, Retire 104 meter loops due to service line/ meter loop leakage at various locations in the service area of Ulysses, Kansas office,	382 382	12/31/2008 12/31/2008	8/1/2009 8/1/2009	7 7	6.86% 6.86%	0.00 0.00	0.00 0.00	5.00% 5.00%	9.50% 9.50%	0.00 0.00	0.00 0.00	
Replace 284' main with 4" steel due to leakage in various short sections throughout the service area of Olathe, Kansas office. Replace 1949' main with 2" PE plastic due to leakage in various short sections throughout the service area of Olathe, Kansas office. Replace 293' main with 4" PE plastic due to leakage in various short sections throughout the service area of Olathe, Kansas office. Replace 112' main with 5" PE plastic due to leakage in various short sections throughout the service area of Olathe, Kansas office. Replace 112' main with 5" PE plastic due to leakage in various short sections throughout the service area of Olathe, Kansas office. Retire 2295' of various size main due to leakage in various short sections throughout the service area of Olathe, Kansas office.	376 376 376 376 376 376	12/31/2008 12/31/2008 12/31/2008 12/31/2008 12/31/2008	8/1/2009 8/1/2009 8/1/2009 8/1/2009 8/1/2009	7 7 7 7 7	2.02% 2.02% 2.02% 2.02% 2.02%	1,972.64 12,089.10 2,315.55 106.18 0.00	1,167.15 7,152.72 1,370.03 62.82 0.00	5.00% 5.00% 5.00% 5.00% 5.00%	9.50% 9.50% 9.50% 9.50% 9.50%	14,160.02 86,778.19 16,621.53 762.21 0.00	{12,992.87} {79,625.47} {15,251.50} (699.39) 0.00	
Replace 2 service lines with 2" steel due to leakage throughout the service area of Olathe, Kansas office. Replace 1134 service lines with 1" PE plastic due to leakage throughout the service area of Olathe, Kansas office. Replace 30 service lines with 1 1/4" PE plastic due to leakage throughout the service area of Olathe, Kansas office. Replace 19 service lines with 2" PE plastic due to leakage throughout the service area of Olathe, Kansas office. Replace 19 service lines with 2" PE plastic due to leakage throughout the service area of Olathe, Kansas office. Retire 286 of various size services due to leakage throughout the service area of Olathe, Kansas office.	380 380 380 380 380	12/31/2008 12/31/2008 12/31/2008 12/31/2008 12/31/2008 12/31/2008	8/1/2009 8/1/2009 8/1/2009 8/1/2009 8/1/2009	7 7 7 7 7	3.49% 3.49% 3.49% 3.49% 3.49%	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	5.00% 5.00% 5.00% 5.00% 5.00%	9.50% 9.50% 9.50% 9.50% 9.50%	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	
Intalled 8 leak clamps on distribution piping to repair leaks in various locations in the service area of Olathe, Kansas office. Installed 17 anodes on distribution piping to prevent corrosion at various locations in the service area of Olathe, Kansas office. Replace 1188 meter loops due to service line/ meter loop leakage at various locations in the service area of Olathe, Kansas office. Retire 278 meter loops due to service line/ meter loop leakage at various locations in the service area of Olathe, Kansas office.	376 376 382 382	12/31/2008 12/31/2008 12/31/2008 12/31/2008	8/1/2009 8/1/2009 8/1/2009 8/1/2009	7 7 7 7	2.02% 2.02% 6.86% 6.86%	0.00 3,435.65 0.00 0.00	0.00 2,032.76 0.00 0.00	5.00% 5.00% 5.00% 5.00%	9.50% 9.50% 9.50% 9.50%	0.00 24,661.86 0.00 0.00	0.00 {22,629.10} 0.00 0.00	
Replace 3' main with 2" steel due to leakage in various short sections throughout the service area of Independence, Kansas office. Replace 2' main with 1 1/4" PE plastic due to leakage in various short sections throughout the service area of Independence, Kansas office. Replace 574' main with 2" PE plastic due to leakage in various short sections throughout the service area of Independence, Kansas office. Replace 364' main with 2" PE plastic due to leakage in various short sections throughout the service area of Independence, Kansas office. Replace 364' main with 4" PE plastic due to leakage in various short sections throughout the service area of Independence, Kansas office. Retire 1173' of various size main due to leakage in various short sections throughout the service area of Independence, Kansas office.	376 376 376 376 376 376	12/31/2008 12/31/2008 12/31/2008 12/31/2008 12/31/2008 12/31/2008	8/1/2009 8/1/2009 8/1/2009 8/1/2009 8/1/2009 8/1/2009	7 7 7 7 7	2.02% 2.02% 2.02% 2.02% 2.02%	9.17 13.15 747.53 300.44 0.00	5.43 7.78 442.29 177.76 0.00	5.00% 5.00% 5.00% 5.00% 5.00%	9.50% 9.50% 9.50% 9.50% 9.50%	65.80 94.37 5,365.95 2,156.63 0.00	(60.37) (86.59) (4,923.66) (1,978.87) 0.00	
Replace 2 service lines with 1° steel due to leakage throughout the service area of Independence, Kansas office. Replace 172 service lines with 1° EP plastic due to leakage throughout the service area of independence, Kansas office. Replace 212 service lines with 2° EP plastic due to leakage throughout the service area of independence, Kansas office. Retire 240 of various size services due to leakage throughout the service area of independence, Kansas office.	380 380 380 380	12/31/2008 12/31/2008 12/31/2008 12/31/2008	8/1/2009 8/1/2009 8/1/2009 8/1/2009	7 7 7 7	3.49% 3.49% 3.49% 3.49%	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	5.00% 5.00% 5.00% 5.00%	9.50% 9.50% 9.50% 9.50%	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	
Intalled 188 leak clamps on distribution piping to repair leaks in various locations in the service area of independence, Kansas office, Installed 127 anodes on distribution piping to prevent corrosion at various locations in the service area of independence, Kansas office, Replace 273 meter loops due to service info/ meter loop leakage at various locations in the service area of independence, Kansas office, Retire 342 meter loops due to service line/ meter loop leakage at various locations in the service area of independence, Kansas office.	376 376 382 382	12/31/2008 12/31/2008 12/31/2008 12/31/2008 12/31/2008	8/1/2009 8/1/2009 8/1/2009 8/1/2009	7 7 7 7	2.02% 2.02% 6.86% 6.86%	0.00 1,083.47 0.00 0.00	0.00 641.05 0.00 0.00	5.00% 5.00% 5.00% 5.00%	9.50% 9.50% 9.50% 9.50%	0.00 7,777,40 0.00 0.00	0.00 (7,136.35) 0.00 0.00	
Replace 284' main with 2" PE plastic due to leakage in various short sections throughout the service area of Yates Center, Kansas office. Retire 284' of various size main due to leakage in various short sections throughout the service area of Yates Center, Kansas office.	376 376	12/31/2008 12/31/2008	8/1/2009 8/1/2009	7 7	2.02% 2.02%	314.43 0.00	186.04 0.00	5.00% 5.00%	9.50% 9.50%	2,257.08 0.00	(2,071.04) 0.00	
Replace 59 service lines with 1 * PE plastic due to leakage throughout the service area of Yates Center, Kansas office. Replace 6 service lines with 1 1/4* PE plastic due to leakage throughout the service area of Yates Center, Kansas office. Retire 86 of various eize services due to leakage throughout the service area of Yates Center, Kansas office.	380 380 380	12/31/2008 12/31/2008 12/31/2008	8/1/2009 8/1/2009 8/1/2009	7 7 7	3.49% 3.49% 3.49%	0.00 0.00 0.00	0.00 0.00 0.00	5.00% 5.00% 5.00%	9.50% 9.50% 9.50%	0.00 0.00 0.00	0.00 0.00 0.00	
Installed cathodic protection to 13 sections in various locations in the service area of Yates Center, Kansas office. Intailed 40 leak clamps on distribution piping to prepair leaks in various locations in the service area of Yates Center, Kansas office. Installed 31 anodes on distribution piping to prevent corrosion at various locations in the service area of Yates Center, Kansas office. Repiace 243 moter loops due to service ina/ meter loop leakage at various locations in the service area of Yates Center, Kansas office. Retire 258 meter loops due to service line/ meter loop leakage at various locations in the service area of Yates Center, Kansas office.	376 376 376 382 382	12/31/2008 12/31/2008 12/31/2008 12/31/2008 12/31/2008 12/31/2008	8/1/2009 8/1/2009 8/1/2009 8/1/2009 8/1/2009	7 7 7 7 7	2.02% 2.02% 2.02% 6.86% 6.86%	0.00 0.00 273.19 0.00 0.00	0.00 0.00 161.64 0.00 0.00	5.00% 5.00% 5.00% 5.00% 5.00%	9.50% 9.50% 9.50% 9.50% 9.50%	0.00 0.00 1,960.99 0.00 0.00	0.00 0.00 (1,799.35) 0.00 0.00	
						\$27,193.85	\$16,089.70			\$195,203.42	(\$179,113.72)	
Replace 5' main with 2" steel due to leakage in various short sections throughout the service area of Herington, Kansas office. Replace 835' main with 2" PE plastic due to leakage in various short sections throughout the service area of Herington, Kansas office. Retire 720' of various size main due to leakage in various short sections throughout the service area of Herington, Kansas office.	376 376 376	6/30/2009 6/30/2009 6/30/2009	8/1/2009 8/1/2009 8/1/2009	1 1 1	2.02% 2.02% 2.02%	10.32 538.39 0.00	0.92 47.86 0.00	5.00% 5.00% 5.00%	9.50% 9.50% 9.50%	74.07 3,864.71 0.00	(73.15) (3,816.85) 0.00	
Replace 59 service lines with 1° PE plastic due to leakage throughout the service area of Herington, Kansas office. Replace 1 service lines with 11/4° PE plastic due to leakage throughout the service area of Herington, Kansas office. Replace 2 service lines with 2° PE plastic due to leakage throughout the service area of Herington, Kansas office. Retire 114 of various size services due to leakage throughout the service area of Herington, Kansas office.	380 380 380 380	5/30/2009 6/30/2009 5/30/2009	8/1/2009 8/1/2009 8/1/2009 8/1/2009	1 1 1	3.49% 3.49% 3.49% 3.49%	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	5.00% 5.00% 5.00% 5.00%	9.50% 9.50% 9.50% 9.50%	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	
Intalled 11 leak clamps on distribution piping to repair leaks in various locations in the service area of Herington, Kansas office. Installed 3 anode on distribution piping to prevent corrosion at various locations in the service area of Herington, Kansas office. Repizes 179 meter loops due to service line/ meter loop leakage at various locations in the service area of Herington, Kansas office. Retire 201 meter loops due to service line/ meter loop leakage at various locations in the service area of Herington, Kansas office.	376 376 382 382	6/30/2009 6/30/2009 6/30/2009 6/30/2009	8/1/2009 8/1/2009 8/1/2009 8/1/2009	1 1 1 1	2.02% 2.02% 6.86% 6.86%	0.00 25.97 0.00 0.00	0.00 2.31 0.00 0.00	5.00% 5.00% 5.00% 5.00%	9.50% 9.50% 9.50% 9.50%	0.00 186.40 0.00 0.00	0.00 (184.09) 0.00 0.00	
Replace 8' main with 2' steel due to leakage in various short sections throughout the service area of Ulysses, Kansas office. Replace 22' main with 2" PE due to leakage in various short sections throughout the service area of Ulysses, Kansas office. Retire 30' of various size main due to leakage in various short sections throughout the service area of Ulysses, Kansas office.	380 380 376	6/30/2009 6/30/2009 6/30/2009	8/1/2009 8/1/2009 8/1/2009	1 1 1	3.49% 3.49% 2.02%	217.50 267.61 0.00	19.33 23.79 0.00	5.00% 5.00% 5.00%	9.50% 9.50% 9.50%	903.65 1,111.84 0.00	(884.32) (1,088.05) 0.00	
Replace 6 service lines with 1° PE plastic due to leakage throughout the service area of Ulysses, Kansas office. Replace 16 service lines with 1 1/4" PE plastic due to leakage throughout the service area of Ulysses, Kansas office. Replace 1 service lines with 2" PE plastic due to leakage throughout the service area of Ulysses, Kansas office. Retire 23 of various size services due to leakage throughout the service area of Ulysses, Kansas office.	380 380 380 380	6/30/2009 6/30/2009 6/30/2009	8/1/2009 8/1/2009 8/1/2009 8/1/2009	1 1 1	3,49% 3,49% 3,49% 3,49%	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	5.00% 5.00% 5.00% 5.00%	9.50% 9.50% 9.50% 9.50%	0,00 0,00 0,00 0,00	0.00 0.00 0.00 0.00	

Replace 28 meter loops due to service line/ meter loop leakage at various locations in the service area of Ulysses, Kansas office.	382	6/30/2009	8/1/2009	1	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00
Retire 108 meter loops due to service line/ meter loop leakage at various locations in the service area of Ulysses, Kansas office.	382	6/30/2009	8/1/2009	1	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 85' main with 1 1/4" PE plastic due to leakage in various short sections throughout the service area of Olathe, Kansas office,	376	6/30/2009	8/1/2009	1	2.02%	10.62	0.94	5.00%	9.50%	76.23	(75,29)
Replace 790' main with 2" PE plastic due to leakage in various short sections throughout the service area of Olathe, Kansas office,	376	6/30/2009	8/1/2009	1	2.02%	4.954.10	440.36	5.00%	9.50%	35,561.63	(35, 121, 27)
Replace 21' main with 4" PE plastic due to leakage in various short sections throughout the service area of Olathe. Kansas office.	376	6/30/2009	8/1/2009	1	2.02%	2.670.42	237.37	5.00%	9.50%	19,168,88	(18,931.51)
Replace 1' main with 6" PE plastic due to leakage in various short sections throughout the service area of Olathe, Kansas office.	376	6/30/2009	8/1/2009	1	2.02%	142.41	12.66	5.00%	9.50%	1.022.26	(1,009.60)
Retire 1007' of various size main due to leakage in various short sections throughout the service area of Olathe, Kansas office.	376	6/30/2009	8/1/2009	1	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 104 service lines with 1" PE plastic due to leakage throughout the service area of Olathe. Kansas office.	380	6/30/2009	8/1/2009	4	3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace for service lines with :	380	6/30/2009	8/1/2009		3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 1 devices more with 1 + 1 - Desite due to leakage involutions envice area of Diante, Kansas binke. Replace 1 6 service lines with 2 + PE leasts due to leakage throughout the service area of Diante, Kansas office.	380	6/30/2009	8/1/2009		3.49%	0.00	0.00	5,00%	9.50%	0.00	0.00
Reprise to service mess with $2 - r_{2}$ plastic due to leakage throughout the service area of Olatine, Kansas once, Retire 137 of verticus size services due to leakage throughout the service area of Olathe, Kansas office.	380	0/30/2009	8/1/2009	1	3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
	380		8/ 1/2009	1	3.49%	0.00	0.00	5.0070	9.50%	0.00	0.00
Intailed 6 leak clamps on distribution piping to repair leaks in various locations in the service area of Olathe, Kansas office.	376	6/30/2009	8/1/2009	1	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
Installed 9 anodes on distribution piping to prevent corrosion at various locations in the service area of Olathe, Kansas office.	376	6/30/2009	8/1/2009	1	2.02%	1,699.08	151.03	5.00%	9.50%	12,196.40	(12,045.37)
Replace 2 meters at various locations in the service area of Olathe, Kansas office.	381	6/30/2009	8/1/2009	1	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 110 meter loops due to service line/ meter loop leakage at various locations in the service area of Olathe, Kansas office.	382	6/30/2009	8/1/2009	1	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00
Retire 130 meter loops due to service line/ meter loop leakage at various locations in the service area of Olathe, Kansas office.	382	6/30/2009	8/1/2009	1	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 2' main with 2" steel due to leakage in various short sections throughout the service area of independence, Kansas office,	376	6/30/2009	8/1/2009	1	2.02%	69.74	6.20	5.00%	9.50%	500,60	(494,40)
Replace 3' main with 3" steel due to leakage in various short sections throughout the service area of independence. Kansas office,	376	6/30/2009	8/1/2009	1	2.02%	37.34	3.32	5.00%	9.50%	268.05	(264.73)
Replace 966' main with 2" PE plastic due to leakage in various short sections throughout the service area of independence. Kansas office,	376	6/30/2009	8/1/2009	i	2.02%	1,207.32	107.32	5.00%	9.50%	8,666,44	(8,559,12)
Replace 176' main with 4" PE plastic due to leakage in various short sections throughout the service area of independence. Kansas office.	376	6/30/2009	8/1/2009	i	2.02%	216.54	19.25	5,00%	9.50%	1,554.39	(1,535.14)
Retire 1333' of various size main due to leakage in various short sections throughout the service area of independence. Kansas office.	376	6/30/2009	8/1/2009	1	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
		0.00.2000		•							
Replace 109 service lines with 1" PE plastic due to leakage throughout the service area of independence, Kansas office.	380	6/30/2009	8/1/2009	1	3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
Retire 260 of various size services due to leakage throughout the service area of independence, Kansas office.	380		8/1/2009	1	3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
Intailed 103 leak clamps on distribution piping to repair leaks in various locations in the service area of Independence, Kansas office.	376	6/30/2009	8/1/2009	1	2.02%	0.00	0.00	5,00%	9.50%	0.00	0.00
Retired 126 leak clamps that were no longer needed to repair mains from leakage in the service area of independence, Kansas office.	376	6/30/2009	8/1/2009	1	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
Installed 83 anodes on distribution piping to prevent corrosion at various locations in the service area of independence, Kansas office.	376	6/30/2009	8/1/2009	1	2.02%	1,856.20	165.00	5.00%	9.50%	13,324.24	(13,159.24)
Replace 133 meter loops due to service line/ meter loop leakage at various locations in the service area of independence, Kansas office.	362	6/30/2009	8/1/2009	1	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00
Retire 220 meter loops due to service line/ meter loop leakage at various locations in the service area of Independence, Kansas office.	382	6/30/2009	8/1/2009	1	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00
Replace 12 service lines with 1" PE plastic due to leakage throughout the service area of Yates Center, Kanses office.	380	6/30/2009	8/1/2009	1	3.49%	1.394.37	123.94	5,00%	9.50%	5,793,23	(5,669,29)
Retire 81 of various size services due to leakage throughout the service area of Yates Center, Kansas office.	380		8/1/2009	i	3.49%	0.00	0.00	5.00%	9.50%	0.00	0.00
Intalled 38 leak clamps on distribution piping to repair leaks in various locations in the service area of Yates Center, Kansas office.	376	6/30/2009	8/1/2009	1	2.02%	0.00	0.00	5.00%	9.50%	0.00	0.00
Installed 4 anodes on distribution piping to repair lears in various locations in the service area of Yales Center, Kansas office.	376	6/30/2009	8/1/2009	i	2.02%	194.45	17.28	5.00%	9.50%	1.395.81	(1.378.53)
nistance 4 more for dealbound plana or prevent concession at various ocations in the service area of raise center, raises once. Replace 44 meter loops due to service line/meter loop leakage at various locations in the service area of raise center, Kanasa office.	382	6/30/2009	8/1/2009	-	6.86%	0.00	0.00	5,00%	9.50%	0.00	0,00
Retire 110 meter boops due to service inter meter boop leakage at various locations in the service area of rates Center, Kansas office.	382	6/30/2009	8/1/2009	1	6.86%	0.00	0.00	5.00%	9.50%	0.00	0.00
	902	0/00/2009	0, 72000	L	0.00 /	0.00	0.00	0.0076	4.00 10	0.00	
					1	\$15,512.38	\$1,378.88		at the state	\$105,668.83	(\$104,289.95)

\$83,475.23 \$100,442.29	\$446,694,83 (\$396,553.62 \$578,143.90 (\$478,791.61 ,025,838,73 (\$876,255.23	Ó
\$145,495.06 \$150,583.50 \$1	,025,838.73 (\$870,255.23	9

39.58%

(\$346,448.00)



(1,665.31) (13,747.81)

Retirement Data-Staff (d) (e) (f) Schedules

Book

Atmos Energy Corporation Calculation of Depreciation Expense Associated with Amounts Retired

(a)		(b)	(c)	(d)	(e)	(f)
100% of Retirement Dolla	urs Rela	ated to Projects I	ncluded in GSRS	Filing		
month number		(Muitiple Items)	]	•		
cost		include	ferc activity code			
		2		3		Grand Total
depr_group		Addition	Retirement	Addition	Retirement	
060.033.37602:Mains - Plastic			(6,378.53)			(6,378.5
060.081.36700:Mains - Cathod			(38,162.12)			(38,162.1
060.081.37400:Land & Land R	ights	30,722.17				30,722.1
060.081.37500:Structures & Im	provem	7,612.74				7,612.7
060.081.37600:Mains - Cathod	lic Prot	70,194.16	(8,926.22)	773,662.08	(5,095.39)	829,834.6
060.081.37601:Mains - Steel		916,864.17	(330,845.63)	1,680,504.98	(270,605.09)	1,995,918.4
060.081.37602:Mains - Plastic		2,559,044.29	(98,496.90)	2,267,800.11	(17,042.80)	4,711,304.7
060.081.37800:Meas. And Reg	. Sta. E	117,496.27	(235.23)			117,261.0
060.081.37900:Meas & Reg St	ation Eq	89,578.09	(4,540.91)	(350.72)		84,686,4
060.081.38000:Services		307,385.67	(45,944.11)		(821,585.39)	3,096,633,4
060.081.38100:Meters				88,774.03	,	88,774.0
060.081.38200:Meter Installatio	ons	37,706.99		2,924,015.09	(1,946,877.20)	f i
060.081.38300:House Regulate				8,775.29	(1,0 10101	8,775.2
060.081.38500:Industrial Meas				3.032.44		3.032.4
060.086.36700:Mains - Cathod			(9,280.95)			(9,280.9
060.086.37601:Mains - Steel		95,552.86	(5,397.54)	64,957.80	(2,632.51)	
060.086.37602:Mains - Plastic		342,789.57	(17,473.05)	1	(172.73)	
060.086.38000:Services		042,703.07	(17,470.00)	170,548.53	(11,297.23)	
060.086.38200:Meter Installatio	nne		(181.93)	73,310.33	(23,269.74)	
Grand Total	5113	4.574.946.98	(565,863,12)		(3,098,578.08)	12,701,498.9
		1,014,040.00	(000,000.12)	11,100,000,10	(0,000,010,000)	12,701,400.0
\$ Retired By FERC Accou	unt					
•••••••••••••••••••••••••••••••••••••••			Direct Project		Functional Project	Direct Project
		Dep. Rate	Retirement \$		Retirement \$	Depreciation Ex
	367	1.89%	(47,443.07)			(896.6
	376	2.02%	(467,517.87)		(295,548.52)	(9,443.8
	378	4.74%	(407,517.07)		(200,040.02)	(5,443.8
	379	2.53%	(4,540.91)		-	(114.8
	380	2.53%	(45,944.11)		(832,882.62)	•
	382					(1,603.4
	J62 Total	6.86%	*********		(1,970,146.94)	
Step down for % Addition		upstod	(565,863.12)		(3,098,578.08)	(12,082.5
	is rtedi			Fire effected Designed	Fire attack Darks at	
		Functional Project		Functional Project Additions \$ 17	Functional Project % * Retirement \$ 14	Functional Proje
		Additions \$	•			Depreciation Ex
	376	25.7%		3,026,800.86	(75,868.63)	(1,532.55
	380	0.5%		53,853.23	(3,804.04)	(132.76
	382	0.0%			•	-

382 0.0% 45 Total Non-specific in GSRS 24 46 % of total 47 48 Total Depreciation Expense related to Retirements 26.1% 3,080,654.09 (79,672.67)

48 Total Depresentation of Additions multiplied by the total Functional Retirement dollars 50 [1] See detail below 51 [2] Percentage by FERC account of Additions multiplied by the total Functional Retirement dollars

## Non-growth by FERC Account Detail: (per Non-growth func. tab; sorted by Year; FERC)

Cost Center	LOCATION	Year	Functional No.	Amt in Filing	category	Task Type	FERC Acct	)epreciation Rate
3145	Independence	2007	060.14733	648.10	Main	1 1/4" PE main 376		2.02%
3139	Ulysses	2007	060.14729	1,377.72	Main	2" steel main - f 376		2.02%
Yates Center	Yates Center	2007		6,866.52	Main	4" PE main - ft. 376		2.02%
Ulysses	Ulysses	2007		13,061.20	Main	2" PE main - ft. 376		2.02%
	Yates Center	2007		15,535.04	Anodes	Anodes - # 376		2.02%
	Independence	2007		16,137.62	Main	4" PE main - ft. 376		2.02%
	Herington	2007			Clamps	Lk. clamps - # 376		2.02%
3146	Yates Center	2007	060.14735	27,833.25	Main	2" PE main - ft. 376	i	2.02%
	Independence	2007		28,148.29	Anodes	Anodes - # 376		2.02%
3136	Herington	2007	060.14727	44,138.04	Main	2" PE main - ft. 376		2.02%
	Olathe	2007			Clamps	Lk. clamps - # 376		2.02%
	Yates Center	2007			Clamps	Lk. clamps - # 376		2.02%
independence	Independence	2007		98,770.36	Main	2" PE main - ft. 376		2.02%
	Independence	2007			Ciamps	Lk. clamps - # 376		2.02%
	Olathe	2007		220,758.54	Anodes	Anodes - # 376		2.02%
3143	Olathe	2007	060.14731	532,398.37	Main	2" PE main - ft. 376		2.02%
	Ulysses	2007			Services	1" PE service - : 380		3.49%
	Yates Center	2007			Services	1" PE service - 1 380		3.49%
	Independence	2007			Services	1* PE service - 1 380		3.49%
	Olathe	2007			Services	1" steel serv - # 380		3.49%

	Herington	2007			Services	1" st. service - # 380	3.49%
	Ulysses	2007			Meter Loops	Meter loops - # 382	6.86%
	Yates Center	2007			Meter Loops	Meter loops - # 382	6.86%
	Olathe	2007			Meter Loops	Meter loops - # 382	6.86%
	Independence	2007			Meter Loops	Meter loops - # 382	6.86%
	Herington	2007			Meter Loops	Meter loops - # 382	6.86%
		2007	62	\$1,005,673.05	13(16 <b>8</b> 04805)		
3145	Independence	2008	060.15610	453.78	Main	2" steel main - f 376	2.02%
Independence	Independence	2008		650.82	Main	1 1/4" PE main 376	2.02%
	Olathe	2008		5,256.63	Main	6" PE main - ft. 376	2.02%
3136	Herington	2008	060.15601	5,723.08	Main	2" steel main - f 376	2.02%
3139	Ulysses	2008	060.15604	9,008.37	Main	2" steel main - f 376	2.02%
	Herington	2008		10,028.32	Anodes	Anodes - # 376	2.02%
	Herington	2008		11,646.96	Main	4" PE main - ft. 376	2.02%
	Yates Center	2008		13,524.05	Anodes	Anodes - # 376	2.02%
	Independence	2008		14,873.32	Main	4" PE main - ft. 376	2.02%
3146	Yates Center	2008	060.15613	15,566.06	Main	2" PE main - ft. 376	2.02%
Ulysses	Ulysses	2008		20,144.63	main	4" steel mian - f 376	2.02%
	Herington	2008			Clamps	Lk. clamps - # 376	2.02%
	Independence	2008		37,006.56	Main	2" PE main - ft. 376	2.02%
Herington	Herington	2008		39,096.63	Main	4" steel mian - f 376	2.02%
	Independence	2008		53,637.23	Anodes	Anodes - # 376	2.02%
	Ulysses	2008		54,929.78	Main	2" PE main - ft. 376	2.02%
	Olathe	2008			Clamps	Lk. clamps - # 376	2.02%
	Herington	2008		73,845.60	Main	2" PE main - ft. 376	2.02%
3143	Olathe	2008	060.15607	97,655.28	Main	4" steel main - f 376	2.02%
	Yates Center	2008			Clamps	Lk. clamps - # 376	2.02%
	Olathe	2008		114,631.26	Main	4" PE main - ft. 376	2.02%
	Olathe	2008		170,081.77	Anodes	Anodes - # 376	2.02%
	Independence	2008			Clamps	Lk. clamps - # 376	2.02%
Olathe	Olathe	2008		598,470.29	Main	2" PE main - ft. 376	2.02%
	Ulysses	2008		<i>,</i>	Services	1" PE service - ; 380	3.49%
	Independence	2008			Services	1" steel serv - # 380	3.49%
	Yates Center	2008			Services	1" PE service - i 380	3.49%
	Olathe	2008			Services	2" steel serv - # 380	3.49%
	Herington	2008			Services	1" PE service - ; 380	3.49%
	Ulysses	2008			Meter Loops	Meter loops - # 382	6.86%
	Yates Center	2008			Meter Loops	Meter loops - # 382	6.86%
	Olathe	2008			Meter Loops	Meter loops - # 382	6.86%
	Independence	2008			Meter Loops	Meter loops - # 382	6.86%
	Herington	2008			Meter Loops	Meter loops - # 382	6.86%
		2008		\$1,346,230.42			
3136	Herington	2009	060.16386	510.84	Main	2" steel main - f 376	2.02%
3143	Olathe	2009	060.16392	525.72	Main	1 1/4" PE main 376	2.02%
	Herington	2009		1,285.52	Anodes	Anodes - # 376	2.02%
Independence	Independence	2009		1,848.60	Main	3" steel main - f 376	2.02%
3145	Independence	2009	060.16395	3,452.40	Main	2" steel main - f 376	2.02%
	Olathe	2009		7,050.10	Main	6" PE main - ft. 376	2.02%
	Yates Center	2009		9,626.31	Anodes	Anodes - # 376	2.02%
	Independence	2009		10,719.96	Main	4" PE main - ft. 376	2.02%
	Herington	2009			Ciamps	Lk. clamps - # 376	2.02%
Herington	Herington	2009		26,653.19	Main	2" PE main - ft. 376	2.02%
	Olathe	2009			Clamps	Lk. clamps - # 376	2.02%
	Independence	2009		59,768.55	Main	2" PE main - ft. 376	2.02%
	Yates Center	2009			Clamps	Lk. clamps - # 376	2.02%
	Olathe	2009		84,113.09	Anodes	Anodes - # 376	2.02%
	Independence	2009		91,891.30	Anodes	Anodes - # 376	2.02%
	Olathe	2009		132,199.16	Main	4" PE main - ft. 376	2.02%
	Independence	2009		-	Clamps	Lk. clamps - # 376	2.02%
Olathe	Olathe	2009		245,252.65	Main	2" PE main - ft. 376	2.02%
3139	Uiysses	2009	060.16389	6,232.08	Main	2" steel main - f 380	3.49%
Ulysses	Ulysses	2009		7,667.83	Main	2" PE main - ft. 380	3.49%
	Ulysses	2009			Services	1" PE service - ; 380	3.49%
3146	Yates Center	2009	060.16398	39,953.32	Services	1" PE service - i 380	3.49%
	Herington	2009			Services	1" PE service - i 380	3.49%
	independence	2009			Services	1" PE service -: 380	3.49%
	Olathe	2009			Services	1" PE service - : 380	3.49%
	Ulysses	2009			Meter Loops	Meter loops - # 382	6.86%
	Yates Center	2009			Meter Loops	Meter loops - # 382	6.86%
	independence	2009			Meter Loops	Meter loops - # 382	6.86%
	Herington	2009			Meter Loops	Meter loops - # 382	6.86%
	Olathe	2009			Meter Loops	Meter loops - # 382	6.86%
			11.5		•	-	

\$728,750.62

avg

\$3,080,654.09

Total By FERC

## 376-2

## Kansas Corporation Commission Information Request

Request No: 8

Company Name ATMOS ENERGY CORPORATION Docket Number 10-ATMG-133-TAR ATMG

Request Date October 9, 2009

Date Information Needed October 20, 2009

RE: Re-Calculation of GSRS Revenue Requirement **Please Provide the Following:** 

Attached is a spreadsheet that was provided by Atmos to Justin Grady via email on October 6, 2009. This spreadsheet contains the re-calculation of Atmos' GSRS filing in order to incorporate several changes and clarifications discussed by Staff and Atmos informally over the last few weeks. The changes and clarifications that exist within this re-calculation are as follows:

1. There is no Cash Working Capital component included in Atmos' GSRS revenue requirement calculation. This was simply a misstatement included in the Atmos testimony in support of this docket.

2. The GSRS revenue requirement has been updated to include the increase associated with depreciation expense. This was accidentally excluded from Atmos' original filing.

3. The Kansas state tax rate used in the filing was changed to 7.05%, versus the 7.35% accidentally included in the original filing.

4. The impact of recognizing retired plant when calculating pro forma depreciation expense (a reduction) was included in this re-calculation.

5. The limitation on the amount of the non-residential monthly surcharge was removed from the re-calculation. There is no limitation on the amount of the surcharge to be assessed to non-residential customer classes per K.S.A. 66-2204.

To be clear, it is Staff's understanding that Atmos is not revising its filing at this time. This re-calculation was simply to provide clarity and understanding between Atmos and Staff as to some regulatory accounting and ratemaking items that Staff believed should be reflected in Atmos' GSRS revenue requirement.

1. Do the above statements and spreadsheet accurately reflect Atmos' position on the appropriate regulatory accounting and ratemaking elements to include in a GSRS revenue requirement?

Response: Yes, the Company affirms that the above statements to accurately reflect Atmos' position and that the filing schedules were updated to provide clarity to Staff.

Submitted	By	Justin	Grady
Submitted	То	Karen	Wilkes

If for some reason, the above information cannot be provided by the date requested, please provide a written explanation of those reasons.

### Verification of Response

I have read the foregoing Information Request and answer(s) thereto and find answer(s) to be true, accurate, full and complete and contain no material misrepresentations or omissions to the best of my knowledge and belief; and I will disclose to the Commission Staff any matter subsequently discovered which affects the accuracy or completeness of the answer(s) to this Information Request.

Hilks aren Signed:

# JTG-2

Date: 10/9/8009

### LINE DESCRIPTION NUMBER AMOUNT (b) (a) (c) (d) 1 Gas Plant \$9,792,691 2 **Depreciation & Amortization Reserve** (214, 163)3 Net Gas Plant 9,578,528 4 5 Accumulated Deferred Income Taxes (477,277) 9.101.251 6 **Total Rate Base** 7 8 Rate of Return [line 22] 8.08% 9 Required Operating Income [line 6 \* line 8] 735.381 10 Operating Income At Present Rates [line 28] 18,333 11 12 Deficiency [line 9 + line 16] 753.714 13 Tax Factor [line 36] 60.418% \$1,247,509 14 **Total Proposed Rate Adjustment** 15 16 Weighted 17 Rate of Return Percent Cost Cost 18 19 08-ATMG-280-RTS; Joint Stipulation & Agreement; Paragraph 10 20 Debt 51.9% 6.11% 3.17% 21 Equity 48.1% 4.91% 10.20% 22 100.00% 8.08% 23 24 **Operating Income at Present Rates Calculation** 25 25(a) Depreciation & Amortization Expense - related to Additions \$242.664 Depreciation & Amortization Expense - related to Retirements 25(b) (23, 238)Income Taxes on Depreciation Adjustment 26 (219, 426)39.583% (86, 854)27 Income Taxes on Adjusted Interest Expense (288,609)39.583% (114, 239)28 **Operating Income At Present Rates** \$18.333 Change in Rate Base 29 \$9,101,251 Cost of Debt 30 6.11% 31 **Capital Percentage** 51.9% 32 Adjusted Interest Expense 288.609 33 **Tax Factor Calculation** 34 KansasTax Rate 7.05% 35 Federal Tax Rate 35.00% 36 Tax Factor 60.418%

## Atmos Energy Corporation PROPOSED RATE ADJUSTMENT FOR GSRS

## **Kansas Corporation Commission** Information Request

Request No: 7

Company Name	ATMOS ENERGY CORPORATION	ATMG
Docket Number	10-ATMG-133-TAR	
Request Date	September 30, 2009	
Date Information Needed	October 8, 2009	
RE: Average Unit Cost A	nalysis	
Please Provide the Follow	/ing:	and the second
Attached is a spreadshee attached to Karen Wilke	t listing certain functional projects (Anodes, Clams, Meter Loops) take ' testimony.	n from Exhibit KPW-3, as
	these three types of functional projects vary significantly as presented es on the attached spreadsheet are listed for reference.	in Atmos' GSRS
	average unit costs could vary so significantly. For each example, plea led explanation. If necessary, Staff is willing to meet with Atmos to d	

Atmos Response: In each the above referenced functionals with high average per unit cost, the issue occurred due to an incorrect number of units entered into our FMUS (Functional Material Usage System) system in the Olathe office. For the 2007 anode and clamp tasks in Olathe, the costs are not prorated so the incorrect entries should not effect the requested amount. Second, the 2009 Olathe Meter Loops are high due to a lag in the entry of the units for the recent projects that fell into the filing time period. An additional 91 units need to be added to the filed 110, for an average cost of \$2,073.21 and an amount in filing change from \$151,523.53 to \$82,928.25.

Submitted By Justin Grady

Submitted To Karen Wilkes

If for some reason, the above information cannot be provided by the date requested, please provide a written explanation of those reasons.

### Verification of Response

I have read the foregoing Information Request and answer(s) thereto and find answer(s) to be true, accurate, full and complete and contain no material misrepresentations or omissions to the best of my knowledge and belief; and I will disclose to the Commission Staff any matter subsequently discovered which affects the accuracy or completeness of the answer(s) to this Information Request.

Signed: / Karen R. Duetves Date: \_\_\_\_\_ 10/8/09



Staff Data Request No. 7

Docket No. 10-ATMG-133-TAR

LOCATION	Year Tas	sk Number	Units	Total CY Spend	Average per unit	Units used	Amt in Filing	category
Olathe	2007 198	800	3	\$45,004.72	\$15,001.57	3	\$45,004.72	Clamps
Olathe	2009 198	800	6	\$45,924.16	\$7,654.03	6	\$45,924.16	Clamps
Herington	2008 198	800	36	\$28,658.34	\$796.07	36	\$28,658.34	Clamps
Olathe	2009 382	200	110	\$416,714.46	\$3,788.31	40	\$151,532.53	Meter Loops
Ulysses	2007 382	200	100	\$14,171.25	\$141.71	47	\$6,660.49	Meter Loops
Yates Center	2007 382	200	330	\$82,270.77	\$249.31	33	\$8,227.08	Meter Loops
Herington	2008 382	200	403	\$524,562.37	\$1,301.64	53	\$68,987.11	Meter Loops
Olathe	2007 199	900	11	\$220,758.54	\$20,068.96	11	\$220,758.54	Anodes
Herington	2008 199	900	23	\$10,028.32	\$436.01	23	\$10,028.32	Anodes
Independence	2008 199	900	127	\$53,637.23	\$422.34	127	\$53,637.23	Anodes
Yates Center	2008 199	900	31	\$13,524.05	\$436.26	31	\$13,524.05	Anodes