2021-12-20 14:03:14 Filed Date: 12/20/2021

Kansas Corporation Commission /s/ Lynn M. Retz

KCC OIL/GAS REGULATORY OFFICES /s/ Lynn M. Re

| Inspection Date: | 08/04/20 | 21 D i | istrict: | 3 | | Incident | t Numl | ber: | | 7626 |
|--|--|---|---|---|-------------------------------------|---|--|--|--|-----------------------|
| | | ✓ New Sit | | | | se Inspec | ction | | | |
| | | ✓ Respon | | | _ | plaint | | | | |
| 0 | | ☐ Follow- | | N | Z Field | l Report | | 00 | 04 | 0)4/ |
| Operator License | | AF | '1: | | | Q3 | | Q2: | - | SW |
| Operator Name: Address: P.O. B City: Prairie \ State: Kansas | ox 8396 | | ا م | SEC se: Ale: | | TWP 1 | ı | E 21 FSL: FEL: | RGEDIR: | е |
| Phone contact: Reason for Inves | 913-499-8 | | Lou | 56. 7 (16. | Karraci | | | FR | | |
| Request from Wic | | | | | | | | | | |
| ' | | | | | | | | | | |
| Problem: | | | | | | | | | | |
| To confirm location | n, well status, | and numbe | er of wells | s on oper | ator's i | inventory | /. | | | |
| | , | | | · | | , | | | | |
| Daraona contact | e de | | | | | | | | | |
| Persons contact None | <u>.ea.</u> | | | | | | | | | |
| Findings: | | | | | | | | | | |
| Research of the A as the current ope injection wells (Do 8/4/2021. I refere found one extra w wells located is list | erator with sixte ocket # E-3147 nced twenty-th ell that will nee | een (16) ac 1) listed or iree (23) w | tive oil we their cer ell locatio | ells and s tified wel ons with G | six (6) a I inven SPS an | active Er itory. I pe nd took a | nhance erformo photo | d Oil Re ed the le of each | ecovery (E0 ease inspe well locati | OR) ction on. I |
| K Alexander #1 Al 095.116205 GPS 2.5" casing, 1" pur operator's well inv (continued on pag | S session point mp string, and entory. | t (1). Well v has a fully | was found equipped | d to be a d pump ja | produc ick. W | cing oil w | ell con | structed | d with 6" su | rface |
| Actions / Recomi | mendations | <u>Follo</u> | w-up Re | quired [| | Dea | dline [| Date: | | |
| I will forward this r Haas Petroleum, I to plug, produce, o wells are the K Ale Alexander #11 AP Alexander #BSP-A | eport on to Dis LC license # : or obtain an ap exander #5 AP I #15-059-254 | strict # 3 Co 33640 be s proved CF I #15-059- 45-00-00, | ompliance sent a Not 2-111 on f 21107-00 Alexande | e Officer tice of Vio five (5) of 0-00, Alex or #BSP- | olation the in ander L5 AP | riew. It is Letter wi active oil #9 API # PI #15-05 | my re ith a th wells. #15-059 | comme irty (30) Those 9-24656 | day deadli five inactiv 3-00-00, | ine |
| | | | | | | Photo | 's Tak | en: | 5 | |
| ✓ RBDMS ✓ KO | es 🗆 k | KOLAR R | Report Pr | epared E | 3y: <u>l</u> | Keith Ca | <u>rswell</u> | | | |
| ✓ | District Files | ☐ Cour | thouse | Posi | tion: | E.C.R. | <u>S.</u> | | | |

Additional Findings:

(Continued from Actions/Recommendations)

It is my further recommendation that a thirty (30) day NOV letter be sent stating that the Alexander #11 API #15-059-25445-00-00 needs to be added to their certified well inventory.

(continued from page 1 findings)

K Alexander #2 API# 15-059-20950-00-00 SW SE SW 592 FSL 3786 FEL Lat. 38.449672 Long. - 095.115923 GPS session point (2). Well was found to be a producing oil well constructed with 6" surface 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

K Alexander #3 API# 15-059-21100-00-00 NW SE SW 965 FSL 3648 FEL Lat. 38.450696 Long - 095.115447 GPS session point (3). Well was found to be a producing oil well constructed with 6" surface 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

K Alexander #4 API#15-059-21101-00-00 SW NE SW 1397 FSL 3512 FEL Lat. 38.451882 Long - 095.114977 GPS session point (4). Well was found to be a producing oil well constructed with 6" surface 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

K Alexander #5 API#15-059-21107-00-00 SE SW SW 590 FSL 4460 FEL Lat. 38.449666 Long -095.118276 GPS session point (5). Well was found to be an inactive oil well constructed with 6" surface 2.5" casing with no surface control. One inch is laying beside the well. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Alexander 5).

K Alexander #6 API#15-059-21108-00-00 SW SE SW 219 FSL 4378 FEL Lat. 38.448649 Long -095.117987 GPS session point (6). Well was found to be a producing oil well constructed with 6" surface 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Alexander #9 API#15-059-24656-00-00 NW SW SW 959 FSL 4864 FEL Lat. 38.450681 Long -095.119692 GPS session point (9). Well was found to be an inactive oil well constructed with 6" surface 2.5" casing, 1" pump string, and is shut in with a stuffing box. This well is missing the horse head off the pump jack and the bridal is unhooked. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Alexander 9).

Alexander #10 API#15-059-25444-00-00 NE SW SW 995 FSL 4500 FEL Lat. 38.450780 Long -095.118422 GPS session point (10). Well was found to be a producing oil well constructed with 6" surface 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Alexander #11 API# 15-059-25445-00-00 NE SW SW 1004 FSL 4065 FEL Lat. 38.450803 Long - 095.116901 GPS session point (11). Well was found to be an inactive oil well constructed with 6" surface 2.5" casing, 1" pump string, and the pump jack is missing the horse head. Well is not equipped with a stuffing box. Well is within ½ mile area of review of authorized injection wells. This well was not on Haas's certified well inventory. This well needs to be added to Haas's certified well inventory. See attached photo numbered (Alexander 11).

Alexander #BSP-AL15 API#15-059-26196-00-00 SE NE SW 1435 FSL 2825 FEL Lat. 38.451986 Long: -95.112577 GPS session point (BSP-AL15). Well was found to be a producing oil well constructed with 6" surface 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Alexander #BSI-AL14 API#15-059-26233-00-00 SE NE SW 1658 FSL 3062 FEL Lat. 38.452600 Long: -95.112577 GPS session point (BSI-AL14). Well was found to be an active injection well-constructed with 6" surface and 2.5" casing. This well was hooked up for injection at the time of the inspection. Well is listed as active injection "Al" on operator's well inventory.

95.113901 GPS session point (BSP-AL10). Well was found to be a producing oil well constructed with 6" surface 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Alexander #BSI-AL10 API#15-059-26232-00-00 NE NE SW 2245 FSL 3031 FEL Lat. 38.454212 Long: -95.113306 GPS session point (BSI-AL10). Well was found to be an active injection well-constructed with 6" surface and 2.5" casing. This well was hooked up for injection at the time of the inspection. Well is listed as active injection "AI" on operator's well inventory.

Alexander #BSP-AL6 API#15-059-26192-00-00 NE NE SW 2451 FSL 2844 FEL Lat. 38.454778 Long: - 95.112657 GPS session point (BSP-AL6). Well was found to be a producing oil well constructed with 6" surface 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Alexander #BSP-AL11 API#15-059-26194-00-00 NE NE SW 1992 FSL 2844 FEL Lat. 38.453518 Long: -95.112650 GPS session point (BSP-AL11). Well was found to be a producing oil well constructed with 6" surface 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Alexander #BSP-AL5 API#15-059-26191-00-00 NE NE SW 2457 FSL 3212 FEL Lat. 38.454794 Long: -95.113941 GPS session point (BSP-AL5). Well was found to be an inactive oil well constructed with 6" surface and 2.5" casing. This well is missing the pump jack and the pump string but is shut in with valve and swedge. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Alexander BSP-AL5).

Alexander #BSP-AL18 API#15-059-26483-00-00 SW NW SW 1830 FSL 5037 FEL Lat. 38.453072 Long: -95.120306 GPS session point (BSP-AL18). Well was found to be a producing oil well constructed with 6" surface 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Alexander #BSI-AL22 API# 15-059-26759-00-00 SE SW SW 81 FSL 4221 FEL Lat. 38.448270 Long: -95.113306 GPS session point (BSI-AL22). Well was found to be an active injection well-constructed with 6" surface and 2.5" casing. This well was hooked up for injection at the time of the inspection. Well is listed as active injection "AI" on operator's well inventory.

Alexander #BSI-AL25 API# 15-059-26481-00-00 SE SW SW 389 FSL 4136 FEL Lat. 38.449114 Long: -95.117143 GPS session point (BSI-AL25). Well was found to be an active injection well-constructed with 6" surface and 2.5" casing. This well was hooked up for injection at the time of the inspection. Well is listed as active injection "AI" on operator's well inventory.

Alexander #BSI-AL21 API# 15-059-26480-00-00 NW SE SW 919 FSL 3933 FEL Lat. 38.450570 Long: - 95.116442 GPS session point (BSI-AL21). Well was found to be an active injection well-constructed with 6" surface and 2.5" casing. This well was hooked up for injection at the time of the inspection. Well is listed as active injection "AI" on operator's well inventory.


Alexander #BSI-AL17 API# 15-059-26478-00-00 NW SE SW 1222 FSL 3755 FEL Lat. 38.451403 Long: -95.115891 GPS session point (BSI-AL17). Well was found to be an active injection well-constructed with 6" surface and 2.5" casing. This well was hooked up for injection at the time of the inspection. Well is listed as active injection "AI" on operator's well inventory.

Alexander #BSP-AL14 API#15-059-26195-00-00 SE NW SW 1416 FSL 3983 FEL Lat. 38.451936 Long: -95.116620 GPS session point (BSP-AL14). Well was found to be a producing oil well constructed with 6" surface 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Alexander #BSP-AL24 API#15-059-26301-00-00 SE SE SW 220 FSL 3329 FEL Lat. 38.448652 Long: -95.114323 GPS session point (BSP-AL24). Well was found to be an inactive oil well constructed with 6" surface and 2.5" casing. This well is does not have a pump string or a pump jack. This well is also not shut in. Well is listed as Producing "PR" on operator's well inventory.

In conclusion, I found twenty three (23) wells on the lease, twelve (12) active oil wells, six (6) active injection wells, and five (5) inactive oil wells that are out of compliance. A photo of each of the five (5) wells, put of a

compliance and a google map with the session points which are the same as the well numbers are attached to this report. Operator well inventory only shows twenty-two (22) wells on their certified well inventory.





Operator: Haas Petroleum, LLC

Lease: Alexander

County: FR

Subject: Alexander 5

FSL: 590

FEL: 4460

API#: 15-059-21107-00-00

Date:8/4/2021

Staff: Keith Carswell

KLN: 33640

Legal: 29-18-21E

PIC ID#: 5

PIC Orientation:

Latitude: 38.449666

Longitude: -95.118276

Time: 12:52 PM

Additional Information: This is a photo of well #5. This shows the well shut in with a swedge and valve. This photo also shows the 1 inch laying beside the well and a pump jack at the well location



Operator: Haas Petroleum, LLC

Lease: Alexander

County: FR

Subject: Alexander 9

FSL: 959

FEL: 4864

API#: 15-059-24656-00-00

Date:8/4/2021

Staff: Keith Carswell

KLN: 33640

Legal: 29-18-21E

PIC ID#: 9

PIC Orientation:

Latitude: 38.450681

Longitude: -95.119692

Time: 12:52 PM

Additional Information: This is a photo of well #9. This shows the pump jack missing the horse head and the pump string unhooked from the pump jack



Operator: Haas Petroleum, LLC

Lease: Alexander

County: FR

Subject: Alexander 11

FSL: 1004

FEL: 4065

API#: 15-059-25445-00-00

Date:8/4/2021

Staff: Keith Carswell

KLN: 33640

Legal: 29-18-21E

PIC ID#: 11


PIC Orientation:

Latitude: 38.450803

Longitude: -95.116901

Time: 2:40 PM

Additional Information: This is a photo of well #11. This shows the pump jack missing the horse head and the pump string unhooked from the pump jack



Operator: Haas Petroleum, LLC

Lease: Alexander

County: FR

Subject: Alexander BSP-AL5

FSL: 2457

FEL: 3212

API#: 15-059-26191-00-00

Date:8/4/2021

Staff: Keith Carswell

KLN: 33640

Legal: 29-18-21E

PIC ID#: BSP-AL5


PIC Orientation:

Latitude: 38.454794

Longitude: -95.113941

Time: 12:12 PM

Additional Information: This is a photo of well #BSP-AL5. This shows the well shut in with a swedge and valve. There is no pump string or pump jack at location and the well isn't hooked into the riser.



Operator: Haas Petroleum, LLC

Lease: Alexander

County: FR

Subject: Alexander BSP-AL24

FSL: 220

FEL: 3329

API#: 15-059-26301-00-00

Date:8/4/2021

Staff: Keith Carswell

KLN: 33640

Legal: 29-18-21E

PIC ID#: BSP-AL24

PIC Orientation:

Latitude: 38.448652

Longitude: -95.114323°

Time: 2:17 PM

Additional Information: This is a photo of well #BSP-AL24. This shows the well not shut in. There is no pump string or pump jack at location and the well isn't hooked into the riser.

| Inspection Date: | 10/04/2021 | District: | 3 | Incident N | umber: | | 7737 |
|--|---|--|---|--|---|--|-----------------------------|
| | ✓ Nev | / Situation | ✓ Lea | ase Inspectio | n | | |
| | ✓ Res | ponse to Req | uest 🗌 Co | mplaint | | | |
| | ☐ Foll | ow-up | ✓ Fie | ld Report | | | |
| Operator License No | o : 33640 | API: | | Q3: | Q2: | Q1: | SW |
| Operator Name: Ha Address: P.O. Box 8 City: Prairie Villa State: Kansas Zip | 8396 | C Leas | SEC 8 e: Baldwin | TWP 16 | RGE 20 FSL: FEL: Vell No.: | RGEDIR: | E |
| Phone contact: | 913-499-8373 | | | Coun | ty: FR | | |
| Reason for Investiga | | | | | | | |
| Request from Wichita | l | | | | | | |
| Problem: To confirm location, w | vell status, and nu | mber of wells | on operator's | s inventory. | | | |
| Persons contacted: None | 1 | | | | | | |
| Findings: | | | | | | | |
| Research of the Baldy operator with five (5) i well locations with GP listed below: | inactive oil wells. I | performed the | e lease inspe | ection 10/04/2 | 2021. I refe | renced eig | ht (8) |
| Baldwin #1 API# 15-(GPS session point (B. plugged and abandon is possibly the old lead determine if it's a well depth. Well is listed at certified well inventory | AL 01(1)). Well water At the time of d line for the plugger or an old lead lines Plugged and Ab | as found to be inspection the ged well. Oper e. If it is just a andoned "PA' | e a possible we only thing virator needs to lead line it no on RBDMS. | vell location. isible at surface excavate the eds to be curble. This well is | This well wace was a 1 nis well loca ut off and bunot listed on | as listed as .5" pipe. W tion and ıried below | a /hich / plow |
| Actions / Recommer | ndations F | ollow-up Req | uired | <u>Deadli</u> | ne Date: | | |
| I will forward this repo Haas Petroleum, LLC to plug, produce, or of wells are the Baldwin API #15-059-01377-0 00. (continued on pag | license # 33640 l btain an approved #2 API #15-059-0 0-00, Baldwin #1 | oe sent a Noti CP-111 on fi 1374-00-00, E | ce of Violation ve (5) of the i Baldwin #3 Al | n Letter with nactive wells PI #15-059-0 | a thirty (30) 5. Those five 1375-00-00 | day deadli e (5) inactiv), Baldwin # | ine ve ‡ 4 |
| | | | | Photo's | Taken: | 8 | |
| ☑ RBDMS ☑ KGS | ☐ KOLAR | Report Pre | pared By: | Keith Carsy | <u> </u> | | |
| ✓ Di | istrict Files 🔲 C | Courthouse | Position: | E.C.R.S. | | | |

Additional Findings:

(continued from page 1 Actions/Recommendations)

I further recommend that a Notice of violation letter be sent with a thirty (30) day deadline to add two (2) wells to operator's inventory and to produce, plug, or obtain an approved CP-111 on these two wells: Baldwin #OW-1 API# 15-059-01639-00-00 and Baldwin #OW-2 API# 15-059-01640-00-00. I further recommend that a notice of violation letter be sent on the two wells that are leaking with a 30 day deadline to stop the spills and to start the remediation process on wells: Baldwin #4 API# 15-059-01377-00-00 and Baldwin #OW-2 API# 15-059-01640.

(Continued from page 1 Findings)

Baldwin #OW-1 API# 15-059-01639-00-00 NE SE SW 1054 FSL 3213 FEL Lat. 38.669523 Long. - 95.222763 GPS session point (BAL 02(OW-1)). Well was found to be an inactive "IN" well. Constructed with 8" surface casing, 4.5" casing, 1" pump string, and has a fully equipped pump jack. This well is equipped with a stuffing box well is listed as Inactive "IN" on RBDMS well inventory and needs to be added to Haas's certified well inventory. See attached photo numbered (BAL 02).

Baldwin #OW-2 API# 15-059-01640-00-00 NW SE SW 1276 FSL 3630 FEL Lat. 38.670149 Long. - 95.224221 GPS session point (BAL 03(OW-2)). Well was found to be an inactive oil well constructed with 8" surface casing. This well has no production casing and no surface control. This well was leaking and bubbling at the time of the inspection. Well is listed as inactive "IN" on RBDMS well inventory and will need to be added to Haas's certified well inventory. See attached photo numbered (BAL 03).

Baldwin #2 API# 15-059-01374-00-00 NE SW SW 981 FSL 4029 FEL Lat. 38.669355 Long. -95.225623 GPS session point (BAL 04(2)). Well was found to be an inactive "IN" oil well. Constructed with 8" surface casing, 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. This well is equipped with a stuffing box well is listed as Inactive "IN" on operator's well inventory and the well doesn't have a current approved CP-111 on this well. See attached photo numbered (BAL 04).


Baldwin #3 API# 15-059-01375-00-00 SW NE SW 1513 FSL 3655 FEL Lat. 38.670801 Long. -95.224307 GPS session point (BAL 05(3)). Well was found to be an inactive oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and a fully equipped pump jack. This well was equipped with a stuffing box. Well is listed as inactive "IN" on operator's well inventory, this well also doesn't have a current approved CP-111. See attached photo numbered (BAL 05).

Baldwin #4 API# 15-059-01377-00-00 SW NE SW 1918 FSL 3653 FEL Lat. 38.671911 Long. -95.224297 GPS session point (BAL 06(4)). Well was found to be an inactive oil well constructed with 4.5" casing with no surface control. This well was leaking and bubbling at the time of the inspection. Well is listed as inactive "IN" on operator's well inventory and the well doesn't have a current approved CP-111 on this well. See attached photo numbered (BAL 06).

Baldwin #4 API# 15-059-01376-00-00 SE NE SW 1556 FSL 3098 FEL Lat. 38.670897 Long. -95.222356 GPS session point (BAL 08(4)). Well was found to be an inactive oil well constructed with 8" surface, 4.5" casing, and 1" pump string. This well did not have any surface control. Well is listed as inactive "IN" on operator's well inventory and the well doesn't have a current approved CP-111 on this well. See attached photo numbered (BAL 08).

Baldwin #1 API# 15-059-01373-00-00 SW SE SW 226 FSL 3958 FEL Lat. 38.667279 Long. -95.225384 GPS session point (BAL 09(1)). Well was found to be an inactive "IN" well. Constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. This well doesn't have any surface control. The well is listed as Inactive "IN" on operator's well inventory. See attached photo numbered (BAL 09).

In conclusion, I found seven (7) inactive wells on the lease and one (1) possible well location. A photo of each of the eight (8) wells out of compliance and a google map with the session points. Operator well inventory shows five (5) inactive wells. According to KGS records this lease hasn't sold a load of oil since July of 2016.









Yearly and monthly production



BALDWIN Lease

Lease: BALDWIN

Operator: Haas Petroleum, LLC **Location:** T16S, R20E, Sec. 8

Cumulative Production: 2707.53 barrels (from 1991 to 2016)

KS Dept. of Revenue Lease Code: 130134 KS Dept. of Revenue Lease Name: BALDWIN

View T1 PDF (from KCC)

Field: Ottawa County: Franklin Producing Zone:

Well Data (may be an incomplete list):

| T16S R20E, Sec. 8, SW SW SE SW | T16S R20E, Sec. 8, SE NE SW SW |
|---------------------------------------|---------------------------------------|
| Lease: BALDWIN 1 | Lease: BALDWIN 2 |
| Operator: | Operator: |
| Current Operator: Haas Petroleum, LLC | Current Operator: Haas Petroleum, LLC |
| API Number: 15-059-01373 | API Number: 15-059-01374 |
| T16S R20E, Sec. 8, SW SW NE SW | T16S R20E, Sec. 8, SW SE NE SW |
| Lease: BALDWIN 3 | Lease: BALDWIN 4 |
| Operator: | Operator: |
| Current Operator: Haas Petroleum, LLC | Current Operator: Haas Petroleum, LLC |
| API Number: 15-059-01375 | API Number: 15-059-01376 |
| T16S R20E, Sec. 8, NE SW NE SW | |
| Lease: BALDWIN 4 | |
| Operator: | |
| Current Operator: Haas Petroleum, LLC | |
| API Number: 15-059-01377 | |
| | |

Data are received monthly from the Kansas Department of Revenue.

Annual Oil Production, (bbls)

Please Note: New Prototype charting system.

| system. | | | | | | | | |
|---|-------|---|--|--|--|--|--|--|
| Year | Wells | | | | | | | |
| Production Charts | | | | | | | | |
| Protoype Chart System | | | | | | | | |
| Note: The Flash-based chart has been discontinued, as Flash is no longer supported by web browsers. | | | | | | | | |
| 1991 | 52 | 4 | | | | | | |
| 1992 | 115 | 4 | | | | | | |
| | | | | | | | | |

Recent Monthly Oil Production, (bbls)

(Complete production available in file saved using blue button at top of page.)

| Year | Month | Production | Wells | Reporter or Purchaser/ Reporting Customer |
|------|-------|------------|-------|---|
| 2014 | 3 | 79.63 | | Coffeyville Resources Refining & Marketing (100%) |
| 2014 | 12 | 70.41 | | Coffeyville Resources Refining & Marketing (100%) |
| 2015 | 11 | 83.82 | | Coffeyville Resources Refining & Marketing (100%) |
| 2016 | 7 | 57.86 | | Coffeyville Resources Refining & Marketing (100%) |

| 1993 | 160 | 4 |
|------|-----|---|
| 1994 | 245 | 4 |
| 1995 | 83 | 4 |
| 1996 | 171 | 4 |
| 1997 | 153 | 4 |
| 1998 | 151 | 4 |
| 1999 | - | _ |
| 2000 | 79 | 4 |
| 2001 | 164 | 4 |
| 2002 | 83 | 4 |
| 2003 | 140 | 4 |
| 2004 | 77 | 4 |
| 2005 | 142 | 4 |
| 2006 | - | - |
| 2007 | 80 | 4 |
| 2008 | 86 | 4 |
| 2009 | 157 | 4 |
| 2010 | 74 | 4 |
| 2011 | 58 | 4 |
| 2012 | 146 | 4 |
| 2013 | - | - |
| 2014 | 150 | 4 |
| 2015 | 84 | 4 |
| 2016 | 58 | 5 |

Reported through 7-2016.

Note: bbls is barrels; mcf is 1000 cubic feet.

Pre-1987 cumulative data and monthly volume data is provided under license agreement to the KGS by IHS Energy. As such, it may be reviewed and used for public service and research purposes. It may not be downloaded or used for purposes of re-packaging, reselling or dissemination to third parties.

Kansas Geological Survey Comments to webadmin@kgs.ku.edu URL=http://www.kgs.ku.edu/Magellan/Field/lease.html Programs Updated May 27, 2014 Data from Kansas Dept. of Revenue files monthly.



Operator: Haas Petroleum, LLC

Lease: Baldwin

County: FR

Subject: Baldwin #1

FSL: 659

FEL: 3254

API#: 15-059-70369-00-00

Date: 10/04/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-16-20E

PIC ID#: BAL 01

PIC Orientation:

Latitude: 38.668440

Longitude: -95.222911

Time: 9:57 AM

Additional Information: This is a photo of a possible well location at Session point BAL 01. This an inch and half pipe sticking up with a valve shutting the pipe in. This location needs to be excavated to determine if this is a well or just a production line.



Operator: Haas Petroleum, LLC

Lease: Baldwin

County: FR

Subject: Baldwin #OW-1

FSL: 1054

FEL: 3213

API#: 15-059-01639-00-00

Date: 10/04/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-16-20E

PIC ID#: BAL 02

PIC Orientation:

Latitude: 38.669523

Longitude: -95.222763

Time: 10:02 AM

Additional Information: This is a photo of well location BAL 02. This shows the well-constructed with 8 inch surface, 4.5" casing, 2" tubing, and one inch pump string with a stuffing box.



Operator: Haas Petroleum, LLC

Lease: Baldwin

County: FR

Subject: Baldwin #OW-2

FSL: 1276

FEL: 3630

API#: 15-059-01640-00-00

Date: 10/04/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-16-20E

PIC ID#: BAL 03


PIC Orientation:

Latitude: 38.670149

Longitude: -95.224221

Time: 10:10 AM

Additional Information: This is a photo of well location BAL 03. This shows the well with 8" surface only. This picture shows the well leaking and a large kill area around the well. This well doesn't have a production string and no surface control.



Operator: Haas Petroleum, LLC

Lease: Baldwin

County: FR

Subject: Baldwin #2

FSL: 981

FEL: 4029

API#: 15-059-01374-00-00

Date: 10/04/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-16-20E

PIC ID#: BAL 04

PIC Orientation:

Latitude: 38.669355

Longitude: -95.225623

Time: 10:14 AM

Additional Information: This is a photo of well location BAL 04. This shows the well with 8" surface, 4.5" casing, 2" tubing, and 1 inch pump string with a stuffing box.



Operator: Haas Petroleum, LLC

Lease: Baldwin

County: FR

Subject: Baldwin #3

FSL: 1513

FEL: 3655

API#: 15-059-01375-00-00

Date: 10/04/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-16-20E

PIC ID#: BAL 05


PIC Orientation:

Latitude: 38.670801

Longitude: --95.224307

Time: 10:33 AM

Additional Information: This is a photo of well location BAL 05. This shows the well with 4.5" casing, 2" tubing, and 1 inch pump string with a stuffing box.



Operator: Haas Petroleum, LLC

Lease: Baldwin

County: FR

Subject: Baldwin #4

FSL: 1918

FEL: 3653

API#: 15-059-01377-00-00

Date: 10/04/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-16-20E

PIC ID#: BAL 06


PIC Orientation:

Latitude: 38.671911

Longitude: -95.224297

Time: 10:10 AM

Additional Information: This is a photo of well location BAL 06. This shows the well with 4.5" casing only. This picture shows the well leaking and a large kill area around the well. This well doesn't have a production string and no surface control.



Operator: Haas Petroleum, LLC

Lease: Baldwin

County: FR

Subject: Baldwin #4

FSL: 1556

FEL: 3098

API#: 15-059-01376-00-00

Date: 10/04/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-16-20E

PIC ID#: BAL 08

PIC Orientation:

Latitude: 38.670897

Longitude: -95.222356

Time: 11:08 AM

Additional Information: This is a photo of well location BAL 08. This shows the well with 4.5" casing, and 1" tubing. This well wasn't equipped with a stuffing box or any other surface control



Operator: Haas Petroleum, LLC

Lease: Baldwin

County: FR

Subject: Baldwin #1

FSL: 226

FEL: 3958

API#: 15-059-01373-00-00

Date: 10/04/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-16-20E

PIC ID#: BAL 09

PIC Orientation:

Latitude: 38.667279

Longitude: -95.225384

Time: 11:34 AM

Additional Information: This is a photo of well location BAL 09. This shows the well with 4.5" casing, and 1" tubing. This well wasn't equipped with a stuffing box or any other surface control

| Inspection Date: | 08/16/2021 | District: | 3 | | Incident | Number: | 7715 |
|--|--|--|---|---|--|---|---|
| | ✓ | New Situation | | ✓ Lea | se Inspect | ion | |
| | ✓ | Response to R | equest | ☐ Con | nplaint | | |
| | | Follow-up | | ✓ Field | d Report | | |
| Operator License N | o : 33640 | API: | | | Q3: | Q2: | Q1: |
| Operator Name: Ha Address: P.O. Box City: Prairie Villa | 8396 age | | SE | C 17 | TWP 18 | RGE 21 FSL: FEL: | RGEDIR: e |
| State: Kansas Zip | | | ase: (| Carter "A | | Well No.: | |
| Phone contact: | 913-499-837 | 3 | | | Cou | nty: FR | |
| Reason for Investig | | | | | | | |
| Request from Wichita | 3 | | | | | | |
| | | | | | | | |
| Problem: | | | | | | | |
| To confirm location, v | vell status, and | I number of we | lls on op | erator's | inventory. | | |
| | | | | | | | |
| Persons contacted | <u>:</u> | | | | | | |
| Haas Petroleum pun | npers Terry an | d Chad | | | | | |
| | | | | | | | |
| Findings: | | | | | | | |
| Research of the Cartwith eighty-two (82) a wells (Docket # E-05-8/25/2021. I reference each well location. D | active oil wells a 419) on their co ced one hundre | and fifty-eight (sertified well inve ed and forty one | 58) activentory. e (141) v | e Enhar I perform vell loca | nced Oil Re ned the lea tions with (| ecovery (EO se inspectio | R) injection n 8/23- |
| Carter A #24 API# 1: 095.112617 GPS se surface casing, 4.5" o Producing "PR" on op | ession point (24 casing, 1" pum | 4). Well was foւ p string, and ha | und to b | e a prod | ucing oil w | ell construct | ed with 8.625" |
| (continued in addition | nal findings on | page 2) | | | | | |
| | | | | | | | |
| Actions / Recomme | <u>ndations</u> | Follow-up R | equired | | <u>Dead</u> | line Date: | |
| I will forward this report Haas Petroleum, LLC to plug, produce, or or inactive oil wells are to 059-25970-00-00, Carter 207-00, (continued in a | C license # 336 obtain an appro the Carter A #E arter A #BSP-C A #BSP-CA15 | 40 be sent a Noved CP-111 on SSP-CA33 API A20 API #15-0 API #15-059-2 | otice of i fifteen #15-059 59-2576 | Violatior (15) of tl 9-25821- 67-00-00 | Letter with he inactive 00-00, Car , Carter A | n a thirty (30 oil wells. Tl ter A #BSP- #BSP-CA21 |) day deadline nose fifteen CA53 API #15- API #15-059- |
| , (| | 5 ·-·g- =/ | | | Photo's | s Taken: | 18 |
| ✓ RBDMS ✓ KGS | □ KOL | AR Report P | repare | d By: | Keith Cars | - swell | |
| ☑ D | istrict Files | Courthouse | Po | sition: | E.C.R.S | | |

Additional Findings:

(Continued from page 1 actions and recommendations)

Carter A #BSI-CA59 API #15-059-26745-00-00, Carter A #11 API #15-059-20299-00-00, Carter A #12 API #15-059-20305-00-00, Carter A #1 API #15-059-19263-00-00, Carter A #BSI-CA54 API #15-059-25971-00-00, Carter A #BSI-CA46 API #15-059-25860-00-00, Carter A #BSI-CA50 API#15-059-25967-00-00, Carter A #BSI-CA52 API #15-059-25969-00-00, and Carter A #BSI-CA40 API #15-059-25854-00-00. It is my further recommendation that a thirty (30) day NOV letter be sent stating that the Carter A #OW-3 API #15-059-01607-00-00 needs to be properly completed or plugged. The well status needs to be changed to inactive for all of the previous 16 wells listed above. It is my further recommendation that the well #OW-4 API# 15-059-01638-00-00 will need to have a casing integrity test preformed before the well can have an approved CP-111 as it's believed to be an old well completed Alternate 1.

(Continued from page 1 findings)

Carter A #23 API# 15-059-24804-00-00 SE SE SW 352 FSL 3048 FEL Lat. 38.478196 Long. -095.113501 GPS session point (23). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA50 API# 15-059-25905-00-00 SE SE SW 661 FSL 3062 FEL Lat. 38.479045 Long: -95.113554 GPS session point (BSP-CA50). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #22 API# 15-059-24798-00-01 NW SE SW 670 FSL 3450 FEL Lat. 38.479079 Long.-95.114909 GPS session point (22). Well was found to be a producing oil well constructed with 7" surface casing, 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSI-CA39 API# 15-059-25853-00-00 NE SE SW 907 FSL 3175 FEL Lat: 38.479722 Long: -95.113953 GPS session point (BSI-CA39). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/11/2017. Staff did witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA42 API# 15-059-25856-00-00 NW SE SW 920 FSL 3538 FEL Lat: 38.479769 Long: -95.115222 GPS session point (BSI-CA42). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 03/10/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA34 API# 15-059-25848-00-00 NE SE SW 853 FSL 2761 FEL Lat: 38.479565 Long: -95.112506 GPS session point (BSI-CA34). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/11/2017. Staff did witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA43 API# 15-059-25857-00-00 SW SE SW 400 FSL 3579 FEL Lat: 38.478339 Long: -95.115359 GPS session point (BSI-CA43). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 03/10/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA44 API# 15-059-25858-00-00 NW SE SW 895 FSL 3902 FEL Lat: 38.479708 Long: -95.116494 GPS session point (BSI-CA44). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 05/19/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA38 API# 15-059-25852-00-00 NE SE SW 1308 FSL 3107 FEL Lat: 38.480823 Long: 95.113723 GPS session point (BSI-CA38). Well is an active authorized EOR well-constructe E whithir Karaace

casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/11/2017. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA33 API# 15-059-25847-00-00 NE SE SW 1308 FSL 2665 FEL Lat: 38.480812 Long: -95.112179 GPS session point (BSI-CA33). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/11/2017. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA32 API# 15-059-25846-00-00 SE NE SW 1684 FSL 2678 FEL Lat: 38.481846 Long: -95.112230 GPS session point (BSI-CA32). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/11/2017. Staff did witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA37 API# 15-059-25851-00-00 SE NE SW 1694 FSL 3134 FEL Lat: 38.481884 Long: -95.113820 GPS session point (BSI-CA37). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 03/10/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSP-CA46 API# 15-059-25841-00-00 SW SE SW 186 FSL 3347 FEL Lat. 38.477747 Long: -95.114544 GPS session point (BSP-CA46). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA41 API# 15-059-25829-00-00 SW SE SW 619 FSL 3807 FEL Lat. 38.478946 Long: -95.116158 GPS session point (BSP-CA41). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA47 API# 15-059-25842-00-00 SW SE SW 187 FSL 3790 FEL Lat. 38.477760 Long: -95.116091 GPS session point (BSP-CA47). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA36 API# 15-059-25824-00-00 NE SE SW 1105 FSL 2918 FEL Lat. 38.480260 Long: -95.113058 GPS session point (BSP-CA36). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA35 API# 15-059-25823-00-00 SE NE SW 1494 FSL 2917 FEL Lat. 38.481330 Long: -95.113061 GPS session point (BSP-CA35). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA34 API# 15-059-25822-00-00 SE NE SW 1866 FSL 2921 FEL Lat. 38.482351 Long: -95.113082 GPS session point (BSP-CA34). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA33 API# 15-059-25821-00-00 NE NE SW 2408 FSL 2893 FEL Lat. 38.483839Long: -95.112991 GPS session point (BSP-CA33). Well was found to be an inactive oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a pump jack that is broke. This well has no surface control. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Carter A BSP-CA33).

Carter A #OW-3 API# 15-059-01607-00-00 NE SW SW 1194 FSL 4094 FEL Lat: 38.480532 Long: -95.117167 GPS session point (OW-3). Well was found to be an inactive oil well constructed with 7" surface casing only. Well has no production casing visible at surface. This well has water visible inside the surface casing. Fluid level is at surface level. This well was called in to be plugged by Energiex (pervious plugged) but

no CP2/3 or CP4 has been filed for this well. This well needs to be drilled down and production casing set or well needs to be plugged. Operator will not be able to obtain an approved CP-111 because there is no production casing and appears well was never completed. Well is listed as Producing "PR" on operator's well inventory. This well is not capable of being produced the way the well is constructed at this time. See attached photo numbered (Carter A OW-3).

Carter A #BSP-CA37 API# 15-059-25825-00-00 SW NE SW 1910 FSL 3358 FEL Lat. 38.482481 Long: -95.114609 GPS session point (BSP-CA37). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #9 API# 15-059-20188-00-00 SW NE SW 1536 FSL 3749 FEL Lat. 38.481462 Long -95.115966 GPS session point (9). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA38 API# 15-059-25826-00-00 SW NE SW 1503 FSL 3350 FEL Lat. 38.481365 Long: -95.114573 GPS session point (BSP-CA38). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA39 API# 15-059-25827-00-00 NW SE SW 1095 FSL 3319 FEL Lat. 38.480241 Long: -95.114459 GPS session point (BSP-CA39). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA40 API# 15-059-25828-00-00 NW SE SW 1069 FSL 3676 FEL Lat. 38.480179 Long: -95.115707 GPS session point (BSP-CA40). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #8 API# 15-059-19269-00-00 SW NE SW 1928 FSL 3732 FEL Lat. 38.481462 Long -95.115966 GPS session point (9). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSI-CA36 API# 15-059-25850-00-00 NW NE SW 2209 FSL 3351 FEL Lat: 38.483301 Long: -95.114588 GPS session point (BSI-CA36). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/13/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA40 API# 15-059-25854-00-00 SW NE SW 1715 FSL 3495 FEL Lat: 38.481950 Long: -95.115085 GPS session point (BSI-CA40). Well is an inactive authorized EOR well-constructed with 7" surface casing and 2.875" casing. The injection line is broke that runs to the well head. The well is shut in with a valve and swedge. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 03/10/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory. See attached photo numbered (Carter A BSI-CA40).

Carter A #BSI-CA41 API# 15-059-25855-00-00 SW NE SW 1329 FSL 3552 FEL Lat: 38.480891 Long: -95.115278 GPS session point (BSI-CA41). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 03/10/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA47 API# 15-059-25972-00-00 NE SW SW 1279 FSL 3972 FEL Lat: 38.480891 Long: -95.115278 GPS session point (BSI-CA41). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 05/09/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA54 API# 15-059-25971-00-00 SE SW SW 445 FSL 4402 FEL Lat: 38.478482 Long: -95.118231 GPS session point (BSI-CA54). Well is an inactive authorized EOR well-constructed with 7" surface casing and 2.875" casing. The well is shut in with a valve and swedge. The injection line is unbooked EXNIBITION.

that runs to the well head. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 05/11/2017. Staff did witness this test. Well is listed as Active "Al" on operator's well inventory. See attached photo numbered (Carter A BSI-CA54).

Carter A #BSI-CA46 API# 15-059-25860-00-00 NE SW SW 859 FSL 4377 FEL Lat: 38.479621 Long: -95.118152 GPS session point (BSI-CA46). Well is an inactive authorized EOR well-constructed with 7" surface casing and 2.875" casing. The well is shut in with a valve and swedge. The injection line is unhooked that runs to the well head. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 05/09/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory. See attached photo numbered (Carter A BSI-CA46).

Carter A #BSI-CA50 API# 15-059-25967-00-00 NW SW SW 851 FSL 4793 FEL Lat: 38.479606 Long: -95.119603 GPS session point (BSI-CA50). Well is an inactive authorized EOR well-constructed with 7" surface casing and 2.875" casing. The well is shut in with a valve and swedge. The injection line is unhooked that runs to the well head. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/20/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory. See attached photo numbered (Carter A BSI-CA50).

Carter A #BSI-CA45 API# 15-059-25859-00-00 SE SW SW 394 FSL 3988 FEL Lat: 38.478332 Long: - 95.116787 GPS session point (BSI-CA45). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/20/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA48 API# 15-059-25965-00-00 NE SW SW 1267 FSL 4402 FEL Lat: 38.480741 Long: -95.118246 GPS session point (BSI-CA48). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 05/09/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA57 API# 15-059-26308-00-00 NW SW SW 1306 FSL 4751 FEL Lat: 38.480856 Long: -95.119464 GPS session point (BSI-CA57). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/21/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA49 API# 15-059-25966-00-00 NW SW SW 1289 FSL 4751 FEL Lat: 38.480809 Long: -95.119465 GPS session point (BSI-CA49). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/20/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA60 API# 15-059-26754-00-00 NW SW SW 874 FSL 4792 FEL Lat: 38.479617 Long: -95.119627 GPS session point (BSI-CA60). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 07/29/2019. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSP-CA48 API# 15-059-25843-00-00 SE SW SW 220 FSL 4158 FEL Lat. 38.477861 Long: -95.117376 GPS session point (BSP-CA48). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA43 API# 15-059-25831-00-00 NE SW SW 664 FSL 4134 FEL Lat. 38.479078 Long: -95.117301 GPS session point (BSP-CA43). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA42 API# 15-059-25830-00-00 NE SW SW 1005 FSL 4149 FEL Lat. 38.480015 Long: -95.117358 GPS session point (BSP-CA42). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Exhibit KC-2a

Carter A #BSP-CA44 API# 15-059-25832-00-00 NE SW SW 1040 FSL 4621 FEL Lat. 38.480122 Long: -95.119006 GPS session point (BSP-CA44). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA51 API# 15-059-25964-00-00 NW SW SW 1054 FSL 4931 FEL Lat. 38.480166 Long: -95.120090 GPS session point (BSP-CA51). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA52 API# 15-059-25974-00-00 NW SW SW 666 FSL 4976 FEL Lat. 38.479104 Long: -95.120241 GPS session point (BSP-CA52). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA45 API# 15-059-25840-00-00 NE SW SW 681 FSL 4605 FEL Lat. 38.479135 Long: -95.118945 GPS session point (BSP-CA45). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA54 API# 15-059-25975-00-00 SE SW SW 186 FSL 4620 FEL Lat. 38.477777 Long: -95.118991 GPS session point (BSP-CA54). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #7 API# 15-059-19268-00-00 NW NE SW 2360 FSL 3703 FEL Lat. 38.483724 Long -95.115820 GPS session point (7). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSI-CA53 API# 15-059-25973-00-00 SW SW SW SW 425 FSL 4796 FEL Lat: 38.478437 Long: -95.119608 GPS session point (BSI-CA53). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/11/2017. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA51 API# 15-059-25968-00-00 NW SW SW 840 FSL 5204 FEL Lat: 38.479587 Long: -95.121040 GPS session point (BSI-CA51). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/20/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA55 API# 15-059-25976-00-00 NW SW SW 1260 FSL 5220 FEL Lat: 38.480744 Long: -95.121023 GPS session point (BSI-CA55). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/20/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #2-E API# 15-059-24696-00-00 SW SE NW 2704 FSL 3505 FEL Lat: 38.484667 Long: - 95.115133 GPS session point (2-E). Well is an active authorized EOR well-constructed with 2.5" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 08/31/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA52 API# 15-059-25969-00-00 SW SW SW 422 FSL 5214 FEL Lat: 38.478439 Long: -95.121070 GPS session point (BSI-CA52). Well is an inactive authorized EOR well-constructed with 7" surface casing and 2.875" casing. The well is shut in with a valve and swedge. The injection line is broke that runs to the well head. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 04/20/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory. See attached photo numbered (Carter A BSI-CA52).

95.120311 GPS session point (BSP-CA53). Well was found to be an inactive oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a pump jack that is missing the belt. This well doesn't have any surface control. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Carter A BSP-CA53).

Carter A #11 API# 15-059-20299-00-00 NE NE SW 2507 FSL 3302 FEL Lat. 38.484119 Long -95.114419 GPS session point (11). Well was found to be an inactive oil well constructed with 2.5" casing. This well is hooked into the riser. This well is missing the pump string and the pump jack that is at the well site is missing the belt and motor. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Carter A 11).

Carter A #OW-4 API# 15-059-01638-00-00 NW NE SW 2452 FSL 3711 FEL Lat. 38.483979 Long: - 95.115847 GPS session point (OW-4). Well was found to be an inactive oil well constructed with 8" casing swedged down to 4.5" with well head. This well also has 2" tubing and 1 inch rods as the pump string. The horse head is also missing off of the pump jack. This well is shut in with a stuffing box. This well was not listed on Haas's certified well inventory but has since been added to their well inventory because of the Area of review for injection wells. See attached photo numbered (OW-4.) This well falls into the Area of Review for over 20 injection wells on Haas's certified well inventory.

Carter A #12 API# 15-059-20305-00-00 SW SE NW 3302 FSL 3336 FEL Lat. 38.486305 Long -95.114552 GPS session point (12). Well was found to be an inactive oil well constructed with 2.5" casing and one inch pump string hanging on a clamp. This well is missing the pump jack. See attached photo numbered (Carter A 12)

Carter A #BSI-CA59 API# 15-059-26745-00-00 SE SE NW 2709 FSL 2754 FEL Lat. 38.484660 Long: - 95.112508 GPS session point (BSI-CA59). Well was found to be an inactive oil well constructed with7" surface casing, 2.875" casing and one inch pump string hanging on a clamp. This well is missing the pump jack. See attached photo numbered (Carter A BSI-CA59)

Carter A #1-E API# 15-059-22743-00-00 SW SE NW 3302 FSL 3536 FEL Lat: 38.485809 Long: - 95.115249 GPS session point (1-E). Well is an active authorized EOR well-constructed with 4.5" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 10/30/2020. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #6 API# 15-059-19267-00-00 SW SE NW 2895 FSL 3700 FEL Lat. 38.485196 Long -95.115818 GPS session point (6). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #10 API# 15-059-20233-00-00 SW SE NW 2925 FSL 3347 FEL Lat. 38.485267 Long -95.114586 GPS session point (10). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA32 API# 15-059-25811-00-00 SE SE NW 2910 FSL 2908 FEL Lat. 38.485217 Long: -95.113050 GPS session point (BSP-CA32). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA31 API# 15-059-25810-00-00 SW SW NE 2925 FSL 2522 FEL Lat. 38.485250 Long: -95.111702 GPS session point (BSP-CA31). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSI-CA58 API# 15-059-26744-00-00 SE SE NW 2714 FSL 3083 FEL Lat. 38.484683 Long: - 95.113658 GPS session point (BSI-CA58). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSI-CA29 API# 15-059-25803-00-00 SE SE NW 3095 FSL 3104 FEL Lat. 38.485731 Long: - 95.113738 GPS session point (BSI-CA29). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 12/06/2016. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Page 30 of 276

Carter A #BSI-CA28 API# 15-059-25802-00-00 SE SE NW 3102 FSL 2690 FEL Lat. 38.485739 Long: -95.112291 GPS session point (BSI-CA28). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 12/06/2016. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #4-E API# 15-059-24697-00-00 NE SE NW 3499 FSL 2721 FEL Lat. 38.486829 Long -95.112406 GPS session point (4-E). Well is an active authorized EOR well-constructed with 7" surface casing and 2.5" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 8/31/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #3-E API# 15-059-24698-00-00 NE SE NW 3494 FSL 3127 FEL Lat. 38.486825 Long -95.113825 GPS session point (3-E). Well is an active authorized EOR well-constructed with 7" surface casing and 2.5" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 8/31/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #7-E API# 15-059-24777-00-00 NW SE NW 3517 FSL 3573 FEL Lat. 38.486900 Long - 95.115383 GPS session point (7-E). Well is an active authorized EOR well-constructed with 7" surface casing and 2.5" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 01/09/2019. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA17 API# 15-059-25750-00-00 NE SE NW 3737 FSL 3151 FEL Lat. 38.487493 Long: -95.113912 GPS session point (BSI-CA17). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 12/06/2016. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #21 API# 15-059-24680-00-00 SE SE NW 3309 FSL 2914 FEL Lat. 38.486312 Long -95.113076 GPS session point (21). Well was found to be a producing oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #20 API# 15-059-24699-00-00 SW SW NE 3298 FSL 2502 FEL Lat. 38.486273 Long -95.111636 GPS session point (20). Well was found to be a producing oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #18 API# 15-059-24679-00-00 NW SW NE 3711 FSL 2507 FEL Lat. 38.487408 Long -95.111662 GPS session point (18). Well was found to be a producing oil well constructed with 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #17 API# 15-059-24700-00-00 NW SE NW 3672 FSL 3333 FEL Lat. 38.487320 Long -95.114546 GPS session point (17). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #5 API# 15-059-19266-00-00 NW SE NW 3326 FSL 3736 FEL Lat. 38.486379 Long -95.115947 GPS session point (5). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #4 API# 15-059-19265-00-00 NW SE NW 3767 FSL 3740 FEL Lat. 38.487590 Long -95.115968 GPS session point (4). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA25 API# 15-059-25755-00-00 NW SE NW 3904 FSL 3458 FEL Lat. 38.487959 Long: -95.114986 GPS session point (BSP-CA25). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA49 API# 15-059-25861-00-00 NE SE NW 3924 FSL 3078 FEL Lat. 38.488005 Long: - 95.113659 GPS session point (BSP-CA49). Well was found to be a producing oil well constructed with 7" Exhibit KC-2a

surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA30 API# 15-059-25806-00-00 SE NE NW 4000 FSL 2778 FEL Lat. 38.488207 Long: -95.112613 GPS session point (BSP-CA30). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA29 API# 15-059-25805-00-00 SW NW NE 4024 FSL 2509 FEL Lat. 38.488266 Long: -95.111674 GPS session point (BSP-CA29). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #19 API# 15-059-24701-00-00 NE SE NW 3689 FSL 2928 FEL Lat. 38.487356 Long -95.113132 GPS session point (BSP-CA29). Well was found to be a producing oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA27 API# 15-059-25770-00-00 NW SW NE 3367 FSL 2154 FEL Lat. 38.486453 Long: -95.110423 GPS session point (BSP-CA27). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA23 API# 15-059-25759-00-00 NE SW NE 3381 FSL 1834 FEL Lat. 38.486485 Long: -95.109306 GPS session point (BSP-CA23). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA19 API# 15-059-25757-00-00 NE SW NE 3402 FSL 1510 FEL Lat. 38.486536 Long: -95.108175 GPS session point (BSP-CA19). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA20 API# 15-059-25767-00-00 SE SW NE 3113 FSL 1497 FEL Lat. 38.485743 Long: -95.108123 GPS session point (BSP-CA20). Well was found to be an inactive oil well constructed with 7" surface and 2.875" casing. This well is shut in with a valve and swedge. This well is missing the pump string and a pump jack. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (BSP-CA20.)

Carter A #BSP-CA24 API# 15-059-25768-00-00 SE SW NE 3055 FSL 1815 FEL Lat. 38.485591 Long: -95.109236 GPS session point (BSP-CA24). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA28 API# 15-059-25804-00-00 SW SW NE 3037 FSL 2145 FEL Lat. 38.485548 Long: -95.110386 GPS session point (BSP-CA28). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSI-CA27 API# 15-059-25801-00-00 NE SE NW 3779 FSL 2748 FEL Lat. 38.487599 Long: -95.112502 GPS session point (BSI-CA27). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 12/06/2016. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA20 API# 15-059-25764-00-00 SE SW NE 3231 FSL 1652 FEL Lat. 38.486070 Long: - 95.108667 GPS session point (BSI-CA20). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/21/2016. Staff did witness this test. Well is listed as Active "Al" on operator's well inventory.

95.109840 GPS session point (BSI-CA23). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/21/2016. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA25 API# 15-059-25766-00-00 NW SW NE 3515 FSL 2317 FEL Lat. 38.486863 Long: -95.110995 GPS session point (BSI-CA25). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 12/6/2016. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA56 API# 15-059-26293-00-00 SW NW NE 4247 FSL 2346 FEL Lat. 38.488876 Long: -95.111107 GPS session point (BSI-CA56). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/21/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA26 API# 15-059-25800-00-00 SW SW NE 3168 FSL 2328 FEL Lat. 38.485913 Long: -95.111027 GPS session point (BSI-CA26). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/21/2016. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA21 API# 15-059-25752-00-00 NW SW NE 3840 FSL 1996 FEL Lat. 38.487751 Long: -95.109878 GPS session point (BSI-CA21). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/21/2016. Staff did witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA18 API# 15-059-25751-00-00 NE SW NE 3859 FSL 1664 FEL Lat. 38.487794 Long: -95.108720 GPS session point (BSI-CA18). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/21/2016. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA19 API# 15-059-25760-00-00 NE SW NE 3557 FSL 1654 FEL Lat. 38.486963 Long: -95.108678 GPS session point (BSI-CA19). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/21/2016. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA22 API# 15-059-25761-00-00 NE SW NE 3543 FSL 1983 FEL Lat. 38.486935 Long: - 95.109827 GPS session point (BSI-CA22). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/21/2016. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSP-CA26 API# 15-059-25769-00-00 NW SW NE 3684 FSL 2160 FEL Lat. 38.487325 Long: -95.110449 GPS session point (BSP-CA26). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA22 API# 15-059-25758-00-00 NE SW NE 3703 FSL 1817 FEL Lat. 38.487370 Long: - 95.109250 GPS session point (BSP-CA22). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA18 API# 15-059-25756-00-00 NE SW NE 3729 FSL 1505 FEL Lat. 38.487434 Long: -95.108163 GPS session point (BSP-CA18). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA17 API# 15-059-25753-00-00 SE NW NE 4042 FSL 1499 FEL Lat. 38.488293 Long: -95.108145 GPS session point (BSP-CA17). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #16 API# 15-059-19262-00-00 SW NW NE 4028 FSL 2254 FEL Lat. 38.488272 Long -95.110781 GPS session point (16). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA21 API# 15-059-25754-00-00 NE SW NE 3975 FSL 1831 FEL Lat. 38.488117 Long: -95.109303 GPS session point (BSP-CA21). Well was found to be an inactive oil well constructed with 7" surface, 2.875" casing, 1" pump string, and a pump jack that was missing the belt. Well is shut in with a rag and clamp. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (BSP-CA21.)

Carter A #BSP-CA15 API# 15-059-25575-00-00 SE NW NE 4557 FSL 1481 FEL Lat. 38.489707 Long: -95.108090 GPS session point (BSP-CA15). Well was found to be an inactive oil well constructed with 7" surface and 2.875" casing. This well is missing the pump string, and a pump jack. This well doesn't have surface control. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (BSP-CA15.)

Carter A #BSP-CA14 API# 15-059-25574-00-00 NE NW NE 4872 FSL 1486 FEL Lat. 38.490572 Long: -95.108109 GPS session point (BSP-CA14). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA13 API# 15-059-25573-00-00 NE NW NE 5174 FSL 1577 FEL Lat. 38.491402 Long: - 95.108435 GPS session point (BSP-CA13). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-3A API# 15-059-25693-00-00 NW NW NE 5177 FSL 2033 FEL Lat. 38.491420 Long: - 95.110027 GPS session point (BSP-3A). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA4 API# 15-059-25554-00-00 NW NW NE 4902 FSL 1990 FEL Lat. 38.490666 Long: -95.109874 GPS session point (BSP-CA4). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA12 API# 15-059-25572-00-00 SE NW NE 4559 FSL 1863 FEL Lat. 38.489722 Long: -95.109425 GPS session point (BSP-CA12). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-2 API# 15-059-25548-00-00 NW NW NE 5129 FSL 2327 FEL Lat. 38.491295 Long: -95.111052 GPS session point (BSP-2). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA55 API# 15-059-26292-00-00 SW NW NE 4216 FSL 2007 FEL Lat. 38.488783 Long: -95.109922 GPS session point (BSP-CA55). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA11 API# 15-059-25581-00-00 SW NW NE 4522 FSL 2262 FEL Lat. 38.489627 Long: -95.110817 GPS session point (BSP-CA11). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

95.108766 GPS session point (BSI-CA10). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 6/03/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA4 API# 15-059-25571-00-00 NE NW NE 5085 FSL 1777 FEL Lat. 38.491164 Long: -95.109130 GPS session point (BSI-CA4). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 6/03/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA3 API# 15-059-25552-00-00 NW NW NE 5013 FSL 2156 FEL Lat. 38.490975 Long: - 95.110453 GPS session point (BSI-CA3). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 5/24/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA9 API# 15-059-25578-00-00 NW NW NE 4668 FSL 2088 FEL Lat. 38.490025 Long: -95.110210 GPS session point (BSI-CA9). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 7/22/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA15 API# 15-059-25645-00-00 NW NW NE 4711 FSL 2424 FEL Lat. 38.490152 Long: -95.111384 GPS session point (BSI-CA15). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 5/24/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-2 API# 15-059-25546-00-00 NW NW NE 4990 FSL 2456 FEL Lat. 38.490918 Long: -95.111503 GPS session point (BSI-2). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 3/09/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-1 API# 15-059-25545-00-00 NE NE NW 5003 FSL 2818 FEL Lat. 38.490961 Long - 95.112768 GPS session point (BSI-1). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 3/09/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA7 API# 15-059-25603-00-00 NE NE NW 4724 FSL 2783 FEL Lat. 38.490195 Long - 95.112639 GPS session point (BSI-CA7). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 7/27/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA5 API# 15-059-25576-00-00 NE NE NW 4992 FSL 3183 FEL Lat. 38.490941 Long - 95.114042 GPS session point (BSI-CA5). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 5/24/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #1 API# 15-059-19263-00-00 NW NE NW 5123 FSL 3766 FEL Lat. 38.491312 Long: -95.116080 GPS session point (1). Well was found to be an inactive oil well constructed with 4.5" casing. This well has been pulled and the pump string is laying beside the well. This well is hooked into the riser. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (1.)

Carter A #BSP-CA5 API# 15-059-25567-00-00 NW NE NW 5123 FSL 3352 FEL Lat. 38.491303 Long: -95.114634 GPS session point (BSP-CA5). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-1 API# 15-059-25547-00-00 NE NE NW 4847 FSL 2980 FEL Lat. 38.490538 Long: - 95.113328 GPS session point (BSP-1). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA10 API# 15-059-25643-00-00 SW NW NE 4604 FSL 2559 FEL Lat. 38.489859 Long: -95.111854 GPS session point (BSP-CA10). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #14 API# 15-059-21757-00-00 NE NE NW 5125 FSL 3001 FEL Lat. 38.491300 Long -95.113407 GPS session point (14). Well was found to be a producing oil well constructed with 2" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #15 API# 15-059-21600-00-00 NW NW NE 5139 FSL 2632 FEL Lat. 38.491330 Long -95.112120 GPS session point (15). Well was found to be a producing oil well constructed with 4.5" casing reduced to 2" at surface, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #30 API# 15-059-25270-00-00 NW NW NE 4850 FSL 2588 FEL Lat. 38.490536 Long -95.111961 GPS session point (30). Well was found to be a producing oil well constructed with 2" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #31 API# 15-059-25271-00-00 NW NW NE 4823 FSL 2286 FEL Lat. 38.490455 Long -95.110904 GPS session point (31). Well was found to be a producing oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #3 API# 15-059-19264-00-00 SW NE NW 4221 FSL 3732 FEL Lat. 38.488836 Long -95.115948 GPS session point (3). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA6 API# 15-059-25568-00-00 NW NE NW 4854 FSL 3348 FEL Lat. 38.490565 Long: -95.114618 GPS session point (BSP-CA6). Well was found to be an inactive oil well constructed with 7" surface, 2.875" casing. This well has been pulled and the pump string is laying beside the well. This well is hooked into the riser. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (BSP-CA6.)

Carter A #BSI-CA14 API# 15-059-25644-00-00 SW NE NW 4342 FSL 3523 FEL Lat. 38.489163 Long: -95.115221 GPS session point (BSI-CA14). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 5/24/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA16 API# 15-059-25763-00-00 SW NE NW 4040 FSL 3641 FEL Lat. 38.488338 Long: -95.115627 GPS session point (BSI-CA16). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 12/06/2016. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA12 API# 15-059-25641-00-00 NW NE NW 4951 FSL 3583 FEL Lat. 38.490837 Long: -95.115438 GPS session point (BSI-CA12). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 5/24/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter A #BSI-CA13 API# 15-059-25642-00-00 NW NE NW 4703 FSL 3534 FEL Lat. 38.490155 Long: -95.115265 GPS session point (BSI-CA13). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 5/24/2021. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Page 36 of 276

Carter A #BSI-CA24 API# 15-059-25762-00-00 NW SW NE 3820 FSL 2302 FEL Lat. 38.487701 Long: -95.110946 GPS session point (BSI-CA24). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 12/06/2016. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter A #BSI-CA31 API# 15-059-25845-00-00 NE NE SW 2141 FSL 2667 FEL Lat. 38.483100 Long: -95.112198 GPS session point (BSI-CA24). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 1/24/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.


Carter A #BSP-CA16 API# 15-059-25640-00-00 SW NE NW 4484 FSL 3754 FEL Lat. 38.489557 Long: -95.116028 GPS session point (BSP-CA16). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.


Carter A #BSP-CA9 API# 15-059-25639-00-00 NW NE NW 4768 FSL 3753 FEL Lat. 38.490339 Long: -95.116028 GPS session point (BSP-CA9). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.


Carter A #BSP-CA8 API# 15-059-25570-00-00 SW NE NW 4167 FSL 3410 FEL Lat. 38.488680 Long: -95.114821 GPS session point (BSP-CA8). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter A #BSP-CA7 API# 15-059-25569-00-00 SW NE NW 4547 FSL 3365 FEL Lat. 38.489724 Long: -95.114673 GPS session point (BSP-CA7). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

In conclusion, I found one hundred forty one (141) wells on the lease, seventy-one (71) active oil wells, fifty-three (53) active injection wells, twelve (12) inactive oil wells that are out of compliance, and five (5) inactive injection wells that are out of compliance. A photo of each of the seventeen (17) wells out of compliance and a google map with the session points which are the same as the well numbers are attached to this report. Operator well inventory shows no inactive wells.







Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A 1

FSL: 5123

FEL: 3766

API#: 15-059-19263-00-00

Date: 8/18/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: 1

PIC Orientation:

Latitude: 38.491312

Longitude: -95.116080

Time: 2:52 PM

Additional Information: This is a photo of well 1. This shows the well missing the pump string. The well is hooked into the riser.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A 11

FSL: 2507

FEL: 3302

API#: 15-059-20299-00-00

Date: 8/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: 11


PIC Orientation:

Latitude: 38.484119

Longitude: -95.114419

Time: 1:34 PM

Additional Information: This is a photo of well 11. This shows the well is hooked into the riser. The well is missing the pump string.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A 12

FSL: 3302

FEL: 3336

API#: 15-059-20305-00-00

Date: 8/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: 12


PIC Orientation:

Latitude: 38.486305

Longitude: -95.114552

Time: 2:46 PM

Additional Information: This is a photo of well 12. This shows the well has a pump string shut in with a stuffing box. The pump jack is missing from this well.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSI-CA40

FSL: 1715

FEL: 3495

API#: 15-059-25854-00-00

Date: 8/16/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSI-CA40


PIC Orientation:

Latitude: 38.481950

Longitude: -95.115085

Time: 2:26 PM

Additional Information: This is a photo of well BSI-CA40. This shows the injection line broke and the well shut in with a valve



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSI-CA46

FSL: 859

FEL: 4377

API#: 15-059-25860-00-00

Date: 8/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSI-CA46


PIC Orientation:

Latitude: 38.479621

Longitude: -95.118152

Time: 10:00 AM

Additional Information: This is a photo of well BSI-CA46. This shows the injection line unhooked.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSI-CA50

FSL: 851

FEL: 4793

API#: 15-059-25967-00-00

Date: 8/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSI-CA50

PIC Orientation:

Latitude: 38.479606

Longitude: -95.119603

Time: 10:32 AM

Additional Information: This is a photo of well BSI-CA50. This shows the injection line unhooked.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSI-CA52

FSL: 422

FEL: 5214

API#: 15-059-25964-00-00

Date: 8/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSI-CA52

PIC Orientation:

Latitude: 38.478439

Longitude: -95.121070

Time: 10:32 AM

Additional Information: This is a photo of well BSI-CA52. This shows the injection line unhooked.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSI-CA54

FSL: 445

FEL: 4402

API#: 15-059-25971-00-00

Date: 8/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSI-CA54


PIC Orientation:

Latitude: 38.478482

Longitude: -95.118231

Time: 9:45 AM

Additional Information: This is a photo of well BSI-CA54. This shows the injection line unhooked.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSI-CA59

FSL: 2709

FEL: 2754

API#: 15-059-26745-00-00

Date: 8/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSI-CA59


PIC Orientation:

Latitude: 38.484660

Longitude: -95.112508

Time: 3:18 PM

Additional Information: This is a photo of well BSI-CA59. This shows the well has a pump string hanging on a clamp. The pump jack is missing from this well.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSP-CA6

FSL: 4854

FEL: 3348

API#: 15-059-25568-00-00

Date: 8/18/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSP-CA6

PIC Orientation:

Latitude: 38.490565

Longitude: -95.114618

Time: 3:11 PM

Additional Information: This is a photo of well BSP-CA6. This shows the well missing the pump string and pump jack. The well is hooked into the riser.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSP-CA15

FSL: 4557

FEL: 1481

API#: 15-059-25575-00-00

Date: 8/18/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSP-CA15

PIC Orientation:

Latitude: 38.489707

Longitude: -95.108090

Time: 1:21 PM

Additional Information: This is a photo of well BSP-CA15. This shows the well missing the pump string and pump jack, the well is not shut in.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSP-CA20

FSL: 3113

FEL: 1497

API#: 15-059-25767-00-00

Date: 8/18/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSP-CA20

PIC Orientation:

Latitude: 38.485743

Longitude: -95.108123

Time: 12:08 PM

Additional Information: This is a photo of well BSP-CA20. This shows the well is missing the pump string and pump jack. This well is shut in with a valve and swedge.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSP-CA21

FSL: 3975

FEL: 1831

API#: 15-059-25754-00-00

Date: 8/18/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSP-CA21

PIC Orientation:

Latitude: 38.488117

Longitude: -95.109303

Time: 1:02 PM

Additional Information: This is a photo of well BSP-CA21. This shows the pump string unhooked from the pump jack and is shut in with a rag and clamp. The pump jack is also missing the belt



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSP-CA33

FSL: 2408

FEL: 2893

API#: 15-059-25821-00-00

Date: 8/16/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSP-CA33

PIC Orientation:

Latitude: 38.483839

Longitude: -95.112991

Time: 2:02 PM

Additional Information: This is a photo of well BSP-CA33. This shows the arm of the pump jack is broke.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A BSP-CA53

FSL: 183

FEL: 4998

API#: 15-059-25964-00-00

Date: 8/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSP-CA53

PIC Orientation:

Latitude: 38.477779

Longitude: -95.120311

Time: 10:58 AM

Additional Information: This is a photo of well BSP-CA53. This shows the pump jack is missing the belt



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A OW-3

FSL: 1194

FEL: 4094

API#: 15-059-01607-00-00

Date: 8/16/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: OW-3

PIC Orientation:

Latitude: 38.480532

Longitude: -95.117167

Time: 2:51 PM

Additional Information: This is a photo of well OW-3. This shows this well just has surface set. No production pipe set and is full of water.



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A OW-4

FSL: 2452

FEL: 3711

API#: 15-059-01638-00-00

Date: 8/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: OW-4 Pic 1

PIC Orientation:

Latitude: 38.483979

Longitude: -95.115847

Time: 2:15 PM

Additional Information: This is a photo of well #OW-4. This shows the well is constructed with 8 inch pipe reduced down to 4.5 inch with a well head. There is also 2" tubing ran in the well and 1" pump string with a stuffing box. This well does have surface control



Operator: Haas Petroleum, LLC

Lease: Carter A

County: FR

Subject: Carter A OW-4

FSL: 2452

FEL: 3711

API#: 15-059-01638-00-00

Date: 8/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: OW-4 Pic 2

PIC Orientation:

Latitude: 38.483979

Longitude: -95.115847

Time: 2:15 PM

Additional Information: This is a photo of well #OW-4. This shows the pump jack at the well

| Inspection Date: | 10/05/2021 | District: | 3 | Incident Number: 7700 | | | 7706 | |
|--|----------------------------------|--------------|------------------|-----------------------|---------------------|---------------|------------|------------|
| ✓ New Situation ✓ Lease Inspection | | | | | | | | |
| | ✓ Res | ponse to Rec | quest 🗌 | Complair | ıt | | | |
| | ☐ Follo | ow-up | ✓ | Field Rep | ort | | | |
| Operator License No | 33640 | API: | | | Q3: | Q2: | Q1: | |
| Operator Name: Ha | as Petroleum, LL | С | SEC 1 | 8 TW | 1 8 F | RGE 21 | RGEDIR: | Е |
| Address: P.O. Box 8 | | | | | | FSL: | | |
| City: Prairie Villag | • | | 0 1 | "D" | 147 | FEL: | | |
| State: Kansas Zip Phone contact: | Code : 66208 913-499-8373 | Leas | se: Carte | r "B" | | ell No.: | | |
| Reason for Investiga | | | | | County | : FR | | |
| Request from Wichita | | | | | | | | |
| request nom vvisina | | | | | | | | |
| Doobless | | | | | | | | |
| Problem: | | | | | | | | |
| To confirm location, well status, and number of wells on operator's inventory. | | | | | | | | |
| | | | | | | | | |
| Persons contacted: | | | | | | | | |
| Haas Petroleum pum | pers Terry and Cl | had | | | | | | |
| | | | | | | | | |
| Findings: | | | | | | | | |
| Research of the Carte | | | | | | | | |
| with thirty-two (32) act Recovery (EOR) inject | | | | | | | | |
| (55) well locations with is listed below: | n GPS and took a | photo of eac | h well loca | tion. Do | cumenta | tion of the | wells loca | ted |
| is listed below. | | | | | | | | |
| Carter B #F-2 API# 19 095.122181 GPS see | | | | | | | | : " |
| casing, 2" tubing, 1" p | | | | | | | | |
| operator's well invento | ory. | | | | | | | |
| (continued on page 2) |) | | | | | | | |
| | | | | | | | | |
| Actions / Recommen | idations <u>Fo</u> | ollow-up Red | quired \square | | Deadlin | e Date: | | |
| I will forward this repo | | | | | | | | |
| Haas Petroleum, LLC to plug, produce, or ob | | | | | | | | |
| oil wells are the Carter | r B #BSP-CB15 A | PI #15-059-2 | 6756-00-0 | 0, Carter | B #BSP | -CB8 API | #15-059- | |
| 26040-00-00, Carter E 4A API #15-059-2480 | | | | | | | | |
| 20794-00-00, Carter E | | | | | | | | |
| _ | | | | <u>Pł</u> | oto's T | aken: | 10 | |
| ✓ RBDMS ✓ KGS | ☐ KOLAR | Report Pre | epared By | : Keith | Carswe | <u>:11</u> | | |
| ☑ Di | strict Files C | Courthouse | Positio | on: <u>E.C</u> | C.R.S. | | | |

Additional Findings:

(continued from page 1)

Carter B #B-4 API# 15-059-24501-00-00 NW NE NE 4726 FSL 1094 FEL Lat. 38.490260 Long. - 095.125230 GPS session point (B-4). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #2 API# 15-059-19270-00-00 SW NE NE 4293 FSL 702 FEL Lat. 38.489072 Long. -095.123848 GPS session point (2). Well was found to be a producing oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #6 API# 15-059-21109-00-00 NW SE NE 3885 FSL 664 FEL Lat. 38.487951 Long. -095.123708 GPS session point (6). Well was found to be a producing oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #7 API# 15-059-21113-00-00 NW SE NE 3475 FSL 647 FEL Lat. 38.486825 Long. -095.123637 GPS session point (7). Well was found to be a producing oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #D-12 API# 15-059-24511-00-00 SW SE NE 3089 FSL 662 FEL Lat. 38.485765 Long. - 095.123680 GPS session point (D-12). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #E-7 API# 15-059-24744-00-00 SE NE NE 4103 FSL 553 FEL Lat: 38.488550 Long: -095.123324 GPS session point (E-7). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 01/19/2019. Staff did witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter B #C-7 API# 15-059-24507-00-00 SW NE NE 4114 FSL 903 FEL Lat: 38.488579 Long: -095.124547 GPS session point (C-7). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 07/30/2020. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #C-9 API# 15-059-24508-00-00 NW SE NE 3702 FSL 881 FEL Lat: 38.487448 Long: -095.124459 GPS session point (C-9). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 07/30/2020. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #C-5 API# 15-059-24506-00-00 SW NE NE 4493 FSL 1001 FEL Lat: 38.489620 Long: -095.124898 GPS session point (C-5). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 07/30/2020. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #C-11 API# 15-059-24509-00-00 SW SE NE 3279 FSL 857 FEL Lat: 38.486287 Long: -095.124367 GPS session point (C-11). Well is an inactive authorized EOR well-constructed with 7" surface casing and 2.875" casing. The well was equipped with a valve on the swedge but the valve was open at the time of inspection. The injection line was unhooked. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 07/30/2020. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory. See attached photo numbered (Carter B #C-11).

Carter B #B-12 API# 15-059-24505-00-00 SW SE NE 4726 FSL 1094 FEL Lat. 38.485839 Long. - 095.124998 GPS session point (B-12). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #B-10 API# 15-059-24504-00-00 NW SE NE 3500 FSL 1098 FEL Lat. 38.486896 Long. - 095.125214 GPS session point (B-10). Well was found to be a producing oil well constructe white item (B-10) with the construction of the

casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #B-8 API# 15-059-24503-00-00 NW SE NE 3925 FSL 1113 FEL Lat. 38.488062 Long. - 095.125278 GPS session point (B-8). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #B-6 API# 15-059-24502-00-00 SW NE NE 4337 FSL 1114 FEL Lat. 38.489194 Long. - 095.125291 GPS session point (B-6). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #BSP-CB7 API# 15-059-26039-00-00 SE NE SE 1952 FSL 181 FEL Lat. 38.482640 Long.-95.121974 GPS session point (BSP-CB7). Well was found to be an inactive oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack, but there is something lodged in the pump jack making it not capable of production. The well was shut in with a rag and clamp. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Carter B #BSP-CB7).

Carter B #BSP-CB4 API# 15-059-26036-00-00 NE NE SE 2339 FSL 176 FEL Lat. 38.483703 Long: -95.121967 GPS session point (BSP-CB4). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #BSI-CB3 API# 15-059-26046-00-00 NE NE SE 2527 FSL 0 FEL Lat: 38.484219 Long: - 095.121355 GPS session point (BSI-CB3). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/13/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter B #BSI-CB14 API# 15-059-26088-00-00 NE NE SE 2064 FSL 3 FEL Lat: 38.482948 Long: - 095.121356 GPS session point (BSI-CB14). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/10/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #BSI-CB5 API# 15-059-26048-00-00 NE NE SE 2125 FSL 428 FEL Lat: 38.483117 Long: - 95.122843 GPS session point (BSI-CB5). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 6/13/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #BSI-CB7 API# 15-059-26050-00-00 SE NE SE 1767 FSL 424 FEL Lat: 38.482135 Long: -95.122818 GPS session point (BSI-CB7). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 6/13/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #BSI-CB2 API# 15-059-26045-00-00 NE NE SE 2531 FSL 463 FEL Lat: 38.484233 Long: -95.122974 GPS session point (BSI-CB2). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 6/09/2017. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #E-11 API# 15-059-24513-00-00 SE SE NE 3306 FSL 414 FEL Lat: 38.486360 Long: -95.122821 GPS session point (E-11). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 7/30/2020. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #E-9 API# 15-059-24512-00-00 NE SE NE 3703 FSL 429 FEL Lat: 38.487450 Long: -95.122883 GPS session point (E-9). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MET) was KC-2a

completed on 7/30/2020. Staff did witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter B #13 API# 15-059-20513-00-00 SE SE NE 3086 FSL 183 FEL Lat. 38.485755 Long. -095.122007 GPS session point (13). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. This well was an extra well not listed on Haas's License. I matched the session point to this well and API #. I have updated RBDMS and made Haas Petroleum the operator as well as switched this well from a permitted well to an Producing "PR" oil well on operator's well inventory. See attached photo numbered (Carter B #13).

Carter B #5 API# 15-059-20794-00-00 NE SE NE 3488 FSL 201 FEL Lat. 38.488062 Long. -095.125278 GPS session point (5). Well was found to be an inactive oil well constructed with 4.5" casing. The 1" pump string has been pulled and is laying beside the well. There is a pump jack at well location but its missing its belt and horse head. The well is shut in with a bull plug. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Carter B #5).

Carter B #WSW-CB1 API# 15-059-26355-00-01 SW SE NE 2949 FSL 839 FEL Lat. 38.485382 Long: - 095.124295 GPS session point (WSW-CB1). Well was found to be an inactive water supply well-constructed with 8" surface and 4.5" casing. This well has no pump string or pump jack. The well is not shut in. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Carter B #WSW-CB1).

Carter B #D-14 API# 15-059-24703-00-00 SW SE NE 2712 FSL 715 FEL Lat. 38.484729 Long. - 095.123859 GPS session point (D-14). Well was found to be a producing oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory

Carter B #9 API# 15-059-23457-00-00 SE SE NE 2669 FSL 187 FEL Lat. 38.484611 Long. -095.122014 GPS session point (9). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory

Carter B #4 API# 15-059-20752-00-00 SE NE NE 4270 FSL 208 FEL Lat. 38.489006 Long. -095.122121 GPS session point (4). Well was found to be an inactive oil well constructed with 4.5" casing. This well is shut in with a valve and swedge. This well is missing a pump string and pump jack. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Carter B #4).

Carter B #F-4A API# 15-059-24808-00-01 NE NE NE 4711 FSL 304 FEL Lat. 38.490217 Long. - 095.122469 GPS session point (F-4A). Well was found to be an inactive oil well constructed with 4.5" casing. This well is hooked into the riser. This well is missing a pump string and the pump jack is missing the horse head. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Carter B #F-4A).

Carter B #BSP-CB5 API# 15-059-26037-00-00 SW NE SE 1972 FSL 1157 FEL Lat. 38.482699 Long: -95.125385 GPS session point (BSP-CB5). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. This well is also equipped with a stuffing box. Well is listed as Producing "PR" on operator's well inventory.

Carter B #BSI-CB4 API# 15-059-26047-00-00 NW NE SE 2158 FSL 941 FEL Lat: 38.483209 Long: - 95.124634 GPS session point (BSI-CB4). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/10/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #BSP-CB2 API# 15-059-26034-00-00 NW NE SE 2292 FSL 940 FEL Lat. 38.483577 Long: -95.125347 GPS session point (BSP-CB2). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. This well is also equipped with a stuffing box. Well is listed as Producing "PR" on operator's well inventory.

Carter B #BSP-CB1 API# 15-059-26033-00-00 NW NE SE 2615 FSL 1149 FEL Lat. 38.484464 Long: -95.125373 GPS session point (BSP-CB1). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. This well is also equipped with a stuffing box. Well is listed as Producing "PR" on operator's well inventory.

95.124406 GPS session point (BSI-CB1). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/13/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #BSP-CB3 API# 15-059-26035-00-00 NW NE SE 2322 FSL 670 FEL Lat. 38.483660 Long: -95.123692 GPS session point (BSP-CB3). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and has a fully equipped pump jack. This well is also equipped with a stuffing box. Well is listed as Producing "PR" on operator's well inventory.

Carter B #E-13 API# 15-059-24702-00-00 SE SE NE 2904 FSL 456 FEL Lat: 38.485255 Long: -95.122956 GPS session point (E-13). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 08/31/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter B #G-5 API# 15-059-24821-00-01 SE SE NE 4553 FSL 24 FEL Lat: 38.489783 Long: -95.121485 GPS session point (G-5). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 12/18/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter B #BSI-CB6 API# 15-059-26049-00-00 SW NE SE 1714 FSL 905 FEL Lat: 38.481990 Long: - 95.124500 GPS session point (BSI-CB6). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 6/13/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter B #BSI-CB8 API# 15-059-26051-00-00 SW NE SE 1337 FSL 899 FEL Lat: 38.480956 Long: -95.124469 GPS session point (BSI-CB8). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 6/13/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Carter B #3 API# 15-059-20742-00-00 NE SE NE 3949 FSL 185 FEL Lat. 38.488125 Long. -095.122036 GPS session point (3). Well was found to be an inactive oil well constructed with 4.5" casing. This well is hooked into the riser. The pump string has been pulled and is laying beside the well. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Carter B #3).

Carter B #BSP-CB6 API# 15-059-26038-00-00 SW NE SE 1897 FSL 672 FEL Lat. 38.482492 Long: -95.123688 GPS session point (BSP-CB6). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #BSP-CB8 API# 15-059-26040-00-00 SW NE SE 1542 FSL 1117 FEL Lat. 38.481518 Long: - 95.125234 GPS session point (BSP-CB8). Well was found to be an inactive oil well constructed with 7" surface and 2.875" casing. This well is hooked into the riser. The 1" pump string has been pulled and is laying beside the well. This well is also missing the pump jack. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Carter B #BSP-CB8).

Carter B #BSP-CB11 API# 15-059-26043-00-00 NW SE SE 1178 FSL 1125 FEL Lat. 38.480520 Long: - 95.125254 GPS session point (BSP-CB11). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #BSP-CB9 API# 15-059-26041-00-00 SW NE SE 1521 FSL 672 FEL Lat. 38.481460 Long: - 95.123680 GPS session point (BSP-CB9). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #BSP-CB12 API# 15-059-26757-00-00 NW SE SE 1035 FSL 684 FEL Lat. 38.480124 Long: - 95.123711 GPS session point (BSP-CB12). Well was found to be a producing oil well constructed with 7" Exhibit KC-2a

surface, 2.875" casing, 1" pump string, and a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #BSP-CB14 API#15-059-26755-00-00 NW SE SE 796 FSL 749 FEL Lat. 38.479470 Long.-95.123932 GPS session point (BSP-CB14). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #BSP-CB16 API#15-059-26061-00-00 SE SE SE 644 FSL 189 FEL Lat. 38.479049 Long.-95.121971 GPS session point (BSP-CB16). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #BSP-CB13 API#15-059-26058-00-00 NE SE SE 1032 FSL 178 FEL Lat. 38.480116 Long.-95.121944 GPS session point (BSP-CB13). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Carter B #BSP-CB10 API#15-059-26042-00-00 SE NE SE 1425 FSL 158 FEL Lat. 38.481194 Long.-95.121882 GPS session point (BSP-CB10). Well was found to be a producing oil well constructed with 7" surface, 2.875" casing, 1" pump string, and a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.


Carter B #BSI-CB15 API# 15-059-26089-00-00 SE NE SE 1664 FSL 19 FEL Lat: 38.481849 Long: -95.121404 GPS session point (BSI-CB15). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/10/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.


Carter B #BSI-CB9 API# 15-059-26052-00-00 NE SE SE 1261 FSL 436 FEL Lat: 38.480746 Long: -95.122850 GPS session point (BSI-CB9). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 6/13/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #BSI-CB11 API# 15-059-26054-00-00 NE SE SE 886 FSL 406 FEL Lat: 38.4779716 Long: -95.122737 GPS session point (BSI-CB11). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 6/9/2017. Staff did witness this test. Well is listed as Active "AI" on operator's well inventory.

Carter B #BSP-CB15 API# 15-059-26756-00-00 SW SE SE 515 FSL 733 FEL Lat. 38.478697 Long: -95.123871 GPS session point (BSP-CB15). Well was found to be an inactive oil well constructed with 7" surface and 2.875" casing. The 1" pump string and the pump jack are missing from this well. The well is shut in with a valve and swedge. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Carter B #BSP-CB15).

In conclusion, I found fifty-five (55) wells on the lease, twenty-six (26) active oil wells, twenty (20) active injection wells, seven (7) inactive oil wells that are out of compliance, one (1) inactive water supply well, and one (1) inactive injection well that are out of compliance. A photo of each of the nine (9) wells out of compliance and a google map with the session points which are the same as the well numbers are attached to this report. Operator well inventory shows no inactive wells. I have also attached a photo of the well Carter #13 15-059-20513 that was added to Haas Petroleum's license as a result of this lease inspection finding the well in production.







Operator: Haas Petroleum, LLC

Lease: Carter B

County: FR

Subject: Carter B 3

FSL: 3949

FEL: 185

API#: 15-059-20742-00-00

Date: 10/05/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: 3

PIC Orientation:

Latitude: 38.488125

Longitude: -95.122036

Time: 2:05 PM

Additional Information: This is a photo of well #3. This shows the well hooked into the riser



Operator: Haas Petroleum, LLC

Lease: Carter B

County: FR

Subject: Carter B 4

FSL: 4270

FEL: 208

API#: 15-059-20752-00-00

Date: 10/05/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: 4

PIC Orientation:

Latitude: 38.489006

Longitude: -95.122121

Time: 1:51 PM

Additional Information: This is a photo of well #4. This shows the well shut in with a valve and swedge.



Operator: Haas Petroleum, LLC

Lease: Carter B

County: FR

Subject: Carter B 5

FSL: 3488

FEL: 201

API#: 15-059-20794-00-00

Date: 10/05/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: 5

PIC Orientation:

Latitude: 38.486858

Longitude: -95.122081

Time: 11:58 AM

Additional Information: This is a photo of well #5. This shows the well shut in with a bull plug



Operator: Haas Petroleum, LLC

Lease: Carter B

County: FR

Subject: Carter B 13

FSL: 3086

FEL: 183

API#: 15-059-20513-00-00

Date: 10/05/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: 13

PIC Orientation:

Latitude: 38.485755

Longitude: -95.122007

Time: 11:49 AM

Additional Information: This is a photo of well #13. This shows the well was fully equipped for production. This well was producing at the time of inspection.



Operator: Haas Petroleum, LLC

Lease: Carter B

County: FR

Subject: Carter B BSP-CB7

FSL: 1952

FEL: 181

API#: 15-059-26039-00-00

Date: 10/05/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: BSP-CB7

PIC Orientation:

Latitude: 38.482640

Longitude: -95.121974

Time: 11:09 AM

Additional Information: This is a photo of well #BSP-CB7. This shows the well had something lodged in the pump jack making it inoperable at the time of inspection.



Operator: Haas Petroleum, LLC

Lease: Carter B

County: FR

Subject: Carter B BSP-CB8

FSL: 1542

FEL: 1117

API#: 15-059-26040-00-00

Date: 10/06/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: BSP-CB8

PIC Orientation:

Latitude: 38.481518

Longitude: -95.125234

Time: 11:28 AM

Additional Information: This is a photo of well BSP-CB8. This shows the well hooked into the riser.



Operator: Haas Petroleum, LLC

Lease: Carter B

County: FR

Subject: Carter B BSP-CB15

FSL: 515

FEL: 733

API#: 15-059-26756-00-00

Date: 10/06/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: BSP-CB15

PIC Orientation:

Latitude: 38.478697

Longitude: -95.123871

Time: 11:42 AM

Additional Information: This is a photo of well BSP-CB15. This shows the well shut in with a valve and swedge. It also shows the pump string and pump jack are missing.



Operator: Haas Petroleum, LLC

Lease: Carter B

County: FR

Subject: Carter B C-11

FSL: 3279

FEL: 857

API#: 15-059-24509-00-00

Date: 9/02/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: C-11

PIC Orientation:

Latitude: 38.486287

Longitude: -95.124367

Time: 2:56 PM

Additional Information: This is a photo of well #C-11. This shows injection line was unhooked.



Operator: Haas Petroleum, LLC

Lease: Carter B

County: FR

Subject: Carter B F-4A

FSL: 4711

FEL: 304

API#: 15-059-24808-00-01

Date: 10/05/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: F-4A

PIC Orientation:

Latitude: 38.490217

Longitude: -95.122469

Time: 1:47 PM

Additional Information: This is a photo of well #F-4A. This shows the well hooked into the riser.



Operator: Haas Petroleum, LLC

Lease: Carter B

County: FR

Subject: Carter B WSW-CB1

FSL: 2949

FEL: 839

API#: 15-059-26355-00-01

Date: 10/05/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: WSW-CB1

PIC Orientation:

Latitude: 38.485382

Longitude: -95.124295

Time: 12:16 PM

Additional Information: This is a photo of well #WSW-CB1. This shows the well open at the surface with no pump string or pump jack.

| Inspection Date: | 09/29/2021 | District: | 3 | | Incident | Number: | | 7770 |
|--|--|---|--|---|---|--|--|----------|
| | V No | ew Situation | | ✓ Lea | se Inspect | on | | |
| | ✓ R | esponse to R | equest | ☐ Cor | nplaint | | | |
| | | ollow-up | | ✓ Fiel | d Report | | | |
| Operator License No |): 33640 | API: | | | Q3: | Q2: | Q1: | SW |
| Operator Name: Ha Address: P.O. Box 8 City: Prairie Villa | 8396 | LLC | SE | C 3 | TWP 16 | RGE 21 FSL: FEL: | RGEDIR: | Е |
| State: Kansas Zip | | Le | ase: (| Coughen | | Well No.: | | |
| Phone contact: | 913-499-8373 | | | | Cou | nty: FR | | |
| Reason for Investiga | | | | | | | | |
| Request from Wichita | 1 | | | | | | | |
| | | | | | | | | |
| Problem: | | | | | | | | |
| To confirm location, w | vell status, and r | number of we | lls on op | erator's | inventory. | | | |
| | | | | | | | | |
| Persons contacted: | | | | | | | | |
| Haas Pumper Shawr | - | | | | | | | |
| • | | | | | | | | |
| Findings: | | | | | | | | |
| Research of the Coug current operator with to injection wells (Docke well inventory. I perfor with GPS and took a p | twenty-five (25) et # E-07526,) ni ormed the lease | active oil well ne (9) expired inspection 9/2 | s, eight d intents 29/2021 | (8) activ , and tw . I refer | ve Enhance to (2) plugg enced thirty | d Oil Recov ed wells on y-four (34) w | ery (EOR) their certific ell location: | ed s |
| COUGHENHOUR #2: Long095.080389 G | | | | | | | | ith 2" |
| casing, 1" pump string well inventory. | | | | | | | | |
| (continued on page 2) |) | | | | | | | |
| | | | | | | | | |
| Actions / Recommen | ndations | Follow-up R | equired | | <u>Dead</u> | line Date: | | |
| I will forward this report Haas Petroleum, LLC to plug, produce, or of inactive oil wells are the 26271-00-00, Coughe 00, Coughenour #13-1 (continued on page 2) | license # 33640 btain an approve he Coughenour enour #9-HP AP F API #15-059- | 0 be sent a No ed CP-111 on #28 API #15- I #15-059-270 | otice of eleven 059-25 012-00-(| Violatior (11) of 1 150-00-0 00, Cou | n Letter with the inactive 00, Coughe ghenour #1 | n a thirty (30 oil wells. T nour #30 AF 1-F API #15 |) day deadl hose eleve Pl #15-059- -059-19556 | ine n |
| (| , | | | | Photo's | s Taken: | 12 | |
| ▼ RBDMS ▼ KGS | □ KOLA | R Report P | repare | d By: | Keith Cars | | | |
| ✓ Di | istrict Files | Courthouse | Po | sition: | E.C.R.S | | | |

Additional Findings:

(continued from page 1 Actions/Recommendations)

Coughenour #16-F API #15-059-19561-00-00, Coughenour #19-F API #15-059-19546-00-00, Coughenour #20-F API #15-059-19547-00-00, Coughenour #5-F API #15-059-19550-00-00, and Coughenour #1-HP API #15-059-27004-00-00. The well status needs to be changed to inactive for all of the previous eleven (11) wells listed above. It is my further recommendation that a thirty (30) day NOV letter be sent stating that the Coughenour #10-W-10 API #15-059-01108-00-00 needs to be cutoff and buried below plow depth.

(continued from page 1 Findings)

COUGHENOUR #10-W-12 API #15059011160000 NE NW SW 1963 FSL 4547 FEL Lat. 38.686368 Long. -095.081668 GPS session point (10-W-12) Well was found to be a producing oil well constructed with 2" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #1-HP API #15059270040000 SW NW SW 1532 FSL 4899 FEL Lat. 38.685200 Long. 095.082887 GPS session point (1-HP) Well was found to be an active unauthorized EOR well constructed with 6" surface casing and 2.875" casing. Staff contacted the pumper and the pumper had unhooked the well when staff rechecked this well on 9/29/2021. The well is now inactive and shut-in with a swedge and valve. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Coughenour 1-HP).

COUGHENOUR #1I-HP API #15059270170000 SW NE SW 1724 FSL 3702 FEL Lat. 38.685673 Long. - 095.078700 GPS session point (1I-HP) Well was found to be an active authorized EOR well constructed with 6" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 9/8/2020 and KCC staff did not witness this test. Well is listed as Active "Al" on operator well inventory.

COUGHENOUR #1W-07 API #15059252740000 NW NW SW 2201 FSL 4972 FEL Lat. 38.687041 Long. -095.083162 GPS session point (1W-07) Well was found to be an active authorized EOR well constructed with 6" surface casing and 2.375" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 5/26/2017 and KCC staff witnessed this test. Well is listed as Active "Al" on operator well inventory.

COUGHENOUR #1W-08 API #15059254520000 NW SW SW 1008 FSL 4993 FEL Lat. 38.683767 Long. -095.083199 GPS session point (1W-08) Well was found to be an active authorized EOR well constructed with 6" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 7/13/2020 and KCC staff witnessed this test. Well is listed as Active "Al" on operator well inventory.

COUGHENOUR #21 API #15059205570000 NW NW SW 2469 FSL 4813 FEL Lat. 38.687769 Long. - 095.082614 GPS session point (21) Well was found to be a producing oil well constructed with 2" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #22 API #15059205690000 NE NW SW 2465 FSL 4535 FEL Lat. 38.687747 Long. - 095.081639 GPS session point (22) Well was found to be a producing oil well constructed with 2" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #25 API #15059221980000 NW NW SW 1939 FSL 4951 FEL Lat. 38.686320 Long. - 095.083082 GPS Session point (25) Well was found to be a producing oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #28 API #15059254500000 NW SW SW 1259 FSL 5043 FEL Lat. 38.684457 Long. - 095.083382 GPS session point (28) Well was found to be an inactive oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and a pump jack. The hose connecting 1" pump string to riser is missing. The casing is open and has no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Coughenour 28).

COUGHENOUR #29 API #15059257840000 NE NW SW 1967 FSL 4213 FEL Lat. 38.686363 Long. - 95.080498 GPS session point (29) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Facility (12) 1076

Page 77 of 276

on operator well inventory.

COUGHENOUR #2-HP API #15059270050000 SW NE SW 1881 FSL 3862 FEL Lat. 38.686111 Long. - 095.079264 GPS session point (2-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #2I-HP API #15059270180000 SW NE SW 1716 FSL 3381 FEL Lat. 38.685636 Long. - 095.077573 GPS session point (2I-HP) Well was found to be an active authorized EOR well constructed with 6" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 4/21/2017 and KCC staff witnessed this test. Well is listed as Active "AI" on operator well inventory.

COUGHENOUR #2W-07 API #15059252750000 NW NW SW 2197 FSL 4698 FEL Lat. 38.687019 Long. -095.082202 GPS session point (2W-07) Well was found to be an active authorized EOR well constructed with 6" surface casing and 2.375" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 5/26/2017 and KCC staff witnessed this test. Well is listed as Active "AI" on operator well inventory.

COUGHENOUR #30 API #15059262710000 SE NW SW 1541 FSL 4204 FEL Lat. 38.685194 Long. - 095.080453 GPS session point (30) Well was found to be an inactive oil well constructed with 2" casing. The 1" pipe has been pulled and lying beside the 2" casing. The casing is hooked to the riser. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Coughenour 30).

COUGHENOUR #3-HP API #15059270060000 SW NE SW 1890 FSL 3549 FEL Lat. 38.686121 Long. - 095.078167 GPS session point (3-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #3W-07 API #15059255160000 NE NW SW 2217 FSL 4354 FEL Lat. 38.687058 Long. - 095.080997 GPS session point (3W-07) Well was found to be an active authorized EOR well constructed with 6" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 12/21/2020 and KCC staff witnessed this test. Well is listed as Active "Al" on operator well inventory.

COUGHENOUR #3W-10 API #15059257850000 SE NW SW 1746 FSL 4374 FEL Lat. 38.685764 - 095.081053 GPS session point (3W-10) Well was found to be an active authorized EOR well constructed with 2" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 4/12/2018 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

COUGHENOUR #4-HP API #15059270070000 SE NE SW 1895 FSL 3216 FEL Lat. 38.686119 Long. - 095.077002 GPS session point (4-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #5-HP API #15059270080000 SW NE SW 1561 FSL 3881 FEL Lat. 38.685234 Long. - 095.079323 GPS session point (5-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #6-HP API #15059270090000 SW NE SW 1554 FSL 3546 FEL Lat. 38.685199 Long. - 095.078148 GPS session point (6-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #7-HP API #15059270100000 SE NE SW 1549 FSL 3207 FEL Lat. 38.685170 Long. - 095.076958 GPS session point (7-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #9-HP API #15059270120000 NE SW SW 1213 FSL 4122 FEL Lat. 38.684290 Long. - 095.080156 GPS session point (9-HP) Well was found to be an inactive oil well constructed with 6" surface casing and 2.875" casing. The casing is shut-in with a swedge and valve. There is no pump string to pump

jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Coughenour 9-HP).

COUGHENOUR #F 11 API #15059195560000 SE SW SW 443 FSL 4342 FEL Lat. 38.682186 Long. - 095.080902 GPS session point (11-F) Well was found to be an inactive oil well constructed with what appears to be 8" surface that is swedge down to 5.5" casing. The casing is open with no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Coughenour 11-F)

COUGHENOUR #F 12 API #15059195570000 NE SW SW 747 FSL 4103 FEL Lat. 38.683009 Long. - 095.080076 GPS session point (12-F) Well was found to be a producing oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #F 13 API #15059195580000 NW SE SW 1035 FSL 3875 FEL Lat. 38.683789 Long. - 095.079283 GPS session point (13-F) Well was found to be an inactive oil well constructed with 8" surface casing and 4.5" casing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Coughenour 13-F).

COUGHENOUR #F 14 API #15059195590000 SW NE SW 1355 FSL 3612 FEL Lat. 38.684656 Long. - 095.078374 GPS session point (14-F) Well was found to be an inactive oil well constructed with 10" surface casing, 4.5" casing, and 2" tubing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Coughenour 14-F).

COUGHENOUR #F 15 API #15059195600000 NW SW SW 784 FSL 4979 FEL Lat. 38.683150 Long. - 095.083146 GPS session point (15-F) Well was found to be a producing oil well constructed with 8" surface casing, 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #F 16 API #15059195610000 NW SW SW 1104 FSL 4771 FEL Lat. 38.684020 Long. - 095.082426 GPS session point (16-F) Well was found to be an inactive oil well constructed with 4.5" casing, 2" tubing, 1" pump string and a pump jack. The pump jack is missing the horse head and bridal. The 1" is hanging on a clamp inside the 2" tubing. The casing is open and has no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Coughenour 16-F).

COUGHENOUR #F 17 API #15059195620000 SE NW SW 1433 FSL 4567 FEL Lat. 38.684913 Long. - 95.081721 GPS session point (17-F) Well was found to be a producing oil well constructed with 8" surface casing, 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

COUGHENOUR #F 19 API #15059195460000 SW SW SW 457 FSL 5182 FEL Lat. 38.682261 Long. - 095.083845 GPS session point (19-F) Well was found to be an inactive oil well constructed with 8" surface casing, 4.5" casing, 2" tubing, 1" pump string and a pump jack. The pump jack is missing the electric motor. The casing is open and has no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Coughenour 19-F).

COUGHENOUR #F 20 API #15059195470000 SW NW SW 1594 FSL 4878 FEL Lat. 38.685371 Long. - 095.082816 GPS session point (20-F) Well was found to be an inactive oil well constructed with 4.5" casing and 2" tubing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Coughenour 20-F).

COUGHENOUR #F 5 API #15059195500000 SE SW SW 138 FSL 4581 FEL Lat. 38.681359 Long. - 095.081731 GPS session point (5-F) Well was found to be an inactive oil well constructed with 8" surface casing and 4.5" casing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Coughenour 5-F).

COUGHENOUR (ACKLEY) #10 W 10 API #15059011080000 SW NW SW 1594 FSL 4878 FEL Lat. 38.685371 Long. -095.082816 GPS session point (10-W-10) Well was found to be Plugged and Abandoned "PA" with 6" surface casing and 2" casing still above ground. Operator reported they included a


this well on 9/1/2017. KCC staff did not witness this plugging. Operator did not complete a Plugging Application (CP-1) until 10/11/2016. Operator then filed a Well Plugging Record (CP-4) on 4/5/2017. KCC staff completed a Well Plugging Report (CP-2/3) on 2/10/2017. A Copy of the CP-1, CP-4 and CP-2/3 are attached to this report. Operator will need to dig down and cut the casing off below surface. Well is listed as Plugged and Abandoned "PA" on operator well inventory. See attached photo numbered (Coughenour 10-W-10)

COUGHENOUR (ACKLEY) #9 W 7 API #15059011120000 NE SW SW 947 FSL 4374 FEL Lat. 38.683569 Long. -095.081031 GPS session point (9-W-7) Well was found to be an active authorized EOR well constructed with 2" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 2/21/2019 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

COUGHENOUR (ACKLEY) #9 W 5 API #15059011140000 This well is listed as plugged and abandoned "PA" on the operator's well inventory. No well was located at surface at the spot location listed on RBDMS.

The following list of wells were not located at the spot location listed on the operator well inventory. COUGHENOUR #10-HP API #15059270130000, COUGHENOUR #11-HP API #15059270140000, COUGHENOUR #12-HP API #15059270150000, COUGHENOUR #13-HP API #15059270160000, COUGHENOUR #3I-HP API #15059270190000, COUGHENOUR #4I-HP API #15059270200000, COUGHENOUR #5I-HP API #15059270210000, COUGHENOUR #6I-HP API #15059270220000, and the COUGHENOUR #8-HP API #15059270110000. These well locations are listed on the operator well inventory as Expired Intents "EX".

In conclusion, I found thirty-four (34) wells on the lease which included fourteen (14) producing oil wells, eight (8) active injection wells, eleven (11) inactive oil wells, and one (1) plugged well. No wells were found at any of the nine (9) expired intent locations or one (1) of the plugged well locations per operator footages. One (1) of the inactive oil wells (1-HP) was being used as an injection well until the pumper was told to unhook the well. A photo of each of the twelve (12) wells out of compliance, and a photo of the other three (3) wells that need transferred to Haas's license have been attached to this report. Also attached to this report is a google map with the session points which are the same as the well numbers are attached to this report. Operator well inventory shows no inactive wells.







Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 1-HP

FSL: 1532

FEL: 4899

API#: 15-059-27004-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 1-HP


PIC Orientation:

Latitude: 38.685200

Longitude: -095.082887

Time: 10:59 AM

Additional Information: This is a photo of well #1-HP. This photo shows the well was hooked up as an unauthorized injection well. The pumper was contacted and told to unhook the well. He unhooked the injection line and shut the well in.



Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 5-F

FSL: 138

FEL: 4581

API#: 15-059-19550-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 5-F


PIC Orientation:

Latitude: 38.681359

Longitude: -095.081731

Time: 2:40 PM

Additional Information: This is a photo of well #5-F. This photo shows the well as inactive. The well didn't have any surface control. This well is missing the pump string and pump jack.



Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 9-HP

FSL: 1213

FEL: 4122

API#: 15-059-27012-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 9-HP


PIC Orientation:

Latitude: 38.684290

Longitude: -095.080156

Time: 2:24 PM

Additional Information: This is a photo of well #9-HP. This photo shows the well as inactive. The well was missing the pump string and pump jack. The well was shut in with a valve and swedge.



Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 10-W-10

FSL: 1594

FEL: 4878

API#: 15-059-01108-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 10-W-10

PIC Orientation:

Latitude: 38.685371

Longitude: -095.082816

Time: 10:37 AM

Additional Information: This is a photo of well #10-W-10. This photo shows the well is still at surface. This well is a plugged and abandoned well. This well needs to be cut-off and buried below plow depth



Kansas Corporation Commission Oil & Gas Conservation Division

1319312

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: 33640 | API No. 15 - 15-059-01108-00-00 | | | | | | | |
|--|--|--|--|--|--|--|--|--|
| Name: Haas Petroleum, LLC | If pre 1967, supply original completion date: Spot Description: | | | | | | | |
| Address 1: 10551 BARKLEY ST. #307 | | | | | | | | |
| Address 2: | SW_NW_SW Sec. 3 Twp. 16 S. R. 21 VEast West | | | | | | | |
| City: OVERLAND PARK State: KS Zip: 66212 + 1812 | 1600 Feet from North / South Line of Section | | | | | | | |
| Contact Person: Mark Haas | Feet from Feet from East / West Line of Section | | | | | | | |
| Phone: (913) 499-8373 | Footages Calculated from Nearest Outside Section Corner: | | | | | | | |
| Fildle. () | — | | | | | | | |
| | Lease Name: COUGHENOUR (ACKLEY) Well #: 10 W 10 | | | | | | | |
| Check One: Oil Well Gas Well OG D&A Ca | athodic Water Supply Well Other: | | | | | | | |
| SWD Permit #: ▼ ENHR Permit #: | | | | | | | | |
| Conductor Casing Size: Set at: | Cemented with: Sacks | | | | | | | |
| Surface Casing Size: 6.2500 Set at: 50 | Cemented with: 25 Sacks | | | | | | | |
| Production Casing Size: 2.000 Set at: 726 | Cemented with: 110 Sacks | | | | | | | |
| List (ALL) Perforations and Bridge Plug Sets: | | | | | | | | |
| Elevation: 1004 (G.L. / K.B.) T.D.: 734 PBTD: | Anhydrite Depth: (Stone Corral Formation) (Interval) | | | | | | | |
| Is Well Log attached to this application? Yes No Is ACO-1 filed? If ACO-1 not filed, explain why: | Yes No | | | | | | | |
| Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and the Company Representative authorized to supervise plugging operations: | S | | | | | | | |
| | City: Overland Park State: Kansas Zip: 66212 + | | | | | | | |
| Phone: (913) 499-8373 | | | | | | | | |
| | Name: Skyy Drilling, LLC | | | | | | | |
| | Address 2: | | | | | | | |
| | State: KS Zip: 66212 + 1869 | | | | | | | |
| Phone: (<u>620</u>) <u>531-5922</u> | | | | | | | | |
| Proposed Date of Plugging (if known): | | | | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



Kansas Corporation Commission Oil & Gas Conservation Division

1319312

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB-1 (C | Cathodic Protection Borehole Intent) T-1 (Transfer) X CP-1 (Plugging Application) |
|--|---|
| OPERATOR: License #33640 Name: Haas Petroleum, LLC | Well Location: |
| Address 1: 10551 BARKLEY ST. #307 Address 2: | County: COUGHENOUR (ACKLEY) Well #: 10 W 10 |
| City: OVERLAND PARK State: KS Zip: 66212 + 1812 Contact Person: Mark Haas Phone: (913) 499-8373 Fax: () Email Address: | If filing a Form T-1 for multiple wells on a lease, enter the legal description of the lease below: |
| Surface Owner Information: Name: Elizabeth Coughenour Address 1: 13810 Metcalf Ave #12111 Address 2: | When filing a Form T-1 involving multiple surface owners, attach an additional sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the county, and in the real estate property tax records of the county treasurer. |
| the KCC with a plat showing the predicted locations of lease roads, tank | dic Protection Borehole Intent), you must supply the surface owners and k batteries, pipelines, and electrical lines. The locations shown on the plat n the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. |
| | ocated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form being filed is a Form C-1 or Form CB-1, the plat(s) required by this |
| KCC will be required to send this information to the surface ow | cknowledge that, because I have not provided this information, the vner(s). To mitigate the additional cost of the KCC performing this of the surface owner by filling out the top section of this form and KCC, which is enclosed with this form. |
| If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP- | fee with this form. If the fee is not received with this form, the KSONA-1 will be returned. |
| Submitted Electronically | |
| ı | _ |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

October 11, 2016

Mark Haas Haas Petroleum, LLC 10551 BARKLEY ST. #307 OVERLAND PARK, KS 66212-1812

Re: Plugging Application API 15-059-01108-00-00 COUGHENOUR (ACKLEY) 10 W 10 SW/4 Sec.03-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after April 11, 2017. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The April 11, 2017 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3

TO: API Well Number: <u>15-059-01108-00-00</u> Spot: SWNWSW Sec/Twnshp/Rge: 3-16S-21E STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING 1587 feet from S Section Line, 4883 feet from E Section Line 266 N. Main St., Ste. 220 Lease Name: COUGHENOUR (ACKLEY) Well #: 10 W 10 Wichita, KS 67202-1513 County: FRANKLIN Total Vertical Depth: 734 feet Depth (ft) Pulled (ft) Comment String Size Operator License No.: 33640 PROD 2 726 110 SX Op Name: HAAS PETROLEUM, LLC SURF 6.25 50 25 SX Address: 10551 BARKLEY ST. #307 **OVERLAND PARK, KS 66212** UIC Docket No: E07526.80 Well Type: EOR Date/Time to Plug: 09/01/2015 10:00 AM Plug Co. License No.: 33557 Plug Co. Name: SKYY DRILLING, LLC Proposal Rcvd. from: MARK HAAS Company: Phone: (913) 499-8373 Proposed Pump full of cement from top to bottom Plugging Method: Plugging Proposal Received By: <u>LEVI SHORT</u> WitnessType: NONE Date/Time Plugging Completed: 09/01/2015 11:00 AM KCC Agent: LEVI SHORT KCC WICHITA **Actual Plugging Report:** Perfs: RUN 1-INCH TUBING TO TD (734 FEET) THEN PUMP PORTLAND CEMENT TO FEB 1 0 2017 SURFACE. RECEIVED **RECEIVED** KCC DIST#3 FEB 08 2017 CHANUTE, KS Remarks: Plugged through: TBG Signed _____ District: 03

FEB 1 6 7/17
Exhibit KC-2a
Page 89 of 276

(TECHNICIAN)



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

1351037

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117


| OPERATOR: License #: 3 | 3640 | | _ • · · · | API No. 15 | ; 15-059-011 | 08-00-00 | | | |
|--------------------------------|---------------------------------|--------------------------------|-----------|-------------------|------------------------|---|--|--|--|
| Name: Haas Petro | | | | Spot Description: | | | | | |
| Address 1: 10551 BAI | ddress 1:10551 BARKLEY ST. #307 | | | | | | | | |
| Address 2: | | | | | | | | | |
| City: OVERLAND PA | RK State: KS | Zip: <u>66212</u> + <u>181</u> | 2 | | | | | | |
| Contact Person: Mark H | | | | 1 | | est Outside Section Corner: | | | |
| Phone: (913) 499-83 | 73 | | | | NE NW | / SE SW | | | |
| Type of Well: (Check one) | | OG D&A Cathodi | | County: | Franklin | | | | |
| Water Supply Well | | SWD Permit #: | | Lease Nar | me: COUGHENOUR | (ACKLEY) Well #: 10 W 10 | | | |
| ENHR Permit #: E075 | | rage Permit #: | 7 | | | | | | |
| Is ACO-1 filed? ✓ Yes | _ | log attached? Yes | No | | | oved on: (Date) | | | |
| Producing Formation(s): List A | • | · sheet) m: T.D | | 1 ' | | (KCC District Agent's Name) | | | |
| | | m: T.D | | | Commenced: 10/01 | | | | |
| Depth to | | m: T.D | | Plugging C | Completed: 10/1/2 | 2015 | | | |
| | | | | | | | | | |
| Show depth and thickness of a | all water, oil and gas forma | ations. | | | | | | | |
| Oil, Gas or Water | Records | | Casing | Record (Surfa | ace, Conductor & Produ | ction) | | | |
| Formation | Content | Casing | Size | | Setting Depth | Pulled Out | | | |
| | | Surface | 6.25 | 00 | 50 | | | | |
| | | Production | 2.00 | 00 | 726 | | | | |
| | | | | - | 1 - 0 | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | . 00 | | | • | | ds used in introducing it into the hole. If | | | |
| cement or other plugs were us | sed, state the character of | same depth placed from (bot | tom), to | (top) for each | plug set. | | | | |
| Pump full of cemei | nt from top to bo | ttom | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | 22557 | | | Shw D | rilling LLC | | | | |
| Plugging Contractor License # | | | | | | | | | |
| Address 1: 10551 BAR | KLEY ST., Ste 30 |)7 | Addres | s 2: | | | | | |
| City: OVERLAND PK | City: OVERLAND PK | | | | 3 | zip: <u>66212</u> + <u>1869</u> | | | |
| Phone: (913) 499-83 | 373 | | | _ | | | | | |
| Name of Party Responsible fo | r Plugging Fees: <u>Mark</u> | Haas | | | | | | | |
| State of | County, _ | | | , ss. | | | | | |
| | | | | Fm | plovee of Operator or | Operator on above-described well | | | |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and

(Print Name)

the same are true and correct, so help me God.



Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 11-F

FSL: 443

FEL: 4342

API#: 15-059-19556-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 11-F


PIC Orientation:

Latitude: 38.682186

Longitude: -095.080902

Time: 2:33 PM

Additional Information: This is a photo of well #11-F. This photo shows the well as inactive. The well is missing the pump string and pump jack. The well didn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 13-F

FSL: 1035

FEL: 3875

API#: 15-059-19558-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 13-F


PIC Orientation:

Latitude: 38.683789

Longitude: -095.079283

Time: 2:15 PM

Additional Information: This is a photo of well #13-F. This photo shows the well as inactive. The well is missing the pump jack and pump string. The well didn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 14-F

FSL: 1355

FEL: 3612

API#: 15-059-19559-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 14-F

PIC Orientation:

Latitude: 38.684656

Longitude: -095.078374

Time: 1:13 PM

Additional Information: This is a photo of well #14-F. This photo shows the well as inactive. The well didn't have any surface control. The 2 inch tubing in the well is sticking above surface approximately 10 feet. This well was also missing the pump string and pump jack.



Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 16-F

FSL: 1104

FEL: 4771

API#: 15-059-19561-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 16-F

PIC Orientation:

Latitude: 38.684020

Longitude: -095.082426

Time: 12:50 PM

Additional Information: This is a photo of well #16-F. This photo shows the well as inactive. The well didn't have any surface control. The pump string was hanging on a clamp and the pump jack was missing the horse head and bridal that connects the pump string to the pump jack.



Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 19-F

FSL: 457

FEL: 5182

API#: 15-059-19546-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 19-F

PIC Orientation:

Latitude: 38.682261

Longitude: -095.083845

Time: 2:51 PM

Additional Information: This is a photo of well #19-F. This photo shows the well as inactive. The pump jack is missing the motor. The well didn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 20-F

FSL: 1594

FEL: 4878

API#: 15-059-19547-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 20-F

PIC Orientation:

Latitude: 38.685371

Longitude: -095.082816

Time: 10:19 AM

Additional Information: This is a photo of well #20-F. This photo shows the well as inactive. The well didn't have any surface control. The well is missing the pump string and pump jack.



Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 28

FSL: 1259

FEL: 5043

API#: 15-059-25450-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 28

PIC Orientation:

Latitude: 38.684457

Longitude: -095.083382

Time: 12:48 PM

Additional Information: This is a photo of well #28. This photo shows the well as inactive. The well is missing the hose that connects the pump string to the riser. This well didn't have surface control.



Operator: Haas Petroleum, LLC

Lease: Coughenour

County: FR

Subject: Coughenour 30

FSL: 1541

FEL: 4204

API#: 15-059-26271-00-00

Date: 09/29/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 30

PIC Orientation:

Latitude: 38.685194

Longitude: -095.080453

Time: 9:45 AM

Additional Information: This is a photo of well #30. This photo shows the well as inactive. The well was missing the pump jack. The pump string was lying beside the well. The well was hooked into the riser.

| Inspection Date: | 10/05/2021 | District: | 3 | | Incident | Number: | | 7703 |
|---|--------------------|---------------|---------------|-----------|---------------|-------------------|--------------|------------|
| | ✓ New | / Situation | [| ✓ Leas | se Inspect | ion | | |
| | ∨ Res | ponse to Re | quest | Com | nplaint | | | |
| | ☐ Follo | ow-up | | ✓ Field | d Report | | | |
| Operator License No |): 33640 | API: | 15-059- | 26029 | Q3: | SW Q | 2: NW | Q1: SE |
| Operator Name: Ha | | C | SEC | 18 | TWP 18 | | RGE | DIR: E |
| Address: P.O. Box 8 | | | | | | FSL: | | 1962 |
| City: Prairie Village State: Kansas Zip | ge Code: 66208 | Loa | se: D. | Johnst | on | FEL: Well No.: | BSP-I | 1979 |
| Phone contact: | 913-499-8373 | Lea | 56. D. | JUITISE | | nty: FR | | 200 |
| Reason for Investiga | | | | | | | | |
| Request from Wichita | I | | | | | | | |
| | | | | | | | | |
| Problem: | | | | | | | | |
| To confirm location, w | ell status, and nu | mber of wells | s on one | rator's | inventory | | | |
| ro commin location, w | on otatao, and na | TIBOL OF WORK | on opo | 14101 0 | iiivointoi y. | | | |
| | | | | | | | | |
| Persons contacted: | | | | | | | | |
| None | | | | | | | | |
| Findings: | | | | | | | | |
| Research of the D Joh | nnston I ease loca | ted in the Sc | uithaast | allerte | r of 18_18. | 21E show | ad Haas | |
| Petroleum as the curr | ent operator with | one (1) inact | ive oil w | ell liste | d on their o | certified we | ell inven | tory. I |
| performed the lease in of the well location. Do | | | | | | n with GPS | and too | ok a photo |
| | | | | | | | | |
| D. Johnston #BSP-DJ 95.128255 GPS sessi | | | | | | | | |
| surface, 2.875" casing | g and 1 inch pump | string. The | pump ja | ck was | missing fr | om the we | ell location | on. This |
| well had a stuffing box been out of compliance | | | | | | | | |
| 111 filed on the well. | | | | | | | | |
| | | | | | | | | |
| Actions / Pocommon | ndations E | ollow-up Re | auirad | | Dood | lina Data: | | |
| Actions / Recommer | | | | for ro | | line Date: | <u>-</u> ' | on that |
| I will forward this repo Haas Petroleum, LLC | | | | | | | | |
| to plug, produce, or of well is D. Johnston BS | | | | (1) inac | ctive oil we | ll on the le | ase. Th | at one |
| WOIL IO D. COMMISCON DC | 2. DOO ALIII 10-0. | 20029-00 | , 00. | | | | | |
| | | | | | | | | |
| | | | | | Photo's | s Taken: | 1 | |
| ☑ RBDMS ☑ KGS | ☐ KOLAR | Report Pr | epared | Ву: | Keith Cars | well | | |
| ✓ Di | istrict Files C | ourthouse | Pos | ition: | E.C.R.S | <u>.</u> | | |





Operator: Haas Petroleum, LLC

Lease: D Johnston

County: FR

Subject: D Johnston BSP-DJ3

FSL: 1962

FEL: 1979

API#: 15-059-26029-00-00

Date: 10/05/2021

Staff: Keith Carswell

KLN: 33640

Legal: 17-18-21E

PIC ID#: BSP-DJ3

PIC Orientation:

Latitude: 38.482674

Longitude: -95.128255

Time: 1:22 PM

Additional Information: This is a photo of well BSP-DJ3. This shows the well missing the pump jack. The well is shut in with a stuffing box.





Operator Management

Feedback

Close Summary


Summary for Haas Petroleum

Users in KOLAR Group of Haas Petroleum • David Griffin • Jackie Windisch • Julie Barber • Mark Haas • Morgan Haas

| Operator Summary | |
|----------------------|---------------------|
| Company | Haas Petroleum |
| KCC License | 33640 |
| Compliance Evaluated | 11/12/2021 02:42 AM |

| View | Count |
|--------------------------------|-------|
| Wells in Inventory | 1,464 |
| Wells with Future Requirements | 327 |
| Wells Out of Compliance | 101 |
| CDP5 | 2 |
| CP111 O | 67 |
| MIT (| 28 |
| U3C O | 5 |

Wells Out of Compliance



To filter data, enter one or more words in the Search box. Search: Jo

Click to populate Search box: CDP5 CP111 MIT U3C Clear

| Detail | API Number | Lease and Well Name | Location | County | Requirement | Received | Required by |
|--------|--------------------|---------------------|------------|----------|-------------|----------|-------------|
| Detail | 15-059-26029-00-00 | DJOHNSTON BSP-DJ3 | 18-18S-21E | Franklin | CP111 | | 10/15/2018 |

Showing 1 to 1 of 1 entries (filtered from 102 total entries)

Previous 1

Next

| Inspection Date: | 09/30/2021 | District: 3 | | Incident Nu | ımber: | | 7769 |
|---|---|--|---|--|--|--|-------------------------|
| | ✓ Nev | w Situation | ✓ Lea | se Inspection | า | | |
| | ✓ Res | sponse to Reque | est 🗌 Cor | mplaint | | | |
| | ☐ Fol | low-up | ✓ Fiel | d Report | | | |
| Operator License No | o: 33640 | API: | | Q3: | Q2: | Q1: | NW |
| Operator Name: Ha Address: P.O. Box a City: Prairie Villa State: Kansas Zip Phone contact: | 8396 age | .C Lease: | SEC 3 Detar | | FSL: FEL: Gell No.: y: FR | RGEDIR: | E |
| Reason for Investiga | ation: | | | • | • | | |
| Request from Wichita | | | | | | | |
| Problem: To confirm location, w | vell status, and ทเ | ımber of wells o | n operator's | s inventory. | | | |
| Persons contacted: | E | | | | | | |
| Findings: | | | | | | | |
| Research of the Deta operator with eleven ((Docket # E-19891,) f their certified well inve- well locations with GF listed below: | (11) active oil well fifteen (15) expire entory. I performe | s, three (3) actived intents, one (1) add the lease insp | ve Enhance) cancelled pection 09/3 | d Oil Recover API#, and tw 60/2021. I ref | ry (EOR) ir o (2) plugg erenced se | ijection wel ed wells or eventeen (1 | lls 1 17) |
| DETAR #1-04 API # 095.078231 GPS ses surface casing, 2.875 Producing "PR" on op (Continued on page 2 | ssion point (1-04) or casing, 1" pump perator well invent | Well was found string, and has | d to be a pro | ducing oil we | ell construc | ted with 6" | |
| Actions / Recommen | ndations <u>F</u> | ollow-up Requ | ired | Deadlir | ne Date: | | |
| I will forward this report Haas Petroleum, LLC to plug, produce, or o wells are the Detar #1 API #15-059-01237-0 19519-00-00. The we above. (continued on | ort on to District # Clicense # 33640 btain an approved 10-HP API #15-05 00-01, Detar #8-H ell status needs to | 3 Compliance C be sent a Notice d CP-111 on five 59-26978-00-00, P API #15-059-2 | Officer for ree of Violation (5) of the in Detar #12-126976-00-00 | view. It is my n Letter with a nactive oil we HP API #15-0), and Job(De | recomme a thirty (30) ells. Those 059-26980- etar) #1 AP | day deadli five inactiv 00-00, Det I #15-059- | ine /e oil :ar #6 |
| , | , | | | Photo's 1 | Гaken: | 7 | |
| ✓ RBDMS ✓ KGS | ☐ KOLAR | Report Prep | ared By: | Keith Carsw | <u>ell</u> | | |
| ✓ D | istrict Files (| Courthouse | Position: | E.C.R.S. | | | |

Additional Findings:

(continued from page 1 Actions/Recommendations)

It is my further recommendation that a thirty (30) day NOV letter be sent stating that the Detar #4 API #15-059-20541-00-00 and Detar #5 API #15-059-20553-00-01 needs to be cutoff and buried below plow depth. It is also my recommendation that a thirty (30) day NOV letter be sent stating that the well Job(Detar) #1 API #15-059-19519-00-00 needs to have a T-1 completed and the well be transferred to Haas's well inventory.

(continued from page 1 Findings)

DETAR #10-HP API #15059269550000 This well is listed as a cancelled API # "CN". This well was not drilled under this intent. The well found in this spot location was drilled under well #Detar 10-HP API #15059269780000

DETAR #10-HP API #15059269780000 SW SE NW 2792 FSL 3813 FEL Lat. 38.688611 Long. - 095.079119 GPS session point (10-HP) Well was found to be an inactive oil well constructed with 6" surface casing, 2.875" casing, and a pump jack. There is no 1" pump string and the pump jack is missing the electric motor and belt. The casing is open and has no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Detar 10-HP).

DETAR #11-HP API #15059269480000 SW SE NW 2795 FSL 3479 FEL Lat. 38.688605 Long. - 095.077950 GPS Session point (11-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

DETAR #12-HP API #15059269800000 SE SE NW 2798 FSL 3147 FEL Lat. 38.688596 Long. - 095.076785 GPS session point (12-HP) Well was found to be an inactive oil well constructed with 6" surface casing, 2.875" casing, and a pump jack. There is no 1" pump string and the pump jack is missing the electric motor and belt. The casing is open and has no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Detar 12-HP).

DETAR #12I-HP API #15059269530000 SW SE NW 2939 FSL 3648 FEL Lat. 38.689008 Long. - 095.078545 GPS session point (12I-HP) Well was found to be an active authorized EOR well constructed with 6" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 5/11/2020 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

DETAR #3-HP API #15059269440000 NW SE NW 3397 FSL 3808 FEL Lat. 38.690271 Long. - 095.079119 GPS session point (3-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

DETAR #4 API #15059205410000 SW SE NW 3109 FSL 3877 FEL Lat. 38.689485 Long. -095.079353 GPS session point (4) Well was found to be Plugged and Abandoned "PA" with 2" casing still above ground. Operator reported they plugged this well on 5/13/2015. KCC staff did not witness this plugging. Operator completed a Plugging Application (CP-1) on 6/30/2015. Operator then filed a Well Plugging Record (CP-4) on 6/30/2015. KCC staff completed a Well Plugging Report (CP-2/3) on 11/13/2017. A Copy of the CP-1, CP-4 and CP-2/3 are attached to this report. Operator will need to dig down and cut the casing off below surface. Well is listed as Plugged and Abandoned "PA" on operator well inventory. See attached photo numbered (Detar 4)

DETAR #4-HP API #15059269450000 NW SE NW 3392 FSL 3482 FEL Lat. 38.690244 Long. - 095.077980 GPS session point (4-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

DETAR #5-HP API #15059269790000 NE SE NW 3396 FSL 3137 FEL Lat. 38.690239 Long. - 095.076769 GPS session point (5-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

DETAR #6 API #15059012370001 NW SE NW 3705 FSL 3876 FEL Lat. 38.691120 Long. -095.079368 GPS session point (6) Well was found to be an inactive oil well constructed with 2" casing, 1 Exhibit KGn29 Page 104 of 276

and a pump jack. The pump jack is missing the electric motor and belt. The casing is open and has no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Detar 6).

DETAR #6-HPAPI #15059269460000 SW SE NW 3095 FSL 3807 FEL Lat. 38.689442 Long. - 095.079109 GPS session point (6-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

DETAR #7-HPAPI #15059269470000 SW SE NW 3092 FSL 3485 FEL Lat. 38.689419 Long. - 095.077981 GPS session point (7-HP) Well was found to be a producing oil well constructed with 6" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

DETAR #7I-HPAPI #15059269500000 NE SW NW 3240 FSL 3999 FEL Lat. 38.689849 Long. - 095.079785 GPS session point (7I-HP) Well was found to be an active authorized EOR well constructed with 6" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 9/8/2020 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

DETAR #8-HPAPI #15059269760000 SE SE NW 3096 FSL 3143 FEL Lat. 38.689415 Long. - 095.076782 GPS session point (8-HP) Well was found to be an inactive oil well constructed with 6" surface casing, 2.875" casing, and a pump jack. There is no 1" pump string and the pump jack is missing the electric motor and belt. The casing is open and has no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Detar 8-HP).

DETAR #8I-HPAPI #15059269510000 NW SE NW 3230 FSL 3651 FEL Lat. 38.689806 Long. - 095.078564 GPS session point (8I-HP) Well was found to be an active authorized EOR well constructed with 6" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 9/8/2020 and KCC staff did not witness this test. Well is listed as Active "Al" on operator well inventory.

DETAR #5 API #15059205530001 SW SE NW 3108 FSL 3575 FSL Lat. 38.689469 Long. -095.078297 GPS session point (5) Well was found to be Plugged and Abandoned "PA" with 2" casing still above ground. Well is not listed on Operator well inventory. Bogle and Bogle was the operator at the time of the plugging. Previous operator reported they plugged this well on 11/30/2001. KCC staff witnessed this plugging. Operator did not complete a Plugging Application (CP-1) or a Well Plugging Record (CP-4). KCC staff completed a Well Plugging Report (CP-2/3) on 1/3/2001. A Copy of the CP-2/3 is attached to this report. Operator will need to dig down and cut the casing off below surface. Well is listed as Plugged and Abandoned "PA" on operator well inventory. See attached photo numbered (Detar 5)

JOB (DETAR) #1 API #15059195190000 NW SE NW 3391 FSL 3879 FEL Lat. 38.690259 Long. - 095.079371 GPS session point (Job(Detar) 1) Well was found to be an inactive oil well constructed with 4.5" casing. This well was missing the 1" pump string and a pump jack. The casing is open and has no surface control. Well is not listed on operator well inventory. This well falls into the area of review for multiple injection wells. The operator needs to complete a T-1 to transfer this well to their certified well inventory. See attached photo numbered (Job(Detar) 1).

The following well was not located at the spot location listed on the operator well inventory. The well is labeled as the DETAR #3 API #15059205400001. This well is listed as Plugged and Abandoned "PA" on the operator well inventory.

The following list of wells were not located at the spot location listed on the operator well inventory. DETAR #10I-HP API #15059269860000, DETAR #11I-HP API #15059269520000, DETAR #13-HP API #15059270010000, DETAR #13I-HP API #15059269870000, DETAR #14I-HP API #15059269880000, DETAR #1-HPAPI #15059269740000, DETAR #1I-HP API #15059269810000, DETAR #2-HP API #15059269750000, DETAR #2I-HP API #15059269820000, DETAR #3I-HP API #15059269490000, DETAR #4I-HP API #15059269540000, DETAR #5I-HP API #15059269830000, DETAR #6I-HP API #15059269840000, DETAR #9-HP API #15059269770000 and the DETAR #9I-HP API #15059269850000. These well locations are listed on the operator well inventory as Expired Intents "EX".

In conclusion, I found seventeen (17) wells on the lease which included seven (7) producing oil wells, three (3) active injection wells, five (5) inactive oil wells, and two (2) plugged wells. No wells were found at any of the fifteen (15) expired intent locations or one (1) of the plugged well locations per operator footages k One

(1) of the inactive oil wells (Job(Detar)1) is an extra well found during the lease inspection. One (1) extra plugged well was found on the lease also. A photo of each of the seven (7) wells out of compliance, including the one (1) well that needs transferred to Haas's License have been attached to this report. Also attached to this report is a google map with the session points which are the same as the well numbers are attached to this report. Operator well inventory shows no inactive wells.





Operator: Haas Petroleum, LLC

Lease: Detar

County: FR

Subject: Job(Detar)1

FSL: 3391

FEL: 3879

API#: 15-059-19519-00-00

Date: 09/30/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 1

PIC Orientation:

Latitude: 38.690259

Longitude: -095.079371

Time: 2:03 PM

Additional Information: This is a photo of well #1. This photo shows the well doesn't have any surface control. The well is missing the pump string and pump jack. This well isin't listed on Haas's license but is on the lease and falls into the area of review for Haas's injection wells. There is oil less than a foot from surface.



Operator: Haas Petroleum, LLC

Lease: Detar

County: FR

Subject: Detar 4

FSL: 3109

FEL: 3877

API#: 15-059-20541-00-00

Date: 09/30/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 4

PIC Orientation:

Latitude: 38.689485

Longitude: -095.079353

Time: 1:42 PM

Additional Information: This is a photo of well #4. This photo shows this well still at surface. I ran a rod down the well and tagged hard at 3 foot down. This well needs to be cutoff and buried below plow depth.



Kansas Corporation Commission Oil & Gas Conservation Division

1256401

Form CP-1

March 2010

This Form must be Typed

Form must be Signed

All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: _33640 | API No. 15 - 15-059-20541-00-00 | | | | | |
|--|---|--|--|--|--|--|
| Name: Haas Petroleum, LLC | If pre 1967, supply original completion date: | | | | | |
| Address 1: 11551 ASH ST., STE 205 | Spot Description: | | | | | |
| Address 2: | NW_SW_SE_NW Sec. 3 Twp. 16 S. R. 21 ✓ East West | | | | | |
| City: LEAWOOD State: KS Zip: 66211 + | South Line of Section | | | | | |
| Mark Hann | 3885 Feet from ✓ East / West Line of Section | | | | | |
| Contact Person: Mark Haas | Footages Calculated from Nearest Outside Section Corner: | | | | | |
| Phone: (913) 499-8373 | NE NW ✓ SE SW | | | | | |
| | County: Franklin | | | | | |
| | Lease Name: DETAR Well #: 4 | | | | | |
| Check One: ✓ Oil Well Gas Well OG D&A | Cathodic Water Supply Well Other: | | | | | |
| | : Gas Storage Permit #: | | | | | |
| Conductor Casing Size: Set at: | | | | | | |
| Surface Casing Size: 6.2500 Set at: 20 | Cemented with: 10 Sacks | | | | | |
| Production Casing Size: 2.3750 Set at: 700 | Cemented with: 99 Sacks | | | | | |
| List (ALL) Perforations and Bridge Plug Sets: | Centented with Sacks | | | | | |
| Elevation: (G.L. / K.B.) T.D.: 700 PBTD: Condition of Well: Good Poor Junk in Hole Casing Leak at: Proposed Method of Plugging (attach a separate page if additional space is needed): Pump cement from top to bottom | (Stone Corral Formation) | | | | | |
| Is Well Log attached to this application? Yes No Is ACO-1 filed? | Yes No | | | | | |
| If ACO-1 not filed, explain why: | | | | | | |
| | | | | | | |
| Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and | the Rules and Regulations of the State Corporation Commission | | | | | |
| Company Representative authorized to supervise plugging operations: Mark Ha | as | | | | | |
| Address: 11551 Ash Street, # 205 | City: Leawood State: KS Zip: 66211 + | | | | | |
| Phone: (913) 499-8373 | | | | | | |
| Plugging Contractor License #: 33961 | Name: Consolidated Oil Well Services LLC | | | | | |
| | Address 2: PO BOX 884 | | | | | |
| CHANILE | State: KS Zip: 66720 + | | | | | |
| Phone: (<u>620</u>) <u>431-9210</u> | | | | | | |
| Proposed Date of Plugging (if known): | | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



Kansas Corporation Commission Oil & Gas Conservation Division

1256401

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| DEFRATOR: Licenses # 33640 Name: Haas Petroleum, LLC Address 1: | Select the corresponding form being filed: C-1 (Intent) CB- | I (Cathodic Protection Borehole Intent) T-1 (Transfer) X CP-1 (Plugging Application) |
|---|---|--|
| Address 2: Lease Name: DETA: Well #: * City: LEAWOOD State: KS Zip: 66211 + | Name: | NW SW SE NW Sec.3 Twp. 16 S. R. 21 ✓ East West |
| Address 2: Lease Name: DETA: Well #: * City: LEAWOOD State: KS Zip: 66211 + | Address 1: 11551 ASH ST., STE 205 | County: Franklin |
| Contact Person: Mark Haas Phone: (913) 499-8373 Fax: (| Address 2: | Lease Name: Well #: 4 |
| Phone: (913) 499-8373Fax: () Email Address: | City: LEAWOOD State: KS Zip: 66211 + | If filing a Form T-1 for multiple wells on a lease, enter the legal description of |
| Surface Owner Information: Name: Francis Deters Address 1: 36220 W. 159th Street Address 2: State: Kansas Zip: 66030 + If this form is being submitted with a Form C-1 (Intent) or CB-1 (Cathodic Protection Borehole Intent), you must supply the surface owners and the KCC with a plat showing the predicted locations of lease roads, tank batteries, pipelines, and electrical lines. The locations may be entered on the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. Select one of the following: If this form is being submitted with a Form C-1 (Intent) or CB-1 (Cathodic Protection Borehole Intent), you must supply the surface owners and the KCC with a plat showing the predicted locations of lease roads, tank batteries, pipelines, and electrical lines. The locations shown on the plat are preliminary non-binding estimates. The locations may be entered on the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. Select one of the following: I certify that, pursuant to the Kansas Surface Owner Notice Act (House Bill 2032), I have provided the following to the surface owner(s) of the land upon which the subject well is or will be located: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form CP-1 that I am filing in connection with this form; 2) if the form being filed is a Form C-1 or Form CB-1, the plat(s) required by this form; and 3) my operator name, address, phone number, fax, and email address. I have not provided this information to the surface owner(s). To mitigate the additional cost of the KCC performing this task, I acknowledge that I must provide the name and address of the surface owner by filling out the top section of this form and that I am being charged a \$30.00 handling fee, payable to the KCC, which is enclosed with this form. If choosing the second option, submit payment of the \$30.00 handling fee with this form. If the fee is not received with this form, the KSONA-1 form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 will be returned. | | • |
| Surface Owner Information: Name: Francis Deters Address 1: 36220 W. 159th Street Address 2: | Phone: (913) 499-8373 Fax: () | |
| Name: Francis Deters Address 1: 36220 W. 159th Street Address 2: | Email Address: | |
| Address 2: City: Gardner State: Kansas Zip: 66030 + CB-1 (Cathodic Protection Borehole Intent), you must supply the surface owners and the KCC with a plat showing the predicted locations of lease roads, tank batteries, pipelines, and electrical lines. The locations shown on the plat are preliminary non-binding estimates. The locations may be entered on the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. Select one of the following: I certify that, pursuant to the Kansas Surface Owner Notice Act (House Bill 2032), I have provided the following to the surface owner(s) of the land upon which the subject well is or will be located: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form CP-1 that I am filing in connection with this form; 2) if the form being filed is a Form C-1 or Form CB-1, the plat(s) required by this form; and 3) my operator name, address, phone number, fax, and email address. I have not provided this information to the surface owner(s). I acknowledge that, because I have not provided this information, the KCC will be required to send this information to the surface owner(s). To mitigate the additional cost of the KCC performing this task, I acknowledge that I must provide the name and address of the surface owner by filling out the top section of this form and that I am being charged a \$30.00 handling fee, payable to the KCC, which is enclosed with this form. If choosing the second option, submit payment of the \$30.00 handling fee with this form. If the fee is not received with this form, the KSONA-1 form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 will be returned. | | When filing a Form T-1 involving multiple surface owners, attach an additional |
| Address 2: City: Gardner State: Kansas Zip: 66030 + CB-1 (Cathodic Protection Borehole Intent), you must supply the surface owners and the KCC with a plat showing the predicted locations of lease roads, tank batteries, pipelines, and electrical lines. The locations shown on the plat are preliminary non-binding estimates. The locations may be entered on the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. Select one of the following: I certify that, pursuant to the Kansas Surface Owner Notice Act (House Bill 2032), I have provided the following to the surface owner(s) of the land upon which the subject well is or will be located: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form CP-1 that I am filing in connection with this form; 2) if the form being filed is a Form C-1 or Form CB-1, the plat(s) required by this form; and 3) my operator name, address, phone number, fax, and email address. I have not provided this information to the surface owner(s). I acknowledge that, because I have not provided this information, the KCC will be required to send this information to the surface owner(s). To mitigate the additional cost of the KCC performing this task, I acknowledge that I must provide the name and address of the surface owner by filling out the top section of this form and that I am being charged a \$30.00 handling fee, payable to the KCC, which is enclosed with this form. If choosing the second option, submit payment of the \$30.00 handling fee with this form. If the fee is not received with this form, the KSONA-1 form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 will be returned. | Address 1: _36220 W. 159th Street | sheet listing all of the information to the left for each surface owner. Surface |
| If this form is being submitted with a Form C-1 (Intent) or CB-1 (Cathodic Protection Borehole Intent), you must supply the surface owners and the KCC with a plat showing the predicted locations of lease roads, tank batteries, pipelines, and electrical lines. The locations shown on the plat are preliminary non-binding estimates. The locations may be entered on the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. Select one of the following: I certify that, pursuant to the Kansas Surface Owner Notice Act (House Bill 2032), I have provided the following to the surface owner(s) of the land upon which the subject well is or will be located: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form CP-1 that I am filing in connection with this form; 2) if the form being filed is a Form C-1 or Form CB-1, the plat(s) required by this form; and 3) my operator name, address, phone number, fax, and email address. I have not provided this information to the surface owner(s). I acknowledge that, because I have not provided this information, the KCC will be required to send this information to the surface owner(s). To mitigate the additional cost of the KCC performing this task, I acknowledge that I must provide the name and address of the surface owner by filling out the top section of this form and that I am being charged a \$30.00 handling fee, payable to the KCC, which is enclosed with this form. If choosing the second option, submit payment of the \$30.00 handling fee with this form. If the fee is not received with this form, the KSONA-1 form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 will be returned. | Address 2: | county, and in the real estate property tax records of the county treasurer. |
| the KCC with a plat showing the predicted locations of lease roads, tank batteries, pipelines, and electrical lines. The locations shown on the plat are preliminary non-binding estimates. The locations may be entered on the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. Select one of the following: I certify that, pursuant to the Kansas Surface Owner Notice Act (House Bill 2032), I have provided the following to the surface owner(s) of the land upon which the subject well is or will be located: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form CP-1 that I am filing in connection with this form; 2) if the form being filed is a Form C-1 or Form CB-1, the plat(s) required by this form; and 3) my operator name, address, phone number, fax, and email address. I have not provided this information to the surface owner(s). I acknowledge that, because I have not provided this information, the KCC will be required to send this information to the surface owner(s). To mitigate the additional cost of the KCC performing this task, I acknowledge that I must provide the name and address of the surface owner by filling out the top section of this form and that I am being charged a \$30.00 handling fee, payable to the KCC, which is enclosed with this form. If choosing the second option, submit payment of the \$30.00 handling fee with this form. If the fee is not received with this form, the KSONA-1 form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 will be returned. | City: Gardner State: Kansas Zip: 66030 + | |
| owner(s) of the land upon which the subject well is or will be located: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form CP-1 that I am filing in connection with this form; 2) if the form being filed is a Form C-1 or Form CB-1, the plat(s) required by this form; and 3) my operator name, address, phone number, fax, and email address. I have not provided this information to the surface owner(s). I acknowledge that, because I have not provided this information, the KCC will be required to send this information to the surface owner(s). To mitigate the additional cost of the KCC performing this task, I acknowledge that I must provide the name and address of the surface owner by filling out the top section of this form and that I am being charged a \$30.00 handling fee, payable to the KCC, which is enclosed with this form. If choosing the second option, submit payment of the \$30.00 handling fee with this form. If the fee is not received with this form, the KSONA-1 form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 will be returned. | are preliminary non-binding estimates. The locations may be entered | |
| KCC will be required to send this information to the surface owner(s). To mitigate the additional cost of the KCC performing this task, I acknowledge that I must provide the name and address of the surface owner by filling out the top section of this form and that I am being charged a \$30.00 handling fee, payable to the KCC, which is enclosed with this form. If choosing the second option, submit payment of the \$30.00 handling fee with this form. If the fee is not received with this form, the KSONA-1 form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 will be returned. Submitted Electronically | I certify that, pursuant to the Kansas Surface Owner Notice owner(s) of the land upon which the subject well is or will be CP-1 that I am filing in connection with this form; 2) if the form | e located: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form n being filed is a Form C-1 or Form CB-1, the plat(s) required by this |
| form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 will be returned. Submitted Electronically | KCC will be required to send this information to the surface task, I acknowledge that I must provide the name and addre | owner(s). To mitigate the additional cost of the KCC performing this ss of the surface owner by filling out the top section of this form and |
| | | |
| [_ | Submitted Electronically | |
| | [| _ |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Shari Feist Albrecht, Chair Jay Scott Emler, Commissioner Pat Apple, Commissioner

June 30, 2015

Mark Haas Haas Petroleum, LLC 11551 ASH ST., STE 205 LEAWOOD, KS 66211

Re: Plugging Application API 15-059-20541-00-00 DETAR 4 NW/4 Sec.03-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after December 31, 2015. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The December 31, 2015 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3

TO: API Well Number: 15-059-20541-00-00 STATE CORPORATION COMMISSION Spot: NWSWSENW Sec/Twnshp/Rge: 3-16S-21E CONSERVATION DIVISION - PLUGGING 3885 feet from E Section Line 3169 feet from S Section Line, 266 N. Main St., Ste. 220 Well #: 4 Lease Name: **DETAR** Wichita, KS 67202-1513 Total Vertical Depth: 700 County: FRANKLIN Operator License No.: 33640 String Size Depth (ft) Pulled (ft) Comment PROD 2.375 700 99 SX Op Name: HAAS PETROLEUM, LLC 20 10 SX **SURF 6.25** Address: 10551 BARKLEY ST. #307 **OVERLAND PARK, KS 66212** 05/13/2015 12:00 AM Well Type: OIL **UIC Docket No:** Date/Time to Plug: Plug Co. License No.: 33961 Plug Co. Name: CONSOLIDATED OIL WELL SERVICES LLC Proposal Revd, from: MARK HAAS Phone: (913) 499-8373 Company: Proposed Pump cement from top to bottom Plugging Method: Plugging Proposal Received By: <u>LEVI SHORT</u> WitnessType: NONE Date/Time Plugging Completed: 05/13/2015 12:00 AM KCC Agent: LEVI SHORT Actual Plugging Report: Perfs: RUN 1-INCH TUBING TO 700 FEET INSIDE 2-INCH CASING THEN PUMP CEMENT TO SURFACE. A TOTAL OF 29 SACKS OF PORTLAND CEMENT WERE USED TO PLUG WELL. RECEIVED KCC DIST#3 OCT 2 3 2017 CHANUTE, KS Remarks: Plugged through: TBG District: 03 Signed , (TECHNICIAN)

Form CP-2/3



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

Kansas Corporation Commission Oil & Gas Conservation Division

1256404

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

| OPERATOR: License #: 33640 | | | | | API No. 15 - 15-059-20541-00-00 | | | | | |
|---|---|---|---|--|---|--|--|--|--|--|
| Name: Haas Petroleum, LLC | | | | Spot Description: | | | | | | |
| Address 1: 11551 ASH ST., STE 205 | | | | NW_SW_SE_NW Sec.3 Twp.16 S. R. 21 ✓ East West | | | | | | |
| Address 2: | | | | 1 | | North / V South Line of Section | | | | |
| City: LEAWOOD | State: | KS Zip: <u>66211</u> + | | _3885_ | Feet from | ✓ East / West Line of Section | | | | |
| Contact Person: Mark Haas | | | | Footages Calculated from Nearest Outside Section Corner: | | | | | | |
| Phone: (913) 499-8 | | | | | ■ NE ■ NW ▼ | / SE SW | | | | |
| | | OG D&A Catho | | County: _ | Franklin | | | | | |
| Water Supply Well Other: SWD Permit #: | | | | Lease Name: DETAR Well #: 4 | | | | | | |
| ENHR Permit #: Gas Storage Permit #: | | | | Date Well Completed: | | | | | | |
| Is ACO-1 filed? ✓ Yes No If not, is well log attached? Yes No | | | | | The plugging proposal was approved on: (Date) | | | | | |
| Producing Formation(s): List | • | | | 1 | | (KCC District Agent's Nam | | | | |
| | | Bottom: T.D. T.D. T.D. | | Plugging (| Commenced: 05/13 | | | | | |
| | | Bottom: T.D | | Plugging Completed: 05/13/2015 | | | | | | |
| Бериі | ю юр с | 1.D | | | | | | | | |
| Show depth and thickness of | f all water, oil and gas f | ormations. | | | | | | | | |
| Oil, Gas or Wat | | | Casing | Record (Surfa | ace, Conductor & Produc | ction) | | | | |
| Formation | Content | Casing | Size | | Setting Depth | Pulled Out | | | | |
| | | Surface | 6.25 | 00 | | 0 | | | | |
| | | Surface | 6.25 | 00 | 20 | 0 | | | | |
| | | Production | 2.37 | 50 | 700 | 0 | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| cement or other plugs were Establish circulati 6% gel per sack. | used, state the characte on through 1" t Pulled 1/2 tub | er of same depth placed from (b tubing at casing TD, | ottom), to mixed and p | (top) for each | n plug set. mped 12 sack | s of 50/50 Poz Mix with ent to surface. Pulled | | | | |
| Plugging Contractor License #: 33961 | | | _{Name:} Consolidated Oil Well Services LLC | | | | | | | |
| Address 1: 1322 S GRANT Add | | | _ Addres | ess 2: PO BOX 884 | | | | | | |
| City: CHANUTE | Sity: CHANUTE | | | _ State: KS | 3 | zip: <u>66720</u> + | | | | |
| Phone: (620) 431-9 | 9210 | | | _ | | | | | | |
| Name of Party Responsible | for Plugging Fees: <u>M</u> | ark Haas/ Haas Petrol | eum, L | LC | | | | | | |
| State of | Cour | nty, | | , SS. | | | | | | |
| | | , — | | | ployee of Operator or | Operator on above-described we | | | | |
| | (Print Nam | | | | project or operator of | Speciator on above-described we | | | | |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and



Operator: Haas Petroleum, LLC

Lease: Detar

County: FR

Subject: Detar 5

FSL: 3108

FEL: 3575

API#: 15-059-20553-00-01

Date: 09/30/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 5

PIC Orientation:

Latitude: 38.689469

Longitude: -095.078297

Time: 1:47 PM

Additional Information: This is a photo of well #5. This photo shows this well still at surface. I ran a rod down the well and tagged hard at 3 foot down. This well needs to be cutoff and buried below plow depth.

TO: API Well Number: 15-059-20553-00-01 STATE CORPORATION COMMISSION Spot: W2SENW Sec/Twnshp/Rge: 3-16S-21E CONSERVATION DIVISION - PLUGGING 3300 feet from S Section Line, 3630 feet from E Section Line 130 SOUTH MARKET, SUITE 2078 Lease/Unit Name: DETAR Well Number: 5 WICHITA, KANSAS 67202 County: FRANKLIN Total Vertical Depth: 700 feet feet: Operator License No.: 6764 Conductor Pipe: Size 35.00 Surface Casing: Size 6.25 feet: 20 Op Name: BOGLE AND BOGLE Production: Size 2 feet: 690 Address: 40688 W. 255 Liner: Size feet: WELLSVILLE, KS 66092 Well Type: EOR UIC Docket No: E19891.8 Date/Time to Plug: 11/30/2001 8:00 AM Plug Co. License No.: 8469 Plug Co. Name: NICKELL DRILLING Proposal Revd. from: RALPH NICKELL Company: NICKELL DRILLING Phone: (913) 898-6862 Proposed PLUG WELL FROM TD TO SURFACE WITH CEMENT. Plugging Method: Plugging Proposal Received By: FRANK GUILFOYLE WitnessType: Plugging Operations 100% Witnessed (Complete) Date/Time Plugging Completed: 11/30/2001 5:00 PM KCC Agent: FRANK GUILFOYLE Actual Plugging Report: RAN 1" AND WASHED TO TD, PUMPED 14 SACKS OF PORTLAND CEMENT TO SURFACE. PULLED 1" OUT AND TOPPED OFF WELL. RECEIVED District #3 KCC JAN 3 2002 Chanute KS ALC: 45 900 1 Remarks: Plugged through: District: 03 Signed

Signed Frank Sulfoyle by SL
RECEIVED (FECHNICIAN)

KANSAS CORPORATION COMMISSION

JAN 0 7 2002

CONSERVATION DIVISION

DATE OI-08-02
Exhibit KC-2a

20/Page 46 of 2/16



Operator: Haas Petroleum, LLC

Lease: Detar

County: FR

Subject: Detar 6

FSL: 3705

FEL: 3876

API#: 15-059-01237-00-01

Date: 09/30/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 6

PIC Orientation:

Latitude: 38.691120

Longitude: -095.079368

Time: 2:07 PM

Additional Information: This is a photo of well #6. This photo shows the well doesn't have any surface control. The motor and belt are missing from the pump jack.



Operator: Haas Petroleum, LLC

Lease: Detar

County: FR

Subject: Detar 8-HP

FSL: 3096

FEL: 3143

API#: 15-059-26976-00-00

Date: 09/30/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 8-HP

PIC Orientation:

Latitude: 38.689415

Longitude: -095.076782

Time: 1:30 PM

Additional Information: This is a photo of well #8-HP. This photo shows the well doesn't have any surface control. The pump string is missing. The motor and belt are also missing from the pump jack.



Operator: Haas Petroleum, LLC

Lease: Detar

County: FR

Subject: Detar 10-HP

FSL: 2792

FEL: 3813

API#: 15-059-26978-00-00

Date: 09/30/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 10-HP

PIC Orientation:

Latitude: 38.688611

Longitude: -095.079119

Time: 1:37 PM

Additional Information: This is a photo of well #10-HP. This photo shows the well shut in with a valve and swedge. The pump string is missing. The motor and belt are also missing from the pump jack.



Operator: Haas Petroleum, LLC

Lease: Detar

County: FR

Subject: Detar 12-HP

FSL: 2798

FEL: 3147

API#: 15-059-26980-00-00

Date: 09/30/2021

Staff: Keith Carswell

KLN: 33640

Legal: 3-16-21E

PIC ID#: 12-HP

PIC Orientation:

Latitude: 38.688596

Longitude: -095.076785

Time: 1:32 PM

Additional Information: This is a photo of well #12-HP. This photo shows the well doesn't have any surface control. The pump string is missing. The motor and belt are also missing from the pump jack.

| Inspection Date: | 09/01/2021 | District: | 3 | | Incident Number: | | | | 7762 |
|---|------------------|---------------------|-----------|---------------|------------------|---------------|-------------|--------------|------|
| | ✓ | New Situation | | ✓ Lea | se Insped | ction | | | |
| | ✓ | Response to R | Request | ☐ Con | nplaint | | | | |
| | | Follow-up | | ✓ Fiel | d Report | | | | |
| Operator License N | o : 33640 | API: | | | Q3 | 3: | Q2: | Q1: | NW |
| Operator Name: Ha | aas Petroleun | n, LLC | SE | EC 18 | TWP 1 | 8 RG | E 21 | RGEDIR: | Е |
| Address: P.O. Box | 8396 | | | | | | FSL: | | |
| City: Prairie Villa | _ | | | | | | FEL: | | |
| • | Code: 6620 | | ease: | Dimoush | | Well | | | |
| Phone contact: Reason for Investig | 913-499-83 | 13 | | | Col | unty: | FR | | |
| Request from Wichita | <u></u> | | | | | | | | |
| Nequest from Wichita | а | | | | | | | | |
| | | | | | | | | | |
| Problem: | | | | | | | | | |
| To confirm location, v | well status, an | nd number of we | ells on o | perator's | inventory | / . | | | |
| | | | | | | | | | |
| Persons contacted | <u>:</u> | | | | | | | | |
| Haas Petroleum pun | | nd Chad | | | | | | | |
| · | , | | | | | | | | |
| Findings: | | | | | | | | | |
| Research of the Dime | | | | | | | | | |
| current operator with injection wells (Docke | | | | | | | | | ied |
| well inventory. I perfo | ormed the lea | se inspection 9/ | 01/202 | 1. I refer | enced for | ty-thre | e (43) w | ell location | |
| with GPS and took a | photo of each | n well location. | Docume | entation c | of the well | s loca | ted is lis | ted below: | |
| Dimoush #1 API# 15 | | | | | | | | | |
| 095.131023 GPS ses casing, 1" pump strin | | | | | | | | | |
| operator's well invent | |) - 4 | | | | | | | |
| (Continued on page 2 | 2) | | | | | | | | |
| (************************************** | -, | | | | | | | | |
| Actions / Recomme | ndations | Follow-up F | Require | d \square | Dea | dline | Date: | | |
| I will forward this repo | | • | | | - | | | ndation tha | ıt |
| Haas Petroleum, LLC | Clicense # 33 | 640 be sent a N | lotice of | Violation | ı Letter wi | ith a th | irty (30) | day deadli | ne |
| to plug, produce, or clinactive oil wells are t | | | | | | | | | |
| Dimoush #30 API #15 | | | | | | | | | |
| 059-20657-00-00, Din Dimoush #22 API #19 | | | | | | | | | |
| | | | | | <u>Photo</u> | | ` | 16 | , |
| ✓ RBDMS ✓ KGS | □ ко | LAR Report I | Prepare | ed By: | Keith Ca | <u>rswell</u> | | | |
| ✓ D | istrict Files | ☐ Courthouse | Р | osition: | E.C.R. | S. | | | |

Additional Findings:

(Continued from page 1 Actions/Recommendations)

Dimoush #38 API #15-059-21780-00-00, Dimoush #17 API #15-059-20522-00-00, and Dimoush #29 API #15-059-20651-00-00. The well status needs to be changed to inactive for all of the previous twelve (12) wells listed above. It is my further recommendation that a thirty (30) day NOV letter be sent stating that the Dimoush #35 API #15-059-20673-00-00 needs to be cutoff and buried below plow depth. It is also my recommendation that a thirty (30) day NOV letter be sent stating that a T-1 needs to be completed for the following three (3) wells to place them on Haas's certified well inventory. The three wells are Dimoush #31 API #15-059-20656-00-00, Dimoush #37 API #15-059-20675-00-00, and Dimoush #27 API #15-059-20644-00-00.

(Continued from page 1 Findings)

Dimoush #6 API# 15-059-20496-00-00 NW NE NW 5127 FSL 3071 FEL Lat. 38.491369 Long. -095.132143 GPS session point (6). Well was found to be an inactive oil well constructed with 8" surface casing and 4.5" casing. The 1" pump string has been pulled and is laying beside the well. This well was hooked into the riser. Well is listed as Producing "PR" on operator's well inventory. . See attached photo numbered (Dimoush 6).

Dimoush #7 API# 15-059-01213-00-00 NW NE NW 5075 FSL 3373 FEL Lat. 38.491226 Long. -095.133200 GPS session point (7). Well was found to be an inactive oil well constructed with 5.5" casing and 2" tubing. The 1" pump string and pump jack was missing from this well location. This well did not have surface control at the time of inspection. Well is listed as Producing "PR" on operator's well inventory. . See attached photo numbered (Dimoush 7).

Dimoush #8 API# 15-059-20497-00-00 NE NW NW 5136 FSL 3705 FEL Lat. 38.491395 Long. -95.134359 GPS session point (8). Well was found to be a producing oil well constructed with 8" surface casing, 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #9 API# 15-059-20498-00-00 NE NW NW 5129 FSL 4050 FEL Lat. 38.491377 Long. -95.135566 GPS session point (9). Well was found to be a producing oil well constructed with 8" surface casing, 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #10 API# 15-059-20499-00-00 NW NW NW 5130 FSL 4381 FEL Lat. 38.491382 Long. -95.136720 GPS session point (10). Well was found to be a producing oil well constructed with 8" surface casing, 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #11 API# 15-059-01214-00-00 NW NW NW 5216 FSL 4717 FEL Lat. 38.491617 Long. -95.137898 GPS session point (11). Well was found to be a producing oil well constructed with 5.5" casing, 2"tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #31 API# 15-059-20656-00-00 NW NW NW 5216 FSL 4717 FEL Lat. 38.491617 Long. -95.137898 GPS session point (31). Well was found to be a producing oil well constructed with 4.5" casing, 2"tubing, 1" pump string, and has a fully equipped pump jack. This well wasn't on operator's certified well inventory but on the inspection the well was fully equipped for production on the Dimoush lease. Haas Petroleum was added as the working operator and needs to complete a T-1 to transfer the well to their well inventory. Well is now listed as Producing "PR" on RBDMS well inventory with Haas Petroleum as the working operator. See attached photo numbered (Dimoush 31).

Dimoush #30 API# 15-059-20652-00-00 NE NW NW 4858 FSL 4197 FEL Lat: 38.490634 Long: -095.136073 GPS session point (30). Well is an inactive authorized EOR well-constructed with 8" surface casing and 4.5" casing. The injection line was unhooked from the well and the well was shut in with a valve and swedge. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 10/26/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory. See attached photo numbered (Dimoush 30).

Dimoush #5I-HP API# 15-059-27146-00-00 NE NE NW 4992 FSL 2944 FEL Lat: 38.490997 Long: - 95.131697 GPS session point (5I-HP). Well is an active authorized EOR well-constructed with while the 2a section of 276 percentage and 23 of 276

casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 02/9/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dimoush #2 API# 15-059-20480-00-00 NE NE NW 4873 FSL 2815 FEL Lat: 38.490671 Long: -95.131244 GPS session point (2). Well is an active authorized EOR well-constructed with 8" surface casing and 4.5" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 9/29/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dimoush #3 API# 15-059-20476-00-00 SE NE NW 4597 FSL 2834 FEL Lat. 38.489912 Long. -95.131303 GPS session point (3). Well was found to be a producing oil well constructed with 8"surface casing, 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #15 API# 15-059-20508-00-00 NW NE NW 4816 FSL 3095 FEL Lat. 38.490515 Long. -95.132220 GPS session point (15). Well was found to be a producing oil well constructed with 8"surface casing, 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #9I-HP API# 15-059-27139-00-00 NE NE NW 4680 FSL 2987 FEL Lat: 38.490140 Long: -95.131840 GPS session point (9I-HP). Well is an active authorized EOR well-constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 02/03/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dimoush #19 API# 15-059-20575-00-00 NW NE NW 4728 FSL 3426 FEL Lat: 38.490634 Long: - 095.136073 GPS session point (19). Well is an inactive authorized EOR well-constructed with 8" surface casing and 4.5" casing. The injection line was broke from the well and the well was shut in with a valve and swedge. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 09/29/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory. See attached photo numbered (Dimoush 19).

Dimoush #21 API# 15-059-20588-00-00 NE NW NW 4818 FSL 3705 FEL Lat. 38.490521 Long. -95.134351 GPS session point (21). Well was found to be a producing oil well constructed with 8"surface casing, 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #32 API# 15-059-20657-00-00 SW NW NW 4511 FSL 4577 FEL Lat. 38.489681 Long. - 095.137393 GPS session point (32). Well was found to be an inactive oil well constructed with 8" surface casing and 4.5" casing. The 1" pump string and pump jack was missing from the well location. This well was hooked into the riser. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Dimoush 32).

Dimoush #33 API# 15-059-20672-00-00 SW NW NW 4224 FSL 4595 FEL Lat. 38.488895 Long. - 095.137449 GPS session point (33). Well was found to be an inactive oil well constructed with 4.5" casing, 2" tubing, 1" pump string and a pump jack that the bridal was broke on. This well didn't have any surface control. Well is listed as Producing "PR" on operator's well inventory. . See attached photo numbered (Dimoush 33).

Dimoush #36 API# 15-059-20674-00-00 NE SW NW 3710 FSL 3976 FEL Lat: 38.487482 Long: -95.135273 GPS session point (36). Well is an active authorized EOR well-constructed with 8" surface casing and 4.5" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 10/05/2017. Staff did witness this test. Well is listed as Active "Al" on operator's well inventory.

Dimoush #37 API# 15-059-20675-00-00 SE SW NW 3126 FSL 3785 FEL Lat. 38.485876 Long. -95.134591 GPS session point (37). Well was found to be a producing oil well constructed with 4.5" casing, 2"tubing, 1" pump string, and has a fully equipped pump jack. This well wasn't on operator's certified well inventory but on the inspection the well was fully equipped for production on the Dimoush lease. Haas Petroleum was added as the working operator and needs to complete a T-1 to transfer the well to their well inventory. Well is now listed as Producing "PR" on RBDMS well inventory with Haas Petroleum as the working operator. See attached photo numbered (Dimoush 37).

Dimoush #27 API# 15-059-20644-00-00 SE SW NW 3156 FSL 4058 FEL Lat. 38.485959 Long. -95.135545 GPS session point (27). Well was found to be a producing oil well constructed with 8" surface, 4.5" casing, 1" pump string, and has a fully equipped pump jack. This well wasn't on operator's certified well inventory but on the inspection the well was fully equipped for production on the Dimoush lease. Haas Petroleum was added as the working operator and needs to complete a T-1 to transfer the well to their well inventory. Well is now listed as Producing "PR" on RBDMS well inventory with Haas Petroleum as the working operator. See attached photo numbered (Dimoush 27).

Dimoush #28 API# 15-059-20645-00-00 SE SW NW 2867 FSL 4064 FEL Lat. 38.485167 Long. - 095.135561 GPS session point (28). Well was found to be an inactive oil well constructed with 4.5" casing and 2" tubing. The 1" pump string was missing from the well location and the pump jack was missing the belt and motor. This well didn't have any surface control. Well is listed as Producing "PR" on operator's well inventory. . See attached photo numbered (Dimoush 28).

Dimoush #26 API# 15-059-20643-00-00 NE SW NW 3438 FSL 4009 FEL Lat. 38.486735 Long. -95.135381 GPS session point (26). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #25 API# 15-059-20642-00-00 NW SE NW 3486 FSL 3434 FEL Lat: 38.486864 Long: -95.133376 GPS session point (25). Well is an active authorized EOR well-constructed with 8" surface casing and 4.5" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 10/05/2017. Staff did witness this test. Well is listed as Active "Al" on operator's well inventory.

Dimoush #22 API# 15-059-20559-00-00 SW SE NW 3202 FSL 3410 FEL Lat. 38.486083 Long. - 095.133283 GPS session point (22). Well was found to be an inactive oil well constructed with 2.5" casing, 1" pump string, and a pump jack that was missing the motor and belt. This well didn't have any surface control. This well was not listed on Haas's certified well inventory but is now listed as inactive "IN" on operator's well inventory. This well was added to Haas's well inventory due to falling within the area of review (AOR) of 12 injection wells that are on Haas's license. See attached photo numbered (Dimoush 22).

Dimoush #23 API# 15-059-20560-00-00 NW SE NW 3549 FSL 3114 FEL Lat. 38.487035 Long. -95.132259 GPS session point (23). Well was found to be an inactive oil well constructed with 4.5" casing. The 1" pump string has been pulled and is laying beside the well. The pump jack was also missing the belt. This well was shut in with a valve and swedge. Well is listed as Producing "PR" on operator's well inventory. . See attached photo numbered (Dimoush 23).

Dimoush #24 API# 15-059-20561-00-00 SW SE NW 3251 FSL 3117 FEL Lat. 38.486218 Long. -95.132261 GPS session point (24). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #13 API# 15-059-20506-00-00 SE SE NW 3207 FSL 2811 FEL Lat. 38.486095 Long. -95.131192 GPS session point (13). Well was

found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #5 API# 15-059-20478-00-00 NE SE NW 3970 FSL 2814 FEL Lat. 38.488190 Long. -95.131220 GPS session point (5). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #16 API# 15-059-20521-00-00 SW NE NW 4496 FSL 3181 FEL Lat. 38.489635 Long. -95.132514 GPS session point (16). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #14 API# 15-059-20507-00-00 SE SE NW 2912 FSL 2977 FEL Lat: 38.485285 Long: -95.131765 GPS session point (14). Well is an active authorized EOR well-constructed with 8" surface casing and 4.5" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 09/29/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dimoush #12 API# 15-059-20503-00-00 NE SE NW 3604 FSL 2827 FEL Lat: 38.487187 Long: -95.131257 GPS session point (12). Well is an active authorized EOR well-constructed with 8" surface casing and 4.5" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 09/29/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dimoush #4 API# 15-059-20477-00-00 SE NE NW 4279 FSL 2815 FEL Lat: 38.489040 Long: -95.131231 GPS session point (4). Well is an active authorized EOR well-constructed with 8" surface casing and 4.5" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 09/29/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Dimoush #15-HP API# 15-059-27140-00-00 NE SE NW 3738 FSL 2798 FEL Lat. 38.487553 Long. - 95.131157 GPS session point (15-HP). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #38 API# 15-059-21780-00-00 SW SE NW 3202 FSL 3410 FEL Lat. 38.486083 Long. - 095.133283 GPS session point (38). Well was found to be an inactive oil well constructed with 4.5" casing, 2" tubing, and 1" pump string with a stuffing box. The pump jack that was missing from the well location. This well was not listed on Haas's certified well inventory but is now listed as inactive "IN" on operator's well inventory. This well was added to Haas's well inventory due to falling within the area of review (AOR) of 20 injection wells that are on Haas's license. See attached photo numbered (Dimoush 38).

Dimoush #18 API# 15-059-20523-00-00 NW SE NW 3855 FSL 3119 FEL Lat. 38.487875 Long. -95.132284 GPS session point (18). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #34 API# 15-059-20671-00-00 NW SE NW 3713 FSL 3339 FEL Lat. 38.487488 Long. -95.133048 GPS session point (34). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #20 API# 15-059-20576-00-00 SW NE NW 4409 FSL 3484 FEL Lat. 38.489399 Long. -95.133569 GPS session point (20). Well was found to be a producing oil well constructed with 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dimoush #17 API# 15-059-20522-00-00 SW NE NW 4190 FSL 3156 FEL Lat. 38.488796 Long. -95.132420 GPS session point (17). Well was found to be an inactive oil well constructed with 8" surface and 4.5" casing. The 1" pump string has been pulled and is laying beside the well. This well did not have any surface control. Well is listed as Producing "PR" on operator's well inventory. . See attached photo numbered (Dimoush 17).

Dimoush #29 API# 15-059-20651-00-00 SW SE NW 2903 FSL 3258 FEL Lat. 38.485263 Long. -95.132747 GPS session point (29). Well was found to be an inactive oil well constructed with 8" surface casing and 4.5" casing. The 1" pump string the pump jack were missing from the well location. This well did not have any surface control. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Dimoush 29).


Dimoush #35 API# 15-059-20673-00-00 SW NE NW 4022 FSL 3353 FEL Lat. 38.488336 Long. -95.133105 GPS session point (35). Well was found to be a plugged injection well constructed with 8" surface casing and 4.5" casing. This well needs to be cutoff and buried below plow depth Well is listed as Plugged and Abandoned "PA" on operator's well inventory. . See attached photo numbered (Dimoush 35).

These approved intents to drill "PW" were not located at surface at the spot locations provided by operator:

Dimoush 18I-HP API# 15-059-27141-00-00

Dimoush 4I-HP API# 15-059-27135-00-00

In conclusion, I found forty-three (43) wells on the lease which included twenty (20) producing oil wells, eight (8) active injection wells, ten (10) inactive oil wells, two (2) inactive injection wells, and one (1) plugged well. No wells were found at any of the two (2) permitted well locations per operator footages. Three (3) producing oil wells and two (2) inactive oil wells were not listed on operator well inventory. A photo of each of the thirteen (13) wells out of compliance, and a photo of the other three (3) wells that need transferred to Haas's license have been attached to this report. Also attached to this report is a google map with the session points which are the same as the well numbers are attached to this report. Operator well inventory shows no inactive wells.





Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #6

FSL: 5127

FEL: 3071

API#: 15-059-20496-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #6

PIC Orientation:

Latitude: 38.491369

Longitude: -95.132143

Time: 9:18 AM

Additional Information: This is a photo of well #6. This well is hooked into flow



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #7

FSL: 5075

FEL: 3373

API#: 15-059-01213-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #7

PIC Orientation:

Latitude: 38.491226

Longitude: -95.133200

Time: 9:23 AM

Additional Information: This is a photo of well #7. This well is missing the pump jack and pump string. This well is not shut in



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #17

FSL: 4190

FEL: 3156

API#: 15-059-20522-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #17

PIC Orientation:

Latitude: 38.488796

Longitude: -95.132420

Time: 12:39 PM

Additional Information: This is a photo of well #17. The pump string has been pulled and is lying beside the well. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #19

FSL: 4728

FEL: 3426

API#: 15-059-20575-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #19

PIC Orientation:

Latitude: 38.490273

Longitude: -95.133376

Time: 10:25 AM

Additional Information: This is a photo of well #30. This well is shut in with a valve and swedge. The injection line wasn't hooked up to the well at the time of inspection.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #22

FSL: 3202

FEL: 3410

API#: 15-059-20559-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #22

PIC Orientation:

Latitude: 38.486083

Longitude: -95.133283

Time: 11:32 AM

Additional Information: This is a photo of well #22. This well is fully equipped for production except for missing the electric motor and belt. This well wasn't listed on Haas's certified well inventory.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #23

FSL: 3549

FEL: 3114

API#: 15-059-20560-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #23

PIC Orientation:

Latitude: 38.487035

Longitude: -95.132259

Time: 12:06 PM

Additional Information: This is a photo of well #23. The pump string has been pulled and is lying beside the well. The well is shut in with a valve and swedge.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #27

FSL: 3156

FEL: 4058

API#: 15-059-20644-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #27

PIC Orientation:

Latitude: 38.485959

Longitude: -95.135545

Time: 11:13 AM

Additional Information: This is a photo of well #27. This well is fully equipped for production. This well wasn't listed on Haas's certified well inventory.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #28

FSL: 2867

FEL: 4064

API#: 15-059-20645-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #28

PIC Orientation:

Latitude: 38.485167

Longitude: -95.135561

Time: 11:10 AM

Additional Information: This is a photo of well #28. The pump string is missing from this well and the well is not shut in.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #29

FSL: 2903

FEL: 3258

API#: 15-059-20651-00-00

Date: 09/03/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #29

PIC Orientation:

Latitude: 38.485263

Longitude: -95.132747

Time: 10:07 AM

Additional Information: This is a photo of well #29. This well is missing a pump string, pump jack, and surface control.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #30

FSL: 4858

FEL: 4197

API#: 15-059-20652-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #30

PIC Orientation:

Latitude: 38.490634

Longitude: -95.136073

Time: 9:42 AM

Additional Information: This is a photo of well #30. This well is shut in with a valve and swedge. The injection line wasn't hooked up to the well at the time of inspection.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #31

FSL: 4824

FEL: 4551

API#: 15-059-20656-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #31

PIC Orientation:

Latitude: 38.490540

Longitude: -95.137309

Time: 9:40 AM

Additional Information: This is a photo of well #31. This well is fully equipped for production. This well wasn't listed on Haas's certified well inventory.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #32

FSL: 4511

FEL: 4577

API#: 15-059-20657-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #32

PIC Orientation:

Latitude: 38.489681

Longitude: -95.137393

Time: 10:40 AM

Additional Information: This is a photo of well #32. This well is missing the pump jack and pump string. The well is hooked into the riser.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #33

FSL: 4224

FEL: 4595

API#: 15-059-20672-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #33

PIC Orientation:

Latitude: 38.488895

Longitude: -95.137449

Time: 10:40 AM

Additional Information: This is a photo of well #33. The bridal is broke that connects the pump string to the pump jack.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #35

FSL: 4022

FEL: 3353

API#: 15-059-20673-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #35

PIC Orientation:

Latitude: 38.488336

Longitude: -95.133105

Time: 1:37 PM

Additional Information: This is a photo of well #35. This well is plugged and abandoned but needs to be cutoff and buried below plow depth.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #37

FSL: 3126

FEL: 3785

API#: 15-059-20675-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #37

PIC Orientation:

Latitude: 38.485876

Longitude: -95.134591

Time: 11:06 AM

Additional Information: This is a photo of well #37. This well is fully equipped for production. This well wasn't listed on Haas's certified well inventory.



Operator: Haas Petroleum, LLC

Lease: Dimoush

County: FR

Subject: Dimoush #38

FSL: 4130

FEL: 2913

API#: 15-059-21780-00-00

Date: 09/01/2021

Staff: Keith Carswell

KLN: 33640

Legal: 18-18-21E

PIC ID#: Dimoush #38

PIC Orientation:

Latitude: 38.488630

Longitude: -95.131568

Time: 12:27 PM

Additional Information: This is a photo of well #22. This well is missing the pump jack but has a pump string.

| Inspection Date: | 08/25/2021 | District: | 3 | Incident Number: | | | | 7627 |
|---|------------------|------------------|----------|------------------|----------------|---------------|-------------|------|
| | ✓ | New Situation | | ✓ Lea | se Inspectio | n | | |
| | ✓ | Response to R | equest | ☐ Con | nplaint | | | |
| | | Follow-up | | ✓ Field | d Report | | | |
| Operator License No | o: 33640 | API: | | | Q3: | Q2: | Q1: | SE |
| Operator Name: Ha | aas Petroleum, | LLC | SE | C 8 | TWP 18 | RGE 21 | RGEDIR: | Ε |
| Address: P.O. Box | | | | | | FSL: | | |
| City: Prairie Villa | • | | | | | FEL: | | |
| • | Code: 66208 | | ase: [| Oreher | | Vell No.: | | |
| Phone contact: Reason for Investigation | 913-499-8373 | 3 | | | Coun | ty: FR | | |
| Request from Wichita | | | | | | | | |
| request from vviolite | 4 | | | | | | | |
| 5 | | | | | | | | |
| Problem: | | | | | | | | |
| To confirm location, v | vell status, and | I number of we | lls on o | perator's | inventory. | | | |
| | | | | | | | | |
| Persons contacted: | <u>:</u> | | | | | | | |
| Haas Petroleum pun | npers Terry and | d Chad | | | | | | |
| | | | | | | | | |
| Findings: | | | | | | | | |
| Research of the Dreh | | | | | | | | |
| the current operator v (EOR) injection wells | | | | | | | | ry |
| inventory. I performe | | | | | | | | S |
| with GPS and took a | prioto oi each | well location. I | Jocume | entation o | i trie wells i | ocated is iis | sted below. | |
| Dreher #10 API# 15- 095.110397 GPS se | | | | | | | , | _ |
| casing, 1" pump string | | | | | | | | |
| operator's well invent | ory. | | | | | | | |
| (continued on page 2 | 2) | | | | | | | |
| | | | | | | | | |
| Actions / Recommen | <u>ndations</u> | Follow-up R | equire | _ <u>k</u> | <u>Deadl</u> | ine Date: | | |
| I will forward this repo | | | | | | | | |
| Haas Petroleum, LLC to plug, produce, or o | | | | | | | | |
| oil wells are the Drehe | er #11 API #15 | 5-059-01106-00 | 0-00, Dr | eher #3 / | API #15-059 | 9-01098-00- | 00, Dreher | #5 |
| API #15-059-01100-0 that a thirty (30) day N | | | | | | | | |
| to be properly comple | | | | | | | | |
| | | | | | Photo's | Taken: | 5 | |
| ▼ RBDMS ▼ KGS | ☐ KOL | AR Report F | Prepare | d By: | Keith Carsy | <u>vell</u> | | |
| ✓ D | istrict Files | Courthouse | P | osition: | E.C.R.S. | | | |

Additional Findings:

(continued from page 1)

Dreher #11 API# 15-059-01106-00-00 NE SE SW SE 545 FSL 1425 FEL Lat: 38.493258 Long: -095.107886 GPS session point (11). Well was found to be an inactive oil well constructed with 2.5 inch casing and is connected to the riser in case well begins to flow. The 1 inch has been pulled and is lying beside the well. The pump jack is also at the well site. There has been no CP-111 application filed for this well at the time of inspection. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Dreher 11).

Dreher #2 API# 15-059-01097-00-00 SW NE SW SE 849 FSL 1743 FEL Lat: 38.494097 Long:-095.108991 GPS session point (2). Well was found to be a producing oil well constructed with 2.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dreher #3 API# 15-059-01098-00-00 NE NW SW SE 1139 FSL 2105 FEL Lat: 38.494898 Long: -095.110246 GPS session point (3). Well was found to be an inactive oil well constructed with 6" surface casing, 2.5" casing and is connected to the riser in case well begins to flow. The 1 inch has been pulled and is lying beside the well. The pump jack is also at the well site. There has been no CP-111 application filed for this well at the time of inspection. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Dreher 3).

Dreher #4 API# 15-059-01099-00-00 SW NW SW SE 883 FSL 2417 FEL Lat:38.494200 Long:-095.111343 GPS session point (4). Well was found to be a producing oil well constructed with 2.5" casing, 1" pump string, and pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dreher #5 API# 15-059-01100-00-00 NW SE SW SE 562 FSL 1871 FEL Lat: 38.493310 Long: -095.109445 GPS session point (5). Well was found to be an inactive oil well constructed with 2.5 inch casing and is shut in with a valve and swedge. Well is listed as Producing "PR" on operator's well inventory. This well needs status changed to Inactive "IN" and the operator needs to either obtain an approved CP-111, plug the well, or return the well to service. See attached photo numbered (Dreher 5).

Dreher #6 API# 15-059-01101-00-00 NE SW SW SE 590 FSL 2146 FEL Lat: 38.493390 Long: -095.110406 GPS session point (6). Well was found to be a producing oil well constructed with 2.5" casing, 1" pump string, and pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dreher #7 API# 15-059-01102-00-00 NW SW SW SE 504 FSL 2450 FEL Lat: 38.493159 Long: -095.111471 GPS session point (7). Well was found to be a producing oil well constructed with 2.5" casing 1" pump string, and pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dreher #8 API# 15-059-01103-00-00 SW SE SW SE 188 FSL 1828 FEL Lat: 38.492283 Long:-095.109304 GPS session point (8). Well was found to be an inactive oil well constructed with 2.5" casing and is connected to the riser in case well begins to flow. There is a pump jack at the well site. There has been no CP-111 application filed for this well at the time of inspection. Well is listed as Producing "PR" on operator's well inventory. See attached photo numbered (Dreher 8).

Dreher #9 API# 15-059-01104-00-00 SW SW SW SE 197 FSL 2454 FEL Lat: 38.492316 Long:-095.111492 GPS session point (9). Well was found to be a producing oil well constructed with 2.5" casing, 1" pump string, and a pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dreher #BSI-DR1 API# 15-059-25998-00-00 SW SW SW SE 79 FSL 2561 FEL Lat: 38.491993 Long: -095.111870 GPS session point (BSI-DR1). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/12/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Dreher #BSI-DR10 API# 15-059-26005-00-00 SE SE SW SE 321 FSL 1332 FEL Lat: 38.492643 Long: -095.107569 GPS session point (BSI-DR10). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 05/09/2017. This test was witnessed by District # 3 staff. Well is listed as Active "AI" on operator's well inventory.

095.111948 GPS session point (BSI-DR11). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/12/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dreher #BSI-DR12 API# 15-059-26020-00-00 SE NW SW SE 703 FSL 2291 FEL Lat: 38.493703 Long:-095.110908 GPS session point (BSI-DR12). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/12/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Dreher #BSI-DR13 API# 15-059-26021-00-00 SW NE SW SE 723 FSL 1982 FEL Lat: 38.493753 Long: -095.109828 GPS session point (BSI-DR13). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/12/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dreher #BSI-DR14 API# 15-059-26022-00-00 NE SE SW SE 609 FSL 1639 FEL Lat: 38.493438 Long: -095.108632 GPS session point (BSI-DR14). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 05/09/2017. This test was witnessed by District # 3 staff. Well is listed as Active "AI" on operator's well inventory.

Dreher #BSI-DR15 API# 15-059-26006-00-00 SW NW SE SE 676 FSL 1267 FEL Lat: 38.493617 Long:-095.107333 GPS session point (BSI-DR15). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 05/09/2017. This test was witnessed by District # 3 staff. Well is listed as Active "AI" on operator's well inventory.

Dreher #BSI-DR16 API# 15-059-26023-00-00 NW NW SW SE 1133 FSL 2321 FEL Lat 38.494885 Long: -095.111002 GPS session point (BSI-DR16). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/12/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dreher #BSI-DR17 API# 15-059-26024-00-00 NE SW SE SE 371 FSL 955 FEL Lat 38.492777 Long: - 095.106250 GPS session point (BSI-DR17). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/10/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dreher #BSI-DR2 API# 15-059-25999-00-00 SE SW SW SE 58 FSL 2294 FEL Lat 38.491933 Long: - 095.110938 GPS session point (BSI-DR2). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/12/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dreher #BSI-DR3 API# 15-059-26000-00-00 SW SE SW SE 34 FSL 1962 FEL Lat 38.492085 Long: - 095.109777 GPS session point (BSI-DR3). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/12/2017. Staff did not witness this test. Well is listed as Active "Al" on operator's well inventory.

Dreher #BSI-DR4 API# 15-059-26001-00-00 SW SE SW SE 116 FSL 1674 FEL Lat 38.492085 Long - 095.108768 GPS session point (BSI-DR4). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/12/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dreher #BSI-DR5 API# 15-059-26002-00-00 SE SE SW SE 68 FSL 1329 FEL Lat 38.491949 Long:-095.107567 GPS session point (BSI-DR5). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT)

was completed on 05/09/2017. This test was witnessed by District # 3 staff. Well is listed as Active "AI" on operator's well inventory.

Dreher #BSI-DR6 API# 15-059-26003-00-00 NW SW SW SE 362 FSL 2582 FEL Lat 38.492769 Long: -095.111933 GPS session point (BSI-DR6). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 06/12/2017. Staff did not witness this test. Well is listed as Active "AI" on operator's well inventory.

Dreher #BSI-DR7 API# 15-059-26004-00-00 NE SW SW SE 373 FSL 2266 FEL Lat 38.492796 Long: -095.110830 GPS session point (BSI-DR7). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 05/09/2017. This test was witnessed by District # 3 staff. Well is listed as Active "Al" on operator's well inventory.

Dreher #BSI-DR8 API# 15-059-26017-00-00 NE SW SW SE 363 FSL 1995 FEL Lat 38.492765 Long: - 095.109883 GPS session point (BSI-DR8). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT's and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 05/09/2017. This test was witnessed by District # 3 staff. Well is listed as Active "Al" on operator's well inventory.

Dreher #BSI-DR9 API# 15-059-26018-00-00 SE SE SW SE 306 FSL 1590 FEL Lat 38.492604 Long: -095.108469 GPS session point (BSI-DR9). Well is an active authorized EOR well constructed with 7" surface casing and 2.875" casing. Well is current on MIT and U3C's. A satisfactory Mechanical Integrity Test (MIT) was completed on 05/09/2017. This test was witnessed by District # 3 staff. Well is listed as Active "Al" on operator's well inventory.

Dreher #BSP-DR1 API# 15-059-26007-00-00 NW NW SW SE 1168 FSL 2452 FEL Lat 38.494981 Long:-095.111456 GPS session point (BSP-DR1). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and a pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dreher #BSP-DR10 API# 15-059-26016-00-00 SW SW SE SE 209 FSL 1121 FEL Lat 38.492333 Long - 095.106836 GPS session point (BSP-DR10). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and a pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dreher #BSP-DR13 API# 15-059-26275-00-00 NE NW SE SE 1061 FSL 882 FEL Lat 38.494669 Long: -095.105975 GPS session point (BSP-DR13). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and a pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dreher #BSP-DR6 API# 15-059-26012-00-00 SE NE SW SE 809 FSL 1422 FEL Lat 38.494065 Long: -095.107868 GPS session point (BSP-DR6). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and a pump jack. Well is listed as Producing "PR" on operator's well inventory.


Dreher #BSP-DR7 API# 15-059-26013-00-00 SW NW SE SE 839 FSL 1188 FEL Lat 38.493983 Long: -095.107050 GPS session point (BSP-DR7). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and a pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dreher #BSP-DR8 API# 15-059-26014-00-00 NW SW SE SE 502 FSL 1120 FEL Lat: 38.493137 Long: -095.106823 GPS session point (BSP-DR8). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and a pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dreher #BSP-DR9 API# 15-059-26015-00-00 SE SE SW SE 221 FSL 1479 FEL Lat: 38.492369 Long: -095.108084 GPS session point (BSP-DR9). Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and a pump jack. Well is listed as Producing "PR" on operator's well inventory.

Dreher #OW-1 API# 15-059-01608-00-00 NW SW SW SE 604 FSL 2422 FEL Lat: 38.493434 Long: -095.111369 GPS session point (OW-1). Well was found to be an inactive oil well constructed with 7" surface casing only. Well has no production casing visible at surface. This well has oil visible inside the surface casing and is bubbling. Fluid level is approximately 8-10 ft. down from surface. There is also an open pit next to the surface casing that has oil in it. This well needs to be drilled down and production casing set or well needs to be plugged. Well shows out of compliance on KOLAR for needing a CP-111 filed on it. Operator will not be able to obtain an approved CP-111 because there is no production casing and appears well was never completed. Well is listed as Inactive "IN" on operator's well inventory. See attached photo numbered (Dreher OW-1).

In conclusion, I found thirty-five (35) wells on the lease, thirteen (13) active oil wells, seventeen (17) active injection wells, and five (5) inactive oil wells that are out of compliance. A photo of each of the five (5) wells out of compliance and a google map with the session points which are the same as the well numbers are attached to this report. Operator well inventory only shows one (1) inactive well.





Operator Management

Close Summary

Summary for Haas Petroleum

Users in KOLAR Group of Haas Petroleum • David Griffin • Jackie Windisch • Julie Barber • Mark Haas • Morgan Haas

| Operator Summary | | | | | | |
|----------------------|---------------------|--|--|--|--|--|
| Company | Haas Petroleum | | | | | |
| KCC License | 33640 | | | | | |
| Compliance Evaluated | 10/18/2021 11:13 AM | | | | | |

| View | Count |
|--------------------------------|-------|
| Wells in Inventory | 1,517 |
| Wells with Future Requirements | 315 |
| Wells Out of Compliance | 111 |
| CDP5 | 2 |
| CP111 O | 75 |
| MIT O | 30 |
| U3C O | 5 |

Wells Out of Compliance



To filter data, enter one or more words in the Search box. Search: dreher

Click to populate Search box: CDP5 CP111 MIT U3C Clear

| Detail | API Number | Lease and Well Name | Location | County | Requirement | Received | Required by |
|--------|--------------------|---------------------|------------|----------|-------------|----------|-------------|
| Detail | 15-059-01608-00-00 | DREHER OW-1 | 08-18S-21E | Franklin | CP111 | | 06/05/2016 |

Showing 1 to 1 of 1 entries (filtered from 112 total entries)

https://kolar.kgs.ku.edu/kcc/management.v.1/?KCCLicense=33640&submit=Submit

Previous

Next



Operator: Haas Petroleum, LLC

Lease: Dreher

County: FR

Subject: Dreher 3

FSL: 1139

FEL: 2105

API#: 15-059-01098-00-00

Date:8/23/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-18-21E

PIC ID#: 3

PIC Orientation:

Latitude: 38.494898

Longitude: 095.110246

Time: 12:20 PM

Additional Information: This is a photo of well #3. This shows the well hooked into the riser. This photo also shows the 1 inch laying beside the well and a pump jack at the well location



Operator: Haas Petroleum, LLC

Lease: Dreher

County: FR

Subject: Dreher 5

FSL: 562

FEL: 1871

API#: 15-059-01100-00-00

Date:8/23/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-18-21E

PIC ID#: 5

PIC Orientation:

Latitude: 38.493310

Longitude: -095.109445

Time: 11:21 AM

Additional Information: This well is inactive but is listed as an active producing oil well on operator's inventory. This well needs status changed to inactive and the operator needs to either file a CP-111, plug the well, or return the well to service. This well has 2.5 inch casing and is shut in with a valve and swedge.



Operator: Haas Petroleum, LLC

Lease: Dreher

County: FR

Subject: Dreher 8

FSL: 188

FEL: 1828

API#: 15-059-01103-00-00

Date:8/23/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-18-21E

PIC ID#: 8

PIC Orientation:

Latitude: 38.492283

Longitude: -95.109304

Time: 11:15 AM

Additional Information: This is a photo of well #8. This shows the well hooked into the riser.



Operator: Haas Petroleum, LLC

Lease: Dreher

County: FR

Subject: Dreher 11

FSL: 545

FEL: 1425

API#: 15-059-01106-00-00

Date:8/24/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-18-21E

PIC ID#: 11

PIC Orientation:

Latitude: 38.493258

Longitude: -095.107886

Time: 10:21 AM

Additional Information: This is a photo of well #11. This shows the well hooked into the riser.



Operator: Haas Petroleum, LLC

Lease: Dreher

County: FR

Subject: Dreher OW-1

FSL: 604

FEL: 2422

API#: 15-059-01608-00-00

Date: 8/23/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-18-21E

PIC ID#: OW-1 Pic 1


PIC Orientation:

Latitude: 38.493310

Longitude: -095.109445

Time: 11:41 AM

Additional Information: This is a photo of well #OW-1. This shows 7 inch surface with no production casing visible at surface.



Operator: Haas Petroleum, LLC

Lease: Dreher

County: FR

Subject: Dreher OW-1

FSL: 604

FEL: 2422

API#: 15-059-01608-00-00

Date: 8/23/2021

Staff: Keith Carswell

KLN: 33640

Legal: 8-18-21E

PIC ID#: OW-1 Pic 2

PIC Orientation:

Latitude: 38.493310

Longitude: -095.109445

Time: 11:42 AM

Additional Information: This picture shows the open pit that has oil standing in it next to the well head of OW-1

| Inspection Date: | 09/13/20 | 21 | District: | 3 | | Incide | ent N | umber: | | 7767 |
|---|-----------------|---------------|--------------|-----------|------------|----------|---------|-------------|--------------|------|
| | | ✓ New | Situation | | ✓ Lea | se Insp | ectio | า | | |
| | | ✓ Resp | onse to R | equest | ☐ Cor | mplaint | | | | |
| | | ☐ Follo | w-up | | ✓ Fiel | d Repo | rt | | | |
| Operator License No | o: 33640 | | API: | | | (| Q3: | Q2: | Q1: | |
| Operator Name: Ha | aas Petrole | eum, LLC | | SE | C 4 | TWP | 16 | RGE 21 | RGEDIR: | Е |
| Address: P.O. Box | 8396 | | | | | | | FSL: | | |
| City: Prairie Villa | ıge | | | | | | | FEL: | | |
| • | Code: 66 | | Le | ase: E | E. Lidika | | | ell No.: | | |
| Phone contact: | 913-499-8 | 8373 | | | | C | Count | y: FR | | |
| Reason for Investiga | | | | | | | | | | |
| Request from Wichita | 1 | | | | | | | | | |
| | | | | | | | | | | |
| Problem: | | | | | | | | | | |
| To confirm location, w | vell status, | and nur | nber of we | lls on o | perator's | invento | ory. | | | |
| | | | | | | | | | | |
| Persons contacted: | : | | | | | | | | | |
| Haas Pumper Shawr | _ | | | | | | | | | |
| • | | | | | | | | | | |
| Findings: | | | | | | | | | | |
| Research of the E. Li | | | | | | | | | | |
| current operator with (EOR) injection wells | | | | | | | | | | |
| abandoned wells, and | d twenty-six | x (26) ex | pired inten | ts on th | eir certif | ied wel | I inver | ntory. I pe | rformed the | |
| lease inspection 9/13 each well location. D | | | | | | | ith GF | 'S and too | k a photo of | f |
| | | | e wells look | atod io i | iotou bo | iow. | | | | |
| (continued on page 2 |) | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Actions / Recommen | <u>ndations</u> | Fo | llow-up R | equired | <u>ı</u> 🗆 | D | eadlir | ne Date: | | |
| I will forward this repo | ort on to Di | strict # 3 | Complian | ce Offic | er for re | view. It | t is my | / recomme | endation tha | at |
| Haas Petroleum, LLC to plug, produce, or o | | | | | | | | | | ine |
| twenty-nine inactive w | | | | | | | | | | |
| API#1505926868000 API#1505919872000 | | | | | | | | | | |
| API#1505926890000 | | | | T 10008 | 1301400 | ,00, LA | O I LII | DIIVAI #1 | O-1 II | |
| | | | | | | Pho | to's | Гaken: | 44 | |
| ✓ RBDMS ✓ KGS | | KOLAR | Report P | repare | d By: | Keith C | Carsw | <u>ell</u> | | |
| ✓ D | istrict Files | s \square C | ourthouse | Po | sition: | E.C. | R.S. | | | |

Additional Findings:

(continued from page 1 Actions/Recommendations)

EAST LIDIKAY #17 F API#15059195900000, EAST LIDIKAY #19 F API#15059195920000, EAST LIDIKAY #3 API#15059198690000, EAST LIDIKAY #38-HP API#15059269700000, EAST LIDIKAY #3-HP API#15059268880000, EAST LIDIKAY #42 API#15059198780000, EAST LIDIKAY #43-HP API#15059269730000, EAST LIDIKAY #48-HP API#15059269930000, EAST LIDIKAY #49-HP API#15059251780000, EAST LIDIKAY #50-HP API#15059251790000, EAST LIDIKAY #52-HP API#15059270380000, EAST LIDIKAY #54-HP API#15059270350000, EAST LIDIKAY #55-HP API#15059270300000, EAST LIDIKAY #5-HP API#15059268690000, EAST LIDIKAY #5I-HP API#15059268940000, EAST LIDIKAY #8 API#15059195790000, EAST LIDIKAY #9-HP API#15059268890000, LIDIKAY #1 F W API#15059198950001, LIDIKAY #10 W 3 F API#15059198890001, LIDIKAY #10 W 6 API#15059198910001, LIDIKAY #20 F API#15059195930000, LIDIKAY #27 API#15059211520000, LIDIKAY #7 F W API#15059198930001. The well status needs to be changed to inactive for all of the previous twenty-nine (29) wells listed above. It is my further recommendation that a thirty (30) day NOV letter be sent stating that the thirteen (13) wells found at surface and listed as plugged and abandoned need to be ran in until cement is tagged, then topped off with cement to surface, then cut-off and buried below plow depth. It also needs to state that a KCC representative needs to be on all locations to verify the well is plugged. Those thirteen (13) wells are as follows: EAST LIDIKAY #13 API#15059198730000, DR LIDIKAY #11 W 3 API#15059199000001, EAST LIDIKAY #14F API#15059195880000, EAST LIDIKAY #15F API#15059198750000, LIDIKAY #10 W 2 API#15059198860001, LIDIKAY #10 W 4 API#15059198960001, LIDIKAY #11 W 1 API#15059198900001, LIDIKAY #11 W 10 API#15059198810001, LIDIKAY #11 W 11 API#15059198800001, LIDIKAY #11 W 9 API#15059198820001, LIDIKAY #11F API#15059195870000, LIDIKAY #12 W 6 API#15059199010001, LIDIKAY #5 F W API#15059198940001.

(continued from page 1 Findings)

DR LIDIKAY #11 W 3 API#15059199000001 NE NE SE 2045 FSL 146 FEL Lat. 38.686627 Long. - 095.084729 GPS session point (11-W-3) Well was found to be Plugged and Abandoned "PA" with 8" surface casing and 2" casing still above ground. Operator reported they plugged this well on 1/9/2015. KCC staff did not witness this plugging. Operator did not complete a Plugging Application (CP-1) until 2/6/2015. Operator then filed a Well Plugging Record (CP-4) on 2/6/2015. KCC staff completed a Well Plugging Report (CP-2/3) on 3/24/2015. A Copy of the CP-1, CP-4, and CP-2/3 are attached to this report. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface. Well is listed as Plugged and Abandoned "PA" on operator well inventory. See attached photo numbered (Lidikay 11-W-3)

E. LIDIKAY #18F API#15059195910000 SE SW SE 441 FSL 1444 FEL Lat. 38.682223 Long. - 095.089229 GPS session point (18-F) Well was found to be a producing oil well constructed with 2" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

E. LIDIKAY #2F API#15059198680000 SE SE SE 71 FSL 147 FEL Lat. 38.681206 Long. -095.084672 GPS session point (2-F) Well was found to be an inactive oil well constructed with 4" casing. The casing is open and has no surface control. The top of the casing is at ground level. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 2F).

EAST LIDIKAY #1 API#15059198670000 SE SW SE 143 FSL 1776 FEL Lat. 38.681405 Long. - 095.090381 GPS session point (1) Well was found to be a producing oil well constructed with 2" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #10-HP API#15059268680000 NW NE SE 2155 FSL 1174 FEL Lat. 38.686928 Long. - 095.088336 GPS session point (10-HP) Well was found to be an inactive oil well constructed with 7" surface casing, 2.875" casing, 1" pumping string and a pump jack. Pump jack is not totally equipped as it is missing a belt. There is no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 10-HP).

EAST LIDIKAY #11-HP API#15059268710000 NW NE SE 2155 FSL 867 FEL Lat. 38.686928 Long. - 095.087260 GPS session point (11-HP) Well was found to be an active unauthorized EOR well constructed with 7" surface casing and 2.875" casing. This well was hooked up and being used for injection of fluids. Pumper was contacted and told to unhook this well immediately as the well was not authorized with 60 and 10 and

Page 157 of 276

purposes. Pumper had the well unhooked 9/29/2021 when I returned. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 11-HP).

EAST LIDIKAY #11I-HP API#15059268930000 NW NE SE 1955 FSL 1299 FEL Lat. 38.686380 Long. - 095.088765 GPS session point (11I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 3/6/2020 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #12F API#15059198720000 NW NE SE 2467 FSL 1222 FEL Lat. 38.687784 Long. - 095.088511 GPS session point (12-F) Well was found to be an inactive oil well constructed with 4.5" casing, 2" tubing, 1" pumping string and a pump jack. The pump jack is not totally equipped as it is missing an electric motor and a belt. There is no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 12-F).

EAST LIDIKAY #12I-HP API#15059268970000 NW NE SE 1982 FSL 982 FEL Lat. 38.686453 Long. - 095.087655 GPS session point (12I-HP) NE NW SE 2306 FSL 1672 FEL Lat. 38.687343 Long. - 095.090083 GPS session point (3I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 3/6/2020 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #13 API#15059198730000 SE SE SE 427 FSL 458 FEL Lat. 38.682184 Long. - 095.085773 GPS session point (13) Well was found to be an inactive oil well constructed with 2" casing. This well is open with no surface control. There is also an open pit that is full of water at the well location. This well is listed as Plugged and Abandoned "PA" on operator well inventory. Operator reported they plugged this well on 6/24/2015. KCC staff did not witness this plugging. Operator did not complete a Plugging Application (CP-1) until 10/24/2016. Operator then filed a Well Plugging Record (CP-4) on 10/24/2016. KCC staff completed a Well Plugging Report (CP-2/3) on 2/10/2017. A Copy of the CP-1, CP-4, and CP-2/3 are attached to this report. No sign of cement around or inside the well casing. Well appears to have never been plugged. Operator will need to tag cement inside of the 2" casing and if this well is not plugged the operator should perforate the casing to insure proper plugging of the well. Operator will then be required to pump and circulate cement to surface before cutting off the casing below surface. See attached photo numbered (Lidikay 13)

EAST LIDIKAY #13F API#15059198740000 SW NE SE 1740 FSL 980 FEL Lat. 38.685789 Long. - 095.087642 GPS session point (13-F) Well was found to be an inactive oil well constructed with 4.5" casing and 1" pumping string hanging in 4.5" casing. There is no surface control. There is no pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 13-F).

EAST LIDIKAY #13I-HP API#15059269110000 NE NE SE 1933 FSL 323 FEL Lat. 38.686320 Long. - 095.085347 GPS Session point (13I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 2/20/2020 and KCC staff did witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #14F API#15059195880000 NE SE SE 704 FSL 597 FEL Lat. 38.682943 Long. - 095.086270 GPS session point (14-F) Well was found to be Plugged and Abandoned "PA" with 4.5" casing still above ground. Staff stuck a rod down the 4.5" casing and did not hit anything six feet down. Operator reported they plugged this well on 6/24/2015. KCC staff did not witness this plugging. Operator did not complete a Plugging Application (CP-1) until 10/21/2016. Operator then filed a Well Plugging Record (CP-4) on 10/21/2016. KCC staff completed a Well Plugging Report (CP-2/3) on 2/10/2017. A Copy of the CP-1, CP-4, and CP-2/3 are attached to this report. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface. Well is listed as Plugged and Abandoned "PA" on operator well inventory. See attached photo numbered (Lidikay 14-F)

EAST LIDIKAY #15F API#15059198750000 SW NE SE 1461 FSL 1025 FEL Lat. 38.685024 Long. - 095.087790 GPS session point (15-F) Well was found to be Plugged and Abandoned "PA" with 4.5" casing still above ground. Operator reported they plugged this well on 4/7/2015. KCC staff did not witness this plugging. Operator did not complete a Plugging Application (CP-1) until 4/21/2015. Operator then filed a Well Plugging Record (CP-4) on 4/21/2015. KCC staff completed a Well Plugging Report (CP-2/3) on 10/19/2015. A Copy of the CP-1, CP-4, and CP-2/3 are attached to this report. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface. Well is listed as Plugged and Abandoned "PA" on operator well KC-2a

inventory. See attached photo numbered (Lidikay 15-F)

EAST LIDIKAY #15-HP API#15059268900000 SE NW SE 1805 FSL 1467 FEL Lat. 38.685967 Long. - 095.089350 GPS session point (15-HP) Well was found to be an inactive oil well constructed with 7" surface casing, 2.875" casing, 1" pumping string and a pump jack. The pump jack is not totally equipped as it is missing an electric motor and belt. No stuffing box is present so there is no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 15-HP).

EAST LIDIKAY #17 F API#15059195900000 SE SE SE 130 FSL 471 FEL Lat. 38.681368 Long. - 095.085810 GPS session point (17-F) Well was found to be an inactive oil well constructed with 6" surface casing and 2.875" casing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 17-F).

EAST LIDIKAY #17-HP API#15059268730000 SE NE SE 1799 FSL 477 FEL Lat. 38.685950 Long. - 095.085881 GPS session point (17-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #18-HP API#15059268750000 SE NE SE 1843 FSL 171 FEL Lat. 38.686072 Long. - 095.084811 GPS session point (18-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #19 F API#15059195920000 NE NE SE 1941 FSL 604 FEL Lat. 38.686342 Long. - 095.086331 GPS session point (19-F) Well was found to be an inactive oil well constructed with 4.5" casing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 19-F).

EAST LIDIKAY #19I-HP API#15059269150000 SE NE SE 1621 FSL 604 FEL Lat. 38.685461 Long. - 095.086322 GPS session point (19I-HP) NE NW SE 2306 FSL 1672 FEL Lat. 38.687343 Long. - 095.090083 GPS session point (3I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 2/20/2020 and KCC staff did witness this test. Well is listed as Active "Al" on operator well inventory.

EAST LIDIKAY #20F API#15059198790000 SE NE SE 1538 FSL 95 FEL Lat. 38.685234 Long. - 095.084535 GPS session point (20-F) Well was found to be a producing oil well constructed 4.5" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #20I-HP API#15059269120000 SE NE SE 1667 FSL 274 FEL Lat. 38.685588 Long. - 095.085167 GPS session point (20I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 2/20/2020 and KCC staff did witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #23-HP API#15059268740000 SW NE SE 1443 FSL 724 FEL Lat. 38.684974 Long. - 095.086737 GPS session point (23-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #24-HP API#15059268760000 SE NE SE 1523 FSL 409 FEL Lat. 38.685193 Long. - 095.085635 GPS session point (24-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #25I-HP API#15059269170000 SE NE SE 1288 FSL 973 FEL Lat. 38.684549 Long. - 095.087605 GPS session point (25I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 3/6/2020 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #27I-HP API#15059269360000 SENESE 1373 FSL 246 FEL Lat. 38.684781 Long. - 095.085059 GSP Session point (27I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed an

3/6/2020 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #29-HP API#15059269370000 NW SE SE 1139 FSL 784 FEL Lat. 38.684139 Long. - 095.086938 GPS session point (29-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #3 API#15059198690000 SE SW SE 431 FSL 1724 FEL Lat. 38.682194 Long. - 095.090209 GPS session point (3) Well was found to be an inactive oil well constructed with 4.5" casing and 2" tubing. The casing is open and has no surface control. There is no pump string or pump jack. There is an open pit near the well. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 3).

EAST LIDIKAY #30-HP API#15059269210000 NE SE SE 1229 FSL 449 FEL Lat. 38.684386 Long. - 095.085766 GPS session point (30-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #31-HP API#15059269380000 NE SE SE 1181 FSL 164 FEL Lat. 38.684255 Long. - 095.084767 GPS session point (31-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #32I-HP API#15059269620000 NW SE SE 937 FSL 971 FEL Lat. 38.683584 Long. - 095.087585 GPS session point (32I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 7/13/2020 and KCC staff did witness this test. Well is listed as Active "Al" on operator well inventory.

EAST LIDIKAY #33I-HP API#15059269630000 NE SE SE 989 FSL 610 FEL Lat. 38.683728 Long. - 095.086322 GPS session point (33I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 5/11/2020 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #34I-HP API#15059269640000 NE SE SE 1007 FSL 314 FEL Lat. 38.683776 Long. - 095.085287 GPS session point (34I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 5/11/2020 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #35-HP API#15059269670000 NW SE SE 750 FSL 1135 FEL Lat. 38.683070 Long. - 095.088154 GPS session point (35-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #36-HP API#15059269680000 NW SE SE 839 FSL 811 FEL Lat. 38.683316 Long. - 095.087023 GPS session point (36-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #37-HP API#15059269690000 NE SE SE 847 FSL 493 FEL Lat. 38.683337 Long. - 095.085908 GPS session point (37-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #38-HP API#15059269700000 NE SE SE 855 FSL 170 FEL Lat. 38.683359 Long. - 095.084779 GPS session point (38-HP) Well was found to be an inactive oil well constructed with 7" surface casing, 2.875" casing, 1" pumping string, and a pump jack. The pump jack is not totally equipped due to missing electric motor and belt. There is no stuffing box so the well has no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 38-HP).

EAST LIDIKAY #39 API#15059198770000 NE NE SE 2137 FSL 549 FEL Lat. 38.686878 Long. - 095.086145 Session point (39) Well was found to be a producing oil well constructed 4.5" casing, 2" tubing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well C-2a

inventory.

EAST LIDIKAY #39I-HP API#15059269650000 NW SE SE 638 FSL 964 FEL Lat. 38.682763 Long. - 095.087554 GPS session point (39I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 7/13/2020 and KCC staff did witness this test. Well is listed as Active "Al" on operator well inventory.

EAST LIDIKAY #3-HP API#15059268880000 NE NW SE 2453 FSL 1848 FEL Lat. 38.687746 Long. - 095.090703 GPS session point (3-HP) Well was found to be an inactive oil well constructed with 7" surface casing and 2.875" casing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 3-HP).

EAST LIDIKAY #3I-HP API#15059268910000 NE NW SE 2306 FSL 1672 FEL Lat. 38.687343 Long. - 095.090083 GPS session point (3I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 3/6/2020 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #40I-HP API#15059269660000 NE SE SE 678 FSL 339 FEL Lat. 38.682874 Long. - 095.085366 GPS session point (40I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 6/8/2020 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #41-HP API#15059269710000 SW SE SE 502 FSL 824 FEL Lat. 38.682389 Long. - 095.087058 GPS session point (41-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #42 API#15059198780000 SW NE SE 1838 FSL 790 FEL Lat. 38.686059 Long. - 095.086979 GPS session point (42) Well was found to be an inactive oil well constructed with 4.5" casing, 2" tubing, 1" pump string, and a pump jack. Pump jack is not totally equipped as it is missing the belt. There is no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 42).

EAST LIDIKAY #42-HP API#15059269720000 SE SE SE 516 FSL 496 FEL Lat. 38.682429 Long. - 095.085909 GPS session point (42-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #43-HP API#15059269730000 SE SE SE 525 FSL 172 FEL Lat. 38.682453 Long. - 095.084775 GPS session point (43-HP) Well was found to be an inactive oil well constructed with 7" surface casing and 2.875" casing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 43-HP).

EAST LIDIKAY #43I-HP API#15059269430000 SE SW SE 304 FSL 1609 FEL Lat. 38.681845 Long. - 095.089801 GPS session point (43I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 3/6/2020 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #45I-HP API#15059269600000 SW SE SE 324 FSL 965 FEL Lat. 38.681901 Long. - 095.087546 GPS session point (45I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 8/5/2020 and KCC staff did witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #46I-HP API#15059270360000 SE SE SE 354 FSL 652 FEL Lat. 38.681983 Long. - 095.086452 GPS session point (46I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 8/5/2020 and KCC staff did witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #48-HP API#15059269930000 SW NE SE 1459 FSL 1106 FEL Lat. 38.685018 Long. - 095.088075 GPS session point (48-HP) Well was found to be an inactive oil well constructed with 7" KC-2a

surface casing and 2.875" casing. The casing is shut in with a swedge and valve. There is no pump string but there is a pump jack present. The pump jack is not totally equipped as it is missing the horse head and belt. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 48-HP).

EAST LIDIKAY #48I-HP API#15059270330000 NE SE SE 664 FSL 660 FEL Lat. 38.682835 Long. - 095.086487 GPS session point (48I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 6/8/2020 and KCC staff did not witness this test. Well is listed as Active "Al" on operator well inventory.

EAST LIDIKAY #49-HP API#15059251780000 NE SW SE 758 FSL 1454 FEL Lat. 38.683092 Long. - 095.089272 GPS session point (49-HP) Well was found to be an inactive oil well constructed with 7" surface casing and 2.875" casing. The casing is shut in with a swedge and valve. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 49-HP).

EAST LIDIKAY #4-HP API#15059268670000 NE NW SE 2465 FSL 1543 FEL Lat. 38.687779 Long. - 095.089637 GPS session point (4-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #4I-HP API#15059268920000 NE NW SE 2303 FSL 1366 FEL Lat. 38.687335 Long. - 095.089010 GPS session point (4I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 3/6/2020 and KCC staff did not witness this test. Well is listed as Active "Al" on operator well inventory.

EAST LIDIKAY #50-HP API#15059251790000 NW SE SE 1029 FSL 1127 FEL Lat. 38.683836 Long. - 095.088134 GPS session point (50-HP) Well was found to be an inactive oil well constructed with 7" surface casing and 2.875" casing. The casing is shut in with a swedge and valve. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 50-HP).

EAST LIDIKAY #52-HP API#15059270380000 SW SE SE 150 FSL 1116 FEL Lat. 38.681424 Long. - 095.088071 GPS session point (52-HP) Well was found to be an inactive oil well constructed with 7" surface casing and 2.875" casing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 52-HP).

EAST LIDIKAY #53-HP API#15059270340000 SW SE SE 186 FSL 822 FEL Lat. 38.681521 Long. - 095.087041 GPS session point (53-HP) Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #54-HP API#15059270350000 SE SE SE 193 FSL 498 FEL Lat. 38.681540 Long. - 095.085905 GPS session point (54-HP) Well was found to be an inactive oil well constructed with 7" surface casing and 2.875" casing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 54-HP).

EAST LIDIKAY #55-HP API#15059270300000 SE SE SE 199 FSL 169 FEL Lat. 38.681557 Long: - 095.084756 GPS session point (55-HP) Well was found to be an inactive oil well constructed with 7" surface casing and 2.875" casing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 55-HP).

EAST LIDIKAY #5-HP API#15059268690000 NW NE SE 2466 FSL 924 FEL Lat. 38.687783 Long. - 095.087468 GPS session point (5-HP) Well was found to be an inactive oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and a pump jack. The pump jack is not totally equipped as it is missing an electric motor and belt. The hose connecting the pump string to the lead line is also broke. There is no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 5-HP).

EAST LIDIKAY #5I-HP API#15059268940000 NW NE SE 2312 FSL 1042 FEL Lat. 38.687360 Long. - 095.087877 GPS session point (5I-HP) Well was found to be an inactive EOR well constructed with 7" surface casing and 2.875" casing. This well was drilled as an EOR well but never permitted. The casing is open and there is no surface control. Well is listed as Inactive "IN" on operator well inventory. See attached photo numbered (Lidikay 5I-HP).

EAST LIDIKAY #6-HP API#15059268700000 NE NE SE 2454 FSL 618 FEL Lat. 38.687749 Long. - 095.086395 GPS session point (6-HP) Well was found to be a producing oil well constructed 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #7 API#15059195770000 SE SW SE 119 FSL 1431 FEL Lat. 38.681337 Long. - 095.089172 GPS session point (7) Well was found to be a producing oil well constructed with 2" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY #7I-HP API#15059268960000 NE NE SE 2299 FSL 472 FEL Lat. 38.687324 Long. - 095.085881 GPS session point (7I-HP) Well was found to be an active authorized EOR well constructed with 7" surface casing and 2.875" casing. A satisfactory Mechanical Integrity Test (MIT) was completed on 2/20/2020 and KCC staff did witness this test. Well is listed as Active "AI" on operator well inventory.

EAST LIDIKAY #8 API#15059195790000 SW SE SE 123 FSL 1192 FEL Lat. 38.681350 Long. - 095.088335 GPS session point (8) Well was found to be an inactive oil well constructed with 2" casing. The casing is shut in with a swedge and valve. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 8).

EAST LIDIKAY #9 API#15059198710000 SW SE SE 444 FSL 1125 FEL Lat. 38.682231 Long. - 095.088110 GPS session point (9) Well was found to be a producing oil well constructed with 2" casing, 1" pump string, and has a fully equipped pump jack. Well is listed as Producing "PR" on operator well inventory.

EAST LIDIKAY # 9-HP API#15059268890000 NW NW SE 2133 FSL 1820 FEL Lat. 38.686869 Long. - 095.090597 GPS session point (9-HP) Well was found to be an inactive oil well constructed with 7" surface casing and 2.875" casing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 9-HP).

LIDIKAY #1 F W API#15059198950001 NE SW SE 986 FSL 1847 FEL Lat. 38.683718 Long. - 095.090655 GPS session point (1-F-W) Well was found to be an inactive authorized EOR well (Docket #E-28723) that is constructed with 6" surface casing and 2" casing. Fluid is present inside the casing approximately 1' from surface. No cement is present on the backside of the 2" casing inside the 6" surface casing. There is no surface control. A satisfactory Mechanical Integrity Test (MIT) was completed on 11/10/2017 and KCC staff did witness this test. Well is listed as Active "AI" on operator well inventory. See attached photo numbered (Lidikay 1-F-W)

LIDIKAY #10 W 2 API#15059198860001 SE SE SE 250 FSL 475 FEL Lat. 38.681699 Long. - 095.085829 GPS session point (10-W-2) Well was found to be Plugged and Abandoned "PA" with 7" surface casing and 2" casing still above ground. Staff stuck a pipe down the 2" casing and hit solid three feet down. Operator reported they plugged this well on 6/24/2015. KCC staff did not witness this plugging. Operator completed a Plugging Application (CP-1) until 9/29/2015. Operator then filed a Well Plugging Record (CP-4) on 9/29/2015. KCC staff completed a Well Plugging Report (CP-2/3) on 10/19/2015. A Copy of the CP-1, CP-4, and CP-2/3 are attached to this report. Operator will need to dig down and cut the casing off below surface. Well is listed as Plugged and Abandoned "PA" on operator well inventory. See attached photo numbered (Lidikay 10-W-2)

LIDIKAY #10 W 3 F API#15059198890001 SE SE SE 76 FSL 590 FEL Lat. 38.681221 Long. - 095.086224 GPS session point (10-W-3-F) Well was found to be an inactive authorized EOR well (Docket #E-28723) that is constructed with 8" surface casing, 2" casing and 1" pipe. The well is open and has no surface control. A satisfactory MIT was done on 2/8/2017 that was not witnessed by KCC staff. It appears that the operator must have ran 1" inside the 2" casing to convert to a producer. However, no paperwork has been filed. Well is listed as Active "Al" on operator well inventory. See attached photo numbered (Lidikay 10-W-3-F)

LIDIKAY #10 W 4 API#15059198960001 SE SE SE 588 FSL 261 FEL Lat. 38.682626 Long. - 095.085089 GPS session point (10-W-4) Well was found to be Plugged and Abandoned "PA" with 8" surface casing and 2" casing still above ground. Operator reported they plugged this well on 6/24/2015. KCC staff did not witness this plugging. Operator did not complete a Plugging Application (CP-1) until 10/25/2016. Operator then filed a Well Plugging Record (CP-4) on 10/25/2016. KCC staff completed a Well Plugging Report (CP-2/3) on 2/10/2017. A Copy of the CP-1, CP-4, and CP-2/3 are attached to this report. Operator will need to run down and tag cement. Operator will need to circulate cement from TD to surface. Operator will need to dig down and cut the casing off below surface. Well is listed as Plugged and Abandoned "PA" on operator well inventory. See attached photo numbered (Lidikay 10-W-4)

LIDIKAY #10 W 6 API#15059198910001 NE SE SE 913 FSL 43 FEL Lat. 38.683517 Long. -095.084334 GPS session point (10-W-6) Well was found to be an inactive authorized EOR well (Docket #E-28723) that is constructed with 2" casing. The well is shut-In with a plug. A satisfactory Mechanical Integrity Test (MIT) was completed on 10/12/2016 and KCC staff did not witness this test. Well is listed as Active "AI" on operator well inventory. See attached photo numbered (Lidikay 10-W-6)

LIDIKAY #11 W 1 API#15059198900001 SW SE SE 564 FSL 1171 FEL Lat. 38.682559 Long. - 095.088276 GPS session point (11-W-1) Well was found to be an inactive "IN" authorized EOR well constructed with 8" surface casing and two (2) strings of 2" casing inside the 8" surface casing. Neither strings appear to be cemented inside the surface casing. The casings are open and have no surface control. Well is listed as Plugged and Abandoned "PA" on operator well inventory. Operator reported they plugged this well on 7/25/2016. KCC staff did not witness this plugging. Operator completed a Plugging Application (CP-1) on 7/18/2016. Operator then filed a Well Plugging Record (CP-4) on 10/03/2016. KCC staff completed a Well Plugging Report (CP-2/3) on 10/13/2016. A Copy of the CP-1, CP-4, and CP-2/3 are attached to this report. No sign of cement around or inside the well casing. Well appears to have never been plugged. Operator will be required to plug this well per KCC regulations. After plugging is complete, operator will be required to dig down and cut the casing off below surface. See attached photo numbered (Lidikay 11-W-1).

LIDIKAY #11 W 10 API#15059198810001 NW SE SE 726 FSL 1062 FEL Lat. 38.683006 Long. - 095.087897 GPS session point (11-W-10) Well was found to be an inactive "IN" authorized EOR well constructed with 2" casing with 1" pipe hanging on a clamp inside the 2" casing. The 1" pipe is shut in with a valve. Well is listed as Plugged and Abandoned "PA" on operator well inventory. Operator reported they plugged this well on 6/24/2015. KCC staff did not witness this plugging. Operator did complete a Plugging Application (CP-1) on 10/21/2016. Operator then filed a Well Plugging Record (CP-4) on 10/21/2016. KCC staff completed a Well Plugging Report (CP-2/3) on 2/10/2017. A Copy of the CP-1, CP-4, and CP-2/3 are attached to this report. It appears the operator ran the 1" down the 2" casing for a plugging string and then never plugged the well. Operator will be required to circulate cement to surface through the 1" pipe, pull the 1" pipe out of the casing, and top the well off with cement. Operator will then need to dig down and cut the casing off below surface. See attached photo numbered (Lidikay 11-W-10).

LIDIKAY #11 W 11 API#15059198800001 SW SE SE 390 FSL 1286 FEL Lat. 38.682081 Long. - 095.088673 GPS session point (11-W-11) Well was found to be Plugged and Abandoned "PA" with 2" casing still above ground. Operator reported they plugged this well on 7/9/2015. KCC staff did not witness this plugging. Operator did not complete a Plugging Application (CP-1) until 10/25/2016. Operator then filed a Well Plugging Record (CP-4) on 10/25/2016. KCC staff completed a Well Plugging Report (CP-2/3) on 2/10/2017. A Copy of the CP-1, CP-4, and CP-2/3 are attached to this report. Casing appears to be full of cement at surface. Operator will need to dig down and cut the casing off below surface. Well is listed as Plugged and Abandoned "PA" on operator well inventory. See attached photo numbered (Lidikay 11-W-11)

LIDIKAY #11 W 9 API#15059198820001 NW SE SE 894 FSL 948 FEL Lat. 38.683465 Long. - 095.087505 GPS session point (11-W-9) Well was found to be Plugged and Abandoned "PA" with 2" casing still above ground. Operator reported they plugged this well on 7/22/2015. KCC staff did not witness this plugging. Operator did not complete a Plugging Application (CP-1) until 11/25/2015. Operator then filed a Well Plugging Record (CP-4) on 11/25/2015. KCC staff completed a Well Plugging Report (CP-2/3) on 3/25/2016. A Copy of the CP-1, CP-4, and CP-2/3 are attached to this report. Signs of cement around and on casing. Casing shut in with a valve. Operator will need to insure cement is at surface then dig down and cut the casing off below surface. Well is listed as Plugged and Abandoned "PA" on operator well inventory. See attached photo numbered (Lidikay 11-W-9)

LIDIKAY #11F API#15059195870000 NE SE SE 988 FSL 390 FEL Lat. 38.683723 Long. -095.085552 GPS session point (11-F) Well was found to be an inactive oil well constructed with 8" surface casing and exhibit Renamed

4.5" casing. This well is open with no surface control. This well is listed as Plugged and Abandoned "PA" on operator well inventory. Operator reported they plugged this well on 6/8/2015. KCC staff did not witness this plugging. Operator did not complete a Plugging Application (CP-1). Operator then filed a Well Plugging Record (CP-4) on 12/5/2017. KCC staff completed a Well Plugging Report (CP-2/3) on 9/15/2017. A Copy of the CP-4 and CP-2/3 are attached to this report. No sign of cement around or inside the well casing. Well appears to have never been plugged. Operator will need to perforate the 4.5" casing to insure cement gets on the backside of the 4.5" inside the 8" surface. Operator will then run 1" to bottom and circulate cement to surface before digging down and cutting off the casing below surface. See attached photo numbered (Lidikay 11F)

LIDIKAY #12 W 6 API#15059199010001 SW NE SE 1877 FSL 1177 FEL Lat. 38.686166 Long. - 095.088253 GPS session point (12-W-6) Well was found to be Plugged and Abandoned "PA" with 6" surface casing and 2" casing still above ground. Operator reported they plugged this well on 5/11/2018. KCC staff did not witness this plugging. Operator did not complete a Plugging Application (CP-1). Operator then filed a Well Plugging Record (CP-4) on 8/8/2018. KCC staff completed a Well Plugging Report (CP-2/3) on 8/10/2016. A Copy of the CP-4 and CP-2/3 are attached to this report. Operator will need to run 1" down the inside of the 2" casing and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface. Well is listed as Plugged and Abandoned "PA" on operator well inventory. See attached photo numbered (Lidikay 12-W-6)

LIDIKAY #20 F API#15059195930000 NE NW SE 2142 FSL 1495 FEL Lat. 38.686892 Long. - 095.089457 GPS session point (20-F) Well was found to be an inactive oil well constructed with 4.5" casing, 1" pump string, and a pump jack. Pump jack is not totally equipped as it is missing the electric motor and belt. There is no surface control. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 20-F).

LIDIKAY #27 API#15059211520000 SW SE SE 125 FSL 832 FEL Lat. 38.681354 Long. -095.087074 GPS session point (27) Well was found to be an inactive oil well constructed with 2.875" casing. The casing is open and has no surface control. There is no pump string or pump jack. Well is listed as Producing "PR" on operator well inventory. See attached photo numbered (Lidikay 27).

LIDIKAY #5 F W API#15059198940001 SE SE SE 425 FSL 362 FEL Lat. 38.682177 Long. –095.085438 GPS session point (5-F-W) Well was found to be an inactive authorized EOR well (Docket #E-28723) constructed with 10" surface casing and 2" casing. This well is open with no surface control. There is a piece of wood shoved down the backside of the 2" casing and inside the 10" surface casing. This well is listed as Plugged and Abandoned "PA" on operator well inventory. Operator reported they plugged this well on 6/24/2015. KCC staff did not witness this plugging. Operator did not complete a Plugging Application (CP-1) until 10/25/2016. Operator then filed a Well Plugging Record (CP-4) on 10/25/2016. KCC staff completed a Well Plugging Report (CP-2/3) on 2/10/2017. A Copy of the CP-1, CP-4, and CP-2/3 are attached to this report. No sign of cement around or inside the well casing. Well appears to have never been plugged. Operator will need to tag cement inside and outside of the 2" casing and circulate cement to surface before cutting off the casing below surface. See attached photo numbered (Lidikay 5-F-W)

LIDIKAY #7 F W API#15059198930001 NW SW SE 648 FSL 2129 FEL Lat. 38.682775 Long. - 095.091643 GPS session point (7-F-W) Well was found to be an inactive authorized EOR well (Docket #E-28723) that is constructed with 8" surface casing and 2" casing. The 2" casing appears not to be cemented inside the 8" surface as it wobbles from side to side when pushed. High fluid on the backside of the 2" casing inside the 8" surface casing. There is no surface control. Well is listed as Active "Al" on operator well inventory. A satisfactory Mechanical Integrity Test (MIT) was completed on 7/24/2017 and KCC staff did witness this test. See attached photo numbered (Lidikay 7-F-W)

LIDIKAY #32 API #15059220140000 NE NE SE 2450 FSL 318 FEL Lat. 38.687739 Long. -095.085345 GPS session point (32) Well was found to be a producing oil well constructed with 6" surface casing, 2" casing, 1" pump string, and has a fully equipped pump jack. Well was added to Haas's certified well inventory due to being in production and for area of review of their injection wells on lease. See attached photo numbered (Lidikay 32)

LIDIKAY #10 F API #15059195860000 NE NE SE 2117 FSL 333 FEL Lat. 38.686823 Long. - 095.085386 GPS session point (10-F) Well was found to be a producing oil well constructed with 7" surface casing, 2.875" casing, 1" pump string, and has a fully equipped pump jack. Well is not listed on operator well inventory. Well was added to Haas's certified well inventory due to being in production and for area of review of their injection wells on lease. See attached photo numbered (Lidikay 10-F)

Exhibit KC-2a


The following list of wells were not located at the spot location listed on the operator well inventory. EAST LIDIKAY #10I-HP API#15059269940000, EAST LIDIKAY #14-HP API#15059269890000, EAST LIDIKAY #16I-HP API#15059269950000. EAST


LIDIKAY #17I-HP API#15059269130000, EAST LIDIKAY #18I-HP API#15059269140000, EAST LIDIKAY #21-HP API#15059269900000, EAST LIDIKAY #22-HP API#15059269190000, EAST LIDIKAY #23I-HP API#15059269960000, EAST

LIDIKAY #24I-HP API#15059269160000, EAST LIDIKAY #26I-HP API#15059269180000, EAST LIDIKAY #27-HP API#15059269910000, EAST LIDIKAY #30I-HP API#15059269970000, EAST LIDIKAY #31I-HP API#15059269980000, EAST LIDIKAY #33-HP API#15059269220000, EAST LIDIKAY #34-HP API#15059269920000, EAST LIDIKAY #36I-HP API#15059269420000, EAST LIDIKAY #37I-HP API#15059269570000, EAST LIDIKAY #38I-HP API#15059269580000, EAST LIDIKAY #40-HP API#15059269230000, EAST LIDIKAY #42I-HP API#15059269410000, EAST LIDIKAY #44I-HP API#15059269590000, EAST LIDIKAY #46-HP API#15059270020000, EAST LIDIKAY #47-HP API#15059269610000, EAST LIDIKAY #47I-HP API#15059270370000, EAST LIDIKAY #51-HP API#15059270030000 and the EAST LIDIKAY #6I-HP API#15059268950000. These well locations are listed on the operator well inventory as Expired Intents (EX).

The following list of wells were not located at the spot location listed on the operator well inventory. E. LIDIKAY #11 W 6 API#15059198870001, E. LIDIKAY #11 W 8 API#15059198830001, EAST LIDIKAY #16-HP API#15059268720000, EAST LIDIKAY #20 API#15059198760000, EAST LIDIKAY #28-HP API#15059198700000, EAST LIDIKAY #45-HP API#15059269240000, EAST LIDIKAY #4F API#15059198700000, EAST LIDIKAY #9F API#15059195850000, LIDIKAY #10 W 5 API#15059198920000, LIDIKAY #11 W 12 API#15059199050001, LIDIKAY #11 W 5 API#15059199030001, LIDIKAY #12 W 1 API#15059199040001, LIDIKAY #12 W 2 API#15059199030001, LIDIKAY #12 W 3 API#15059199020001, LIDIKAY #12 W 4 API#15059198880001, LIDIKAY #13 W 1 API#15059198990001, LIDIKAY #13 W 4 API#15059198980001, LIDIKAY #19 W F API#15059198970001, EAST LIDIKAY #10 W 5 API#15059198920001 and the LIDIKAY #4 API#15059195730000. These well locations are listed on the operator well inventory as Plugged and Abandoned "PA".

In conclusion, I found eighty-four (84) wells on the lease which included twenty-three (23) producing oil wells, nineteen (19) active injection wells, twenty-four (24) inactive oil wells, five (5) inactive injection wells, and thirteen (13) plugged wells. No wells were found at the twenty-six (26) expired intent well locations and twenty (20) plugged well locations per operator footages. A photo of each of the forty-two (42) wells out of compliance have been attached to this report. I have also attached a photo of each of the two (2) wells that were added to Haas's well inventory. Also attached to this report is a google map with the session points which are the same as the well numbers are attached to this report. Attached to this report are the plugging reports for the wells in question. Operator well inventory shows one inactive well.







Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 5-F-W

FSL: 425

FEL: 362

API#: 15-059-19894-00-01

Date: 09/13/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 5-F-W

PIC Orientation:

Latitude: 38.682177

Longitude: -095.085438

Time: 2:06 PM

Additional Information: This is a photo of well #5-F-W. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.



Kansas Corporation Commission Oil & Gas Conservation Division

1320489

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: _33640 | API No. 15 - 15-059-19894-00-01 | | | | |
|--|--|--|--|--|--|
| Name: Haas Petroleum, LLC | If pre 1967, supply original completion date: | | | | |
| Address 1: 10551 BARKLEY ST. #307 | Spot Description: | | | | |
| Address 2: | <u>SE</u> Sec. 4 Twp. 16 S. R. 21 🗸 East West | | | | |
| City: OVERLAND PARK State: KS Zip: 66212 + 1812 | 350 Feet from North / ✓ South Line of Section | | | | |
| Contact Person: Mark Haas | Feet from Fast / West Line of Section | | | | |
| Phone: (913) 499-8373 | Footages Calculated from Nearest Outside Section Corner: | | | | |
| Phone: (see) | | | | | |
| | County: FTATIKITI Lease Name: LIDIKAY Well #: 5 F W | | | | |
| Check One: Oil Well Gas Well OG D&A Cat | hodic Water Supply Well Other: | | | | |
| SWD Permit #: FNHR Permit #: | 28723.18 Gas Storage Permit #: | | | | |
| Conductor Casing Size: Set at: | Cemented with: Sacks | | | | |
| Surface Casing Size: 8.0000 Set at: 20 | Cemented with: 22 Sacks | | | | |
| Production Casing Size: 2.3750 Set at: 682 | Cemented with: 82 Sacks | | | | |
| List (ALL) Perforations and Bridge Plug Sets: | | | | | |
| Elevation: 1000 (G.L. / K.B.) T.D.: 693 PBTD: Condition of Well: Good Poor Junk in Hole Casing Leak at: - Proposed Method of Plugging (attach a separate page if additional space is needed): Pump full of cement from top to bottom | Anhydrite Depth: (Stone Corral Formation) (Interval) | | | | |
| Is Well Log attached to this application? Yes No Is ACO-1 filed? ✓ Yes ACO-1 not filed, explain why: | Yes No | | | | |
| Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and the Company Representative authorized to supervise plugging operations: | · | | | | |
| | Sity: Overland Park State: KS Zip: 66212 + | | | | |
| Phone: (913) 499-8373 | | | | | |
| Plugging Contractor License #: _33961 | Name: Consolidated Oil Well Services LLC | | | | |
| Address 1: 1322 S GRANT | | | | | |
| | State: KS Zip: 66720 + | | | | |
| Phone: (<u>620</u>) <u>431-9210</u> | | | | | |
| Proposed Date of Plugging (if known): | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



Kansas Corporation Commission Oil & Gas Conservation Division

1320489

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB-1 (Ca | rathodic Protection Borehole Intent) T-1 (Transfer) X CP-1 (Plugging Application) | | | | |
|---|---|--|--|--|--|
| OPERATOR: License # | Well Location: | | | | |
| Name: Haas Petroleum, LLC | <u>-SE</u> Sec. ⁴ Twp. 16S. R. 21 / East _ West | | | | |
| Address 1:10551 BARKLEY ST. #307 | County: Franklin | | | | |
| Address 2: | Lease Name: LIDIKAY Well #: _5 F W | | | | |
| City: OVERLAND PARK State: KS Zip: 66212 + 1812 | | | | | |
| Contact Person: Mark Haas | | | | | |
| Phone: (913) 499-8373 Fax: () | | | | | |
| Email Address: | | | | | |
| Surface Owner Information: Name: Karen Lidikay Address 1: 1355 N. Grover Address 2: | When filing a Form T-1 involving multiple surface owners, attach an additional sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the county, and in the real estate property tax records of the county treasurer. | | | | |
| City: Wenatchee State: WA Zip: 98801 + | , | | | | |
| | batteries, pipelines, and electrical lines. The locations shown on the plat the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. | | | | |
| form; and 3) my operator name, address, phone number, fax, an | | | | | |
| KCC will be required to send this information to the surface owr | cknowledge that, because I have not provided this information, the ner(s). To mitigate the additional cost of the KCC performing this of the surface owner by filling out the top section of this form and CC, which is enclosed with this form. | | | | |
| If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 | | | | | |
| Submitted Electronically | | | | | |
| 1 | | | | | |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

October 25, 2016

Mark Haas Haas Petroleum, LLC 10551 BARKLEY ST. #307 OVERLAND PARK, KS 66212-1812

Re: Plugging Application API 15-059-19894-00-01 LIDIKAY 5 F W SE/4 Sec.04-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after April 25, 2017. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The April 25, 2017 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3

| TO: | , | ĄPI Well | Number: <u>15-0</u> : | <u>59-19894-00-01</u> | • | • |
|-------------------------|---------------------------------------|-------------------|-----------------------|-----------------------|------------------|---------------------------------------|
| | TON COMMISSION | Spot: SE | | | <u>4-16S-21E</u> | |
| 266 N. Main St., Ste. | OIVISION - PLUGGING | | eet from S Section | on Line, 3 | | rom E Section Line |
| Wichita, KS 67202-1 | | | me: <u>LIDIKAY</u> | | | Well #: <u>5 F W</u> |
| | | | FRANKLIN | | | al Depth: 682 feet |
| Operator License No | 1 | String | | (ft) Pulled (ft |) Comm | <u>ent</u> |
| Op Name: <u>HAAS PE</u> | | PROD SURF | | | • | · · · · · · · · · · · · · · · · · · · |
| Address: 10551 BA | RKLEY ST. #307 ND PARK, KS 66212 | | | | | · · · · · · · · · · · · · · · · · · · |
| Well Type: EOR | | ocket No: E28723. | 18 | Date/Time to P | lug: 00 | 5/24/2015 12:00 AM |
| Plug Co. License No | | Name: CONSOLII | | • | _ | · · · · · · · · · · · · · · · · · · · |
| Proposal Revd. from | 1: | Company: | | • | | Phone: |
| Proposed | | | | ** | • | |
| Plugging Method: | • | | • • | | • | |
| | • | | | | | |
| | , · · · · · | | | , | | |
| | | | | · · | | |
| Plugging Proposal I | Received By: LEVI SHORT | ٠ - 1 | WitnessType: N | ONE: | · | • |
| Date/Time Plugging | Completed: <u>06/24/2015 1</u> | 2:00 AM | KCC Agent: L | EVI SHORT | | |
| Actual Plugging Re | port: | | | Ρ́ε | erfs: | |
| RUN 1-INCH TUBI | NG TO 680 FEET INSIDE | 2-INCH CASING | THEN FILL TO | : | | |
| SURFACE WITH PO | ORTLAND CEMENT. | - | | ŀ | | |
| , | | | | | • | |
| | | • | • . | | | D. |
| | | · | • | | | RECEIVED KCC DIST # 3 |
| · . | | | | . | | FEB 08 2017 |
| | , | • | | | | • • |
| | | • | | ' | | CHANUTE, KS |
| · · | | | | | | 10 |
| | | | | 1 | | |
| | | | | 1 | , | KCC WICHITA |
| \ \tag{\alpha} | • | | | 1 | | FEB 1 0 2017 |
| | | | | | | • |
| | | | | | • | RECEIVED |
| Remarks: | | | | | | |
| Plugged through: 2 | <u>rbg</u> | | | | | |
| | | | | | : : | |
| District: 03 | • | Signed | All | , . | | |
| District: <u>05</u> | | Signed | | (TECHNI | CIAND | |
| | | | | (TECHIAL | Jan 11) | |

INVO[†]CTE^{13/3} FEB 1 6 7017



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

Kansas Corporation Commission Oil & Gas Conservation Division

1320490

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

| OPERATOR: License #:3 | 3640 | | API No. 1 | _{5 -} <u>15-059-198</u> | 94-00-01 | | | | |
|---|-----------------------------|------------------------------|-------------------------|---|--|--|--|----------|-----------------------------|
| Name: Haas Petro | oleum, LLC | | | Spot Description: | | | | | |
| Address 1:10551 BARKLEY ST. #307 Address 2: City: _OVERLAND PARK State: KS Zip: _66212 + 1812 Contact Person: _Mark Haas Phone: (913) 499-8373 | | | | | | | | | |
| | | | | | | | | | est Outside Section Corner: |
| | | | | | | | | | |
| | | | | Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodic Water Supply Well Other: SWD Permit #: | | | | Franklin | |
| | | - | Lease Na | me: LIDIKAY | Well #: 5 F W | | | | |
| ✓ ENHR Permit #: E28723.18 Gas Storage Permit #: If not, is well log attached? Yes No No No Output Description: No No No No No No No No No N | | | | • | roved on: (Date) | | | | |
| Producing Formation(s): List A | | | _ I The plage | | (KCC District Agent's Name) | | | | |
| Depth to Top: Bottom: T.D | | | | Commenced: 06/24 | | | | | |
| Depth to | Top: Botton | m: T.D | Plugging | Commenced: 06/24 | 4/2015 | | | | |
| Depth to | Top: Botton | m: T.D | —— Plugging (| Completed: Completed: | 112010 | | | | |
| | | | | | | | | | |
| Show depth and thickness of a | | itions. | Occine December 10 | | <i>"</i> | | | | |
| Oil, Gas or Water Formation | Content | Casing | Size Size | Setting Depth | Pulled Out | | | | |
| Tomaton | Content | Casing | GIZE | Jetting Deptin | 1 ulled Out | | | | |
| | | Surface | 8.0000 | 20 | | | | | |
| | | Production | 2.3750 | 682 | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Describe in detail the manner cement or other plugs were us Rig and ran 1" tubi | sed, state the character of | same depth placed from (both | tom), to (top) for each | h plug set. | ods used in introducing it into the hole. If | | | | |
| Plugging Contractor License # | | | | | Services LLC | | | | |
| Address 1: 1322 S GRANT Address 1: 1322 S GRANT | | | Address 2: PO | BOX 884 | | | | | |
| City: CHANUTE | | | State: <u>K</u> | S | zip: <u>66720</u> + | | | | |
| Phone: (620) 431-92 | 210 | | | | | | | | |
| Name of Party Responsible fo | r Plugging Fees: Mark | Haas | | | | | | | |
| State of | County, _ | | , SS. | | | | | | |
| | | | Em | ployee of Operator or | Operator on above-described well, | | | | |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 10-W-2

FSL: 250

FEL: 475

API#: 15-059-19886-00-01

Date: 09/13/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 10-W-2

PIC Orientation:

Latitude: 38.681699

Longitude: -095.085829

Time: 2:53 PM

Additional Information: This is a photo of well #10-W-2. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.



Kansas Corporation Commission Oil & Gas Conservation Division

1265596

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: _33640 | API No. 15 - 15-059-19886-00-01 | | | | |
|---|--|--|--|--|--|
| Name: Haas Petroleum, LLC | If pre 1967, supply original completion date: | | | | |
| Address 1: 11551 ASH ST., STE 205 | Spot Description: | | | | |
| Address 2: | | | | | |
| City: LEAWOOD State: KS Zip: 66211 + | Feet from North / 🗹 South Line of Section | | | | |
| Mad Hara | Feet from Feat / West Line of Section | | | | |
| Contact Person: Mark Haas | Footages Calculated from Nearest Outside Section Corner: | | | | |
| Phone: (913) 499-8373 | — NE NW ✓ SE SW | | | | |
| | County: Franklin | | | | |
| | Lease Name: LIDIKAY Well #: 10 W 2 | | | | |
| Check One: Oil Well Gas Well OG D&A | Cathodic Water Supply Well Other: | | | | |
| SWD Permit #: | | | | | |
| Conductor Casing Size: Set at: | | | | | |
| 0.05 | Cemented with: 5 Sacks | | | | |
| Production Casing Size: 2.375 Set at: 734 | Cemented with: 112 Sacks | | | | |
| | Cemented with: Sacks | | | | |
| List (ALL) Perforations and Bridge Plug Sets: Attached | | | | | |
| Attached | | | | | |
| Elevation: 999 ([G.L. / [K.B.) T.D.: | A 1 1 2 B 4 | | | | |
| Elevation: OSS (F.G.E./ N.B./ I.D.: 1947 PBTD: | Annydrite Deptn: (Stone Corral Formation) | | | | |
| Condition of Well: Good Door Junk in Hole Casing Leak at: | (Interval) | | | | |
| Proposed Method of Plugging (attach a separate page if additional space is needed): | | | | | |
| Pump full of cement from top to bottom | | | | | |
| | | | | | |
| Is Well Log attached to this application? | Yes No | | | | |
| If ACO-1 not filed, explain why: | | | | | |
| | | | | | |
| | | | | | |
| Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and t | · | | | | |
| Company Representative authorized to supervise plugging operations: John Haa | | | | | |
| Address: 11551 Ash Street, # 205 | City: Leawood State: Kansas Zip: 66211 + | | | | |
| Phone: (913) 499-8373 | | | | | |
| | Name: Consolidated Oil Well Services LLC | | | | |
| Address 1: 1322 S GRANT | Address 2: PO BOX 884 | | | | |
| CHANILITE | State: KS Zip: 66720 + | | | | |
| Phone: (<u>620</u>) <u>431-9210</u> | | | | | |
| Proposed Date of Plugging (if known): 06/24/2015 | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



Kansas Corporation Commission Oil & Gas Conservation Division

1265596

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB-1 (Ca | athodic Protection Borehole Intent) T-1 (Transfer) X CP-1 (Plugging Application) | | | | |
|---|---|--|--|--|--|
| OPERATOR: License # | Well Location: | | | | |
| Name: | SW SE SE SE Sec.4 Twp. 16 S. R. 21 ✓ East West | | | | |
| Address 1: 11551 ASH ST., STE 205 | County: Franklin | | | | |
| Address 2: | Lease Name: LIDIKAY Well #: 10 W 2 | | | | |
| City: LEAWOOD State: KS Zip: 66211 + Contact Person: Mark Haas | If filing a Form T-1 for multiple wells on a lease, enter the legal description o the lease below: | | | | |
| Contact Person: Mark Haas | | | | | |
| Phone: (913) 499-8373 Fax: () | | | | | |
| Email Address: | | | | | |
| Surface Owner Information: Name: Mrs. John Layle Address 1: 5800 High Drive Address 2: | When filing a Form T-1 involving multiple surface owners, attach an additional sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the county, and in the real estate property tax records of the county treasurer. | | | | |
| If this form is being submitted with a Form C-1 (Intent) or CB-1 (Cathod the KCC with a plat showing the predicted locations of lease roads, tank are preliminary non-binding estimates. The locations may be entered on Select one of the following: | batteries, pipelines, and electrical lines. The locations shown on the plat | | | | |
| | cated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form eing filed is a Form C-1 or Form CB-1, the plat(s) required by this | | | | |
| KCC will be required to send this information to the surface owr | knowledge that, because I have not provided this information, the ner(s). To mitigate the additional cost of the KCC performing this of the surface owner by filling out the top section of this form and CC, which is enclosed with this form. | | | | |
| If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 | | | | | |
| Submitted Electronically | | | | | |
| I | | | | | |
| | _ | | | | |

| Form | CP1 - Well Plugging Application | | |
|-----------|---------------------------------|--|--|
| Operator | Haas Petroleum, LLC | | |
| Well Name | LIDIKAY 10 W 2 | | |
| Doc ID | 1265596 | | |

Perforations And Bridge Plug Sets

| Perforation Top | Perforation Base | Formation | Bridge Plug Depth |
|-----------------|------------------|--------------------|-------------------|
| 665.0 | 695.0 | Squirrel Sandstone | |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Shari Feist Albrecht, Chair Jay Scott Emler, Commissioner Pat Apple, Commissioner

September 29, 2015

Mark Haas Haas Petroleum, LLC 11551 ASH ST., STE 205 LEAWOOD, KS 66211

Re: Plugging Application API 15-059-19886-00-01 LIDIKAY 10 W 2 SE/4 Sec.04-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after March 29, 2016. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The March 29, 2016 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3

TO: API Well Number: 15-059-19886-00-01 Spot: SESESE STATE CORPORATION COMMISSION Sec/Twnshp/Rge: 4-16S-21E CONSERVATION DIVISION - PLUGGING 252 feet from S Section Line, 478 feet from E Section Line 266 N. Maih St., Ste. 220 Lease Name: LIDIKAY Well #: 10 W 2 Wichita, KS 67202-1513 County: FRANKLIN Total Vertical Depth: 734 Depth (ft) Pulled (ft) Comment Operator License No.: 33640 String Size PROD 2.375 734 112 SX Op Name: HAAS PETROLEUM, LLC SURF 6.25 20 5 SX Address: 11551 ASH ST., STE 205 LEAWOOD, KS 66211 Well Type: EOR **UIC Docket No: E28723.20** Date/Time to Plug: 06/24/2015 12:00 AM Plug Co. License No.: 33961 Plug Co. Name: CONSOLIDATED OIL WELL SERVICES LLC Proposal Revd. from: JOHN HAAS Company: Phone: (913) 499-8373 Proposed Pump full of cement from top to bottom Plugging Method: Plugging Proposal Received By: LEVI SHORT WitnessType: NONE Date/Time Plugging Completed: 06/24/2015 12:00 AM KCC Agent: LEVI SHORT **Actual Plugging Report:** Perfs: RUN 1-INCH TUBING TO TD (734 FEET) THEN PUMP PORTLAND CEMENT TO Top Bot Thru Comments SURFACE. A TOTAL OF 25 SACKS OF CEMENT WERE USED TO PLUG WELL. 665 695 RECEIVED KCC DIST#3 **OCT** 1.5 2015 CHANUTE, KS Remarks: Plugged through: TBG Signed -District: 03 (TECHNICIAN)

Form CP-2/3



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

1265601

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

| OPERATOR: License #: 3 | 3640 | | | API No. 15 | _{5 -} <u>15-059-198</u> | 386-00-01 | |
|---|----------------------------|---|-------------|---|---------------------------------------|--|--|
| Name: Haas Petroleum, LLC | | | | Spot Desc | Spot Description: | | |
| Address 1: 11551 ASH ST., STE 205 | | | | <u>SE</u> _{Sec.} 4_ _{Twp.} 16_ s. R. 21_ y East West | | | |
| Address 2: | | | | | | | |
| | | | | | | | |
| Phone: (913_) 499-83 | 73 | | | | □ NE □ NW ✓ SE □ SW County: Franklin | | |
| | | OG D&A Cath | odic | County: _ | | | |
| Water Supply Well | | SWD Permit #: | | Lease Nar | me: LIDIKAY | Well #: 10 W 2 | |
| | | Storage Permit #: | | Date Well | Completed: | | |
| | | vell log attached? Yes | No | The plugg | ing proposal was app | proved on: (Date) | |
| Producing Formation(s): List | , | , | | | | (KCC District Agent's Name) | |
| Depth t | • | ttom: T.D | | Plugging (| Commenced: 06/2 | | |
| | | ttom: T.D ttom: T.D | | Plugging (| Completed: 06/2 | 4/2015 | |
| Depth t | о тор: во | ttom: 1.D | | | | | |
| Show depth and thickness of | all water, oil and gas for | mations. | | | | | |
| Oil, Gas or Wate | r Records | | Casing | ing Record (Surface, Conductor & Production) | | | |
| Formation | Content | Casing | Size | | Setting Depth | Pulled Out | |
| | | Surface | 6.25 | 50 | 20 | 0 | |
| | | Production | 2.37 | ' 5 | 734 | 0 | |
| | | rioddollori | 2.07 | <u> </u> | 701 | 0 | |
| | | | | | | | |
| | | | | | | | |
| | • | | | • | | ods used in introducing it into the hole. If | |
| cement or other plugs were u | sed, state the character | of same depth placed from (b | oottom), to | (top) for each | n plug set. | | |
| | • | bing at casing TD, ed 1" tubing from v | | | | • | |
| Plugging Contractor License | #: <u>33961</u> | | Name: | Consol | lidated Oil Well | l Services LLC | |
| Address 1: 1322 S GRANT Address 1: 1322 S GRANT | | | Addres | ss 2: PO E | 3OX 884 | | |
| City: _CHANUTE | | | | State:_ K \$ | 3 | zip: <u>66720</u> + | |
| Phone: (620_) _431-9 | 210 | | | _ | | | |
| Name of Party Responsible for | or Plugging Fees: Ma | rk Haas/Haas Petrol | eum, L | .LC | | | |
| State of | County | /, | | , ss. | | | |
| | | | | Em | ployee of Operator or | Operator on above-described well, | |


Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and

(Print Name)

the same are true and correct, so help me God.

KCC DISTRICT III OFFICE FIELD REPORT PHOTO ID FORM



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 10-W-4

FSL: 588

FEL: 261

API#: 15-059-19896-00-01

Date: 09/14/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 10-W-4

PIC Orientation:

Latitude: 38.682626

Longitude: -095.085089

Time: 9:46 AM

Additional Information: This is a photo of well #10-W-4. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.



1320485

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: 33640 | API No. 15 - 15-059-19896-00-01 | | | | |
|---|---|--|--|--|--|
| Name: Haas Petroleum, LLC | If pre 1967, supply original completion date: Spot Description: | | | | |
| Address 1: 10551 BARKLEY ST. #307 | | | | | |
| Address 2: | <u>SE</u> Sec. 4 Twp. 16 S. R. 21 🗸 East West | | | | |
| City: OVERLAND PARK State: KS Zip: 66212 + 1812 | | | | | |
| Contact Person: Mark Haas | 495 Feet from 🗹 East / 🗌 West Line of Section | | | | |
| Phone: (913) 499-8373 | Footages Calculated from Nearest Outside Section Corner: | | | | |
| Fildle. () | — | | | | |
| | Lease Name: LIDIKAY Well #: 10 W 4 | | | | |
| | | | | | |
| Check One: Oil Well Gas Well OG D&A Ca | athodic Water Supply Well Other: | | | | |
| SWD Permit #: ENHR Permit #: | E28723.22 Gas Storage Permit #: | | | | |
| Conductor Casing Size: Set at: | Cemented with: Sacks | | | | |
| Surface Casing Size: 6.2500 Set at: 20 | Cemented with: Sacks | | | | |
| Production Casing Size: 2.3375 Set at: 737 | Cemented with: Sacks | | | | |
| List (ALL) Perforations and Bridge Plug Sets: | | | | | |
| Elevation: 999 (G.L. / K.B.) T.D.: 737 PBTD: | Anhydrite Depth: (Stone Corral Formation) (Interval) | | | | |
| Pump full of cement from top to bottom. Is Well Log attached to this application? Yes No Is ACO-1 filed? If ACO-1 not filed, explain why: | Yes No | | | | |
| Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and the Company Representative authorized to supervise plugging operations: Mark Haas | · | | | | |
| Address: 10551 Barkley St. # 307 | City: Overland Park State: KS Zip: 66212 + | | | | |
| Phone: (913) 499-8373 | | | | | |
| Plugging Contractor License #: 33961 | Name: Consolidated Oil Well Services LLC | | | | |
| | Address 2: PO BOX 884 | | | | |
| City: CHANUTE | State: KS Zip: 66720 + | | | | |
| Phone: (<u>620</u>) <u>431-9210</u> | | | | | |
| Proposed Date of Plugging (if known): | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



1320485

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB-1 (C | athodic Protection Borehole Intent) T-1 (Transfer) X CP-1 (Plugging Application) | | | | |
|---|---|--|--|--|--|
| OPERATOR: License # | Well Location: | | | | |
| Address 2: | | | | | |
| Surface Owner Information: Name: Karen Lidikay Address 1: 1355 N. Grover Address 2: | When filing a Form T-1 involving multiple surface owners, attach an additional sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the county, and in the real estate property tax records of the county treasurer. | | | | |
| the KCC with a plat showing the predicted locations of lease roads, tank | dic Protection Borehole Intent), you must supply the surface owners and batteries, pipelines, and electrical lines. The locations shown on the plat at the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. | | | | |
| | cated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form being filed is a Form C-1 or Form CB-1, the plat(s) required by this | | | | |
| KCC will be required to send this information to the surface ow | cknowledge that, because I have not provided this information, the ner(s). To mitigate the additional cost of the KCC performing this of the surface owner by filling out the top section of this form and CCC, which is enclosed with this form. | | | | |
| If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 | fee with this form. If the fee is not received with this form, the KSONA-1 1 will be returned. | | | | |
| Submitted Electronically | | | | | |
| I | - | | | | |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

October 25, 2016

Mark Haas Haas Petroleum, LLC 10551 BARKLEY ST. #307 OVERLAND PARK, KS 66212-1812

Re: Plugging Application API 15-059-19896-00-01 LIDIKAY 10 W 4 SE/4 Sec.04-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after April 25, 2017. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The April 25, 2017 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3

| TO: | API Well Number: <u>15-059-19896-00-01</u> |
|---|---|
| STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING | Spot: SESESE Sec/Twnshp/Rge: 4-16S-21E |
| 266 N. Main St., Ste. 220 | 581 feet from S Section Line, 258 feet from E Section Line |
| Wichita, KS 67202-1513 | Lease Name: LIDIKAY Well #: 10 W 4 County: FRANKLIN Total Vertical Depth: 737 feet |
| O | String Size Depth (ft) Pulled (ft) Comment |
| Operator License No.: 33640 Op Name: HAAS PETROLEUM, LLC | PROD 2.3375 737 102 SX |
| Address: 10551 BARKLEY ST. #307 | SURF 6.25 20 15 SX |
| OVERLAND PARK, KS 66212 | |
| Well Type: EOR UIC Docket N | o: <u>E28723.22</u> Date/Time to Plug: <u>06/24/2015 12:00 AM</u> |
| Plug Co. License No.: 33961 Plug Co. Name: | CONSOLIDATED OIL WELL SERVICES LLC |
| Proposal Revd. from: MARK HAAS | Company: Phone: (913) 499-8373 |
| Proposed Pump full of cement from top to bottom. Plugging Method: | |
| Plugging Proposal Received By: LEVI SHORT Date/Time Plugging Completed: 06/24/2015 12:00 A Actual Plugging Report: RUN 1-INCH TUBING TO 730 FEET INSIDE 2-INCH SURFACE WITH PORTLAND CEMENT. | Perfs: |
| | RECEIVED RCC DIST#3 FEB 08 2017 CHANUTE, KS KCC WICHITA |
| | FEB 1 0 2017 RECEIVED |
| Remarks: | |
| Plugged through: <u>TBG</u> | |
| | |

Form CP-2/3

INVOICED



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

Kansas Corporation Commission Oil & Gas Conservation Division

1320488

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

| OPERATOR: License #:3 | 3640 | | API No. 1 | _{5 -} <u>15-059-198</u> | 96-00-01 | | | | | | | | | |
|---|-----------------------------|------------------------------|-------------------------|---|---|--------|--|---------------------------|--|-----------------|-----------|----------|-------|---|
| Name: Haas Petroleum, LLC | | | | Spot Description: | | | | | | | | | | |
| Address 1:10551 BARKLEY ST. #307 | | | | | | | | | | | | | | |
| Address 2: | | | | | | | | | | | | | | |
| | | | | | | | | Phone: (913) 499-83 | | | | NE NW | SE SW | |
| | | | | | | | | Type of Well: (Check one) | | OG D&A Cathodic | County: _ | Franklin | | _ |
| Water Supply Well □ C ENHR Permit #: E2872 | | | Lease Na | | Well #: <u>10 W 4</u> | — | | | | | | | | |
| Is ACO-1 filed? ✓ Yes | _ | | | | roved on: (Da | | | | | | | | | |
| Producing Formation(s): List A | | | | | (KCC District Agent's Nan | | | | | | | | | |
| Depth to | Top: Botton | m: T.D | | Commenced: 6/24/ | | 10) | | | | | | | | |
| Depth to | Top: Botton | m: T.D | — Plugging (| Completed: 06/24 | 4/2015 | _ | | | | | | | | |
| Depth to | Top: Botton | m:T.D | Trugging (| ompieted | | _ | | | | | | | | |
| Observed and the analytic language of a | -11 | | I | | | _ | | | | | | | | |
| Show depth and thickness of a Oil, Gas or Water | | | Casing Record (Surf | ace, Conductor & Produ | uction) | \neg | | | | | | | | |
| Formation | Content | Casing | Size | Setting Depth | Pulled Out | | | | | | | | | |
| | | | | | | 7 | | | | | | | | |
| | | Surface | 6.2500 | 20 | | - | | | | | | | | |
| | | Production | 2.3750 | 737 | | _ | | | | | | | | |
| | | | | | | _ | | | | | | | | |
| | | | | | | | | | | | | | | |
| cement or other plugs were us | sed, state the character of | same depth placed from (bott | tom), to (top) for each | n plug set. | ods used in introducing it into the hole. | If | | | | | | | | |
| Plugging Contractor License # | | | | | Services LLC | | | | | | | | | |
| Address 1: 1322 S GRANT Add | | | Address 2: PO | 3OX 884 | | _ | | | | | | | | |
| City: CHANUTE | | | State: <u>K</u> | S | zip: <u>66720</u> + | _ | | | | | | | | |
| Phone: (620) 431-92 | 210 | | | | | | | | | | | | | |
| Name of Party Responsible fo | r Plugging Fees: Mark | Haas | | | | _ | | | | | | | | |
| State of | County, _ | | , SS. | | | | | | | | | | | |
| | | | Em | Employee of Operator or Operator on above-described well, | | | | | | | | | | |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and

KCC DISTRICT III OFFICE FIELD REPORT PHOTO ID FORM



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 11F

FSL: 988

FEL: 390

API#: 15-059-19587-00-00

Date: 09/14/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 11F

PIC Orientation:

Latitude: 38.683723

Longitude: -095.085552

Time: 10:40 AM

Additional Information: This is a photo of well #11F. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.

TO: API Well Number: 15-059-19587-00-00 Spot: NESESE Sec/Twnshp/Rge: 4-16S-21E STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING 992 feet from S Section Line, 390 feet from E Section Line 266 N. Main St., Ste. 220 Lease Name: LIDIKAY Well #: 11F Wichita, KS 67202-1513 County: FRANKLIN Total Vertical Depth: 760 Operator License No.: 33640 .. Op Name: HAAS PETROLEUM, LLC Address: 10551 BARKLEY ST. #307 OVERLAND PARK, KS 66212 Date/Time to Plug: 06/08/2015 10:00 AM UIC Docket No: Well Type: OIL Plug Co. License No.: 33961 Plug Co. Name: CONSOLIDATED OIL WELL SERVICES LLC Phone: (913) 207-0257 Proposal Revd. from: JOHN HAAS Company: HAAS PETROLEUM Proposed FILL TO SURFACE WITH CEMENT. Plugging Method: WitnessType: NONE Plugging Proposal Received By: Date/Time Plugging Completed: 06/08/2015 11:00 AM KCC Agent: LEVI SHORT Perfs: **Actual Plugging Report:** RUN 1-INCH TUBING TO TD (756 FEET) THEN PUMP PORTLAND CEMENT TO SURFACE. A TOTAL OF 30 SACKS OF CEMENT WERE USED TO PLUG WELL. RECEIVED KCC DIST #3 SEP 13 2017 CHANUTE, KS Remarks: Plugged through: TBG District: 03 Signed (TECHNICIAN) INVOICED

> Exhibit KC-2a Page 189 of 276

SEP 1 5 2017

Form CP-2/3



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

1375088

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

API No. 15 - 15-059-19587-00-00 OPERATOR: License #: 33640 Name: Haas Petroleum, LLC Spot Description: ___ __NE_SE_SE_Sec.4 __Two. 16 _ S. _ R. _ 21 _ \(\nabla \) East \(\nabla \) West Address 1: 10551 BARKLEY ST. #307 992 Feet from North / South Line of Section Address 2: __ City: OVERLAND PARK State: KS Zip: 66212 + 1812 --_____ Feet from 📝 East / ___ West Line of Section Contact Person: Mark Haas Footages Calculated from Nearest Outside Section Corner: Phone: (913) 499-8373 NE NW ✓ SE SW Type of Well: (Check one) ✓ Oil Well Gas Well OG D&A Cathodic County: Franklin Water Supply Well Other: SWD Permit #:_ Lease Name: LIDIKAY Well #: 11F ENHR Permit #: _____ Gas Storage Permit #: __ Date Well Completed: _ Is ACO-1 filed?

✓ Yes No If not, is well log attached? Yes No The plugging proposal was approved on: ____ _____(KCC **District** Agent's Name) Producing Formation(s): List All (If needed attach another sheet) _____ Depth to Top: _____ Plugging Commenced: 06/08/2015 ____ T.D. ___ Depth to Top: ___ Bottom: Plugging Completed: 06/08/2015 _____ Depth to Top: _____ Bottom: ______T.D. ____ Show depth and thickness of all water, oil and gas formations. Oil, Gas or Water Records Casing Record (Surface, Conductor & Production) Size Pulled Out Formation Content Casing Setting Depth Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set. Run1 inch tubing to TD - 756' - then pump portland cement to surface. 30 sacks of cement were used to plug well. Name: Consolidated Oil Well Services LLC Plugging Contractor License #: _ 33961 Address 1:__1322 S GRANT Address 2: PO BOX 884 ______ State: KS _____ Zip: 66720 ___+ _____ City: CHANUTE Phone: (620_) 431-9210 Name of Party Responsible for Plugging Fees: Mark Haas State of _____ Employee of Operator or Operator on above-described well, (Print Name)

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and

KCC DISTRICT III OFFICE FIELD REPORT PHOTO ID FORM



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 11-W-1

FSL: 564

FEL: 1171

API#: 15-059-19890-00-01

Date: 09/14/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 11-W-1

PIC Orientation:

Latitude: 38.682559

Longitude: -095.088276

Time: 9:33 AM

Additional Information: This is a photo of well #11-W-1. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.



1312102

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: 33640 | | API No. 15 - 15-059-19890-00-01 | | | | | |
|---|----------------------|--|-----------------|--|--|--|--|
| Name: Haas Petroleum, LLC | | If pre 1967, supply original completion date: Spot Description: | | | | | |
| Address 1:10551 Barkley St. #307 | | | | | | | |
| Address 2: | | SE _Sec. 4 _ Twp. 16 S. R. 21 | ZEast West | | | | |
| City: Overland Park State: KS | -z: 66212 . 1812 | | Line of Section | | | | |
| Maul III | Zip: + | | Line of Section | | | | |
| Contact i Groom: | | Footages Calculated from Nearest Outside Section Corn | er: | | | | |
| Phone: (913) 499-8373 | | _ NE NW ✓ SE SW | | | | | |
| | | County: Franklin Lease Name: LIDIKAY Well #: 11 | \/\/ 1 | | | | |
| | | Lease Name: LIDIKAT Well #: | VVI | | | | |
| Check One: Oil Well Gas Well OG | D&A Catho | dic Water Supply Well Other: | | | | | |
| SWD Permit #: | ▼ ENHR Permit #: E28 | | | | | | |
| Conductor Casing Size: | | | | | | | |
| • | 40 | Cemented with: 15 | | | | | |
| Production Casing Size: 2.3750 | | Cemented with: 90 | | | | | |
| List (ALL) Perforations and Bridge Plug Sets: | . 001 a | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Elevation: 988 (VG.L./ KB.) T.D.: 731 | PRTD: | Anhydrite Denth | | | | | |
| | | (Stone Corral Formation) | | | | | |
| Condition of Well: Good Poor Junk in Hole | | (Interval) | | | | | |
| Proposed Method of Plugging (attach a separate page if addition | | | | | | | |
| Pump full of cement from top to botto | <i>o</i> m | | | | | | |
| | | | | | | | |
| Is Well Log attached to this application? | Is ACO-1 filed? | s No | | | | | |
| If ACO-1 not filed, explain why: | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | ules and Regulations of the State Corporation Commission | | | | | |
| Company Representative authorized to supervise plugging o | | 0 1 10 1 | | | | | |
| | City | v: Overland Park State: Kansas Zip: 66212 | -+ | | | | |
| Phone: (913) 499-8373 | | | | | | | |
| Plugging Contractor License #: 33557 | Nar | me: Skyy Drilling, LLC | | | | | |
| Address 1: 10551 BARKLEY ST., Ste 307 | | Iress 2: | | | | | |
| City: OVERLAND PK | | State: KS Zip: 66212 | _ + _1869 | | | | |
| Phone: (<u>620</u>) <u>531-5922</u> | | | | | | | |
| Proposed Data of Plugging (if known): | | | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



1312102

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB-1 (Ca | athodic Protection Borehole Intent) | | | | |
|---|---|--|--|--|--|
| OPERATOR: License # | Well Location: | | | | |
| Name: | SESec.4Twp. 16S. R. 21 | | | | |
| Address 1:10551 Barkley St. #307 | County: Franklin | | | | |
| Address 2: | Lease Name: LIDIKAY Well #: _11 W 1 | | | | |
| City: Overland Park State: KS Zip: 66212 + 1812 Contact Person: Mark Haas | If filing a Form T-1 for multiple wells on a lease, enter the legal description of | | | | |
| Contact Person: Mark Haas | the lease below: | | | | |
| Phone: (913) 499-8373 Fax: () | | | | | |
| Email Address: | | | | | |
| Surface Owner Information: Name: Karen Lidikay Address 1: 1355 N. Grover | When filing a Form T-1 involving multiple surface owners, attach an additional | | | | |
| Address 1: 1355 N. Grover | sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the | | | | |
| Address 2: | county, and in the real estate property tax records of the county treasurer. | | | | |
| City: Wenatchee State: WA Zip: 98801 + | | | | | |
| If this form is being submitted with a Form C-1 (Intent) or CB-1 (Cathod the KCC with a plat showing the predicted locations of lease roads, tank are preliminary non-binding estimates. The locations may be entered on Select one of the following: | batteries, pipelines, and electrical lines. The locations shown on the plat | | | | |
| | cated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form eing filed is a Form C-1 or Form CB-1, the plat(s) required by this | | | | |
| KCC will be required to send this information to the surface owr | knowledge that, because I have not provided this information, the ner(s). To mitigate the additional cost of the KCC performing this of the surface owner by filling out the top section of this form and CC, which is enclosed with this form. | | | | |
| If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 | | | | | |
| Submitted Electronically | | | | | |
| ι | _ | | | | |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

July 18, 2016

Mark Haas Haas Petroleum, LLC 10551 Barkley St. #307 Overland Park, KS 66212-1812

Re: Plugging Application API 15-059-19890-00-01 LIDIKAY 11 W 1 SE/4 Sec.04-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after January 18, 2017. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The January 18, 2017 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3

API Well Number: 15-059-19890-00-01 TO: Sec/Twnshp/Rge: 4-16S-21E Spot: SE STATE CORPORATION COMMISSION **CONSERVATION DIVISION - PLUGGING** 565 feet from S Section Line, 1194 feet from E Section Line 266 N. Main St., Ste. 220 Lease Name: LIDIKAY Well #: 11 W 1 Wichita, KS 67202-1513 County: FRANKLIN Total Vertical Depth: 731 feet Operator License No.: 33640 String Size Depth (ft) Pulled (ft) Comment PROD 2.375 731 90 SX Op Name: HAAS PETROLEUM; LLC **SURF** 6.25 40 15 SX Address: 10551 BARKLEY ST. #307 **OVERLAND PARK, KS 66212** Well Type: EOR UIC Docket No: E28723.1 Date/Time to Plug: 07/25/2016 12:00 AM Plug Co. License No.: 33557 Plug Co. Name: SKYY DRILLING, LLC Proposal Revd. from: MARK HAAS Phone: (913) 499-8373 Company: Proposed Pump full of cement from top to bottom Plugging Method: Plugging Proposal Received By: <u>LEVI SHORT</u> WitnessType: NONE Date/Time Plugging Completed: 07/25/2016 12:00 AM KCC Agent: LEVI SHORT Actual Plugging Report: RUN 1-INCH TUBING TO TD (731 FEET) THEN PUMP PORTLAND CEMENT TO SURFACE. A TOTAL OF 20 SACKS OF CEMENT WERE USED TO PLUG WELL. CEMENT SUPPLIED BY CONSOLIDATED OWS (33961). RECEIVED KCC DIST#3 OCT 05 2016 CHANUTE. KS Remarks: FAILED MIT. Plugged through: TBG District: 03 Signed

KCC WICHITA

OCT 1.3 2016

RECEIVED

(TECHNICIAN)

OCT 1 4 2016

Form CP-2/3

ານ ພຸເ Exhibit**/k**e-2a Page 195 of 276



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

Kansas Corporation Commission Oil & Gas Conservation Division

1318475

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

| OPERATOR: License #: 3 | 33640 | | 1 | API No. 15 | 15-059-198 | 90-00-01 | |
|-----------------------------------|------------------------------|---------------------------------|--------------|---|--|--|--|
| Name: Haas Petroleum, LLC | | | | Spot Desc | cription: | | |
| Address 1: 10551 BARKLEY ST. #307 | | | | | <u>SE</u> _{Sec.} 4 _T | wp. <u>16</u> S. R. <u>21</u> V East West | |
| Address 2: | | | | | | | |
| City: OVERLAND PA | ARK State: KS | Zip: <u>66212</u> + <u>18</u> 1 | 12 | | | | |
| Contact Person: Mark H | | | | Footages | Calculated from Neare | est Outside Section Corner: | |
| Phone: (913) 499-83 | 373 | | | | NE NW | SE SW | |
| Type of Well: (Check one) | | OG D&A Cathoo | | County: _ | Franklin | | |
| Water Supply Well | | SWD Permit #: | | Lease Na | me: LIDIKAY | Well #: 11 W 1 | |
| ENHR Permit #: E287 | | rage Permit #: | _ | | | | |
| Is ACO-1 filed? ✓ Yes | | l log attached? Yes | No | | | roved on: (Date) | |
| Producing Formation(s): List | • | r sheet) m: T.D | | | | (KCC District Agent's Name) | |
| | | m: T.D | | Plugging (| Commenced: 7/25/ | 2016 | |
| | | m: T.D | | Plugging (| Completed: 07/25 | 5/2016 | |
| | 0 юр воло | п п.д | | | | | |
| Show depth and thickness of | all water, oil and gas forma | ations. | | | | | |
| Oil, Gas or Wate | r Records | | Casing F | Casing Record (Surface, Conductor & Production) | | | |
| Formation | Content | Casing | Size | | Setting Depth | Pulled Out | |
| | | Surface | 6.250 | | 40 | | |
| | | Production | 2.375 | 0 | 731 | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| cement or other plugs were u | ised, state the character of | same depth placed from (bo | ottom), to (| top) for each | n plug set. | off well with cement. | |
| Plugging Contractor License | #: 33557 | | _ Name: _ | Skyy D | Orilling, LLC | | |
| Address 1: 10551 BAR | RKLEY ST., Ste 30 |)7 | _ Address | 2: | | | |
| City: _OVERLAND PK | | | | State: KS | 3 | z _{ip:} <u>66212</u> + <u>1869</u> | |
| Phone: (620) 531-5 | 922 | | | | | | |
| Name of Party Responsible for | or Plugging Fees: Mark | Haas | | | | | |
| State of | County, _ | | | _ , SS. | | | |
| | | | | | ployee of Operator or | Operator on above-described well, | |
| | (Print Name) | | | | | | |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and

KCC DISTRICT III OFFICE FIELD REPORT PHOTO ID FORM



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: DR Lidikay 11-W-3

FSL: 2045

FEL: 146

API#: 15-059-19000-00-01

Date: 09/15/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 11-W-3

PIC Orientation:

Latitude: 38.686627

Longitude: -95.084729

Time: 2:22 PM

Additional Information: This is a photo of well #11-W-3. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.



Form CP-1 March 2010 This Form must be Typed Form must be Signed All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: 33640 | | API No. | _{15 -} 15-059 | -19900 |)-00-(| 01 | |
|--|--|--------------------|------------------------|---------------|------------------|--------------------|------------|
| Name: Haas Petroleum, LLC | If pre 1967, supply original completion date: Spot Description: | | | | | | |
| Address 1: 11551 ASH ST., STE 205 | | | | | | | |
| Address 2: | _ | <u>-SE</u> Sec. | 4 Twp. | <u>16</u> s. | R. <u>21</u> | ₹ East West | |
| City: LEAWOOD State: KS | 2475 | Fee | t from | North | / 🚺 South | Line of Section | |
| Contact Person: Mark Haas | <u>495</u> | Fee | t from | East | / West | Line of Section | |
| Phone: (913) 499-8373 | | Footage | s Calculated from | | _ | _ | ner: |
| Phone: (918) 488 8878 | | _ | Eropklin | 1W ✓ S | SE _ | SW | |
| | | County: Lease N | ame: DR LI | DIKAY | | Well #: 11 | W 3 |
| Check One: Oil Well Gas Well OG | D&A Cath | nodic Wate | er Supply Well | Othe | er: | | |
| SWD Permit #: | ENHR Permit #: E2 | 28723 | Gas S | torage P | ermit #: | | |
| Conductor Casing Size: | Set at: | | Cemented with: | | | | Sacks |
| Surface Casing Size: 6.0000 | _ Set at: | | Cemented with: | 5 | | | Sacks |
| Production Casing Size: 2.3750 | _ Set at:741 | | Cemented with: | 255 | | | Sacks |
| List (ALL) Perforations and Bridge Plug Sets: | | | | | | | |
| Condition of Well: Good Poor Junk in Hole Proposed Method of Plugging (attach a separate page if addit Pump full of cement from top to bottom. | Casing Leak at:itional space is needed): | _ Anhydrite Dept | h: | (Stor | e Corral i | Formation) | |
| Is Well Log attached to this application? Yes No | o Is ACO-1 filed? 🗸 Y | ⁄es No | | | | | |
| If ACO-1 not filed, explain why: | | | | | | | |
| Plugging of this Well will be done in accordance with K. Company Representative authorized to supervise plugging | | Rules and Regu | lations of the Sta | ite Corpoi | ation C | ommission | |
| Address: 11551 Ash Street, # 205 | C | ity. Leawood | Stat | e: KS | Zip: | 66211 | |
| Phone: (913) 499-8373 | | ту | Oldi | o | – 2 1p. – | | _ ' |
| Plugging Contractor License #: 33961 | N | lame. Conso | lidated Oil V | Vell Se | rvices | LLC | |
| Address 1: 1322 S GRANT | Ac | | | | | | |
| City: CHANUTE | AC | | | te: KS | 7in: | 66720 | |
| Phone: (<u>620</u>) <u>431-9210</u> | | | Sia | | _ - 1P | | - ' |
| Proposed Date of Plugging (if known): | | | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



1241762

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB- | 1 (Cathodic Protection Borehole Intent) T-1 (Transfer) X CP-1 (Plugging Application) | | | | |
|--|--|--|--|--|--|
| OPERATOR: License # | Well Location: | | | | |
| Address 1:11551 ASH ST., STE 205 | County: Franklin | | | | |
| Address 2: | Lease Name: D R LIDIKAY Well #: _11 W 3 | | | | |
| City: LEAWOOD State: KS Zip: 66211 + | | | | | |
| City: LEAWOOD State: KS Zip: 66211 + Contact Person: John Haas/Mark Haas | the lease below: | | | | |
| Phone: (913) 499-8373 Fax: () | | | | | |
| Email Address: | - | | | | |
| Surface Owner Information: Name: Karen Lidikay Address 1: 1355 N. Grover | When filing a Form T-1 involving multiple surface owners, attach an additional | | | | |
| Address 1: 1355 N. Grover | sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the county, and in the real estate property tax records of the county treasurer. | | | | |
| Address 2: | | | | | |
| City: Wenatchee State: WA Zip: 98801 + | - | | | | |
| the KCC with a plat showing the predicted locations of lease roads, ta | hodic Protection Borehole Intent), you must supply the surface owners and ank batteries, pipelines, and electrical lines. The locations shown on the plat I on the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. | | | | |
| owner(s) of the land upon which the subject well is or will be | e Act (House Bill 2032), I have provided the following to the surface e located: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form being filed is a Form C-1 or Form CB-1, the plat(s) required by this , and email address. | | | | |
| KCC will be required to send this information to the surface | I acknowledge that, because I have not provided this information, the owner(s). To mitigate the additional cost of the KCC performing this ass of the surface owner by filling out the top section of this form and the KCC, which is enclosed with this form. | | | | |
| If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form C | ng fee with this form. If the fee is not received with this form, the KSONA-1 P-1 will be returned. | | | | |
| Submitted Electronically | | | | | |
| I | _ | | | | |
| | | | | | |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Shari Feist Albrecht, Chair Jay Scott Emler, Commissioner Pat Apple, Commissioner

February 06, 2015

Mark Haas Haas Petroleum, LLC 11551 ASH ST., STE 205 LEAWOOD, KS 66211

Re: Plugging Application API 15-059-19900-00-01 D R LIDIKAY 11 W 3 SE/4 Sec.04-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after August 06, 2015. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The August 06, 2015 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3

TO: API Well Number: 15-059-19900-00-01 Spot: NENESE Sec/Twnshp/Rge: 4-16S-21E STATE CORPORATION COMMISSION **CONSERVATION DIVISION - PLUGGING** 2044 feet from S Section Line, 152 feet from E Section Line 266 N. Main St., Ste. 220 Lease Name: DR LIDIKAY Well #: 11 W 3 Wichita, KS 67202-1513 County: FRANKLIN Total Vertical Depth: 741 feet Depth (ft) Pulled (ft) Comment String Size Operator License No.: 33640 PROD 2.375 741 255 SX Op Name: HAAS PETROLEUM, LLC 20 5 SX SURF 6 Address: 11551 ASH ST., STE 205 LEAWOOD, KS 66211 Well Type: EOR Date/Time to Plug: 01/09/2015 12:00 AM UIC Docket No: E28723.25 Plug Co. License No.: 33961 Plug Co. Name: CONSOLIDATED OIL WELL SERVICES LLC Proposal Rcvd. from: JOHN HAAS Phone: (913) 499-8373 Company: Proposed Pump full of cement from top to bottom Plugging Method: Plugging Proposal Received By: <u>LEVI SHORT</u> WitnessType: COMPLETE (100%) Date/Time Plugging Completed: 01/09/2015 12:00 AM KCC Agent: LEVI SHORT Perfs: **Actual Plugging Report:** HOOK ON TO PRODUCTION CASING THEN PUMP PORTLAND CEMENT TO SURFACE, A TOTAL OF 255 SACKS OF CEMENT WERE USED TO PLUG WELL. RECEIVED KCC DIST#3 MAR 1 9 2015 CHANUTE, KS Received KANSAS CORPORATION COMMISSION MAR 2 4 2015 Remarks: **CONSERVATION DIVISION** WICHITA KS Plugged through: CSG MAR 25 2012/1

District: 03

(TECHNICIAN)

Signed



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

Kansas Corporation Commission Oil & Gas Conservation Division

1241797

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD

| OPERATOR: License #: 3 | 3640 | KAK. 0 | 2-3-117 | I APINo 15 | ; 15-059-1990 | 00-00-01 | |
|---|------------------------------|-----------------------------|----------|--|-----------------------|---|--|
| Name: Haas Petroleum, LLC | | | | Spot Description: | | | |
| Address 1:1551 ASH ST., STE 205 | | | | SE Sec. 4 Twp. 16 S. R. 21 Feast West | | | |
| Address 2: | | | | | | North / V South Line of Section | |
| City: <u>LEAWOOD</u> State: <u>KS</u> Zip: <u>66211</u> + | | | | 495 Feet from Feat / West Line of Section | | | |
| Contact Person: Mark H | | | | Footages (| Calculated from Neare | est Outside Section Corner: | |
| Phone: (913) 499-83 | 73 | | | | NE NW V | / SE SW | |
| Type of Well: (Check one) | | | | County: | Franklin | | |
| Water Supply Well | | SWD Permit #: | | Lease Nar | me: DR LIDIKA | Y Well #: 11 W 3 | |
| ✓ ENHR Permit #: E287 | | | _ | Date Well | Completed: | | |
| Is ACO-1 filed? ✓ Yes | No If not, is well | log attached? Yes | No | | | oved on: (Date) | |
| Producing Formation(s): List A | • | , | | | | (KCC District Agent's Name) | |
| | | m: T.D | | Plugging C | Commenced: 01/09 | | |
| Depth to | • | m: T.D m: T.D | | Plugging C | Completed: 01/09 |)/2015 | |
| Depth to | э тор: вошо | m: 1.D | | | | | |
| Show depth and thickness of | all water, oil and gas forma | ations. | | | | | |
| Oil, Gas or Water | Records | | Casing | g Record (Surface, Conductor & Production) | | | |
| Formation | Content | Casing | Size | | Setting Depth | Pulled Out | |
| | | Surface | 6.00 | 00 | 20 | 0 | |
| | | Longstring | 2.37 | 50 | 741 | 0 | |
| | | Longoning | 2.07 | 00 | 7.1. | | |
| | | | | | | | |
| | | | | | | | |
| | . 00 | | | • | | ds used in introducing it into the hole. If | |
| cement or other plugs were us | sed, state the character of | same depth placed from (bot | tom), to | (top) for each | plug set. | | |
| Mix and pump 255 | sks 50/50 Poz I | Mix into well. Shut | in ca | asing. | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | 22004 | | | Consol | : data d O:1 \\/all | Camiana II C | |
| Plugging Contractor License #: 33961 Name | | | | : Consolidated Oil Well Services LLC | | | |
| Address 1: 1322 S GRANT Addr | | | | s 2: PO E | 3OX 884 | | |
| City: _CHANUTE | | | | _ State: <u>KS</u> | 3 | zip: <u>66720</u> + | |
| Phone: (620_) _431-92 | 210 | | | _ | | | |
| Name of Party Responsible for | or Plugging Fees: Mark | Has/Haas Petroleur | n, LL | С | | | |
| State of | County, _ | | | , SS. | | | |
| | | | | Em | ployee of Operator or | Operator on above-described well, | |

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

(Print Name)

KCC DISTRICT III OFFICE FIELD REPORT PHOTO ID FORM



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 11-W-9

FSL: 894

FEL: 948

API#: 15-059-19882-00-01

Date: 09/14/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 11-W-9

PIC Orientation:

Latitude: 38.683465

Longitude: -095.087505

Time: 10:26 AM

Additional Information: This is a photo of well #11-W-9. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.



1270256

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: _33640 | API No. 15 - 15-059-19882-00-01 | | | | |
|---|--|--|--|--|--|
| Name: Haas Petroleum, LLC | If pre 1967, supply original completion date: | | | | |
| Address 1: 11551 ASH ST., STE 205 | Spot Description: | | | | |
| Address 2: | | | | | |
| | Feet from North / 🗹 South Line of Section | | | | |
| Mad Hann | 845 Feet from Feet from Section | | | | |
| Contact Person: Mark Haas | Footages Calculated from Nearest Outside Section Corner: | | | | |
| Phone: (913) 499-8373 | — NE ☐ NW ✓ SE ☐ SW | | | | |
| | County: Franklin | | | | |
| | Lease Name: LIDIKAY Well #: 11 W 9 | | | | |
| Check One: Oil Well Gas Well OG D&A | Cathodic Water Supply Well Other: | | | | |
| SWD Permit #: | | | | | |
| Conductor Casing Size: Set at: | | | | | |
| 7,000 | _ | | | | |
| | | | | | |
| | Cemented with: 20 Sacks | | | | |
| List (ALL) Perforations and Bridge Plug Sets: Attached | | | | | |
| Attached | | | | | |
| 004 7 740 | | | | | |
| Elevation: 991 (G.L. / K.B.) T.D.: 749 PBTD: | Anhydrite Depth:(Stone Corral Formation) | | | | |
| Condition of Well: Good Door Junk in Hole Casing Leak at: | (Interval) | | | | |
| Proposed Method of Plugging (attach a separate page if additional space is needed): | (mo vai) | | | | |
| Pump full of cement from top to bottom | | | | | |
| | | | | | |
| Is Well Log attached to this application? | Yes No | | | | |
| If ACO-1 not filed, explain why: | | | | | |
| | | | | | |
| | | | | | |
| Plugging of this Well will be done in accordance with K.S.A. 55-101 $\underline{\text{et.}}$ $\underline{\text{seq}}.$ and $\underline{\text{t}}$ | · | | | | |
| Company Representative authorized to supervise plugging operations: Mark Haa | | | | | |
| Address: 11551 Ash Street, # 205 | City: Leawood State: Kansas Zip: 66211 + | | | | |
| Phone: (913) 499-8373 | | | | | |
| | Name: Consolidated Oil Well Services LLC | | | | |
| Address 1: 1322 S GRANT | Address 2: PO BOX 884 | | | | |
| CHANILITE | State: KS Zip: 66720 + | | | | |
| Phone: (<u>620</u>) <u>431-9210</u> | | | | | |
| Proposed Date of Plugging (if known). 07/22/2015 | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



1270256

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB-1 | 1 (Cathodic Protection Borehole Intent) T-1 (Transfer) X CP-1 (Plugging Application) | | | |
|--|---|--|--|--|
| OPERATOR: License # | Well Location: SE | | | |
| Address 1: 11551 ASH ST., STE 205 | County: Franklin | | | |
| Address 2: | County: Franklin Lease Name: LIDIKAY Well #: 11 W 9 | | | |
| City: <u>LEAWOOD</u> State: <u>KS</u> Zip: <u>66211</u> + | | | | |
| Contact Person: Mark Haas | the lease below: | | | |
| Phone: (913) 499-8373 Fax: () | _ | | | |
| Email Address: | | | | |
| Surface Owner Information: Name: Mrs. John Layle Address 1: 5800 High Drive | When filing a Form T-1 involving multiple surface owners, attach an additional | | | |
| Address 1: _5800 High Drive | sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the | | | |
| Address 2: | county, and in the real estate property tax records of the county treasurer. | | | |
| City: Mission Haills State: Kansas Zip: 66208 + | | | | |
| the KCC with a plat showing the predicted locations of lease roads, ta | nodic Protection Borehole Intent), you must supply the surface owners and ink batteries, pipelines, and electrical lines. The locations shown on the plat on the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. | | | |
| owner(s) of the land upon which the subject well is or will be | Act (House Bill 2032), I have provided the following to the surface clocated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form being filed is a Form C-1 or Form CB-1, the plat(s) required by this and email address. | | | |
| KCC will be required to send this information to the surface | acknowledge that, because I have not provided this information, the owner(s). To mitigate the additional cost of the KCC performing this ss of the surface owner by filling out the top section of this form and e KCC, which is enclosed with this form. | | | |
| If choosing the second option, submit payment of the \$30.00 handlir form and the associated Form C-1, Form CB-1, Form T-1, or Form CB-1 | ng fee with this form. If the fee is not received with this form, the KSONA-1 P-1 will be returned. | | | |
| Submitted Electronically | | | | |
| I | | | | |
| | _ | | | |

| Form | CP1 - Well Plugging Application |
|-----------|---------------------------------|
| Operator | Haas Petroleum, LLC |
| Well Name | LIDIKAY 11 W 9 |
| Doc ID | 1270256 |

Perforations And Bridge Plug Sets

| Perforation Top | Perforation Base | Formation | Bridge Plug Depth |
|-----------------|------------------|-----------|-------------------|
| 680 | 710 | Squirrel | 749 |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Shari Feist Albrecht, Chair Jay Scott Emler, Commissioner Pat Apple, Commissioner

November 25, 2015

Mark Haas Haas Petroleum, LLC 11551 ASH ST., STE 205 LEAWOOD, KS 66211

Re: Plugging Application API 15-059-19882-00-01 LIDIKAY 11 W 9 SE/4 Sec.04-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after May 25, 2016. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The May 25, 2016 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3

TO:

STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING

266 N. Main St., Ste. 220 Wichita, KS 67202-1513 API Well Number: 15-059-19882-00-01

Spot: NWSESE

Sec/Twnshp/Rge: 4-16S-21E

892 feet from S Section Line,

948 feet from E Section Line

feet

Lease Name: LIDIKAY

County: FRANKLIN

Well #: 11 W 9

Total Vertical Depth: 749

Operator License No.: 33640

Op Name: HAAS PETROLEUM, LLC Address: 10551 BARKLEY ST. #307

OVERLAND PARK, KS 66212

| Strin CIB | | Depth (ft) 749 | Pulled (ft) | Comment | |
|--------------|---------|-------------------|-------------|---------|--|
| PRO | D 2 | 700 | | 20 SX | |
| PRO | D 2.375 | 749 | | | |
| SUR | F 7 | 20 | | 5 SX | |
| SUR | F 6.25 | 25 | | | |

Well Type: EOR

UIC Docket No: E28723.5

Date/Time to Plug: 07/22/2015 12:00 AM

Plug Co. License No.: 33961

Plug Co. Name: CONSOLIDATED OIL WELL SERVICES LLC

Proposal Revd. from: MARK HAAS

Company:

Phone: (913) 499-8373

Plugging Method:

Proposed Pump full of cement from top to bottom

Plugging Proposal Received By: LEVI SHORT

WitnessType: NONE

Date/Time Plugging Completed: 07/22/2015 12:00 AM

KCC Agent: LEVI SHORT

Actual Plugging Reports

Perfs:

| Actual Flugging Keport: | rens. |
|--|---|
| RUN 1-INCH TUBING TO TD (749 FEET) THEN PUMP PORTLAND CEMENT TO SURFACE. A TOTAL OF 20 SACKS OF CEMENT WERE USED TO PLUG WELL. | Top Bot Thru Comments 680 710 |
| | RECEIVED KCC DIST#3 MAR 2 1 2016 CHANUTE, KS |
| | LS |
| | |

Remarks:

Plugged through: TBG

District: 03

Signed &

(TECHNICK GC WICH!TA

MAR 25 2016

Form CP-2/3

RECEIVERC-2a Page 208 of 276



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

1272307

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD

| | | K.A.R. 8 | 2-3-117 | | | |
|--|------------------------------|-----------------------------|--|--|--|--|
| OPERATOR: License #: 33640 | | | API No. 15 - 15-059-19882-00-01 | | | |
| Name: Haas Petroleum, LLC | | | Spot Description: | | | |
| Address 1: 11551 ASH ST., STE 205 | | | <u>SE</u> _{Sec.} 4 | _{Twp.} <u>16</u> s. R. <u>21</u> √ East West | | |
| Address 2: | | | Feet from | North / 🗸 South Line of Section | | |
| City: <u>LEAWOOD</u> State: <u>KS</u> Zip: <u>66211</u> + | | Zip: <u>66211</u> + | 845 | Feet from | East / West Line of Section | |
| Contact Person: Mark Ha | aas | | - - | | | |
| Phone: (913) 499-8373 Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodi | | | Ins Ne Ne Ne Ne Ne Ne Ne Ne Ne N | | | |
| | | | | | | |
| ✓ ENHR Permit #: E287 | 23.5 Gas Sto | rage Permit #: | | | | |
| Is ACO-1 filed? ✓ Yes | No If not, is well | log attached? Yes | | • | proved on: (Date) | |
| Producing Formation(s): List A | | | _ | | (KCC District Agent's Name) | |
| Depth to | • | m: T.D | | | • | |
| | • | m: T.D | Plugging | Commenced: 07/2 | 2/2015 | |
| | | m:T.D | I Pluaaina | Completed: 07/2 | 2/2013 | |
| | • | | | | | |
| Show depth and thickness of a | all water, oil and gas forma | ations. | | | | |
| Oil, Gas or Water | Records | | Casing Record (Sur | face, Conductor & Prod | uction) | |
| Formation | Content | Casing | Size | Setting Depth | Pulled Out | |
| | | | | | _ | |
| | | Surface | 7.000 | 20 | 0 | |
| | | Production | 2.000 | 700 | 0 | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| cement or other plugs were us | ng to TD. Fill to | same depth placed from (bot | tom), to (top) for eac | h plug set. | ods used in introducing it into the hole. If | |
| Plugging Contractor License # Address 1: 1322 S GRA | ANT | | Address 2: PO | BOX 884 | | |
| City: <u>CHANUTE</u> Phone: (620) 431-92 | | | | S | zip: <u>66720</u> + | |
| // | | Наас | | | | |
| Name of Party Responsible for | | | | | | |
| State of | County, _ | | , SS. | | | |

the same are true and correct, so help me God.

Employee of Operator or Operator on above-described well,

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and

(Print Name)

KCC DISTRICT III OFFICE FIELD REPORT PHOTO ID FORM



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 11-W-10

FSL: 726

FEL: 1062

API#: 15-059-19881-00-01

Date: 09/14/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 11-W-10

PIC Orientation:

Latitude: 38.683006

Longitude: -095.087897

Time: 10:16 AM

Additional Information: This is a photo of well #11-W-10. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.



1320122

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: 33640 | API No. 15 - 15-059-19881-00-01 | | |
|---|---|--|--|
| Name: Haas Petroleum, LLC | If pre 1967, supply original completion date: Spot Description: | | |
| Address 1: 10551 BARKLEY ST. #307 | | | |
| Address 2: | <u>SE</u> Sec. 4 Twp. 16 S. R. 21 🗸 East West | | |
| City: OVERLAND PARK State: KS Zip: 66212 + 1812 | 730 Feet from North / ✓ South Line of Section | | |
| Contact Person: Mark Haas | 1075 Feet from 🗹 East / 🗌 West Line of Section | | |
| Phone: (913) 499-8373 | Footages Calculated from Nearest Outside Section Corner: | | |
| Fildle. () | NE NW SE SW County: Franklin | | |
| | Lease Name: LIDIKAY Well #: 11 W 10 | | |
| | | | |
| | athodic Water Supply Well Other: | | |
| SWD Permit #: ENHR Permit #: _ | _ • | | |
| Conductor Casing Size: Set at: | | | |
| | Cemented with: 25 Sacks | | |
| Production Casing Size: 2.3750 Set at: 752 | Cemented with: Sacks | | |
| List (ALL) Perforations and Bridge Plug Sets: | | | |
| Elevation: 991 (G.L. / K.B.) T.D.: 752 PBTD: | Anhydrite Depth: (Stone Corral Formation) (Interval) | | |
| Is Well Log attached to this application? Yes No Is ACO-1 filed? If ACO-1 not filed, explain why: | Yes No | | |
| Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and the | · | | |
| Company Representative authorized to supervise plugging operations: Mark Haas Address: 10551 Barkley St. #307 | | | |
| Address: 10331 Barriey 3t. #307 Phone: (913) 499-8373 | City: Overland Park State: KS Zip: 66212 + | | |
| | Name: Consolidated Oil Well Services LLC | | |
| | | | |
| | Address 2: PO BOX 884 | | |
| • | State: KS Zip: 66720 + | | |
| Phone: (<u>620</u>) <u>431-9210</u> | | | |
| Proposed Date of Plugging (if known): | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



1320122

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB-1 (C | cathodic Protection Borehole Intent) T-1 (Transfer) X CP-1 (Plugging Application) | | | |
|---|---|--|--|--|
| OPERATOR: License # | Well Location: | | | |
| Address 2: | If filing a Form T-1 for multiple wells on a lease, enter the legal description of the lease below: | | | |
| Surface Owner Information: Name: Karen Lidikay Address 1: 1355 N. Grover Address 2: City: Wenatchee State: WA Zip: 98801 + | When filing a Form T-1 involving multiple surface owners, attach an additional sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the county, and in the real estate property tax records of the county treasurer. | | | |
| the KCC with a plat showing the predicted locations of lease roads, tank | dic Protection Borehole Intent), you must supply the surface owners and batteries, pipelines, and electrical lines. The locations shown on the plat in the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. | | | |
| | pcated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form being filed is a Form C-1 or Form CB-1, the plat(s) required by this | | | |
| KCC will be required to send this information to the surface own | cknowledge that, because I have not provided this information, the ner(s). To mitigate the additional cost of the KCC performing this of the surface owner by filling out the top section of this form and CCC, which is enclosed with this form. | | | |
| If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 | fee with this form. If the fee is not received with this form, the KSONA-1 1 will be returned. | | | |
| Submitted Electronically | | | | |
| 1 | - | | | |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

October 20, 2016

Mark Haas Haas Petroleum, LLC 10551 BARKLEY ST. #307 OVERLAND PARK, KS 66212-1812

Re: Plugging Application API 15-059-19881-00-01 LIDIKAY 11 W 10 SE/4 Sec.04-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after April 20, 2017. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The April 20, 2017 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3

| TO: | API Well Number: 15 | <u>5-059-19881-00-01</u> | | |
|--|--|--------------------------|-------------------------------|--|
| STATE CORPORATION COMMISSION | Spot: <u>NWSESE</u> | Sec/Twnshp/Rge | : <u>4-16S-21E</u> | |
| CONSERVATION DIVISION - PLUGGING | 724 feet from S Se | ction Line, 1056 feet | 1056 feet from E Section Line | |
| 266 N. Main St., Ste. 220 | Lease Name: LIDIKAY | • | Well #: 11 W 10 | |
| Wichita, KS 67202-1513 | County: FRANKLIN | = | ical Depth: 752 feet | |
| O | · · | | | |
| Operator License No.: 33640 | <u>String Size</u> <u>De</u> PROD 2.375 752 | pth (ft) Pulled (ft) Com | <u>nent</u> | |
| Op Name: <u>HAAS PETROLEUM, LLC</u> | SURF 6.25 40 | | | |
| Address: 10551 BARKLEY ST. #307 | | | . , . | |
| OVERLAND PARK, KS 66212 | | | | |
| Well Type: <u>EOR</u> UIC Docket N | lo: <u>E28723.6</u> | Date/Time to Plug: | 06/24/2015 12;00 AM | |
| Plug Co. License No.: 33961 Plug Co. Name: | CONSOLIDATED OIL W | VELL SERVICES LLC | | |
| Proposal Revd. from: | Company: | | Phone: | |
| Proposed Plugging Method: | | | | |
| | | | | |
| Plugging Proposal Received By: <u>LEVI SHORT</u> | WitnessType: | | | |
| Date/Time Plugging Completed: 06/24/2015 12:00 A | M KCC Agent: | <u>LEVI SHORT</u> | | |
| Actual Plugging Report: | | Perfs: | | |
| RUN 1-INCH TUBING TO 700 FEET INSIDE 2-INCH | H CASING THEN FILL TO | 0 | | |
| SURFACE WITH PORTLAND CEMENT. | | | | |
| | | | | |
| | | } | | |
| | | | RECEIVED | |
| | | | KCC DIST#3 | |
| | | | FEB 08 2017 | |
| | | | CHANUTE, KS | |
| 1 | | | O111-41011-11/0 | |
| | | | 15 | |
| | | | | |
| | | | | |
| | | | KCC WICHITA | |
| | | | | |
| | | | FEB 1 0 2017 | |
| | | | RECEIVED | |
| Remarks: | | | | |
| | | | | |
| Plugged through: <u>TBG</u> | | | | |
| | | | | |
| District: 02 | gned | | | |
| District: <u>03</u> Si | gnea | //NET/CIERRIE/OF 1 P.Y. | | |
| | | (TECHNICIAN) | | |
| | | 1610 | (1) C Form CP-2/3 | |
| | | 77.0 | OICED Form CP-2/3 | |

Exhibit KC-2a Page 214 of 276

FEB 1 6 2017



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

Kansas Corporation Commission Oil & Gas Conservation Division

1320123

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

| OPERATOR: License #:3 | 3640 | | API No. 1 | _{5 -} <u>15-059-198</u> | 81-00-01 | | |
|--|------------------------------|------------------------------|------------------------|--|---|--|--|
| Name: Haas Petroleum, LLC | | | Spot Des | Feet from North / 📈 South Line of Section | | | |
| Address 1: 10551 BARKLEY ST. #307 | | | | | | | |
| Address 2: | | | | | | | |
| | | | <u>1075</u> | | | | |
| Contact Person: _Mark H | aas | | Footages | Footages Calculated from Nearest Outside Section Corner: | | | |
| Phone: (913) 499-8373 Type of Well: (Check one) | | | | NE NW ✓ SE SW County: Franklin Lease Name: LIDIKAY Well #: 11 W 10 | | | |
| | | | County: _ | | | | |
| | | rage Permit #: | _ Date wei | Date Well Completed: | | | |
| Is ACO-1 filed? Yes | | log attached? Yes | | | oved on: (Date) | | |
| Producing Formation(s): List A | • | <i>sheet)</i> m: T.D | | | (KCC District Agent's Name) | | |
| | | m: T.D | Plugging | Commenced: 06/24 | 1/2015 | | |
| | | m:T.D | Plugging | Completed: 06/24 | /2015 | | |
| Берини | . тор Вошог | II I.D | | | | | |
| Show depth and thickness of | all water, oil and gas forma | itions. | · | | | | |
| Oil, Gas or Water | Records | | Casing Record (Sur | asing Record (Surface, Conductor & Production) | | | |
| Formation | Content | Casing | Size | Setting Depth | Pulled Out | | |
| | | Surface | 6.2500 | 40 | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| cement or other plugs were us | sed, state the character of | same depth placed from (bott | om), to (top) for each | h plug set. | ds used in introducing it into the hole. If off well with cement. | | |
| Plugging Contractor License # | _{::} _33961 | | Name: Consc | olidated Oil Well | Services LLC | | |
| Address 1: 1322 S GRANT | | ddress 2: PO BOX 884 | | | | | |
| City: _CHANUTE | | State: <u>K</u> | S | zip: <u>66720</u> + | | | |
| Phone: (620) 431-92 | | | | | | | |
| Name of Party Responsible for | r Plugging Fees: Mark | Haas | | | | | |
| State of | County, _ | | , SS. | | _ | | |
| | (Drint Mana) | | En | nployee of Operator or | Operator on above-described well, | | |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and

KCC DISTRICT III OFFICE FIELD REPORT PHOTO ID FORM



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 11-W-11

FSL: 390

FEL: 1286

API#: 15-059-19880-00-01

Date: 09/13/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 11-W-11

PIC Orientation:

Latitude: 38.682081

Longitude: -095.088673

Time: 2:25 PM

Additional Information: This is a photo of well #11-W-11. This well is listed as plugged and abandoned. The well appears to be full of cement. Operator will need to dig down and cut the casing off below surface.



1320482

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: 33640 | API No. 15 - 15-059-19880-00-01 | | | | | |
|--|---|--|--|--|--|--|
| Name: Haas Petroleum, LLC | If pre 1967, supply original completion date: | | | | | |
| Address 1: 10551 BARKLEY ST. #307 | Spot Description: | | | | | |
| Address 2: | | | | | | |
| City: OVERLAND PARK State: KS Zip: 66212 + 1812 | 402 Feet from North / ✓ South Line of Section | | | | | |
| Contact Person: Mark Haas | <u>1420</u> Feet from √ East / West Line of Section | | | | | |
| Phone: (913) 499-8373 | Footages Calculated from Nearest Outside Section Corner: | | | | | |
| Fildle. () | — | | | | | |
| | Lease Name: LIDIKAY Well #: 11 W 11 | | | | | |
| | | | | | | |
| | athodic Water Supply Well Other: | | | | | |
| SWD Permit #: ENHR Permit #: _ | E28723.7 Gas Storage Permit #: | | | | | |
| Conductor Casing Size: Set at: | | | | | | |
| Surface Casing Size: 6.2500 Set at: 40 | Cemented with: 25 Sacks | | | | | |
| Production Casing Size: 2.3750 Set at: 700 | Cemented with: 90 Sacks | | | | | |
| List (ALL) Perforations and Bridge Plug Sets: | | | | | | |
| Elevation: 988 (G.L. / K.B.) T.D.: 700 PBTD: | Anhydrite Depth:(Stone Corral Formation) (Interval) | | | | | |
| · · · · · · · · · · · · · · · · · · · | Yes No | | | | | |
| Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and the Company Representative authorized to supervise plugging operations: Mark Haas | · | | | | | |
| | City: Overland Park State: KS Zip: 66212 + | | | | | |
| Phone: (913) 499-8373 | | | | | | |
| Plugging Contractor License #: 33961 | Name: Consolidated Oil Well Services LLC | | | | | |
| | Address 2: PO BOX 884 | | | | | |
| OLIANUTE | State: KS Zip: 66720 + | | | | | |
| Phone: (<u>620</u>) <u>431-9210</u> | | | | | | |
| Proposed Date of Plugging (if known): | | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



1320482

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB-1 (C | Cathodic Protection Borehole Intent) T-1 (Transfer) X CP-1 (Plugging Application) | | | | | |
|---|---|--|--|--|--|--|
| OPERATOR: License # | Well Location: | | | | | |
| Name:Haas Petroleum, LLC | SE_ Sec. ⁴ Twp. 16 S. R. 21 ✔ East West | | | | | |
| Address 1:10551 BARKLEY ST. #307 | County: Franklin | | | | | |
| Address 2: | Lease Name: LIDIKAY Well #: _11 W 11 | | | | | |
| City: OVERLAND PARK State: KS Zip: 66212 + 1812 | If filing a Form T-1 for multiple wells on a lease, enter the legal description of | | | | | |
| Contact Person: Mark Haas | the lease below: | | | | | |
| Phone: (913) 499-8373 Fax: () | | | | | | |
| Email Address: | | | | | | |
| Surface Owner Information: Name: Karen Lidikay Address 1: 1355 N. Grover Address 2: | When filing a Form T-1 involving multiple surface owners, attach an additional sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the county, and in the real estate property tax records of the county treasurer. | | | | | |
| City: Wenatchee State: WA Zip: 98801 + | | | | | | |
| the KCC with a plat showing the predicted locations of lease roads, tank are preliminary non-binding estimates. The locations may be entered or Select one of the following: X I certify that, pursuant to the Kansas Surface Owner Notice Acowner(s) of the land upon which the subject well is or will be locations of lease roads, tank are preliminary non-binding estimates. The locations may be entered or select one of the following: | pcated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form being filed is a Form C-1 or Form CB-1, the plat(s) required by this | | | | | |
| KCC will be required to send this information to the surface ow | cknowledge that, because I have not provided this information, the ner(s). To mitigate the additional cost of the KCC performing this of the surface owner by filling out the top section of this form and CCC, which is enclosed with this form. | | | | | |
| If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 | fee with this form. If the fee is not received with this form, the KSONA-1 1 will be returned. | | | | | |
| Submitted Electronically | | | | | | |
| Į. | _ | | | | | |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

October 25, 2016

Mark Haas Haas Petroleum, LLC 10551 BARKLEY ST. #307 OVERLAND PARK, KS 66212-1812

Re: Plugging Application API 15-059-19880-00-01 LIDIKAY 11 W 11 SE/4 Sec.04-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after April 25, 2017. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The April 25, 2017 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3

| STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING 266 N. Main St., Ste. 220 Wichita, KS 67202-1513 Operator License No.: 33640 Op Name: HAAS PETROLEUM, LLC Address: 10551 BARKLEY ST. #307 OVERLAND PARK, KS 66212 | | | Lease Name: Ll | 392 feet from S Section Line, 1279 feet from E Section Lease Name: LIDIKAY Well #: 11 W 1 County: FRANKLIN Total Vertical Depth: 779 String Size Depth (ft) Pulled (ft) Comment PROD 2.375 700 PROD 2.375 779 | | | | | |
|--|--------------------------|----------------|---------------------|---|--------------|--|--|--|--|
| Well Type: EOR | | | No: <u>E28723.7</u> | Date/Tim | e to Plug: 0 | 7/09/2015 12:00 AM | | | |
| Plug Co. License No | o.: <u>33961</u> | Plug Co. Name | : CONSOLIDATE | OIL WELL SERV | ICES LLC | | | | |
| Proposal Revd. from | n: | | Company: | | | Phone: | | | |
| Proposed Plugging Method: | | | | | | | | | |
| Plugging Proposal I | Received By: <u>L.F.</u> | VI SHORT | Witnes | ssType: <u>NONE</u> | | | | | |
| Date/Time Plugging | Completed: 07 | /09/2015 12:00 | AM KCC | Agent: LEVI SHO | <u>RT</u> | KCC WICHITA | | | |
| Actual Plugging Re | port: | | | | Perfs: | | | | |
| RUN 1-INCH TUBI SURFACE WITH P | | | CH CASING THEN | FILL TO | | FEB 1 0 2017 RECEIVED | | | |
| | | | | | | RECEIVED KCC DIST#3 FEB 08 2017 CHANUTE, KS | | | |
| | | | | | | LS | | | |
| | | | • | | | | | | |
| Remarks: | | | | | | | | | |
| Plugged through: | <u>TBG</u> | | | | | | | | |
| <u>.</u> | | | 11 | h - | | <u> </u> | | | |
| District: <u>03</u> | | ; | Signed | | | | | | |
| | | | | (TEC | EHNICIAN) | | | | |

Form CP-2/3

INVOICED



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

Kansas Corporation Commission Oil & Gas Conservation Division

1318791

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

| OPERATOR: License #: 3 | 33640 | | ı | API No. 15 | _{5 -} 15-059-198 | 80-00-01 | |
|-------------------------------|------------------------------|---------------------------------|--------------|---|---------------------------|--|--|
| Name: Haas Petr | | | | Spot Desc | ription: | | |
| Address 1: 10551 BA | RKLEY ST. #307 | | | | SE Sec. 4 To | wp. <u>16</u> S. R. <u>21</u> √ East West | |
| Address 2: | | | | 402 Feet from North / South Line of Section | | | |
| City: OVERLAND PA | ARK State: KS | Zip: <u>66212</u> + <u>18</u> 1 | 12 | | | | |
| Contact Person: Mark H | | | | Footages | Calculated from Neare | est Outside Section Corner: | |
| Phone: (913) 499-83 | 373 | | | | NE NW | SE SW | |
| Type of Well: (Check one) | | OG D&A Cathoo | | County: _ | Franklin | | |
| Water Supply Well | | SWD Permit #: | | Lease Nar | me: LIDIKAY | Well #: 11 W 11 | |
| ENHR Permit #: E287 | | rage Permit #: | | | | | |
| Is ACO-1 filed? ✓ Yes | | l log attached? Yes | No | | | roved on: (Date) | |
| Producing Formation(s): List | • | r sheet) m: T.D | | - | | (KCC District Agent's Name) | |
| | | m: T.D | | Plugging (| Commenced: 11/29 | 3/2015 | |
| | | m: T.D | | Plugging (| Completed: 11/29 | 9/2015 | |
| | 0 юр воло | п п.д | | | | | |
| Show depth and thickness of | all water, oil and gas forma | ations. | | | | | |
| Oil, Gas or Wate | r Records | | Casing I | Record (Surfa | ace, Conductor & Produ | ction) | |
| Formation | Content | Casing | Size | | Setting Depth | Pulled Out | |
| | | Surface | 6.250 | 0 | 40 | | |
| | | Production | 2.375 | 0 | 779 | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| cement or other plugs were u | ised, state the character of | same depth placed from (bo | ottom), to (| top) for each | n plug set. | off well with cement. | |
| Plugging Contractor License | #: 33557 | | _ Name: _ | Skyy D | Prilling, LLC | | |
| Address 1: 10551 BAR | RKLEY ST., Ste 30 |)7 | _ Address | 2: | | | |
| City: OVERLAND PK | ζ | | | State: KS + <u>1869</u> | | | |
| Phone: (620) 531-5 | 922 | | | _ | | | |
| Name of Party Responsible for | or Plugging Fees: Mark | Haas | | | | | |
| State of | County, _ | | | , SS. | | | |
| | | | | | ployee of Operator or | Operator on above-described well, | |
| | (Print Name) | | | | | | |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

Kansas Corporation Commission Oil & Gas Conservation Division

Form CP-4 March 2009 Type or Print on this Form Form must be Signed All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

| OPERATOR: License #:3 Name: Haas Petro Address 1: 10551 BAI Address 2: | | Spot Desc 402 | | | | |
|--|-----------------------------|---|--|------------------------------|--|--|
| City: OVERLAND PARK Contact Person: Mark Haas Phone: (913_) 499-8373 Type of Well: (Check one) Oil Well Gas Well OG D&A Cathod Water Supply Well Other: SWD Permit #: FINHR Permit #: E28723.7 Gas Storage Permit #: Is ACO-1 filed? Yes No If not, is well log attached? Yes Producing Formation(s): List All (If needed attach another sheet) Depth to Top: Bottom: T.D. Depth to Top: Bottom: T.D. Depth to Top: Bottom: T.D. | | Footages C County: Lease Nai Date Well The plugg by: Plugging (Plugging (| East / West Line of Section est Outside Section Corner: V SE SW Well #: 11 W 11 roved on: (Date) (KCC District Agent's Name) 0/2015 | | | |
| Show depth and thickness of a | | tions. | Opering Department (O.) | 0 1 1 0 0 1 | | |
| Oil, Gas or Water | | Opelan | | ace, Conductor & Production) | | |
| Formation | Content | Casing Surface | 7.0000 | Setting Depth 40 | Pulled Out | |
| | | Production | 2.3750 | 700 | | |
| cement or other plugs were us | sed, state the character of | same depth placed from (both | tom), to (top) for each | n plug set. | ods used in introducing it into the hole. If | |
| Plugging Contractor License # | 33961 | | Name: Conso | lidated Oil Well | Services LLC | |
| Address 1: 1322 S GR | ANT | | Address 2: PO E | 3OX 884 | | |
| City: CHANUTE | | | State: <u>K</u> S | 3 | zip: <u>66720</u> + | |
| Phone: (620) 431-92 | 210 | | | | | |
| Name of Party Responsible fo | r Plugging Fees: Mark | Haas | | | | |
| State of | County, _ | | | ployee of Operator or | Operator on above-described well, | |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 12-W-6

FSL: 1877

FEL: 1177

API#: 15-059-19901-00-01

Date: 09/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 12-W-6

PIC Orientation:

Latitude: 38.686166

Longitude: -095.088253

Time: 11:06 AM

Additional Information: This is a photo of well #12-W-6. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.

| TO: | API Well Number: <u>15-059-19901-00</u> | <u>)-01</u> |
|---|--|--------------------------------|
| STATE CORPORATION COMMISSION | Spot: <u>SWNESE</u> Sec/Ty | vnshp/Rge: <u>4-16S-21E</u> |
| CONSERVATION DIVISION - PLUGGING 266 N. Main St., Ste. 220 | 1873 feet from S Section Line, | 1161 feet from E Section Line |
| Wichita, KS 67202-1513 | Lease Name: LIDIKAY | Well #: <u>12 W 6</u> |
| | - | Total Vertical Depth: 792 feet |
| Operator License No.: 33640 | String Size Depth (ft) Pulled PROD 2,375 788 | (fi) Comments |
| Op Name: HAAS PETROLEUM, LLC | SURF 5.5 20 | |
| Address: 10551 BARKLEY ST. #307 OVERLAND PARK, KS 66212 | | |
| Well Type: EOR UIC Docket N | o: <u>E28723.12</u> Date/Time t | to Plug: 05/11/2018 12:00 AM |
| Plug Co. License No.: 33557 Plug Co. Name: | SKYY DRILLING, LLC | |
| Proposal Revd. from: <u>JULIE BARBER</u> | Company: HAAS PETROLEUM | Phone: (913) 499-8373 |
| Proposed Fill from TD to surface with cement. Plugging Method: | · | |
| Actual Plugging Report: Ran 1" to TD and circulated cement to surface, pulled 1" | M KCC Agent: LARRY MAF | RECEIVED KCC DIST # 3 |
| | | AUG 0 9 2018 |
| | | CHANUTE, KS |
| | INVOICED | 1 |
| | | LM |
| | AUG 1 0 2018 | |
| | | |
| Remarks: | | |
| Plugged through: <u>TBG</u> | | |
| District, 02 | and Dany Marcha | |
| District: 03 Sig | ned Tany Warla | NICTANI) |

Form CP-2/3

KOLAR Document ID: 1418000

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

Kansas Corporation Commission Oil & Gas Conservation Division

WELL PLUGGING RECORD

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

| t West |
|-------------|
| |
| |
| |
| of Section |
| of Section |
| |
| |
| |
| 6 |
| |
| (Date) |
| nt's Name) |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| ne hole. If |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| 1869_ |
| |
| |
| |
| |
| ne |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and

(Print Name)

the same are true and correct, so help me God.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 13

FSL: 427

FEL: 458

API#: 15-059-19873-00-00

Date: 09/13/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 13

PIC Orientation:

Latitude: 38. 682184

Longitude: -95. 085773

Time: 2:11 PM

Additional Information: This is a photo of well #13. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.



1320372

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act,
MUST be submitted with this form.

| OPERATOR: License #: 33640 | | API No. 15 - 15-059-19873-00-00 | | | | | | |
|---|---|--|----------------|--|--|--|--|--|
| Name: Haas Petroleum, LLC | | If pre 1967, supply original completion date: Spot Description: | | | | | | |
| Address 1: 10551 BARKLEY ST. #307 | | | | | | | | |
| Address 2: | | NW_SE_SE_SE Sec. 4 Twp. 16 S. R. 21 V East Wes | | | | | | |
| City: OVERLAND PARK State: KS | 66212 . 1812 | Feet from North / 🗹 South L | ine of Section | | | | | |
| Maul III | _ Zip:+ | Feet from 🗹 East / 🗌 West Li | ine of Section | | | | | |
| Contact Ferson. | | Footages Calculated from Nearest Outside Section Corner | : | | | | | |
| Phone: (913) 499-8373 | | □ NE □ NW ✓ SE □ SW | | | | | | |
| | | County: Franklin | | | | | | |
| | | Lease Name: EAST LIDIKAY Well #: 13 | | | | | | |
| Check One: ✓ Oil Well Gas Well OG | B D&A Cathodi | c Water Supply Well Other: | | | | | | |
| SWD Permit #: | ENHR Permit #: | | | | | | | |
| Conductor Casing Size: | _ | | | | | | | |
| | | Cemented with: 22 | | | | | | |
| Production Casing Size: 2.3750 | | 00 | | | | | | |
| List (ALL) Perforations and Bridge Plug Sets: | _ Set at: | Cemented with: | Sacks | | | | | |
| Elevation: 1000 (G.L. / K.B.) T.D.: 700 Condition of Well: Good Poor Junk in Hole Proposed Method of Plugging (attach a separate page if additional poor pump full of cement from top to bottom. | (Iitional space is needed): | nhydrite Depth:(Stone Corral Formation) nterval) | | | | | | |
| Is Well Log attached to this application? Yes No | o Is ACO-1 filed? ✓ Yes | □ No | | | | | | |
| If ACO-1 not filed, explain why: | | | | | | | | |
| Plugging of this Well will be done in accordance with K | .S.A. 55-101 <u>et. seq</u> . and the Rul | es and Regulations of the State Corporation Commission | | | | | | |
| Company Representative authorized to supervise plugging | operations: Mark Haas | | | | | | | |
| Address: 10551 Barkley St. # 307 | | Overland Park State: KS Zip: 66212 | + | | | | | |
| Phone: (913) 499-8373 | | | | | | | | |
| Plugging Contractor License #: 33961 | Nam | e: Consolidated Oil Well Services LLC | | | | | | |
| Address 1: 1322 S GRANT | Addre | | | | | | | |
| City: CHANUTE | | State: KS Zip: 66720 | + | | | | | |
| Phone: (<u>620</u>) <u>431-9210</u> | | | | | | | | |
| Proposed Date of Plugging (if known): | | | | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



1320372

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB-1 (C | athodic Protection Borehole Intent) | | | | | |
|---|---|--|--|--|--|--|
| OPERATOR: License #_ Name: 10551 BARKLEY ST. #307 | Well Location: NW_SE_SE_SE_Sec.4Twp. 16S. R. 21 ✓ East West County: Franklin Lease Name: EAST LIDIKAY Well #: 13 | | | | | |
| Address 2: | | | | | | |
| Surface Owner Information: Name: Karen Lidikay Address 1: 1355 N. Grover Address 2: | When filing a Form T-1 involving multiple surface owners, attach an additional sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the county, and in the real estate property tax records of the county treasurer. | | | | | |
| If this form is being submitted with a Form C-1 (Intent) or CB-1 (Cathod the KCC with a plat showing the predicted locations of lease roads, tank are preliminary non-binding estimates. The locations may be entered on Select one of the following: | batteries, pipelines, and electrical lines. The locations shown on the plat | | | | | |
| | cated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form eing filed is a Form C-1 or Form CB-1, the plat(s) required by this | | | | | |
| KCC will be required to send this information to the surface own | cknowledge that, because I have not provided this information, the ner(s). To mitigate the additional cost of the KCC performing this of the surface owner by filling out the top section of this form and CC, which is enclosed with this form. | | | | | |
| If choosing the second option, submit payment of the \$30.00 handling to form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 | fee with this form. If the fee is not received with this form, the KSONA-1 will be returned. | | | | | |
| Submitted Electronically | | | | | | |
| I | - | | | | | |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

October 24, 2016

Mark Haas Haas Petroleum, LLC 10551 BARKLEY ST. #307 OVERLAND PARK, KS 66212-1812

Re: Plugging Application API 15-059-19873-00-00 EAST LIDIKAY 13 SE/4 Sec.04-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after April 24, 2017. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The April 24, 2017 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3

| 10: | | API Well Number | : <u>15-059-198</u> | <u> </u> | | | | |
|---|---------------|--|---------------------|-------------------|------------------------------|-------------|--|--|
| STATE CORPORATION COMMISS | SION | Spot: SESESE Sec/Twnshp/Rge: 4-16S-21E | | | | | | |
| CONSERVATION DIVISION - PLU | GGING | 423 feet from | Section Li | ne, <u>458</u> fe | 458 feet from E Section Line | | | |
| 266 N. Main St., Ste. 220 | | Lease Name: EAS | T LIDIKAY | | Well #: 13 | | | |
| Wichita, KS 67202-1513 | | County: FRANKI | | Total Ve | rtical Depth: 700 | feet | | |
| Operator License No.: 33640 | | String Size | | Pulled (ft) Cor | - | | | |
| - | C | PROD 2,375 | 700 | 88 : | | | | |
| Op Name: HAAS PETROLEUM, LL | | SURF 7 | 40 | 22 5 | | | | |
| Address: 10551 BARKLEY ST. #30 OVERLAND PARK, KS 6 | | | | | | | | |
| | | | | | | | | |
| Well Type: OIL | UIC Docket N | | | Fime to Plug: | 06/24/2015_12:00 | <u>AM</u> | | |
| Plug Co. License No.: 33961 Proposal Rcvd. from: MARK HAAS | • | CONSOLIDATED (Company: | <u> JIL WELL SE</u> | KVICES LLC | Phone: (913) 49 | 00 9272 | | |
| <u> </u> | | Company. | | | F Hone. (515)4; | 77-03/3 | | |
| Proposed Pump full of cement from Plugging Method: | top to bottom | | | | | | | |
| Plugging Proposal Received By: LE | EVI SHORT | Witness | Type: <u>NONE</u> | | | | | |
| Date/Time Plugging Completed: 06 | ·- | | gent: <u>LEVI S</u> | HORT | KCCV | | | |
| | | | , <u>=</u> | | NCC V | VICHITA | | |
| Actual Plugging Report: | | | | Perfs: | FEB 1 | 0 2017 | | |
| RUN 1-INCH TUBING TO 700 FEE SURFACE WITH PORTLAND CEM | | H CASING THEN FI | LLTO | | | | | |
| SORFACE WITH FORTLAND CEN | 113141. | | | | REC | EIVED | | |
| | | | | | | | | |
| | | | | | D-0-" | | | |
| | | | | | RECEIVEI KCC DIST # | | | |
| | | | | | | | | |
| | | | | | FEB 08 26 | 017 | | |
| | | | | | CHANUTE, H | K S | | |
| | | | | | - | 10 | | |
|] | | | | | | | | |
| | | | | [| | , | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| D | | | | | | | | |
| Remarks: | | | | | | | | |
| Plugged through: TBG | | | | | | | | |
| | | | | | | | | |
| District 02 | | - AM | | | | | | |
| District: <u>03</u> | Si | gned // | | DECEMBER 4 5 | | | | |
| | | | (1 | FECHNICIAN | () | | | |

Form CP-2/3

INVOICED

FEB 1 6 2017 Exhibit KC-2a 230 of 276



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

1320373

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD


| | | N.A.R. 8 | 2-3-117 | | 45 050 400 | 70.00.00 | |
|--|------------------------------|------------------------------|----------|--|------------------------|---|--|
| OPERATOR: License #:3 | | | | API No. 15 - 15-059-19873-00-00 Spot Description: | | | |
| Name: Haas Petro | | | | | | | |
| Address 1: 10551 BA | KKLEY 51. #307 | | | NW.SE. SE SE Sec. 4 Twp. 16 S. R. 21 Feat Wes | | | |
| Address 2:OVERLAND PA | RK out Ke | 7: 66212 · 101 | | 411 Feet from North / South Line of Section | | | |
| Contact Person: Mark H | | • | | 462 Feet from Feet from Section Footages Calculated from Nearest Outside Section Corner: | | | |
| Phone: (913) 499-83 | | | | rootages | | | |
| | | OG D&A Cathodi | | | | ✓ SE SW | |
| Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodic Water Supply Well Other: SWD Permit #: ENHR Permit #: Gas Storage Permit #: Is ACO-1 filed? Yes No If not, is well log attached? Yes No | | | | | Franklin | ′^\\ | |
| | | | | | XAY Well #: 13 | | |
| | | | 1 | • | reved on (D) | | |
| Producing Formation(s): List A | <u> </u> | |] 140 | | | roved on: (Da (KCC District Agent's Nai | |
| Depth to | • | m: T.D | | 1 - | | · | |
| | • | m: T.D | | | Commenced: 06/24 | 4/2015 4/2015 | |
| | | m:T.D | | Plugging C | Completed: U6/22 | +/2013 | |
| | | | | | | | |
| Show depth and thickness of | all water, oil and gas forma | ations. | | | | | |
| Oil, Gas or Water | r Records | | Casing | Record (Surfa | ace, Conductor & Produ | uction) | |
| Formation | Content | Casing | Size | | Setting Depth | Pulled Out | |
| | | Ourteen | 7.00 | 00 | 40 | | |
| | | Surface | 7.00 | 00 | 40 | | |
| | | Production | 2.37 | 50 | 700 | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Describe in detail the manner | in which the well is plugge | ed, indicating where the mud | fluid wa | as placed and | the method or metho | ods used in introducing it into the hole | |
| cement or other plugs were us | sed, state the character of | same depth placed from (both | tom), to | (top) for each | plug set. | | |
| Rig and Ran 1" tub | oing to TD. Fill to | o surface with cem | ent. | Pull 1" ti | ubing and top | off well with cement. | |
| Plugging Contractor License # | _{#:} _ 33961 | | Name: | Consol | idated Oil Well | Services LLC | |
| Address 1: 1322 S GR | ANT | | Addres | s 2: PO E | 3OX 884 | | |
| City: CHANUTE | | | | _ State:_KS | 3 | z _{ip:} <u>66720</u> + | |
| Phone: (620_) 431-92 | | | | _ | | | |
| Name of Party Responsible for | or Plugging Fees: Mark | Haas | | | | | |
| State of | County, _ | | | , ss. | | | |
| | | | | Em | ployee of Operator or | Operator on above-described w | |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and

(Print Name)

the same are true and correct, so help me God.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 14F

FSL: 704

FEL: 597

API#: 15-059-19588-00-00

Date: 09/14/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 14F

PIC Orientation:

Latitude: 38. 682943

Longitude: -95.086270

Time: 10:04 AM

Additional Information: This is a photo of well #14F. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.

TO: API Well Number: 15-059-19588-00-00 Spot: NESESE Sec/Twnshp/Rge: 4-16S-21E STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING 597 feet from E Section Line 700 feet from S Section Line, 266 N. Main St., Ste. 220 Lease Name: EAST LIDIKAY Well #: 14F Wichita, KS 67202-1513 County: FRANKLIN Total Vertical Depth: 700 feet Depth (ft) Pulled (ft) Comment String Size Operator License No.: 33640 PROD 2.375 700 78 SX Op Name: <u>HAAS PETROLEUM, LLC</u> SURF 7 40 25 SX Address: 10551 BARKLEY ST. #307 **OVERLAND PARK, KS 66212** Well Type: OIL UIC Docket No: Date/Time to Plug: 06/24/2015 12:00 AM Plug Co. Name: CONSOLIDATED OIL WELL SERVICES LLC Plug Co. License No.: 33961 Proposal Rcvd. from: MARK HAAS Company: Phone: (913) 499-8373 Proposed Pump full of cement from top to bottom Plugging Method: Plugging Proposal Received By: <u>LEVI SHORT</u> WitnessType: NONE Date/Time Plugging Completed: 06/24/2015 12:00 AM KCC Agent: LEVI SHORT KCC WICHITA **Actual Plugging Report:** Perfs: RUN 1-INCH TUBING TO 700 FEET INSIDE 2-INCH CASING THEN FILL TO FEB 1 0 2017 SURFACE WITH PORTLAND CEMENT. RECEIVED RECEIVED KCC DIST#3 FEB 0.8 2017 CHANUTE, KS Remarks: Plugged through: TBG District: 03 Signed

Form CP-2/3

FEB 1 6 ZOTY Exhibit KC-2a Page 233 of 276

(TECHNICIAN)



1320124

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: 33640 | | API No. 1515-059-19588-00-00 | | | | | | |
|---|------------------------------|--|--------------------|---------------|---------------|-------------------------|------------|--|
| Name: Haas Petroleum, LLC | | If pre 1967, supply original completion date: Spot Description: | | | | | | |
| Address 1: _ 10551 BARKLEY ST. #307 | | | | | | | | |
| Address 2: | | | | | | | | |
| City: OVERLAND PARK State: KS | zin: 66212 ₊ 1812 | 696 | Fee | t from | North / | South Line | of Section | |
| Contact Person: Mark Haas | Zip + | 606 Feet from | | | | | | |
| Phone: (913) _499-8373 | | Footages | Calculated from | | | | | |
| Phone: (910) 433 0373 | | - | ☐ NE ☐ NE Franklin | \W \ S | SE S | W | | |
| | | County: _ Lease Na | me: EAST L | _IDIKA` | Y We | _{II #:} 14F | | |
| Check One: ✓ Oil Well Gas Well OG | D&A Catho | odic Water | Supply Well | Othe | er: | | | |
| SWD Permit #: | ENHR Permit #: | | Gas S | torage Pe | ermit #: | | | |
| Conductor Casing Size: | Set at: | | Cemented with: | | | | Sacks | |
| Surface Casing Size: 7.000 | Set at:40 | | Cemented with: | 25 | | | Sacks | |
| Production Casing Size: 2.3750 | Set at: | | Cemented with: | 78 | | | Sacks | |
| List (ALL) Perforations and Bridge Plug Sets: | | | | | | | | |
| Elevation: 995 (G.L. / K.B.) T.D.: 700 Condition of Well: Good Poor Junk in Hole Proposed Method of Plugging (attach a separate page if addition of the composed Method of Plugging (attach a separate page if addition of the composed Method of Plugging (attach a separate page if addition of the composed Method of Cement from top to bottom | Casing Leak at: | (Interval) | - | (Ston | e Corral Form | nation) | | |
| Is Well Log attached to this application? Yes No | Is ACO-1 filed? √ Yes | s No | | | | | | |
| If ACO-1 not filed, explain why: | | | | | | | | |
| | | | | | | | | |
| Plugging of this Well will be done in accordance with K.S | - - | ules and Regula | tions of the Sta | ite Corpor | ation Com | mission | | |
| Company Representative authorized to supervise plugging of Address: 10551 Barkley St. #307 | perations: City | Overland | Park Stat | e: KS | Zip: _66 | 5212 _{+ _} | | |
| Phone: (913) 499-8373 | | | | | | | | |
| Plugging Contractor License #:33961 | Nai | me: Consol | idated Oil V | Vell Ser | vices L | LC | | |
| Address 1: 1322 S GRANT | Add | dress 2: PO E | 3OX 884 | | | | | |
| City: CHANUTE | | | | te: KS | Zip: 66 | 720 + . | | |
| Phone: (<u>620</u>) <u>431-9210</u> | | | | | - | | | |
| Proposed Date of Plugging (if known): | | | | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



1320124

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB-1 (C | athodic Protection Borehole Intent) | | | | |
|---|---|--|--|--|--|
| OPERATOR: License #_ Name: | Well Location: SW_NE_SE_SE_Sec.4 Twp. 16 S. R. 21 | | | | |
| Address 2: | Lease Name: EAST LIDIKAY Well #: 14F | | | | |
| Surface Owner Information: Name: Karen Lidikay Address 1: 1355 N. Grover Address 2: | When filing a Form T-1 involving multiple surface owners, attach an additional sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the county, and in the real estate property tax records of the county treasurer. | | | | |
| the KCC with a plat showing the predicted locations of lease roads, tank | lic Protection Borehole Intent), you must supply the surface owners and batteries, pipelines, and electrical lines. The locations shown on the plat the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. | | | | |
| | cated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form eing filed is a Form C-1 or Form CB-1, the plat(s) required by this | | | | |
| KCC will be required to send this information to the surface own | cknowledge that, because I have not provided this information, the ner(s). To mitigate the additional cost of the KCC performing this of the surface owner by filling out the top section of this form and CC, which is enclosed with this form. | | | | |
| If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-1 | fee with this form. If the fee is not received with this form, the KSONA-1 I will be returned. | | | | |
| Submitted Electronically | | | | | |
| I | - | | | | |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

October 20, 2016

Mark Haas Haas Petroleum, LLC 10551 BARKLEY ST. #307 OVERLAND PARK, KS 66212-1812

Re: Plugging Application API 15-059-19588-00-00 EAST LIDIKAY 14F SE/4 Sec.04-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after April 20, 2017. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The April 20, 2017 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

Kansas Corporation Commission Oil & Gas Conservation Division

1320142


Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

| DPERATOR: License #:33640 Name:Haas Petroleum, LLC Address 1:10551 BARKLEY ST. #307 Address 2: | | | Spot Des SW_NE 696 696 Footages C County: | 606 Feet from East / West Line of Section Footages Calculated from Nearest Outside Section Corner: NE NW SE SW County: Franklin | | | |
|--|-----------------------------|------------------------------|---|--|--|--|--|
| ENHR Permit #: Gas Storage Permit #: Is ACO-1 filed? ✓ Yes | | Date Well Completed: | | | | | |
| Oil, Gas or Water | Records | | Casing Record (Sur | cord (Surface, Conductor & Production) | | | |
| Formation | Content | Casing | Size | Setting Depth | Pulled Out | | |
| | | Surface Production | 7.0000 | 700 | | | |
| cement or other plugs were us | sed, state the character of | same depth placed from (both | tom), to (top) for each | h plug set. | ods used in introducing it into the hole. If | | |
| Plugging Contractor License # Address 1: 1322 S GR. City: CHANUTE Phone: (620) 431-92 Name of Party Responsible for | ANT 210 | | Address 2: PO | BOX 884 | Services LLC zip: 66720 + | | |
| State of | County, _ | | | nployee of Operator or | Operator on above-described well, | | |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 15F

FSL: 1461

FEL: 1025

API#: 15-059-19875-00-00

Date: 09/16/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 15F

PIC Orientation:

Latitude: 38.685024

Longitude: -095.087790

Time: 1:57 PM

Additional Information: This is a photo of well #15F. This well is listed as plugged and abandoned. Operator will need to run down and tag cement. Operator will then need to circulate cement to surface before digging down and cutting the casing off below surface.

| TO: | API Well Number: <u>15-059-19875-00-00</u> |
|---|---|
| STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING 266 N. Main St., Ste. 220 Wichita, KS 67202-1513 | Spot: SWNESE Sec/Twnshp/Rge: 4-16S-21E 1454 feet from S Section Line, 1020 feet from E Section Line Lease Name: EAST LIDIKAY Well #: 15F County: FRANKLIN Total Vertical Depth: 770 feet |
| Operator License No.: 33640 Op Name: HAAS PETROLEUM, LLC Address: 11551 ASH ST., STE 205 LEAWOOD, KS 66211 | String Size Depth (ft) Pulled (ft) Comment SURF 6.5 20 |
| Well Type: OIL UIC Docket N | o: Date/Time to Plug: 04/07/2015 12:00 AM |
| Plug Co. License No.: 33961 Plug Co. Name: | CONSOLIDATED OIL WELL SERVICES LLC |
| <u>-</u> | Company: Phone: (913) 207-0257 |
| Proposed FILL FROM TOP TO BOTTOM WITH CEI Plugging Method: | MEN! |
| Plugging Proposal Received By: LEVI SHORT | WitnessType: NONE |
| Date/Time Plugging Completed: 04/07/2015 12:00 At | |
| Actual Plugging Report: | Perfs: |
| RUN 1-INCH TUBING TO TD (770 FEET) THEN PUT SURFACE. A TOTAL OF 50 SACKS OF CEMENT W | |
| Remarks: | |
| Plugged through: TBG | 10/27/15 CKW |
| District: 03 Sig | gned(TECHNICIAN) |

Form CP-2/3



1250447

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

| OPERATOR: License #: 33640 | | AP | 1 No. 15 - 15- | 059-1987 | 5-00-00 | | | |
|--|-----------------------------------|----------------|---|--------------------|----------------|------------------|-----------|--|
| Name: Haas Petroleum, LLC | | | If pre 1967, supply original completion date: | | | | | |
| Address 1: _ 11551 ASH ST., STE 205 | | Spo | ot Description: | | | | | |
| Address 2: | | | <u>NSW NESE</u> | Sec. <u>4</u> Twp. | <u>16</u> s. R | 21 S East | West | |
| | | | | Feet from | North / | South Line of | f Section | |
| | ZIP:+ | · <u>1</u> | 039 | Feet from | | West Line of | Section | |
| Contact i croon. | | Foo | otages Calculated | from Nearest | Outside Se | ction Corner: | | |
| Phone: (913) 499-8373 | | | NE Frankli | NW ✓ : | SE S | SW | | |
| | | | _{unty:} Frankli | | | 15E | | |
| | | Lea | ase Name: Eas | Liulkay | We | #: <u>15F</u> | | |
| Check One: ✓ Oil Well Gas Well OG | D&A | Cathodic | Water Supply We | ell Oth | er: | | | |
| SWD Permit #: | ENHR Permit #: | | | Sas Storage P | | | | |
| Conductor Casing Size: | _ Set at: | | | - | | | _ Sacks | |
| • | 20 | | | | | | | |
| Production Casing Size: 4.5000 | C7F | | Cemented | | | | Sacks | |
| List (ALL) Perforations and Bridge Plug Sets: | - | | | | | | _ | |
| Condition of Well: Good Poor Junk in Hole Proposed Method of Plugging (attach a separate page if additive) Pump full of cement from top to botto | onal space is needed): | (Interval) | | (Stoi | ne Corral Forn | nation) | | |
| | _ | 7 🗆 | | | | | | |
| Is Well Log attached to this application? Yes No | Is ACO-1 filed? ✓ | Yes No | | | | | | |
| If ACO-1 not filed, explain why: | | | | | | | | |
| | | | | | | | | |
| Plugging of this Well will be done in accordance with K.S. | S.A. 55-101 <u>et.</u> seq. and t | he Rules and I | Regulations of th | e State Corpo | ration Com | ımission | | |
| Company Representative authorized to supervise plugging of | pperations: Mark Haa | as | | | | | | |
| Address: 11551 Ash Street, # 205 | | City: Leaw | vood | State: KS | _ Zip: _66 | <u> </u> | | |
| Phone: (913) 499-8373 | | | | | | | | |
| Plugging Contractor License #:33961 | | | nsolidated C | | rvices L | LC | | |
| Address 1: 1322 S GRANT | | Address 2: | PO BOX 884 | 1 | | | | |
| City: CHANUTE | | | | State: KS | _ Zip:_66 | 720 + | | |
| Phone: (620_) 431-9210 | | | | | | | | |
| Proposed Date of Plugging (if known): 04/07/2015 | | | | | | | | |

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



1250447

Form KSONA-1
January 2014
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

| Select the corresponding form being filed: C-1 (Intent) CB-1 (Intent) | Cathodic Protection Borehole Intent) T-1 (Transfer) CP-1 (Plugging Application) |
|--|---|
| OPERATOR: License # | Well Location: SW_SW_NE_SE_Sec.4 Twp. 16 S. R. 21 ✓ East West County: Franklin Lease Name: East Lidikay Well #: 15F If filing a Form T-1 for multiple wells on a lease, enter the legal description of the lease below: |
| Email Address: | |
| Surface Owner Information: Name: John Layle Address 1: 5800 High Drive Address 2: | When filing a Form T-1 involving multiple surface owners, attach an additional sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the county, and in the real estate property tax records of the county treasurer. |
| the KCC with a plat showing the predicted locations of lease roads, tank | dic Protection Borehole Intent), you must supply the surface owners and k batteries, pipelines, and electrical lines. The locations shown on the plat n the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted. |
| | ocated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form being filed is a Form C-1 or Form CB-1, the plat(s) required by this |
| KCC will be required to send this information to the surface ov | acknowledge that, because I have not provided this information, the vner(s). To mitigate the additional cost of the KCC performing this sof the surface owner by filling out the top section of this form and KCC, which is enclosed with this form. |
| If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP- | fee with this form. If the fee is not received with this form, the KSONA-1 will be returned. |
| Submitted Electronically | |
| I | - |

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Shari Feist Albrecht, Chair Jay Scott Emler, Commissioner Pat Apple, Commissioner

April 21, 2015

Mark Haas Haas Petroleum, LLC 11551 ASH ST., STE 205 LEAWOOD, KS 66211

Re: Plugging Application API 15-059-19875-00-00 East Lidikay 15F SE/4 Sec.04-16S-21E Franklin County, Kansas

Dear Mark Haas:

The Conservation Division has received your Well Plugging Application (CP-1).

Under K.A.R. 82-3-113(b)(2), you must notify DISTRICT 3 of your proposed plugging plan at least 5 days before plugging the well. DISTRICT 3's phone number is (620) 432-2300. Failure to notify DISTRICT 3, or failure to file a Well Plugging Record (CP-4) after the well is plugged will result in a penalty recommendation.

Under K.A.R. 82-3-600, you must file an Application for Surface Pit (CDP-1) if you wish to use a workover pit while plugging the well. Failure to timely file a CDP-1, failure to timely remove fluids, or failure to timely file Closure of Surface Pit (CDP-4) or Waste Transfer (CDP-5) forms will result in a penalty recommendation.

This receipt does NOT constitute authorization to plug this well if you do not otherwise have the legal right to do so.

This receipt is VOID after October 21, 2015. If the well is not plugged by then, you will have to submit a new CP-1 if you wish to plug the well.

The October 21, 2015 deadline does NOT override any compliance deadline given to you by Legal, District, or other Commission Staff. Failure to comply with any given deadline will still result in the Commission assessing penalties, or taking other legal action.

Sincerely, Production Department Supervisor

cc: DISTRICT 3



Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

1250451

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

| OPERATOR: License #:33640 Name: Haas Petroleum, LLC Address 1:11551 ASH ST., STE 205 Address 2: | | | API No. 15 - 15-059-19875-00-00 Spot Description: SW_SW_NE_SE_Sec. 4 Twp. 16 S. R. 21 Feast West 1443 Feet from North / South Line of Section 1039 Feet from Feet from Section Corner: NE NW SE SW | | | |
|--|---------------------------------------|---|---|-----------------------------------|--|--|
| Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodic Water Supply Well Other: SWD Permit #: ENHR Permit #: Gas Storage Permit #: Is ACO-1 filed? Yes No If not, is well log attached? Yes Producing Formation(s): List All (If needed attach another sheet) Depth to Top: Bottom: T.D. Depth to Top: Bottom: T.D. | | County: Franklin Lease Name: East Lidikay Well #: 15F Date Well Completed: (Date) The plugging proposal was approved on: (KCC District Agent's Name) Plugging Commenced: 04/07/2015 Plugging Completed: 04/07/2015 | | | | |
| Show depth and thickness of all water, oil and gas format | | 0 1 5 1/0 1 | | | | |
| Oil, Gas or Water Records Formation Content | Casing | Size | Setting Depth Pulled Out | | | |
| Tomaton | Surface | 6.5000 | Setting Depth 20 | 0 | | |
| | Longstring | 4.5000 | 675 | 0 | | |
| Describe in detail the manner in which the well is plugge cement or other plugs were used, state the character of s Establish circulation through 1" tubic cement, pulled 1/2 tubing from well, 22 sacks cement, cement to surface | ng at casing TD. I mixed and pumpe | om), to (top) for each Mixed and pu ed | n plug set. Imped 22 sack | x 50/50 Poz Mix | | |
| Plugging Contractor License #: 33961 Name: | | _{Name:} Consol | Consolidated Oil Well Services LLC | | | |
| Address 1: 1322 S GRANT Addre | | Address 2: PO E | ss 2: PO BOX 884 | | | |
| City: _CHANUTE | | State: KS | 8 | zip: <u>66720</u> + | | |
| Phone: (620) 431-9210 | | | | | | |
| Name of Party Responsible for Plugging Fees: Mark | Haas/Haas Petroleu | ım, LLC | | | | |
| State of County, | | , | ployee of Operator or | Operator on above-described well, | | |

Submitted Electronically

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 1-F-W

FSL: 986

FEL: 1847

API#: 15-059-19895-00-01

Date: 09/16/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 1-F-W

PIC Orientation:

Latitude: 38.683718

Longitude: -095.090655

Time: 1:11 PM

Additional Information: This is a photo of well #1-F-W. This photo shows the well is inactive. The well is an authorized injection well. This well was not hooked up for injection and had no surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 2F

FSL: 71

FEL: 147

API#: 15-059-19868-00-00

Date: 09/13/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 2F

PIC Orientation:

Latitude: 38.681206

Longitude: -095.084672

Time: 2:59 PM

Additional Information: This is a photo of well #2F. This photo shows the well is inactive. This well is missing the pump string and pump jack. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 3

FSL: 431

FEL: 1724

API#: 15-059-19869-00-00

Date: 09/14/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 3

PIC Orientation:

Latitude: 38.682194

Longitude: -095.090209

Time: 9:21 AM

Additional Information: This is a photo of well #3. This well was found to be an inactive well. The pump jack and pump string is missing from this well location. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 3-HP

FSL: 2453

FEL: 1848

API#: 15-059-26888-00-00

Date: 09/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 3-HP

PIC Orientation:

Latitude: 38.687746

Longitude: -095.090703

Time: 9:57 AM

Additional Information: This is a photo of well #3-HP. This well was found to be an inactive well. The pump jack and pump string is missing from this well location. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 5-HP

FSL: 2466

FEL: 924

API#: 15-059-26869-00-00

Date: 09/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 5-HP


PIC Orientation:

Latitude: 38.687783

Longitude -095.087468

Time: 11:17 AM

Additional Information: This is a photo of well #5-HP. This well was found to be an inactive well. The pump jack is missing its belt and motor. The hose that connects the pump string to the riser is also unhooked. This well has a stuffing box



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 5I-HP

FSL: 2312

FEL: 1042

API#: 15-059-26894-00-00

Date: 09/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 5I-HP

PIC Orientation:

Latitude: 38.687360

Longitude: -095.087877

Time: 11:15 AM

Additional Information: This is a photo of well #5I-HP. This photo shows the well is inactive. The well was drilled as an EOR well but never authorized. This well had no surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 7-F-W

FSL: 648

FEL: 2129

API#: 15-059-19893-00-01

Date: 09/16/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 7-F-W

PIC Orientation:

Latitude: 38.682775

Longitude: -095.091643

Time: 1:33 PM

Additional Information: This is a photo of well #7-F-W. This photo shows the well is inactive. The well is an authorized injection well and the injection line is unhooked from the well.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 8

FSL: 123

FEL: 1192

API#: 15-059-19579-00-00

Date: 09/13/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 8

PIC Orientation:

Latitude: 38.681350

Longitude: -095.088335

Time: 2:38 PM

Additional Information: This is a photo of well #8. This well was found to be an inactive well. The pump jack and pump string is missing from this well location. This well is shut in with a valve and swedge.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 9-HP

FSL: 2133

FEL: 1820

API#: 15-059-26889-00-00

Date: 09/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 9-HP

PIC Orientation:

Latitude: 38.686869

Longitude -095.090597

Time: 10:09 AM

Additional Information: This is a photo of well #9-HP. This well was found to be an inactive well. The pump jack and pump string is missing from this well location. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 10-F

FSL: 2117

FEL: 333

API#: 15-059-19586-00-00

Date: 09/15/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 10-F


PIC Orientation:

Latitude: 38.686823

Longitude: -095.085386

Time: 2:35 PM

Additional Information: This is a photo of well #10-F. This well was found to be a producing oil well. This well wasn't on operator's well inventory but has since been placed on operator's well inventory as a producing oil well. This well was added due to the well-being in production and because of the area of review of the injection wells on lease.





Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 10-HP

FSL: 2155

FEL: 1174

API#: 15-059-26868-00-00

Date: 09/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 10-HP

PIC Orientation:

Latitude: 38.686928

Longitude: -095.088336

Time: 11:08 AM

Additional Information: This is a photo of well #10-HP. This photo shows the well is inactive. The pump jack is missing the belt. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 10-W-3-F

FSL: 76

FEL: 590

API#: 15-059-19889-00-01

Date: 09/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 10-W-3-F

PIC Orientation:

Latitude: 38.681221

Longitude: -095.086224

Time: 11:51 AM

Additional Information: This is a photo of well #10-W-3-F. This photo shows the well is inactive. The well is an authorized injection well. This well was not hooked up for injection and had no surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 10-W-6

FSL: 913

FEL: 43

API#: 15-059-19891-00-01

Date: 09/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 10-W-6

PIC Orientation:

Latitude: 38.683517

Longitude: -095.084334

Time: 2:33 PM

Additional Information: This is a photo of well #10-W-6. This photo shows the well is inactive. The well is an authorized injection well and was shut in with a plug.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 11-HP

FSL: 2155

FEL: 867

API#: 15-059-26871-00-00

Date: 09/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 11-HP

PIC Orientation:

Latitude: 38.686928

Longitude: -095.087260

Time: 11:20 AM

Additional Information: This is a photo of well #11-HP. This photo shows the well was hooked up for injection. The pumper was told this well wasn't an authorized EOR well and to unhook the well. I returned on 9/29/2021 and the well was unhooked.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 12-F

FSL: 2467

FEL: 1222

API#: 15-059-19872-00-00

Date: 09/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 12-F

PIC Orientation:

Latitude: 38.687784

Longitude: -095.088511

Time: 11:11 AM

Additional Information: This is a photo of well #12-F. This photo shows the well is inactive. The pump jack is missing the motor and belt. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 13-F

FSL: 1740

FEL: 980

API#: 15-059-19874-00-00

Date: 09/16/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 13-F

PIC Orientation:

Latitude: 38.685789

Longitude: -095.087642

Time: 2:24 PM

Additional Information: This is a photo of well #13-F. This photo shows the well is inactive. The pump string is hanging on a clamp. The pump jack is also missing from this well location. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 15-HP

FSL: 1805

FEL: 1467

API#: 15-059-26890-00-00

Date: 09/16/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 15-HP


PIC Orientation:

Latitude: 38.685967

Longitude: -095.089350

Time: 1:46 PM

Additional Information: This is a photo of well #15-HP. This well was found to be an inactive well. The pump jack is missing the motor and belt. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 17-F

FSL: 130

FEL: 471

API#: 15-059-19590-00-00

Date: 09/13/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 17-F

PIC Orientation:

Latitude: 38.681368

Longitude: -095.085810

Time: 2:50 PM

Additional Information: This is a photo of well #17-F. This photo shows the well is inactive. The pump string and pump jack are missing from this well location. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 19-F

FSL: 1941

FEL: 604

API#: 15-059-19592-00-00

Date: 09/16/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 19-F

PIC Orientation:

Latitude: 38.686342

Longitude: -095.086331

Time: 2:33 PM

Additional Information: This is a photo of well #19-F. This photo shows the well is inactive. The pump string and pump jack are missing from this well location. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 20-F

FSL: 2142

FEL: 1495

API#: 15-059-19593-00-00

Date: 09/17/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 20-F

PIC Orientation:

Latitude: 38.686892

Longitude: -095.089457

Time: 9:44 AM

Additional Information: This is a photo of well #20-F. This photo shows the well is inactive. The pump jack is missing the motor and belt. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 27

FSL: 125

FEL: 832

API#: 15-059-21152-00-00

Date: 09/13/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 27

PIC Orientation:

Latitude: 38.686869

Longitude -095.090597

Time: 2:44 PM

Additional Information: This is a photo of well #27. This well was found to be an inactive well. The pump jack and pump string is missing from this well location. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 32

FSL: 2450

FEL: 318

API#: 15-059-22014-00-00

Date: 09/15/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 32


PIC Orientation:


Latitude: 38.687739

Longitude: -095.085345

Time: 2:56 PM

Additional Information: This is a photo of well #32. This well was found to be a producing oil well. This well wasn't on operator's well inventory but has since been placed on operator's well inventory as a producing oil well. This well was added due to the well-being in production and because of the area of review of the injection wells on lease.





Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 38-HP

FSL: 855

FEL: 170

API#: 15-059-26970-00-00

Date: 09/14/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 38-HP

PIC Orientation:

Latitude: 38.683359

Longitude: -095.084779

Time: 10:09 AM

Additional Information: This is a photo of well #38-HP. This well was found to be an inactive well. The pump jack is missing the motor and belt. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 42

FSL: 1838

FEL: 790

API#: 15-059-19878-00-00

Date: 09/16/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 42


PIC Orientation:

Latitude: 38.686059

Longitude: -095.086979

Time: 2:27 PM

Additional Information: This is a photo of well #42. This well was found to be an inactive well. The pump jack is missing its belt. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 43-HP

FSL: 525

FEL: 172

API#: 15-059-26973-00-00

Date: 09/14/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 43-HP

PIC Orientation:

Latitude: 38.682453

Longitude: -095.084775

Time: 9:40 AM

Additional Information: This is a photo of well #43-HP. This well was found to be an inactive well. The pump jack and pump string are missing from this well location. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 48-HP

FSL: 1459

FEL: 1106

API#: 15-059-26993-00-00

Date: 09/16/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 48-HP


PIC Orientation:

Latitude: 38.685018

Longitude: -095.088075

Time: 1:54 PM

Additional Information: This is a photo of well #48-HP. This well was found to be an inactive well. The pump string is missing from this well. There is a pump jack at location, but its missing the horse head and belt. This well is shut in with a valve and swedge.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 49-HP

FSL: 758

FEL: 1454

API#: 15-059-25178-00-00

Date: 09/14/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 49-HP

PIC Orientation:

Latitude: 38.683092

Longitude: -095.089272

Time: 10:20 AM

Additional Information: This is a photo of well #49-HP. This well was found to be an inactive well. The pump string and pump jack is missing from this well. This well is shut in with a valve and swedge.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 50-HP

FSL: 1029

FEL: 1127

API#: 15-059-25179-00-00

Date: 09/14/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 50-HP

PIC Orientation:

Latitude: 38.683836

Longitude: -095.088134

Time: 10:20 AM

Additional Information: This is a photo of well #50-HP. This well was found to be an inactive well. The pump string and pump jack is missing from this well. This well is shut in with a valve and swedge.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 52-HP

FSL: 150

FEL: 1116

API#: 15-059-27038-00-00

Date: 09/13/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 52-HP

PIC Orientation:

Latitude: 38.681424

Longitude: -095.088071

Time: 2:42 PM

Additional Information: This is a photo of well #52-HP. This well was found to be an inactive well. The pump string and pump jack is missing from this well. This well is shut in with a valve and swedge.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 54-HP

FSL: 193

FEL: 498

API#: 15-059-27035-00-00

Date: 09/13/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 54-HP


PIC Orientation:

Latitude: 38.681540

Longitude: -095.085905

Time: 2:51 PM

Additional Information: This is a photo of well #54-HP. This well was found to be an inactive well. The pump string and pump jack is missing from this well. This well doesn't have any surface control.



Operator: Haas Petroleum, LLC

Lease: E. Lidikay

County: FR

Subject: East Lidikay 55-HP

FSL: 199

FEL: 169

API#: 15-059-27030-00-00

Date: 09/13/2021

Staff: Keith Carswell

KLN: 33640

Legal: 4-16-21E

PIC ID#: 55-HP

PIC Orientation:

Latitude: 38.681557

Longitude: -095.084756

Time: 2:57 PM

Additional Information: This is a photo of well #55-HP. This well was found to be an inactive well. The pump string and pump jack is missing from this well. This well doesn't have any surface control.