DRIVER/VEHICLE EXAMINATION REPORT Kansas Highway Patrol MOTOR CARRIER SAFETY ASSISTANCE Report Number: KSHP01000930 Inspection Date: 11/29/2016 **Certification Date:** 700 SW Jackson, Ste 704 Time Started: 14:00 Time Ended: 15:15 Topeka, KS 66603 Inspection Level: I - Full Inspection Phone # : (785)296-7189 Fax #: (785)296-2858 truckinspection@khp.ks.gov HM Inspection Type: No HM Inspection BENJAMIN, RICHARD L GARRETT BENJAMIN FARMS Driver: State: KS License #: COUNCIL GROVE, K\$ 66846 Date of Birth: USDOT#: Phone #: MC/MX#: Fax #: State #: S00000016541 Location: OLATHE SOUTH M.C.I.S. #24W 213 MilePost: Highway: 1-35 SB Origin: SPRING HILL,KS Bill of Lading: NONE Cargo: FOAM INSULATION County: **JOHNSON** Destination: EMPORIA,KS **CUSTOM HARDWOODS** Shipper: VEHICLE IDENTIFICATION: Unit VIN **GVWR** CVSA# CVSA Issued # Unit Type Make Year State Equipment ID License# TR FORD 2000 KS 59834 8,800 2 ST ELIT 2015 KS NONE 230145 22,500 **BRAKE ADJUSTMENTS:** Axle # 1 2 3 4 N/A N/A Right N/A N/A Left N/A N/A N/A N/A HYDR **HYDR ELEC ELEC** Chamber

OOS Stkr.#

140968

KSHP01000930

VIOLATIONS						· · · · · · · · · · · · · · · · · · ·	
Vio Code	Section	Unit		State Citation Number		Crash	Violation Description
392,8	392.8	D	N		N	N	Falling to inspectfuse emergency equipment: Falling to inspect emergency equipment; Driver falled to ensure vehicle was equipped with emergency equipment as required by 393.95
391.41A-F	391.41(a)	D	N		N	N	Operating a property-carrying vehicle without possessing a valid medical certificate.: Driver didn't know he needed a medical card
392.2DL	392.2	D	N		N	N	Miscellaneous Drivers License Violation: Miscellaneous Drivers . License Violation; KSA 8-2,133, Fall to self-certify medical card status with KDOR correctly - has declared Category 2, but is not exempt
390.21B	390.21(b)	1	N		N	N	Carrier name and/or USDOT Number not displayed as required: No carrier name displayed (does not have USDOT # to display)
385.301A	385.301(a)	1	N		N	N	Failing to register with FMCSA to obtain a USDOT number: Falling to register with FMCSA to obtain a USDOT number; www.fmcsa.dot.gov OR www.truckingks.com
393.60C	393.60(c)	1	N		N	N	Damaged or discolored windshield: Intersecting cracks in approximately center of windshield
393.9	393.9(a)	1	N		N	N	Inoperable Required Lamp; Reverse lamp inoperable - must have at least one white lamp that activates when the vehicle is shifted into reverse
392.2RG	392.2	1	N		N	N	State vehicle registration or License Plate violation: State vehicle registration or License Plate violation; KSA 8-133, Improper display of license plate; Current registration sticker was not displayed (showed 2015)
393,95A	393.95(a)	1	N		N	N	No/discharged/unsecured fire exlinguisher: NONE PRESENT
393,95F	393.95(f)	1	N		N	N	No / insufficient warning devices: NONE PRESENT
396.17C	396.17(c)	1	N		N	N	Operating a CMV without proof of a periodic inspection: Operating a CMV without periodic inspection; No evidence of annual inspection in or on truck
396.17C	396.17(c)	2	N		N	N	Operating a CMV without proof of a periodic inspection: Operating a CMV without periodic inspection; No evidence of annual inspection in or on trailer
392.2RG	392.2	2	N		N	N	State vehicle registration or License Plate violation: State vehicle registration or License Plate violation; KSA 8-142(1), No

Copy Received By:

Х

BENJAMIN, RICHARD L

Badge #:

0100

Report Prepared By:

N.B. Wright

Page 1 of 3

## DRIVER/VEHICLE EXAMINATION REPORT

GARRETT BENJAMIN					Report Number: KSHP01000930 Inspection Date: 11/29/2016 Certification Date: Time Started: 14:00 Time Ended: 15:15 Inspection Level: I - Full Inspection HM Inspection Type: No HM Inspection		
AND THE STATE OF T	S 66848					Driver: BENJAMIN, RICHARD L	
COUNCIL GROVE, K USDOT #: MC/MX #:	3 00010	Pho	10 #: ax #:			License #: State: KS  Date of Birth:	
State #: S00000016	5541	•	******				
393.9	393.9(a)	2	N	N	N	registration for trailer - actual weight was 7,180 lbs on fixed scale; Purchased 10/20/16 Inoperable Required Lamp: Passenger side trailer four-way	
393.9	393.9(a)	2	N	N	N	(hazard warning) lamp inoperable inoperable Required Lamp: Passenger side trailer stop (brake)	
393.9TS	393.9(a)	2	Υ	U	N	lamp inoperable Inoperative turn signal: Passenger side trailer turn signal	
393.48A :	393.48(a)	2	N	N	N	Inoperable Inoperative/defective brakes: Axle #3, Driver side, brakes Inoperable when function checked (trailer actual weight was 7,160 lbs on fixed scale)	
393.48A	393.48(a)	2	N	N	N	Inoperalive/defective brakes: Axle #4, Driver side, brakes Inoperable when function checked (trailer actual weight was 7,160 lbs on fixed scale)	
393.48A :	393.48(a)	2	N	N	N	Inoperative/defective brakes: Axie #3, Passenger side, brakes inoperable when function checked (trailer actual weight was 7,160 lbs on fixed scale)	
393.48A :	393.48(a)	2	N	N	N	Inoperative/defective brakes: Axle #4, Passenger side, brakes inoperable when function checked (trailer actual weight was 7,160 lbs on fixed scale)	
396.3A1BOS	396.3(a)(1)	2	Y	U	И	BRAKES OUT OF SERVICE; The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination; 4 of 8 brakes = 50% of combination	
393.43	393.43	2	Y	U	N	No/improper breakaway or omergency braking: Breakaway was disconnected when vehicle was stopped - no evidence of braking, pin not plugged in, traller actual weight 7,160 lbs	
392. <u>2</u> MI	392.2	2	N	N	N	Miscellaneous Traffic Law Violation: KSA 8-1907, No safety chains connected for trailer - chains resting loosely on bed of truck but not connected (gooseneck ball hitch)	
393.100B	393.100(b)	2	Υ	Α	N	Leaking/spilling/blowing/falling cargo: Foam insulation panels flew off of trailer, I-35 SB MP 213, struck another TT-ST (no damage)	
* N - Non-OOS or Dri	ver OOS Violation; U	Unkn	own; A - Repaired at	Scene		vantaye)	
HazMat:	No HM Tran	sporte	ed.			Placard: NA Cargo Tank:	
Special Checks:	<u>  </u>	y Loca	Substance Check al Jurisdiction nforcement		PAS	To Enforcement Post Crash Inspection  A Conducted Inspection PBBT Inspection  Interdiction Search Arrests:	

Report Prepared	By:
N.B. Wright	

Badge #: 0100 Copy Received By: BENJAMIN, RICHARD L

<u>X</u>

Page 2 of 3



KSHP01000930

## DRIVER/VEHICLE EXAMINATION REPORT

DKIVEKIVERIOLE	EXAMINATION REPORT	
Kansas Highway Patrol MOTOR CARRIER SAFETY ASSISTANCE 700 SW Jackson, Ste 704 Topeka, KS 66603 Phone #: (785)296-7189 Fax #: (785)296-2858 truckinspection@khp.ks.gov	Report Number: KSHP01000930 Inspection Date: 11/29/2016 Certification Date: Time Started: 14:00 Time Ended: 15:15 Inspection Level: I - Full Inspection HM Inspection Type: No HM Inspection	
GARRETT BENJAMIN FARMS	Driver: BENJAMIN, RICHARD L License #: State: KS	
COUNCIL GROVE, KS 66846  USDOT #: Phone #:  MC/MX #: Fex #:  State #: S00000018541	Date of Birth:	
Inspection Notes: *** CIVIL RECOMMENDED ***		
Pulled into scale by another Ruan truck because he lost some foam insu and was securing his load. J. Wilson, K2008, had him pull around back to	iallon that flew off and hit the Ruan TT-ST. He stopped in the left lane of the to finish so he wasn't blocking the lane.	scale
When contacted and asked about the name of his carrier, he immediatel from somewhere in Spring Hill near 215th & US-169 Hwy. He was not he (Garret Benjamin) back to Emporia as he is building a barn for his farm.	y sald it was farm use. He picked up this load of foam insulation (120 panels auling any agricultural products. He sald he was hauling this for his son's far	s of It) m
After I went through the whole inspection, the driver came over to me and which is exactly what I thought he would claim by the end of the inspection.	d sald he spoke to his son. At that point he was claiming it was all personal ion since he had some time to make phone calls.	use,
In-car video). He claimed this was all personal use to build a shop for his insulation panels with the name "Custom Hardwoods Garret Benjamin." I had that receipt. I explained, and he said that is a business is TRYING tumber to him (logs, etc.) and he will plane them down into flooring for the	onal use. I talked to his son on the phone (on speaker phone, recorded on m mself on his own property. The driver had a receipt (I have a photo) for the I asked Garret what that was all about and he inquired how that came up an to buy, which will be a custom flooring business where customers can bring em. At that point, I realized this was likely the purpose of the "shop" on his in commerce, whether it's his farm or his flooring business he's trying to buy	d why
Special Study Fields:		
Special Study1:	Special Study6:	
Special Study2:	Special Study7:	
Special Study3:	Special Study8;	
Special Study4:	Special Study9:	
Special Study5:	Special Study10:	
SERVICE". No person and/or carrier shall permit and/or require the rem ALL out of service defects have been corrected. This Out of Service con Carrier indicated on this report. Driver initials	C.C.C. Reg. 82-4-3, I hereby declare the above marked unit(s) as "OUT OF oval of the "OUT OF SERVICE" stickers or the operation of this motor vehicle idition may result in the assessment of a Civil Penalty being issued against to the contract of the c	ne
**\\** DRIVER: THIS FORM IS REQUIRED TO BE RETURNED TO THE defects on this sheet must be corrected or acknowledged PRIOR TO RE below. RETURN THIS FORM WITHIN 15 DAYS to the Motor Carrier Difform.	ECARRIER BY REGULATION. **//**  *CARRIER CERTIFICATION  E-DISPATCH and then certified by a responsible carrier official who must sign  vision of the KANSAS HIGHWAY PATROL at the address listed at the top of	1
Signature of Carrier Official: X	Dale:	
* NOTE TO MECHANIC: The undersigned certifies that all mechanical d	efects listed on this report HAVE BEEN CORRECTED at the time of signatu	ifê.
Signature of Repairer: X	Facility: Date:	

Report Prepared By: N.B. Wright <u>Badge #;</u> 0100 Copy Received By: BENJAMIN, RICHARD L Page 3 of 3



KSHP01000930