## THE STATE CORPORATION COMMISSION OF THE STATE OF KANSAS

C1 - -: E -: -4 A 11 - - - 1-4 C1 -: -

Before Commissioners:	Jay Scott Em	der
	Dwight D. K	
	8	
In the matter of the failure of Vince	e Coble dba )	Docket No.: 17-CONS-3544-CPEN
Derrick Resources Inc. ("Operator"	") to )	
comply with K.A.R. 82-3-111 at th	ne Ferrin )	CONSERVATION DIVISION

#3-15 in Comanche County, Kansas.

License No.: 35428

#### **SHUT-IN ORDER**

Upon its own motion, the Commission finds and concludes the Operator has violated a Commission Order for the following reasons:

#### I. JURISDICTION

- 1. The Commission has the exclusive jurisdiction and authority to regulate oil and gas activities in Kansas. The Commission has jurisdiction to regulate the "construction, operation, and abandonment of any well and the protection of the usable water of this state from any actual or potential pollution from any well." Every operator conducting oil and gas activity in Kansas must be licensed by the Commission.<sup>3</sup>
- 2. The Commission has the authority to issue a Penalty Order for violation of any provision of K.S.A. 55-101 *et seq.*, rule, regulation, or order of the Commission.<sup>4</sup> The Commission shall take appropriate action, which may include, but not be limited to, imposing a monetary penalty "not to exceed \$10,000, which shall constitute an actual and substantial

<sup>2</sup> K.S.A. 55-152.

<sup>&</sup>lt;sup>1</sup> K.S.A. 74-623.

<sup>&</sup>lt;sup>3</sup> K.S.A. 55-155.

<sup>&</sup>lt;sup>4</sup> K.S.A. 55-162; K.S.A. 55-164.

economic deterrent to the violation for which the penalty is assessed.<sup>5</sup> "In the case of a continuing violation, every day such violation continues shall be deemed a separate violations."

#### II. FINDINGS OF FACT

- 3. On April 20, 2017, the Commission issued a Penalty Order in this docket against the Operator for one violation of K.A.R. 82-3-111 because the Ferrin #3-15 well had been inactive in excess of the time allowed by regulation without being plugged, returned to service, or approved for TA status. The Penalty Order gave the Operator 30 days to pay a \$100 penalty and to plug the subject well, return the well to service, or obtain TA status. The Penalty Order stated that if the Operator failed to comply, then the Operator's license would be suspended without further notice.
- 4. On May 26, 2017, Staff suspended the Operator's license for non-compliance with the Penalty Order. Staff sent a Notice of License Suspension to the Operator, stating that the Operator was in violation of the Penalty Order. Staff's letter stated that if, after 10 days, Staff discovered the Operator performing oil and gas operations, Staff would recommend a Shut-In Order, including an additional \$10,000 penalty.<sup>7</sup>
- 5. On May 17, 2018, Commission District #1 Staff conducted an inspection and found the Operator's Liberal #29-189 well to be in operation. Staff noted the valves on the well were open and the meter run showed a 24 hour total of 16.8 MCF.<sup>8</sup> District #1 Staff also found the Operator's Travis #1-18 well to be in operation. Staff noted the valves on the well were open and the meter run showed a 24 hour total of 25.08 MCF.<sup>9</sup>

<sup>&</sup>lt;sup>5</sup> K.S.A. 55-164.

<sup>6</sup> Id.

<sup>&</sup>lt;sup>7</sup> See Exhibit A.

<sup>&</sup>lt;sup>8</sup> See Exhibit B.

<sup>&</sup>lt;sup>9</sup> See Exhibit C.

6. As of May 31, 2018, the Operator remained in non-compliance with the Penalty Order in this docket, and the Operator's license remained suspended. Although the Operator has paid the \$100 penalty associated with the Penalty Order, the Operator has not plugged, returned to service, or obtained TA status for the Ferrin #3-15 well.

#### III. CONCLUSIONS OF LAW

- 7. The Commission concludes that it has jurisdiction over the Operator and this matter under K.S.A. 55-152 and K.S.A. 74-623.
- 8. The above findings of fact are sufficient evidence to support the conclusion that the Operator has violated the Commission's Penalty Order in this docket, both by its failure to plug the Ferrin #3-15, returned it to service, or obtain TA status for it, and by its failure to cease operations upon the May 26, 2017, suspension of the Operator's license.

#### THEREFORE, THE COMMISSION ORDERS THAT:

- A. The Operator shall pay a \$2,500 penalty.
- B. Staff is directed to shut-in and seal all oil and gas operations of the Operator until such time as the Operator complies with the Commission's Penalty Order in this docket.
- C. <u>If no party requests a hearing, payment of the monetary penalty is due within 30</u> days from the date of service of this Order. Failure to timely submit the monetary penalty shall result in Operator's license being suspended without further notice, if it is not already. The Commission may impose further sanctions, including additional monetary penalties and any other remedies available to the Commission by law, without further notice.
- D. Checks and money orders shall be payable to the Kansas Corporation

  Commission. For credit card payments, include the type of card (Visa, MasterCard, Discover, or

  American Express), account number, and expiration date. Payments shall be mailed to the

Kansas Corporation Commission at 266 N. Main St., Suite 220, Wichita, Kansas 67202. <u>The payment must include a reference to the docket number of this proceeding.</u>

E. Any party may request a hearing on the above issues by submitting a written request, pursuant to K.S.A. 55-164, K.S.A. 77-537, and K.S.A. 77-542, setting forth the specific grounds upon which relief is sought, to the Commission at 266 N. Main St., Suite 220, Wichita, Kansas 67202, within 30 days from the date of service of this Order. Hearings will be scheduled only upon written request. <u>Failure to timely request a hearing will result in a waiver of the Operator's right to a hearing.</u>

- F. A corporation shall appear before the Commission by a Kansas licensed attorney.<sup>10</sup>
- G. The Commission retains jurisdiction over the subject matter and the parties for the purpose of entering such further order or orders, as it may deem necessary.

#### BY THE COMMISSION IT IS SO ORDERED.

Albrecht, Chair; Emler, Commissioner; Keen, Commissioner

Dated:	06/12/2018	Lynn M. Keg
		Lynn M. Retz
		Secretary to the Commission
Mailed Date:	06/13/2018	
LW		

<sup>&</sup>lt;sup>10</sup> K.S.A. 77-515(c); K.A.R. 82-1-228(d)(2).

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Pat Apple, Chairman Shari Feist Albrecht, Commissioner Jay Scott Emler, Commissioner

May 26, 2017

Vince Goble dba Derrick Resources Inc. PO Box 306 Henryetta, OK 74437

#### NOTICE OF LICENSE SUSPENSION License No. 35428 Docket No. 17-CONS-3544-CPEN

Operator:

Our records indicate that you are in violation of a Commission Order in the above Docket.

#### Your license is hereby suspended.

Until your license is reinstated, it is illegal for you to conduct oil and gas operations in Kansas.

If, after 10 days from the date of this letter, Commission Staff discover you performing oil and gas operations, Staff will recommend a Shut-In Order, including an additional \$10,000 penalty. If you are already shut-in, you must remain shut-in.

Any outstanding monetary penalty may be sent to collections.

You may review the Commission Order, which was mailed to you, at the Commission's website. If you have questions, you may contact us at the phone number listed at the top of this page.


Sincerely,

Legal Department Staff

### KCC OIL/GAS REGULATORY OFFICES

Date: <u>5/17/18</u>	District: _1		Case #:
	✓ New Situ	ation	Lease Inspection
	Response	e to Request	Complaint
	Follow-U	<sup>l</sup> p	Field Report
Operator License No: 35428	API Well Num	ber: <u>15-175-20</u>	4455-00-00
Op Name: Coble, Vince, dba Derrick Resources Inc.	Spot:	Sec	4 Twp 35 S Rng 33 E / W
Address 1: P.O. Box 306	•		Feet from N/ S Line of Section
Address 2:	***************************************		Feet from E/W Line of Section
City: Henryetta	GPS: Lat:	Lon	g:Date:
State: OK Zip Code: 74437 -	Lease Name: _	iberal	Well #: <u>29-189</u>
Operator Phone #: (918) 652-1400	County: Sev	vard	
Reason for Investigation:			
Check well Status			
Problem:			
Operator License is suspended and well is pr	roducing		
Persons Contacted:		19.40.00	
None			
Findings:			
Liberal 29-189 is a free flowing gas well with open top, 2'x6' two stage separator, and a res		· ·	• • • • • •
The valves on the well are open and the mete	er run is shov	ving 16.8 MCF	for a 24hr total.
Location is overgrown with weeds			
Action/Recommendations: Follow	v Up Required	Yes No [	Date:
Turn into Office for reveiw.			-
7 4 7 4 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6			
Verification Sources:			Photos Taken: 1
[ <del> </del>	ΓA Program	D <sub>v</sub> ,	
	Courthouse	By:	Joh
✓ Other: On Site Inspection		Heith Wa	UST
Retain 1 Copy District Office Send 1 Copy to Conservation Division			

Exhibit B
Page 1 of 2



# TO ALFLOW


Exhibit B Page 2 of 2

### KCC OIL/GAS REGULATORY OFFICES

Date: <u>5/17/18</u>	District: _1		Case #:
	New Situat	ion	Lease Inspection
	Response t	Request	Complaint
	Follow-Up		Field Report
	•		
Operator License No: 35428	API Well Numbe	r: <u>15-175-00077</u>	-00-01
Op Name: Coble, Vince, dba Derrick Resources Inc.	Spot:	Sec <u>18</u>	Twp <u>35</u> S Rng <u>32</u>
Address 1: P.O. Box 306			Feet fromN/_ S Line of Section
Address 2:	***************************************		Feet from E/W Line of Section
City: Henryetta	GPS: Lat:	Long:	Date:
State: OK Zip Code: 74437 -	Lease Name: <u>Tr</u>	avis	Well #: <u>1-18</u>
Operator Phone #: (918) 652-1400	County: Sewa	rd	
Reason for Investigation:			
Check well status			
Problem:			
Well is producing and Operators licence is su	ienended		
Tiveli is producing and Operators licence is so	ispended.		
Persons Contacted:			
None			
Findings:			
Travis 1-18 is a free flowing gas well with 4 1.	/2" casing Mai	or Pun 300bbl	motal cannod tank 2'v10' two
stage separator, and 2'x8' heated three stage	_	·	· · · · · · · · · · · · · · · · · · ·
stage departator, and 2 No floated times stage	nonzontai se,	diator or locati	orrad wor.
Valves on wellhead are open and the meter r	un shows 25.0	8 MCF for a 24	hr total.
,			
Action/Recommendations: Follow	v Up Required	Yes No	Date:
Turn in to Office for review			
Turn in to Office for review			
Verification Sources:			Photos Taken: 1
<b>V</b> RBDMS KGS 1	TA Program		
	Courthouse	Ву;	
✓ Other: On Site Inspection		Heith Walsh	
Retain 1 Copy District Office Send 1 Copy to Conservation Division			

Exhibit C Page 1 of 2

Form:



#### **CERTIFICATE OF SERVICE**

#### 17-CONS-3544-CPEN

I, the undersigned, certify that the true copy	of the attached Order has been served to the following parties by means of
first class mail and electronic service on	06/12/2018
VINCE COBLE D/B/A DERRICK RESOURCES INC. PO BOX 306 HENRYETTA, OK 74437	MICHELE PENNINGTON KANSAS CORPORATION COMMISSION DISTRICT OFFICE NO. 1 210 E. FRONTVIEW SUITE A DODGE CITY, KS 67801 Fax: 785-271-3354 m.pennington@kcc.ks.gov
STEPHEN PFEIFER KANSAS CORPORATION COMMISSION DISTRICT OFFICE NO. 1 210 E. FRONTVIEW SUITE A DODGE CITY, KS 67801 Fax: 785-271-3354 s.pfeifer@kcc.ks.gov	LAUREN WRIGHT, LITIGATION COUNSEL KANSAS CORPORATION COMMISSION Conservation Division 266 N. Main St. Ste. 220 WICHITA, KS 67202-1513 Fax: 316-337-6211 I.wright@kcc.ks.gov

/S/ DeeAnn Shupe DeeAnn Shupe