State: KS

DRIVER/VEHICLE EXAMINATION REPORT

Kansas Highway Patrol

MOTOR CARRIER SAFETY ASSISTANCE

700 SW Jackson, Ste 704 Topeka, KS 66603

Phone #: (785)296-7189

Fax #: (785)296-2858

truckinspection@khp.ks.gov

Report Number: KSHP04200689

Driver:

License #:

Date of Birth:

Inspection Date: 9/13/2019 Certification Date: Time Started: 13:40 Time Ended: 15:40

Inspection Level: I - Full Inspection
HM Inspection Type: No HM Inspection

DANNY G LAMBETH

22640 PLEASANT VALLEY RD

WELLSVILLE, KS 66092-9803

USDOT #: 00203558

MC/MX #:

Phone #:

Fax #:

State #:

Shipper:

Location: JOHNSON COUNTY - 091

DANNY LAMBETH

Highway: U56 / GARDNER RD, GARDNER

County: JOHNSON

MilePost: Origin:

WELLSVILLE,KS

Destination: GARDNER,KS

Bill of Lading: NONE

LAMBETH, DANNY G

Cargo: TOOLS/LUMBER

VEHICLE IDENTIFICATION:

Unit Type Make Year State License# Equipment ID Unit VIN GVWR CVSA# CVSA Issued# OOS Stkr.#

1 TR KW 1990 KS D37672 549136 50,000

BRAKE ADJUSTMENTS:

 Axle #
 1
 2
 3

 Right
 N/A
 N/A
 N/A

 Left
 N/A
 N/A
 N/A

 Chamber
 NONE
 NONE
 NONE

VΙ	O	LA	ΤI	O	N	S	
γı	$\mathbf{}$			v	14	·	

State Citation Vio Code Section Unit OOS Number Verify* Crash Violation Description								
Vio Code	Section				·		Violation Description	
392.16	392.16(a)	D	N	E002208054	N	N	Failing to use seat belt while operating a CMV	
392.7A	392.7(a)	D	N		Ν	N	Driver failing to conduct pre-trip inspection	
392.8	392.8	D	N		N	N	Failing to inspect/use emergency equipment	
396.17C	396.17(c)	1	N		N	N	Operating a CMV without proof of a periodic inspection: Driver was unable to locate periodic inspection for the unit. [Truck]	
393.9H	393.9(a)	1	Ν		N	N	Inoperable head lamps: Left Highbeam lamp Inop.	
393.9T	393.9(a)	1	Ν		Ν	N	Inoperable tail lamp: Left and right tail lamps INOP.	
393.9TS	393.9(a)	1	N		N	Ν	Inoperative turn signal: Left and Right rear turn signal INOP.	
393.9BRKLAMP	393.9(a)	1	N		Ν	N	Inoperative Brake Lamps: Left and right brake lamps INOP.	
393.9	393.9(a)	1	N		N	N	Inoperable Required Lamp: All ID and cleance lamps INOP.	
393.75A3	393.75(a)(3)	1	Υ		U	N	Tire-flat and/or audible air leak: Axle 2 left outside dual measures at 25psi (max 110psi)	
393.75A3	393.75(a)(3)	1	Υ		U	N	Tire-flat and/or audible air leak: Axle 2 right inside dual 0 psi (Max 110psi)	
393.81	393.81	1	Ν		N	Ν	Horn inoperative	
393.78	393.78	1	Ν		Ν	N	Windshield wipers inoperative/defective	
393.9	393.9(a)	1 ,	N		N	N	Inoperable Required Lamp: Right front clearence lamp INOP	
396.3A1-LLEAK	396.3(a)(1)	1	Υ		U	N	A liquid fuel system with a dripping leak at any point.: Left saddle tank dripping fuel and pooling on ground during inspection.	
392.2RG	392.2	1	N		N	N	State vehicle registration or License Plate violation: Registration plate not displayed to the rear of unit. KSA 08-0133.	
392.9AA1	392.9a(a)(1)	1	N		N	N	Operating without the Required Operating Authority: Per https://kcc.ks.gov/trans/mcsearch.cgi Carrier has no operating authority	
390.19A2	390.19(a)(2)	1	N		N	N	HMSP Motor Carrier failed to file required biennial update of MCS-150B as required.: Per CVIEW MCS-150 was last updated 02/13/2018 (Due an or before August 31, 2019)	
390.21B	390.21(b)	1	N		N	N	Carrier name and/or USDOT Number not displayed as required: No carrier name displayed.	
393.19	393.19	1	Ν		N	N	Inoperative/Defective Hazard Warning Lamp: Rear hazard lamps INOP.	

Report Prepared By:

R. DILKS

Badge #: 0420 Copy Received By: LAMBETH, DANNY G Page 1 of 3



KSHP04200689

DRIVER/VEHICLE EXAMINATION REPORT

Kansas Highway Patrol MOTOR CARRIER SAFETY 700 SW Jackson, Ste 704	ASSISTANCE		Report Number: Inspection Date:			
Topeka, KS 66603		Time Started: 13:40 Time Ended: 15:40				
Phone #: (785)296-7189	Fax #: (785)296-2858		Inspection Level:	I - Full Ins	pection	
truckinspection@khp.ks.gov			HM Inspection Typ	pe: No HM	1 Inspection	
DANNY G LAMBETH			Driver:	LAMBET	H, DANNY G	
22640 PLEASANT VALLEY			License #:		State: KS	
WELLSVILLE, KS 66092-98	03		Date of Birth:			
USDOT #: 00203558	Phone #:					
MC/MX #:	Fax #:					
State #:						
393.51 393.51	1 Y	U N	No or defective be or audible signal.		ing device: No low air warning ligh	t
* N - Non-OOS or Driver OO				511	NIA COLUMNIA	
HazMat:	No HM Transported.		<u></u>	Placard:	NA Cargo Tank:	
Special Checks:	Alcohol/Controled Substance Check	< X Traff	ic Enforcement		Post Crash Inspection	
	Conducted by Local Jurisdiction	PAS	A Conducted Inspect	ion [PBBT Inspection	
	Size and Weight Enforcement	Drug	Interdiction Search	Ā	Arrests:	
	EScreening					
stopped the red traffic light at the upper headache rack on t truck had a Kansas Dealer Fo drivers license. The driver st that the truck he was driving ibuy "parts" the driver initially	westbound U56 at Gardner Road. The back of the cab. Driver had 2 6x6 lull use tag displayed in the front winds ated that he is not a truck driver and his in the businesses inventory and is for	he brake light at the pieces of wood on whield of the truck. He is exempt CVS, or sale. The driver mply with the insp	ne rear of the unit who the bed of truck that The driver identified inspections. The driver was drving from Westion. Their was a	ere not op t was loos I himself w river was ellsville, KS	cooper turned around and the truck was berating. The Truck had brake lights of ely attached by a chain and binder. To with a valid Kansas Class A commercial the owner of the company and states to Gardner, KS, O'Reilly Auto Parts to le air leak coming from the dash of the	n he al d to
Brake measurements were no	ot completed due the driver refusing to	o comply with the	inspection.			

demand payment as it bypas	rrier is contesting oos civil fines and a ses the justice system.	few other violatio	ns. Carrier states he	doesnt ne	eed authority, and states KCC cannot	
brake warning device, there r	n 50% of the max psi, violations are vance of audible or visible warning signal who ground during the inspection with furt	en tested, violatio		ılid		
will address state statute for h	peing able to assess civil penalties					
fines and violations will remai	n as is 10/22/2019 jpeterson					
Special Study Fields:						
Special Study1:		Specia	l Study6:			
Special Study2:		Specia	l Study7:			
Special Study3:		·	l Study8:			
Special Study4:		•	l Study9:			
Special Study5:		•	l Study10:			
	ntained in Title 49, CFR; K.S.A. 66-1,1		•	are the ab	ove marked unit(s) as "OUT OF	
SERVICE". No person and/or	r carrier shall permit and/or require the ve been corrected. This Out of Servic	e removal of the "(OUT OF SERVICE" s	stickers or	the operation of this motor vehicle unt	til
defects on this sheet must be	S REQUIRED TO BE RETURNED TO corrected or acknowledged PRIOR T	O RE-DISPATCH	and then certified by	a respons	*CARRIER CERTIFICATION: All sible carrier official who must sign at the address listed at the top of this	
Signature of Carrier Official:	X				Date:	
Report Prepared By:	Badge #: Copy	Received By:	Page 2 of 3			_
R. DILKS	0420 LAM	BETH, DANNY G				

KSHP04200689

DRIVER/VEHICLE EXAMINATION REPORT

MOTOR CARRIED CAFETY AS	OLOTANOS	Report Number:	Report Number: KSHP04200689				
MOTOR CARRIER SAFETY AS 700 SW Jackson, Ste 704	SISTANCE	Inspection Date:	9/13/2019	Certification Date:			
Topeka, KS 66603	Y	Time Started:	13:40	Time Ended: 15:40			
	ax #: (785)296-2858	Inspection Leve	ı: I - Full Inspe	ection			
truckinspection@khp.ks.gov		HM Inspection T	Type: No HM Inspection				
DANNY G LAMBETH		Driver:	LAMBETH	, DANNY G			
22640 PLEASANT VALLEY RD		License #:		State: KS			
WELLSVILLE, KS 66092-9803		Date of Birth:					
USDOT #: 00203558	Phone #:		_				
MC/MX #:	Fax #:						
State #:							
* NOTE TO MECHANIC: The ur	dersigned certifies that all mechanical	defects listed on this report HAV	E BEEN COF	RRECTED at the time of signature.			
Signature of Repairer:	,	Facility:		Date:			

Report Prepared By: R. DILKS

Badge #: 0420 Copy Received By: LAMBETH, DANNY G Page 3 of 3



KSHP04200689